

SERVICEABLE

Propeller

Mc Cauley

UNIT NAME

MFG. NAME

K/60DTM-7537M1 82113

MODEL OR TYPE

SERIAL NO.

The propeller or appliance identified above was ~~repaired~~ overhauled and inspected in accordance with the 730723 overhaul manual and current Regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details of the repair are on file at this repair station under:

West Valley Aircraft Services
OWNER

8619

WORK ORDER #

05/11/2012

DATE

[Signature]

SIGNED

SULLIVAN PROPELLER SPECIALISTS

2156 AMERICAN AVENUE

HAYWARD, CA 94545

510.782.0920 • FAX 510.264.9162

F.A.A. REPAIR STATION #S5UR963J

PROPELLER MAINTENANCE RECORD

Position Fmt

PITCH RANGE

Propeller Model PC160DTM7557M1 High/Feather

Propeller S/N 82113 Start Lock

Blade Design Low

Blade S/N's Reverse

No. 1

No. 2

No. 3

No. 4

No. 5

No. 6

Aircraft Manufacturer Cessna

Aircraft Model 172N

S/N 17272534


Registration 5346D

Spinner Assembly Part No.

N5346D

McCauley 1C160DTM7557M1

Serial No. 82113



West Valley Aircraft Services, LLC.

Embarcadero Rd. Hangar B, Palo Alto, CA 94303

Tel. (650) 565-0063

7/1/2012

Tach: 3279.23

TTA: 7365.23

Propeller Entry:

Installed propeller following overhaul Sullivan Propeller Specialist CRS #S5UR963J WO#8619.

Kevin R. Pinger A&P 3236526 IA

N5346D

McCauley 1C160DTM7557M1

Serial No. 82113

AERO WORKS dba

1901 Embarcadero Rd. Executive Hangar One, Palo Alto, CA 94303

Tel. (650) 565-0063

1/3/2022

Tach: 3310.92

TTA: 7396.92

PTSO: 31.69

Propeller Entry:

Performed **Annual Inspection** of the aircraft in accordance with 14 CFR Part 43 Appendix D.

I certify that this aircraft has been inspected in accordance with an **Annual Inspection** and was determined to be in airworthy condition.

Kevin R. Pinger A&P 3236526 IA