



PROPELLER SERVICE, INC.

FAA -PS4R451M

**Burlington - Alamance Regional Airport
Burlington, NC 27215**

**Propeller Logbook
(336) 227-1467
1-800-334-6437**

**DESCRIPTIONS OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS**

SERVICEABLE PART

MANUFACTURER Hartnell

PART NAME Propeller

MODEL HC-922K-8D

PART NO. _____

SERIAL NO. 197L

REMARKS: Disassembled C.W.A.D.
Wk(95-1108), s/b 136T, 137A, s/b
258R-1, s/b 169. Assembled, ground,
Painted, balanced, B.L. Aug 4
1947A-12A #1) C93512
H2) C94213

ACCOMPLISHED BY Bobby Evans

THE AIRCRAFT PROPELLER OR COMPONENT IDENTIFIED ABOVE WAS REPAIRED AND INSPECTED IN ACCORDANCE WITH CURRENT REGULATIONS OF THE FEDERAL AVIATION AGENCY AND WAS FOUND AIRWORTHY FOR RETURN TO SERVICE. PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS REPAIR STATION UNDER:

Order No. 23495 Date 5 Aug-19

Signed [Signature]
Signature of Authorized Representative

FOR: H & H PROPELLER SERVICE
Burlington Municipal Airport
Burlington, NC 27215

F.A.A. REPAIR STATION NO. PS4R451M;

Signature _____

**DESCRIPTIONS OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS**

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
9-3-19	2139.33	Installed this prop on PR24-180 SN24-1737 N6616P after being repaired by H4H Propeller Service in Burlington, N.C. I certify that this prop has been inspected in accordance with a 100hr/annual inspection & is approved for return to service.	Samuel Barnes ATP 242644424
5-20-21	2185.02	Had governor overhauled & by H4H Propeller Service in Burlington N.C. Flushed prop out & reinstalled prop using a new shim PNB-1322 & a new O-ring P/N C-3317-329. I certify that this prop has been inspected in accordance with a 100hr inspection & is approved for return to service.	John E. Gutter 402065620 IA