

PROPELLER LOGBOOK

4	ω	N	Blade Serial No. 1	Hub Serial No.	Blade Model	Propeller Model	Engine Model	Aircraft S/N	Aircraft Model
				1.601.81		10160/DTM 1553	S/N		

LIMITED WARRANTY

Northwest Propeller Service warrants this product to be free of defects in workmanship and materials under normal use and service for a period of:_____months or____hours which every comes first.

Northwest Propeller Service obligation under this warranty will be to repair any warrantable unit at the discretion of the Northwest Propeller Service Overhaul Facility.

No field repairs are authorized and any tampering with or breaking of seals will invalidate any and all warranties of this product.

In application for warranty it is the customers responsibility to return this product with any frieght and handling services "pre-paid", with verification of the installation and removal dates of the warranted item (i.e. copies of the log book entries or work orders.)

Warranty will not be valid unless the above information is received with the part.

THIS WARRANTY DOES NOT COVER OR INCLUDE ANY LABOR CHARGES.

					à.	-			
 App Avia 	roving National tion	2.						3. Form Track	king Number:
Auti	erity/Country:	AUTH	IORIZED	RELEA	SEC	ERTIFIC	AIE		*
	/United States	F	AA Form 8130	-3, AIRWORTH	NESS AP	PROVAL TAG			9
4. Orga	nization Name and Ad	ldress:						Work Orde Number:	r/Contract/Invoice
			16709 I	st Propeller Serv Meridian St. E. U	de Inc.			Number.	
			Puya	111Up. WA 98371	3			W/O 208	56
6.	7. Description:	8. F	Certified R Part Number:	Repair Station No.	T6R625N	10. Quantity:	11 Serial/B	atch Number:	12. Status/Work:
Item:			art realiber.	9. Eligibility	(*	10. Quantity.	11.00110#2		12. Otatus/VVOIK.
1	1 MCCAULEY PROPELLER		60/DTM7553	N/A		1 72		7097	OVERHAULED
13. Rem					1				- 4
inform	elete overhaul of propartion. ******** Certifies the items ident	*****	******	*****	*****	30720. Complied ************************************	*****	*****	auley service ****** **** ion specified in Block 13
					Certifies	hat unless otherv	vise specified	in Block 13, th	ne work identified in
	Approved design data	and are in a co	indition for safe o	peration.	Block 12	and described in	Block 13 was	accomplished	in accordance
	Non-approved design	data specified i	n Block 13.			items are approv			in respect to that
15. Auti	norized Signature:	16.	Approval/Authoria	zation No.: 20	Authorized	d Signature:	Z	21. A IT6R6	pproval/Certificate No.: 25N
17. Nan	ne (Typed or Printed):	18.	Date (m/d/y):	122	Name (Ty	ped of Printed):		23. D	ate (m/d/y):
					2/2	x The	6		10/03/2007
				User/Installer	Responsib	() 0700			10/03/2007
20.00									
It is im	portant to understand	that the existen	nce of this docum	ent alone does n	ot automatic	ally constitute au	thority to inst	all the part/com	ponent/assembly.
airwort	r specified in Block 1, in the hiness authority of the	it is essential the country specifi	nat the user/installied in Block 1.	ler ensures that r	il\$/her airwo	rthiness authority	accepts par	ts/components/	
Statem	ents in Block 14 and 1 in accordance with the	9 do not consti	itute installation c	ertification. In all	cases, airc	raft maintenance	records mus	t contain an ins	tallation certification
	rm 8130-3 (6-01) CG	*Insta	ller must cross-ch	neck eligibility wit	n applicable	technical data.		NSN:	0052-00-012-9005

_				MAINTENANCE RECORD
	DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	DESCRIPTION OF THE WORK PERFORMED
		HOURS	HOURS	DESCRIPTION OF THE WORK FERT ORINIED
0	3/07	3247.6	Ø	Northwest Propeller Service, Inc. 16709 Meridian St. E. Unit 3
				Puyallup, WA 98375 REPAIR STATION No. IT6R625N
_		,		W/O 20856 Mfg: McCauley Model: 1C160/DTM7553 s/n: 727097 Complete overhaul of propeller per McCauley manual # SPM100-3
				REV.3 and 730720. Complied with all applicable McCauley service information.
				October 03, 2007 Inspector Cert. No. 2-360475 Date
-	*			

	DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	DESCRIPTION OF THE WORK PERFORMED						
ć	2007	HOURS	HOURS							
l	٥/.	ė.	750	4703.6 TACH. INSTALLED THIS PROP.						
	16		ZERO	ON M9505H WITH NEW SPINNER.						
			~	TURG 550"# AND SAFTED.						
				Plin. Still - 531466102AP						
- - - -	1	4727.5 That	23.9	REMOVED SHOOTER, CHECKED BACKION PLATE AND PROFECER FOR						
/ (2008	That	SPOR	costrios, Formos od.						
,				"I certify that this PROPELER						
				has been inspected in accordance						
				with Assac inspection and was						
				determined to be in airworthy condition."						
				FRE						
				E A1 E1 A O D E5(041000 TA						

F. Alan Edwards A&P 556041022 A

	DATE	TOTAL TIME IN SERVICE HOURS	TOTAL TIME SINCE OVERHAUL HOURS	DESCRIPTION OF THE WORK PERFORMED
5	- //	4843,6	140.0	Performed 100 Hour Visual inspection AND Found Service Abbe - ENDE Aun Van Horn AP 523805 BB
	2010		37011	FOURD SERVICE AND TENIX gray you four for \$2588 08
-				
	,			
		٠.		

DATE	TOTAL TIME IN SERVICE HOURS	TOTAL TIME SINCE OVERHAUL HOURS	DESCRIPTION OF THE WORK PERFORMED	
			SkyView Aviation, LLC 5749 South Tracy Blvd Tracy, CA 95377 (209)830-7666	
			N Number: N9505H Tach: 5103.9 Prop TT: 3653.9 Smoh: 406.3 Complied with Annual inspection in accordance with FAR 43 appendix D. See AD list dated 04/02/2014 for AD information. Propeller determined to be	
-	, ,		AirworthyENDEND	
			Richard Ortenheim A&P 2517877 IA Date: 04/02/2014 X	

	MAINTENANCE NECOND											
DATE	TOTAL TIME IN SERVICE HOURS	TOTAL TIME SINCE OVERHAUL HOURS	SkyView Aviation		SkyView Aviation, LLC 5749 South Tracy Blvd Tracy, CA 95377							
			_	5144.4 146.8	(209)830-7666							
	·		Complied with Annual inspection in accordance See AD list dated 03/08/2015 and old aircrate Propeller determined to be Airworthy and re	att records eturned to s	for AD information.							
			Richard Ortenheim A&P 2517877 IA Date: 03/08/2015 X									

	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERPALIE)
DATE	HOURS	HOUR	(yVie	w Aviot	ion		SkyView Aviation, LLC 5749 South Tracy Blvd Tracy, CA 95377 (209)830-7666	
		1	Number: op TT:	N9505H 3728.2	Tach: Smoh:	5178.2 480.6		
		Se Pr	ee AD list opeller de	dated 03/08/2 etermined to b	spection in action in acti	rcraft record d approved	rith FAR 43 appendix D. ds for AD information. for service.	
			w * .					
		Ric Da	hard Orte te: 03/21/	enheim A&P 2 2016 X	517877 IA			

3-

2

			IVI	AINTENANCE	ILCOND			
DATE	TOTAL TIME IN SERVICE HOURS	TOTAL TIME SINCE OVERHA HOURS	SkyViev	v Aviation	Oraniza t		SkyView Aviation, LLC 5749 South Tracy Blvd Tracy, CA 95377 (209)830-7666	
•			14 Italii Deli	N9505H 3750.8	Tach: Smoh:	5200.8 503.2	•	
			See AD list da	atad 03/08/2015	and old al been inspe	rcraπ record	ith FAR 43 appendix D. Is for AD information. I ordance with an Annual ondition.	
			Richard Orten Date: 03/16/2	nheim A&P 25178				

DATE	TOTAL TIME IN SERVICE HOURS	TOTAL TIME SINCE OVERLAND HO SkyView Aviation, LLC 5749 South Tracy Blvd Tracy, CA 95377 (209)830-7666	
		N Number: N9505H Tach: 5254.6 Prop TT: 3804.6 Smoh: 557.0 Complied with Annual inspection in accordance with CFR 43 appendix D. See AD list dated 04/12/2018 and old aircraft records for AD information. I certify that this Propeller has been inspected in accordance with an Annual inspection and was determined to be in airworthy condition.	
		Richard Ortenheim A&P 2517877 IA Date: 04/12/2018 X	

	MAINTENANCETECONS												
DATE	TOTAL TIME IN SERVICE HOURS	TOTAL 1 SINCE OVE HOUF	SkyVie	SkyView Aviation, LLC 5749 South Tracy Blvd Tracy, CA 95377 (209)830-7666									
			N Number: Prop TT:	N9505H 3826.3	Tach: Smoh:	5276.3 578.7							
			See AD list of certify that the	complied with Annual inspection in accordance with CFR 43 appendix D. see AD list dated 04/12/2018 and old aircraft records for AD information. I ertify that this Propeller has been inspected in accordance with an Annual espection and was determined to be in airworthy condition.									
					END								
	,		Richard Orter Date: 04/02/2	nheim A&P 251 2019 X	7877 IA								

								:	DATE	
								HOURS	TOTAL TIME IN SERVICE	
								HOURS	TOTAL TIME SINCE OVERHAUL	
Richard Ortenhei Date: 04/15/2020			inspection :	Complied v	Prop TT:	N Number:		SkyVi	1	
Richard Ortenheim A&P 2517877 Date: 04/15/2020 X			inspection and was determined	with Annual in dated 04/15/2	3869.7	N9505H	SKY A ICH A MAIGIIOII	ow Aviat		
517877 IA		END	mined to be in	spection in ac 020 and old ai	Smoh:	Tach:		3	DESCRIPTION (
			inspection and was determined to be in airworthy condition.	Complied with Annual inspection in accordance with CFR 43 appendix D. See AD list dated 04/15/2020 and old aircraft records for AD information. I	622.1	5319.7	3/49 SOUTH TRACY BIVE Tracy, CA 95377 (209)830-7666	SkyView Aviation, LLC	DESCRIPTION OF THE WORK PERFORMED	

DATE	TOTAL TIME IN SERVICE HOURS	TOTAL TIME SINCE OVERHAUL HOURS	SkyView Aviation, LLC 5749 South Tracy Blvd Tracy, CA 95377						
			N Number: N9505H Tach: 5363.5 Prop TT: 3913.5 Smoh: 665.9						
			Complied with Annual inspection in accordance with CFR 43 appendix D. See AD list dated 04/15/2020 and old aircraft records for AD information. I certify that this Propeller has been inspected in accordance with an Annual inspection and was determined to be in airworthy condition.						
		F	Richard Ortenheim A&P 2517877 IA Date: 06/02/2021 X						

DATE 7	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL						
	HOURS	HOURS						
		SkyView Aviation				SkyView Aviation, LLC 5749 South Tracy Blvd Tracy, CA 95377 (209)830-7666		
		N Number Prop TT:	: N9505H 3945.9	Tach: Smoh:	5395.9 698.3			
		See AD li	st dated 06/20/2 at this Propeller	with Annual inspection in accordance with CFR 43 appendix D. dated 06/20/2022 and old aircraft records for AD information. I this Propeller has been inspected in accordance with an Annual and was determined to be in airworthy condition.				
	-			END				
		_						
		Richard C	ortenheim A&P	2517877 14				