



ROBINSON®

HELICOPTER COMPANY

R66 AIRFRAME MAINTENANCE RECORD

2901 Airport Drive, Torrance, California 90505

Phone (310) 539-0508 Fax (310) 539-5198

SECTION 2

INSTALLED EQUIPMENT

Serial Number	Registration	Manufacturer	Model	Date of Manufacture
0087	N460BG	ROBINSON HELICOPTER CO.	R66 TURBINE	01/13/2012

Item	Manufacturer	Model	Serial Number	Date Installed	Date Removed
ENGINE	ROLLS-ROYCE	250-C300/A1	RRE-200091	08 NOV 2011	
OAT GAGE	DAVTRON	307 FC	D14305	08 NOV 2011	
INSTRUMENT CLUSTER	ROCHESTER	10290	0259	08 NOV 2011	
CHRONOMETER	DAVTRON	800	D29381	08 NOV 2011	12-5-17
ALTIMETER	UNITED INSTRUMENTS	5934P-3	492249	08 NOV 2011	
VERTICAL SPEED	UNITED INSTRUMENTS	7000	327043	08 NOV 2011	
AIRSPEED INDICATOR	UNITED INSTRUMENTS	8000	203769	08 NOV 2011	10-16-17
TORQUE METER	PHAOSTRON	000-21127	0221	08 NOV 2011	
AMMETER	UNITED INSTRUMENTS	721-21139	089	08 NOV 2011	
TACHOMETER	PHAOSTRON	000-21121	0211	08 NOV 2011	
AUDIO CONTROL	NAT	AA12S-600	71431	08 NOV 2011	
GPS/COM X'CVR	GARMIN	GNC420W	25220607	08 NOV 2011	10-3-19
TRANSPONDER	GARMIN	GTX-330	84142690	08 NOV 2011	
BLIND ENCODER	TRANS CAL	SSD120-RS232	13803	08 NOV 2011	
DIRECTIONAL GYRO	MID-CONTINENT	3300-10	E11-11237	08 NOV 2011	
VERTICAL CARD COMPASS	PRECISION AVIATION	PAI-700	75540	08 NOV 2011	
ELT	KANNAD	406AF	RX1000040545	08 NOV 2011	
ATTIT GYRO W/INCL	MID-CONTINENT	4300-203	G11-10439	08 NOV 2011	
GPS/COM/NAV X'CVR	GARMIN	GNS530AW	24020461	08 NOV 2011	
INDICATOR	GARMIN	GI 106A	E11-10772	08 NOV 2011	
TURN COORDINATOR	MID-CONTINENT	1394T100-7Z	A11-10973	08 NOV 2011	
Airspeed Indicator	United Instruments	8000 (C599-2R)	204154	10-16-17	
CHRONOMETER	Davtron	800 (A064-4)	D 39372	12-5-17	
Traffic System	Garmin	GTS 800 (610-00519-00)		12-18-12	
Traffic System Antennas	Garmin Sea Vector	GA58 (610-10720-00)		12-18-12	



2901 Airport Drive, Torrance, California 90505

Phone (310) 539-0508 Fax (310) 539-5198

INSTALLED EQUIPMENT (Continued)

[illegible]



2901 Airport Drive, Torrance, California 90505

2901 Airport Drive, Torrance, California 90505

Phone (310) 539-0508 Fax (310) 539-5198

MAJOR ALTERATIONS

Serial Number 0087	Registration N460BG	Manufacturer ROBINSON HELICOPTER CO.	Model R66 TURBINE	Date of Manufacture 01/13/2012
------------------------------	-------------------------------	--	-----------------------------	--

Date	Description of Alteration	Field Approval	STC
	WO# 121112-460BG Installed GTS 800 with dual GA 58 upper and lower antennas. System is interfaced to a GNS 500W and a GNS 430W. Traffic information will be displayed and controlled per GNS 530W AND GNS 430W pilot's guide. Details of the installation are in 337 dated 12/18/12.		
	Avionics Solutions LLC CRS# 6ASR11B		
	 18 December 2012		
2-26-14	INSTALLED Emergency Float Kit APPROPRIATE P/N 699,9401 ACCORDING TO STC SKOZ484A USING APPROPRIATE INSTALLATION INSTRUCTIONS 1166-1 REV.B DATED 11/6/14. TCA ARE IN APPROPRIATE REPORT TCAB6-1 REV.A.DATED 11/6/14. FLIGHT MANUAL SUPPLEMENT WAS INSTALLED IN FLIGHT WEIGHT & BALANCE UPDATED TO REFLECT THESE CHANGES.		MINNAPOLIS 1213377797



HELICOPTER COMPANY

2901 Airport Drive, Torrance, California 90505

Phone (310) 539-0508 Fax (310) 539-5198

MAJOR ALTERATIONS (Continued)

[illegible]

SECTION 4

LIFE LIMITED PARTS OR OVERHAUL REQUIREMENTS

Serial Number 0087	Registration N460BG	Manufacturer ROBINSON HELICOPTER CO.	Model R66 TURBINE	Date of Manufacture 01/13/2012			
Part Name	Part Number	Serial Number	Installation Hours/Date	Time on Part at Installation	Life Limit or TBO	Removal Hours/Date	Authorization
SPRAG CLUTCH	A188-2	9587	0 03 NOV 2011	NEW	2000 TBO	HOURS DATE	INSTLD. RHC PC#424WE
MAIN ROTOR SWASHPLATE	C017-6	0445	0 03 NOV 2011	NEW	2000 TBO		INSTLD. RHC PC#424WE
TAIL ROTOR GEARBOX	C021-1	6021	0 03 NOV 2011	NEW	2000 TBO		INSTLD. RHC PC#424WE
TAILCONE ASSEMBLY	C023-35	0197	0 03 NOV 2011	NEW	2000 LIFE		INSTLD. RHC PC#424WE
TAIL ROTOR PITCH CONTROL	C031-1	6735	0 03 NOV 2011	NEW	2000 TBO		INSTLD. RHC PC#424WE
HORIZONTAL STABILIZER	C044-1	6383	0 03 NOV 2011	NEW	2000 LIFE		INSTLD. RHC PC#424WE
MAIN ROTOR HUB	C154-1	6480	0 03 NOV 2011	NEW	2000 LIFE		INSTLD. RHC PC#424WE
MAIN ROTOR SPINDLE	C158-1	13910	0 03 NOV 2011	NEW	2000 LIFE		INSTLD. RHC PC#424WE
MAIN ROTOR SPINDLE	C158-1	13896	0 03 NOV 2011	NEW	2000 LIFE		INSTLD. RHC PC#424WE
MAIN ROTOR DRIVE SHAFT	C251-3	R0093	0 03 NOV 2011	NEW	2000 LIFE		INSTLD. RHC PC#424WE
GEAR SET, TAIL GEARBOX	C545-1	6836	0 03 NOV 2011	NEW	2000 LIFE		INSTLD. RHC PC#424WE
BEARING SET, SWASHPLATE	C647-12	F112506	0 03 NOV 2011	NEW	2000 LIFE		INSTLD. RHC PC#424WE
TAIL ROTOR GUARD	D079-1	6916	0 03 NOV 2011	NEW	2000 LIFE		INSTLD. RHC PC#424WE
TAIL ROTOR DRIVE SHAFT	D196-1	4621	0 03 NOV 2011	NEW	2000 LIFE		INSTLD. RHC PC#424WE



ROBINSON®

HELICOPTER COMPANY

R66 AIRFRAME MAINTENANCE RECORD

2901 Airport Drive, Torrance, California 90505

Phone (310) 539-0508 Fax (310) 539-5198

SECTION 4

LIFE LIMITED PARTS OR OVERHAUL REQUIREMENTS (Continued)

Serial Number 0087	Registration N460BG	Manufacturer ROBINSON HELICOPTER CO.	Model R66 TURBINE	Date of Manufacture 01/13/2012			
Part Name	Part Number	Serial Number	Installation Hours/Date	Time on Part at Installation	Life Limit or TBO	Removal Hours/Date	Authorization
HYDRAULIC RESERVOIR	D211-3	0098	0 03 NOV 2011	NEW	2000 TBO	HOURS DATE	INSTLD. RHC PC#424WE
HYDRAULIC SERVO	D212-5	14583	0 03 NOV 2011	NEW	2000 TBO		INSTLD. RHC PC#424WE
HYDRAULIC SERVO	D212-5	14582	0 03 NOV 2011	NEW	2000 TBO		INSTLD. RHC PC#424WE
HYDRAULIC SERVO	D212-6	14516	0 03 NOV 2011	NEW	2000 TBO	12-21-18 1040.3	INSTLD. RHC PC#424WE
HYDRAULIC PUMP ASSY	D500-2	0095	0 03 NOV 2011	NEW	2000 TBO		INSTLD. RHC PC#424WE
MRGB OIL PUMP ASSEMBLY	D500-3	0095	0 03 NOV 2011	NEW	2000 TBO		INSTLD. RHC PC#424WE
MAIN ROTOR GEARBOX	F006-1	0123	0 03 NOV 2011	NEW	2000 TBO		INSTLD. RHC PC#424WE
MAIN ROTOR BLADE	F016-2	0243	0 03 NOV 2011	NEW	2000 LIFE OR 12 YEARS		INSTLD. RHC PC#424WE
MAIN ROTOR BLADE	F016-2	0231	0 03 NOV 2011	NEW	2000 LIFE OR 12 YEARS		INSTLD. RHC PC#424WE
UPPER FRAME	F020-1	0100	0 03 NOV 2011	NEW	2000 LIFE		INSTLD. RHC PC#424WE
TAIL ROTOR BLADE	F029-1	0245	0 03 NOV 2011	NEW	2000 LIFE OR 12 YEARS		INSTLD. RHC PC#424WE
TAIL ROTOR BLADE	F029-1	0248	0 03 NOV 2011	NEW	2000 LIFE OR 12 YEARS		INSTLD. RHC PC#424WE
MRGB INPUT PINION	F143-1	0104	0 03 NOV 2011	NEW	2000 LIFE		INSTLD. RHC PC#424WE
MRGB OUTPUT PINION	F146-1	0117	0 03 NOV 2011	NEW	2000 LIFE		INSTLD. RHC PC#424WE



ROBINSON[®]
HELICOPTER COMPANY

R66 AIRFRAME MAINTENANCE RECORD

2901 Airport Drive, Torrance, California 90505

Phone (310) 539-0508 Fax (310) 539-5198

SECTION 4

LIFE LIMITED PARTS OR OVERHAUL REQUIREMENTS (Continued)

Serial Number	Registration	Manufacturer	Model	Date of Manufacture
0087	N460BG	ROBINSON HELICOPTER CO.	R66 TURBINE	01/13/2012

Part Name	Part Number	Serial Number	Installation Hours/Date	Time on Part at Installation	Life Limit or TBO	Removal Hours/Date	Authorization
YOKE, TR DRIVE SHAFT	F195-1	0100	0 03 NOV 2011	NEW	2000 LIFE	HOURS DATE	INSTLD. RHC PC#424WE
STRUT, UPPER FRAME	F235-13	0164	0 03 NOV 2011	NEW	2000 LIFE		INSTLD. RHC PC#424WE
STRUT, UPPER FRAME	F235-13	0163	0 03 NOV 2011	NEW	2000 LIFE		INSTLD. RHC PC#424WE
STRUT, UPPER FRAME	F252-1	0097	0 03 NOV 2011	NEW	2000 LIFE		INSTLD. RHC PC#424WE
HOUSING, MRGB	F263-1	0123	0 03 NOV 2011	NEW	2000 LIFE		INSTLD. RHC PC#424WE
COVER, MRGB	F264-1	0137	0 03 NOV 2011	NEW	2000 TBO		INSTLD. RHC PC#424WE
CARTRIDGE, MRGB	F270-1	0112	0 03 NOV 2011	NEW	2000 LIFE		INSTLD. RHC PC#424WE
FUEL TANK BLADDER	G028-1	0202	0 03 NOV 2011	NEW	2000 TBO	198.8 2-16-2013	INSTLD. RHC PC#424WE
TAIL ROTOR HUB	G062-2	0189	0 03 NOV 2011	NEW	2000 LIFE		INSTLD. RHC PC#424WE
FRAME, SERVO SUPPORT	G201-1	0104	0 03 NOV 2011	NEW	2000 LIFE		INSTLD. RHC PC#424WE
Reservoir ASSY	649.9001	13005	426.5 2-26-14	NEW	3 year O/H	839.5 1-30-17	STC. SA 02484CA DUE O/H OF VALUE ASSY
Float Cylinder	604.9811	G2992	426.5 2-26-14	NEW	15 year ret.	839.5 1-30-17	STC SR02484CA DUE HYDRO check
Reservoir ASSY	649.9001	13005	839.5 3-15-17	O/H	3 year O/H & HYDRO	3-10-2020 1128.4	DUE STC O/H of value
Float Cylinder	604.9811	G2992	839.5 3-15-17	O/H	15 year ret.	3-10-2020	DUE 3 year HYDRO



HELICOPTER COMPANY

2901 Airport Drive, Torrance, California 90505

Phone (310) 539-0508 Fax (310) 539-5198

LIFE LIMITED PARTS OR OVERHAUL REQUIREMENTS (Continued)

[illegible]



ROBINSON®

HELICOPTER COMPANY

2901 Airport Drive, Torrance, California 90505

Phone (310) 539-0508 Fax (310) 539-5198

R66 AIRFRAME MAINTENANCE RECORD

SECTION 5

AIRWORTHINESS DIRECTIVES AND MANUFACTURERS SERVICE DOCUMENTS

Serial Number 0087	Registration N460BG	Manufacturer ROBINSON HELICOPTER CO.	Model R66 TURBINE	Date of Manufacture 01/13/2012
-----------------------	------------------------	---	----------------------	-----------------------------------

All Service Bulletins complied with through SB # 02 as applicable. All FAA Airworthiness Directives complied with through biweekly issue # 2011-27 as applicable during production.	Date	Authorization
	01/13/2012	
		RHC PC424WF

Airworthiness Directive or Service Document Number	Item Affected	Time of Compliance		One-Time or Recurring	Next Due	Compliance Details		Authorization
		HOURS	DATE			HOURS	DATE	
SB03	HYD. SERVOS	100.6	5/25/12	1 TIME	N/A	N/A BY SERVO S/W'S		Mylan D 711L AP 3377797
SB04	02L FAN	100.6	5/25/12	1 TIME	N/A	CHECKED AS PER SB		Mylan D 711L AP 3377797
SB05A	CLUTCH RETAIN BOLT	235.6	4/29/13	1 TIME	N/A	INSTALLED NEW BOLT		Mylan D 711L AP 3377797
SB06	FUEL SWITCH PACKAGING	250.0	8-9-13	1 TIME	N/A	INSPECTED ACCORDING TO SB		Mylan D 711L AP 3377797
SB07	THRUSTLE CONTROL ROUZZING	250.0	8-9-13	1 TIME	N/A	INSPECTED ACCORDING TO S.B.		Mylan D 711L AP 3377797
SB08	HYD SOLENOID DRIVE	250.0	8-9-13	1 TIME	N/A	INSTALLED DROPE		Mylan D 711L AP 3377797
SB09	ROTOR RPM SENDER MAG	250.0	8-9-13	1 TIME	N/A	ADD ADHESIVE TO MAGNETS		Mylan D 711L AP 3377797
SB10	HANGAR BEARING ASSEMBLY	401.5	12-21-13	1 TIME	N/A	INSTALLED KZ-222 KZT		Mylan D 711L AP 3377797
SB11	TAIL GEARBOX SIGHT GLASSES	580.7	1-21-15	1 TIME	N/A	INSTALLED SIGHT GLASSES		Mylan D 711L AP 3377797
SB12	LAMPING GEAR ATTACH NUTS	580.7	1-21-15	1 TIME	N/A	INSTALL NEW LOG GEAR		Mylan D 711L AP 3377797
SB 20M-01	C.O. PLACARD removal of	4-22-13		ONE TIME	N/A	ATTACH NEW C.O. PLACARD		As per 43402261 Ritchie's
SB13	MAIN ROTOR modification	662.2	6-24-15	ONE TIME	N/A	removal of C.O. restriction placard		As per 43402261 Ritchie's
					N/A	modification of main rotor blade trailing edge		As per 43402261

SECTION 5

AIRWORTHINESS DIRECTIVES AND MANUFACTURERS SERVICE DOCUMENTS (Continued)

Serial Number	Registration	Manufacturer	Model	Date of Manufacture
0087	N460BG	ROBINSON HELICOPTER CO.	R66 TURBINE	01/13/2012

Airworthiness Directive or Service Document Number	Item Affected	Time of Compliance	One-Time or Recurring	Next Due	Compliance Details	Authorization	SIGN CERT
SB-14 DART	Two most (71.1) rotor bearing bearings	666.2	ONE TIME	N/A	INSTN' TELE TEMP TYPE PER S.B.	Richard L. Rabe	AP 3406265
SB-2014-5	Airspeed Limitation for Flight Inflation	721.6	ONE TIME	N/A	INSTALLED Airspeed Limitation	Richard L. Rabe	AP 3406265
SB-15	Garmin G500H's GDU 620 display	10-30-2015 737.0	ONE TIME	N/A	PLACED PER S.B. N/A By AC Serial #.	AP 3406265	AP 3406265
SB-16	FG42-1 Shaft weldments	12-30-15 737.0	ONE TIME	N/A	Equip. not installed. N/A By AC Serial #.	AP 437291466	AP 437291466
SB-17	FG42-1 Shaft Replacement	758.7	ONE TIME	N/A	Installed New shaft	AP 437291466	AP 437291466
SB-13	5934 Series Altimeters	4-5-16 759.6	ONE TIME	N/A	FG42-G Per S.B. N/A by instrument	AP 437291466	AP 437291466
SB-18	Superseded MRGB Output	by SB-18A	ONE TIME	N/A	Superseded by SB-18A	AP 437291466	AP 437291466
SB-18A	Yoke Retaining Plug Revised Instrument Markings	777.4	ONE TIME	N/A	Inspected plug no defects. Retorqued + Safetied Per S.B.	AP 437291466	AP 437291466
SB-19 A	Indicator	813.9	ONE TIME	N/A	Installed Decals	AP 437291466	AP 437291466
SB-19 B	Tail Rotor Drive	11-29-16 895.1	ONE TIME	N/A	INSTN SB-19 Part A	AP 437291466	AP 437291466
SB-20	Shaft Bearings	10-16-17 839.5	ONE TIME	N/A	Installed C599-28 Air Speed Indicator Per S.B.	AP 437291466	AP 437291466
AD2016-26-04	Main Rotor Blades	2-7-17	ONE TIME	N/A	Installed P224-5 Yoke Assy + Inspected damper bearing	AP 437291466	AP 437291466
SB-21A	Oil Tank Outlet Modification	1-8-17 823.0	ONE TIME	N/A	INSTN SB-20 P.C.W Per S.B. 13	AP 437291466	AP 437291466
SB-22	Horizontal Stabilizer Nut plates	3-16-2017 839.5	ONE TIME	N/A	AT G-24-15 ACT: 662.2	AP 437291466	AP 437291466
		869.3	ONE TIME	N/A	INITIALD ANG'E G-805-1	AP 437291466	AP 437291466
		6-12-17	ONE TIME	N/A	INSTN SB-21	AP 437291466	AP 437291466
			ONE TIME	N/A	N/A by Horizontal Stabilizer S/N 6383	AP 437291466	AP 437291466

SECTION 5

AIRWORTHINESS DIRECTIVES AND MANUFACTURERS SERVICE DOCUMENTS (Continued)

Serial Number 0087	Registration N460BG	Manufacturer ROBINSON HELICOPTER CO.	Model R66 TURBINE	Date of Manufacture 01/13/2012		
Airworthiness Directive or Service Document Number	Item Affected	Time of Compliance	One-Time or Recurring	Next Due	Compliance Details	Authorization
SB-22A	Horizontal Stabilizer Nut Plates	895.1 10-16-17	ONE Time	N/A	Found no movement on bolt torque's. Nut Plates Not Changed.	Kennd/Kell AP437291466
SB-23	Engine Support Weldment Rod Ends	1030.3 11-21-18	ONE Time	N/A	Replaced 2 each FIT4-1 Rod Ends on engine support	Kennd/Kell AP437291466
SB-24	Auxiliary Fuel System Relay	1030.3 11-21-18	ONE Time	N/A	N/A Aux Fuel System not Installed.	Kennd/Kell AP437291466
SB-25	Air Conditioner Time Delay Assembly	1030.3 11-21-18	ONE Time	N/A	N/A by AC Serial #	Kennd/Kell AP437291466
SB-26	Lead Acid Battery Leaking Electrolyte	1030.3 11-21-18	ONE Time	N/A	Installed G-801-2 pod and G123 array under battery	Kennd/Kell AP437291466
SB-27	Drain Holes For Aux Fuel Tank	1030.3 11-21-18	ONE Time	N/A	N/A by Aux Fuel Tank not installed.	Kennd/Kell AP437291466
SB-17A	F642-1 Shaft Replacement Rex.	758.7 4-5-16	ONE Time	N/A	Previously Complied with ON SB 17.	Kennd/Kell AP437291466
SB-20B	Inspection of hanger & damper bearings	1-1-19 839.5	ONE Time	N/A	Found Previously Complied with.	Kennd/Kell AP437291466
SB-21A	Oil Tank Outlet Modification	1040.3 3-15-2017	ONE Time	N/A	Previously Complied with on SB 21 Installed Kit-262-1	Kennd/Kell AP437291466
SB-28	B237 cond Acid battery	1123.4 3-5-20	ONE Time	N/A	N/A Robinson Float kit not installed	Kennd/Kell AP437291466
SB-29	Pop out floats	1058.6 4-4-19	ONE Time	N/A	Complied with IAW SB-30 1 and 17-19.	Kennd/Kell AP437291466
SB-30	Substitution of SWAMPATE BEARINGS	1123.4 3-5-20	Recurring	2123.4 3-5-26	Installed Kit 263-1	Kennd/Kell AP437291466
SB 31	battery compartment stiffener	1123.4 3-5-20	one time	N/A	N/A lithium ion battery not installed	Kennd/Kell AP437291466
SB 32	Lithium Ion battery sense wire	1102.2 10-18-19	one time	N/A N/A		Kennd/Kell AP437291466



ROBINSON®

HELICOPTER COMPANY

R66 AIRFRAME MAINTENANCE RECORD

2901 Airport Drive, Torrance, California 90505

Phone (310) 539-0508 Fax (310) 539-5198

SECTION 5

AIRWORTHINESS DIRECTIVES AND MANUFACTURERS SERVICE DOCUMENTS (Continued)

Serial Number 0087	Registration N460BG	Manufacturer ROBINSON HELICOPTER CO.	Model R66 TURBINE	Date of Manufacture 01/13/2012			
Airworthiness Directive or Service Document Number	Item Affected	Time of Compliance	One-Time or Recurring	Next Due	Compliance Details	Authorization	SIGN CERT
SB 33	PEPDA Float Stabilizer	11022 10-18-19	ONCE	N/A	N/A Robinson Float Lt. + Not installed	Retired List AP434060265	
SB 34	HELI SAS Flight control computer	11022 10-18-19	ONCE	N/A	N/A Heli SAS system not installed	Retired List AP434060265	
SB 35	Chin inspection hole Access cover	1112.7 12-6-19	ONCE	N/A	N/A by A/C S/N	Retired List AP434060265	
SB 36	MAIN rotor tip plate removal	1117.6 12-27-19	ONCE	N/A	N/A by revision letter of BLADE (REV.D) CLW by installation of C-258-S/P/C Linker	Retired List AP434060265	
SL-20	CASB - S.P.C.Link	1123.4 02-21-2020	ONCE	N/A	Found PCW by SB21A.	Retired List AP434060265	
AD 2019-07-02	Engine Oil Tank HELI SAS Autopilot Interface	1123.4 3-5-20	ONCE	N/A	N/A	Retired List AP434060265	
SB 37	F-018-1 clutch ASSY	11440 1147.2	ONCE	N/A	N/A Heli SAS system not installed	Retired List AP434060265	
SB 38 A	Chin Inspection Hole Access	1154.4 01/05/2020	ONCE	N/A	N/A by A/C S/N 2 S/N of SPAS clutch installed	Retired List AP434060265	
SB 35A	Chin Inspection Hole Access	1154.4 11/17/2020	ONCE	N/A	Complied with New Kit Instructions KI-2332	Retired List AP434060265	
AD 2021-04-12	Tail Rotor Drive Shaft ASSY	1161.6 03/01/2021	ONCE	N/A	CLW by incorporation of SB20 blank KI-235.	Retired List AP434060265	
SB 22 A	Horizonal Stabilizer Nut plates	1161.6 04/07/2021	ONCE	N/A	Complied with by replacing 8 nut plates IAW SB22A	Retired List AP434060265	
SB 39	Hydraulic controls pre takeoff check	1165.8 07-02-21	ONCE	N/A	Inserted P.O.H. PAGE in P.O.H.	Retired List AP434060265	
AD 2021-01-01	Float cable tension drilling check	1181.3 10-05-21	ONCE	N/A	performed float cable tension drilling check	Retired List AP434060265	
SB. 40	FOAG-1 T/R BLADE CRACKING	1195.9 02-22-22	ONCE	N/A	N/A by S/N T/R BLADE INSTALLED.	Retired List AP434060265	



2901 Airport Drive, Torrance, California 90505, USA

Phone (310) 539-0508 Fax (310) 539-5198

AIRFRAME MAINTENANCE RECORD

SECTION 5

AIRWORTHINESS DIRECTIVES AND SERVICE BULLETINS

[illegible]