

Paul Domeier Aviation, A&P/IA #3757961
2198 Ashwood Ln
San Jose, CA 95132, (707) 592-6206, pd.avco@gmail.com

April 2022 Annual

Airframe AD Compliance
N11899, C-150L, s/n 15075696
TACH: 4824.4, TTAF: 4824.4

AD 67-03-01	heat muffs	NA	per acft mfr date		
AD 68-17-04	stall horn	NA	per acft mfr date		
AD 71-22-02	nose gear fork	NA	per acft mfr date		
AD 72-03-03 R3	flap jack screw	NA	per acft mfr date		
AD 73-23-07	spar	NA	per acft mfr date		
AD 74-06-02	exhaust	NA	affected unit(s) not installed		
AD 75-15-08	engine oil	NA	affected unit(s) not installed		
AD 77-02-09	flaps	NA	per acft s/n		
AD 79-08-03	electrical	NA	per acft s/n		
AD 79-10-14 R1	fuel vent	PCW	per acft log #1		

AD 80-11-04	cracked nutplates	CW	Inspected IAW AD instruction 4924.4 Nxt due: tach	Paul Domeier A&P 3757961	4/2/2022
AD 81-15-03	air filter	PCW	per acft log #2		
AD 83-17-06	aileron weights	NA	affected STC not employed		
AD 86-24-07	engine controls	PCW	per acft log #1		
AD 87-21-05	placard	NA	affected STC not employed		
AD 88-15-06	battery location	NA	battery not relocated		
AD 96-12-23	wing stall fence	NA	affected STC not employed		
AD 97-01-13	fluid lines	NA	affected unit(s) not installed		
AD 2022-03-15	fuel gauges	NA	affected STC not employed		
AD 2009-10-09 R2	rudder	PCW	per acft log #2		
AD 2011-10-09	seat rails	CW	Inspected IAW AD instruction Nxt due: 4/2/2023	Paul Domeier A&P 3757961	4/2/2022
AD 2008-22-18	BRS	NA	affected unit(s) not installed		

AD 2000-06-01	gascolator	PCW	per acft log #2		
AD 96-12-22	full flow oil filter	NA	affected unit(s) not installed		
AD 96-09-06	air filter	PCW	per acft log #2		

****end AD compliance, Airframe****

Paul Domeier Aviation, A&P #3757961
2198 Ashwood Ln
San Jose, CA 95132, (707) 592-6206, pd.avco@gmail.com

April 2022 Annual

Engine AD Compliance
N11899, O-200-A, s/n 251664-A-48
Tach: 4824.4, TT: 4824.4
TSMOH 3154.1, TSTOH: 20.1

AD 69-24-03	carb	NA	per carb s/n		
AD 80-06-05	slick magneto	NA	per model designator		
AD 81-07-06	fuel pump	NA	affected unit(s) not installed		
AD 81-16-05	slick magneto	NA	per mags OH date		
AD 93-10-02	valve retainer	NA	new SAP cylinders installed, 3-2022		
AD 93-11-03	con rod	NA	per engine s/n		
AD 93-19-04	carb	NA	OH carb installed 4-2019		
AD 93-22-05	carb intake box	NA	per engine s/n		
AD 94-05-05 R1	rockers	NA	new SAP cylinders installed, 3-2022		
AD 98-17-11	crankshaft	NA	crank not serviced by Nelson Balancing		

AD 98-01-06	carb	NA	one-piece venturi		
AD 96-12-22	full flow oil filter	NA	affected unit(s) not installed		
AD 96-12-06	engine timing	NA	new SAP cylinders installed, 3-2022		
AD 95-21-15	fuel	NA	per N number		

*****end AD compliance, Engine*****

Paul Domeier Aviation, A&P #3757961
2198 Ashwood Ln
San Jose, CA 95132, (707) 592-6206, pd.avco@gmail.com

April 2022 Annual

Propeller AD Compliance
N11899, MC 1A101 PCM s/n G12934
Tach: 4024.4

AD 2005-14-1	failed blade	NA	prop not serviced by identified company		
AD 2003-13-17	failed blade	NA	prop not serviced by identified company		

****end AD compliance, Prop****