


Paul Domeier, A&P, IA 3757961
 2198 Ashwood Ln
 San Jose, CA 95132, (707) 592-6206, pd.avco@gmail.com

January 2023 Annual
Tach: 2418.51, TT: 3891.51

Airframe AD Compliance
 N1862X, C-182H, s/n 18255962

recurring

2022-03-15	garmin fuel qty	NA		affected unit(s) not installed		
2020-18-01	door post inspect	NOT DUE	x	Nxt due tach: 3407 or 4/1/2025		
2011-10-09	seat rails/rollers 100 hrs or 12 mos	CW	x	inspected IAW AD instruction Nxt due tach: 2518.51 or 1/2024	 Paul Domeier A&P 3757961	1/10/2023
2008-26-10	instrument error indications	NA		affected unit(s) not installed		
2008-02-18	BRS parachute indications	NA		affected unit(s) not installed		
2007-09-01	ground power	NA		affected unit(s) not installed		
2005-01-19	mode S xpdr	NA		affected unit(s) not installed		
2004-19-01	shoulder harness adjust	NA		affected unit(s) not installed		
2000-06-01	fuel strainer	NA		affected unit(s) not installed		
98-21-21 R1	inflatable door seal	NA		affected unit(s) not installed		
98-25-02	antenna	NA		affected unit(s) not installed		

98-14-03	xpdr	NA		affected unit(s) not installed		
96-12-22	oil filter adapter 100 hrs or filter remove	NOT DUE	x	Nxt due: oil change		
75-05-02	STC oil filter	NA		affected unit(s) not installed		
81-15-03	Air filter	NA		affected unit(s) not installed		
84-10-01 R1	bladder fuel cells	PCW		paragraphs: a, b, c, d, CW per acft records 12 mo. inspection no longer required		
73-17-01	aux fuel	NA		affected unit(s) not installed		
77-23-11	ELT	NA		per acft s/n		
71-22-02	nose fork	NA		affected unit(s) not installed		
79-08-03	electrical system	PCW		per acft records		
83-13-01	fuel caps/placarding 12 mo.s	CW	x	visually inspected IAW AD direction Nxt due: 1/2024	 Paul Domeier A&P 3757961	1/10/2023
97-01-13	fuel, oil, hyd hoses	NA		affected unit(s) not installed per acft records		
79-25-07	alternator ground	PCW		per acft records		

86-24-07	engine controls	PCW		correct hardware installed IAW SE 79-6 per acft records		
77-02-09	flaps	NA		per acft s/n		
77-04-05	carb intake	PCW		per acft records		
78-01-14	ELT	NA		affected unit(s) not installed		
98-16-04	angle stiffener	NA		affected unit(s) not installed		
83-17-06	aileron balance weights	NA		affected unit(s) not installed		
72-03-03 R3	flaps jack screw	PCW		Kit SK150-37A installed IAW SE72-2, per acft records		
72-02-06	autopilot	NA		affected unit(s) not installed		
72-07-09	vert fin/rudder 1,000 hrs	NOT DUE	x	per acft records, Nxt due tach: 3407		
75-16-01	wing fuel tanks	NA		per acft s/n		
79-10-14 R1	fuel tank venting	PCW		kit SK182-85A installed		
73-23-07	wing/spar attach	NA		per acft s/n		

END

Paul Domeier, A&P, IA, 3757961
2198 Ashwood Ln
San Jose, CA 95132
(707) 592-6206, pd.avco@gmail.com

January 2023 Annual

Engine, prop AD Compliance
N1862X, O-470-R, s/n 130859-4-R-4
Tach: 2418.51, TSMOH: 1171.71

prop: MAC D3A32C411C
hub s/n 911629 TSPOH: 51.24

recurring

2022-16-03	magneto	NA		affected unit(s) not installed		
2022-04-04	f&m oil filter	NA		affected unit(s) not installed		
2010-11-04	valve lifters	NA		per par. (f)		
2010-07-08	turbocharger	NA		affected unit(s) not installed		
2009-19-07	cylinders	NA		affected unit(s) not installed		
2007-04-19 R1	superior cylinders	NA		affected unit(s) not installed		
99-19-01	crankshaft	NA		per OH date, 1-1-1992		
98-17-11	crankshaft	NA		crankshaft not serviced by identified shop		
97-21-02	cylinders/piston pins	NA		per OH date, 1-1-1992		
96-12-22	oil filter adapter	NOT DUE	x	Nxt due: oil change		

96-12-04	pistons	NA		per OH date, 1-1-1992		
95-21-15	engine teardown	NA		per N number		
63-15-01	exhaust valves	NA		per OH date, 1-1-1992		
91-19-03	oil filter	NA		affected unit(s) not installed		
73-13-04	carb bowl drain plug	NA		per OH date, 1-1-1992		
56-06-01	piston pin	NA		per OH date, 1-1-1992		
93-08-17	oil pickup tube	NA		per OH date, 1-1-1992		
85-08-02	cylinders	NA		per OH date, 1-1-1992		
2000-23-21	con rod journal	NA		per OH date, 1-1-1992		
93-10-02	cyl valve retainer	NA		per OH date, 1-1-1992		
98-01-08	roller rockers	NA		affected unit(s) not installed		
88-03-06	oil filter	NA		affected unit(s) not installed		
89-04-02	carburetor	NA		per carb p/n		

79-05-09	oil pressure relief valve	NA		per OH date, 1-1-1992		
----------	---------------------------	----	--	-----------------------	--	--

81-16-05	slick magneto	NA		affected unit(s) not installed		
----------	---------------	----	--	--------------------------------	--	--

69-24-03	carburetor	NA		per OH date, 1-1-1992		
----------	------------	----	--	-----------------------	--	--

67-01-04	superior oil filter adapter	NA		affected unit(s) not installed		
----------	-----------------------------	----	--	--------------------------------	--	--

63-22-03	carburetor	NA		per OH date, 1-1-1992		
----------	------------	----	--	-----------------------	--	--

Prop

2006-24-07	blades	NA		not serviced by identified firm		
------------	--------	----	--	---------------------------------	--	--

2005-14-11	blades	NA		not serviced by identified firm		
------------	--------	----	--	---------------------------------	--	--

2003-13-17	blades	NA		not serviced by identified firm		
------------	--------	----	--	---------------------------------	--	--

END