

N320JL PIPER PA-24-260 Year 1969 S/N 24-4886
Engine Lycoming IO-540-D4A5 S/N L-2537-48 Engine TT: 6089
Since Overhaul:1138.17 TACH:: 5767.6 Airframe Total Time:5767.6

Date 3-18-22

Propeller Make: Hartzell Model: HC-E2YR-1BF S/N: DK310
Propeller: TSN:1138.17

Removed and Replaced Main Landing Gear Bungee Chords with new PN 8097 (x2). Action brings aircraft in compliance with AD 77-13-21. Next due 6267.6 Tach Time or 3/25.
Ops check good!

ADRENALINE AVIATION LLC., 333 W. Jack London Blvd.,Ste(Hangar)249,Livermore, CA 94551,
(925)895-1757, ADRENALINEAVIATION1@YAHOO.COM.

Carlos E. Santos III A&P 3534160IA. 

N320JL PIPER PA-24-260 Year 1969 S/N 24-4886
Engine Lycoming IO-540-D4A5 S/N L-2537-48 Engine TT: 6130.73
Since Overhaul:1179.9 Tach: 5809.33 Airframe Total Time:5809.33

Date 6-1-23

Propeller Make: Hartzell Model: HC-E2YR-1BF S/N: DK310
Propeller: TSN:1179.9

Airframe Annual Inspection completed IAW FAR 43 Appendix D. Lubed aircraft flight controls, inspected for airframe for corrosion(good!).

Replaced Left Main landing gear tire with new Airhawk 6 Ply 6.00x6 and tube with new leakguard inner tube.


Tested ELT IAW 91.207 appendix D next due 6/23. ELT Batt Expires 3/24.

Created AD list with current status and method of compliance dated 6-1-23. For more info see list.

Ops check good!

"I certify this Airframe has been inspected IAW an ANNUAL inspection & determined to be in an Airworthy Condition".

ADRENALINE AVIATION LLC., 333 W. Jack London Blvd.,Ste(Hangar)249,Livermore, CA 94551,
(925)895-1757, ADRENALINEAVIATION1@YAHOO.COM.

Carlos E. Santos III A&P 3534160IA. 

CARRIED FORWARD