BROUGHT			_	AS REQUIRED FOR
FORWARD				THES AS REQUIRED FOR COMPLETE
	Tach Ti Performed Annual Inspe Manual. See A.D. log fo This propeller was inspe condition. Work Performed on J.A.	S. Work Order A 9787.	e New 1128.35 Hours chnston Aircraft Service, Ind Annual Inspection and was	
Engine I	PIPER PA-24-260 Yeycoming IO-540-D4A5 Serhaul:1138.17 TACH::	l ear 1969 S/N 24-488 S/N L-2537-48 Engine 5767.6 Airframe Tot	TT. (000	Date 3-1-22
Propelle	Make: Hartzell Model: 1 : TSN:1138.17		: DK310	•
Inspecter Re- Inst	nspection Completed IAW d Prop Spinner & Inspected d Spinner Bulkhead- no d d Propeller- no defects lled Spinner. this Propeller has been i y condition."	ed- do defects detecte lefects	d	ermined to be in an
— Carlos E	Santos III A&P 3534160I	D.COM	(Hangar)249,Livermo	ore,CA 94551 (925)895-1757
 Engine Lyc 	PER PA-24-260 Year oming IO-540-D4A5 S/N aul:1179.9 Tach: 5809.3	1969 S/N 24-4886 L-2537-48 Engine T 3 Airframe Total Tir	T: 6130.73 me:5809.33	Date 6-1-23
Propeller M Propeller: T	ake: Hartzell Model: HC SN:1179.9	C-E2YR-1BF S/N: D	PK310	-
– Annual Insp – Removed P	ection Completed IAW For Spinner & Inspected-	AR 43.13 Appendix D. do defects detected		_

"I certify this Propeller has been inspected IAW an Annual Inspection & determined to be in an

Adrenaline Aviation LLC. 333 W. Jack London Blvd., Ste.(Hangar)249,Livermore,CA 94551 (925)895-1757

Inspected Spinner Bulkhead- no defects
 Inspected Propeller- no defects

ADRENALINEAVIATION1@YAHOO.COM

SI Carlos E. Santos III A&P 3534160IA._____

Re-Installed Spinner.

тот, airworthy condition."

TC