



Federal Aviation Administration

Airworthiness Directives (ADs (Airworthiness Directives)) - Current Only

Search Results for "172k"

[« Back to Airworthiness Directives Main Page](#)

Search Results

Filter within results

Filter

AD No.

Effective Date

Subject

70-10-06

([http://rgl.faa.gov/Regulatory and Guidance Library/rgAD.nsf/AOCADSearch/2DA19BC12EA0898686256E01005AC6B1?OpenDocument](http://rgl.faa.gov/Regulatory_and_Guidance_Library/rgAD.nsf/AOCADSearch/2DA19BC12EA0898686256E01005AC6B1?OpenDocument))

P/C/W

Oil Pressure Instrument Line

2011-10-09

([http://rgl.faa.gov/Regulatory and Guidance Library/rgAD.nsf/AOCADSearch/144A3898BF71041A8625788F004B5DF2?OpenDocument](http://rgl.faa.gov/Regulatory_and_Guidance_Library/rgAD.nsf/AOCADSearch/144A3898BF71041A8625788F004B5DF2?OpenDocument))

6/17/2011

*C/W
inspected
100 hrs or annual*

Seat Rails and Roller Housing
Inspections

2011-06-02

([http://rgl.faa.gov/Regulatory and Guidance Library/rgAD.nsf/AOCADSearch/914991D13EB5AFB5862578790051C56B?OpenDocument](http://rgl.faa.gov/Regulatory_and_Guidance_Library/rgAD.nsf/AOCADSearch/914991D13EB5AFB5862578790051C56B?OpenDocument))

5/26/2011

*NA
O/H*

Engine

2008-26-10

([http://rgl.faa.gov/Regulatory and Guidance Library/rgAD.nsf/AOCADSearch/DD691B864BAC64868625752900585A24?OpenDocument](http://rgl.faa.gov/Regulatory_and_Guidance_Library/rgAD.nsf/AOCADSearch/DD691B864BAC64868625752900585A24?OpenDocument))

1/5/2009

NA

Alternate static air source selector
valve

2008-10-02

([http://rgl.faa.gov/Regulatory and Guidance Library/rgAD.nsf/AOCADSearch/F4B3D1045B1996D58625743D004E1EE0?OpenDocument](http://rgl.faa.gov/Regulatory_and_Guidance_Library/rgAD.nsf/AOCADSearch/F4B3D1045B1996D58625743D004E1EE0?OpenDocument))

5/12/2008

NA

Part number identification placard

2008-02-18 http://rgl.faa.gov/Regulatory and Guidance Library\rgAD.nsf/AOCADSearch/5347E48E2DF1A5F1862573DA0059A97C?OpenDocument)	2/28/2008 <i>NA</i>	Pick-up collar support and nylon screws
2006-03-08 http://rgl.faa.gov/Regulatory and Guidance Library\rgAD.nsf/AOCADSearch/7A6C0FCD3988D1FE8625710E005586E7?OpenDocument)	3/10/2006 <i>NA</i>	Vacuum pumps
2005-01-19 http://rgl.faa.gov/Regulatory and Guidance Library\rgAD.nsf/AOCADSearch/EB7D904CBEBB14C786256F8E00636216?OpenDocument)	2/23/2005 <i>pk/cw</i>	Mode S transponders
2004-19-01 http://rgl.faa.gov/Regulatory and Guidance Library\rgad.nsf/AOCADSearch/EC74A6D4B9C8CC2986256F1200531F70?OpenDocument)	11/1/2004 <i>NA</i>	Upper shoulder harness adjusters
2001-23-03 http://rgl.faa.gov/Regulatory and Guidance Library\rgAD.nsf/AOCADSearch/28C538CC707E1A6086256B090060BC0C?OpenDocument)	12/27/2001 <i>pk/cw</i>	Forward Door Post
2000-06-01 http://rgl.faa.gov/Regulatory and Guidance Library\rgAD.nsf/AOCADSearch/FA9F23E11131B02886256A4C004DF1D7?OpenDocument)	5/5/2000 <i>pk/cw</i>	Fuel Strainer Assembly
98-21-21 R1 http://rgl.faa.gov/Regulatory and Guidance Library\rgAD.nsf/AOCADSearch/D140D1B5B0D327DC86256A0A006E2297?OpenDocument)	5/1/2000 <i>NA not installed</i>	Electric Inflatable Door Seals
99-27-02 http://rgl.faa.gov/Regulatory and Guidance Library\rgAD.nsf/AOCADSearch/6583D4C1A4FC910B86256A49004503BF?OpenDocument)	1/21/2000 <i>NA m#</i>	Fuel Selector Valves

98-25-02

12/22/1998

Top-mounted Antenna

[http://rgl.faa.gov/Regulatory and Guidance Library/rgAD.nsf/AOCADSearch/1EBF0AA24910728C86256A40006C38D9?OpenDocument](http://rgl.faa.gov/Regulatory_and_Guidance_Library/rgAD.nsf/AOCADSearch/1EBF0AA24910728C86256A40006C38D9?OpenDocument)

p/c/w

98-14-03

8/16/1998

Transponders

[http://rgl.faa.gov/Regulatory and Guidance Library/rgAD.nsf/AOCADSearch/F76CA25CDA3CD8B686256A3F004752EB?OpenDocument](http://rgl.faa.gov/Regulatory_and_Guidance_Library/rgAD.nsf/AOCADSearch/F76CA25CDA3CD8B686256A3F004752EB?OpenDocument)

NA

97-01-13

2/3/1997

Fuel, Oil and Hydraulic Hoses

[http://rgl.faa.gov/Regulatory and Guidance Library/rgAD.nsf/AOCADSearch/61096AB0622CB78B86256A4D006A13DC?OpenDocument](http://rgl.faa.gov/Regulatory_and_Guidance_Library/rgAD.nsf/AOCADSearch/61096AB0622CB78B86256A4D006A13DC?OpenDocument)

*NA
c/w*

96-12-22

7/31/1996

Full Flow Engine Oil Adapter

[http://rgl.faa.gov/Regulatory and Guidance Library/rgAD.nsf/AOCADSearch/3B453D53CE6D9DCC86256849005A0715?OpenDocument](http://rgl.faa.gov/Regulatory_and_Guidance_Library/rgAD.nsf/AOCADSearch/3B453D53CE6D9DCC86256849005A0715?OpenDocument)

p/c/w

96-09-06

6/7/1996

Air Filter Assemblies

[http://rgl.faa.gov/Regulatory and Guidance Library/rgAD.nsf/AOCADSearch/ED4848C66447B35686256A40006C6AFE?OpenDocument](http://rgl.faa.gov/Regulatory_and_Guidance_Library/rgAD.nsf/AOCADSearch/ED4848C66447B35686256A40006C6AFE?OpenDocument)

c/w inspect

93-24-15

2/11/1994

Instrument Panel Light Rheostat

[http://rgl.faa.gov/Regulatory and Guidance Library/rgad.nsf/AOCADSearch/656D033011626F9B86256A500043120C?OpenDocument](http://rgl.faa.gov/Regulatory_and_Guidance_Library/rgad.nsf/AOCADSearch/656D033011626F9B86256A500043120C?OpenDocument)

c/w inspect

90-06-03 R1

3/27/1991

Exhaust Heater/Muffler Assembly

[http://rgl.faa.gov/Regulatory and Guidance Library/rgAD.nsf/AOCADSearch/C75D48AE26F0BD0C86256A340062036D?OpenDocument](http://rgl.faa.gov/Regulatory_and_Guidance_Library/rgAD.nsf/AOCADSearch/C75D48AE26F0BD0C86256A340062036D?OpenDocument)

NA

79-10-14 R1

5/30/1988

Fuel Tank Venting

[http://rgl.faa.gov/Regulatory and Guidance Library/rgAD.nsf/AOCADSearch/225F45DF0B489ACE86256A34006AB0A2?OpenDocument](http://rgl.faa.gov/Regulatory_and_Guidance_Library/rgAD.nsf/AOCADSearch/225F45DF0B489ACE86256A34006AB0A2?OpenDocument)

c/w inspect

86-24-07

1/7/1987

Engine Controls Installation

([http://rgl.faa.gov/Regulatory and Guidance Library\rgAD.nsf/AOCADSearch/5233FEB24ABA8984862569BA004BC64B?OpenDocument](http://rgl.faa.gov/Regulatory_and_Guidance_Library/rgAD.nsf/AOCADSearch/5233FEB24ABA8984862569BA004BC64B?OpenDocument))

p/g/cw

86-19-11

10/4/1986

Contaminated Fuel

([http://rgl.faa.gov/Regulatory and Guidance Library\rgAD.nsf/AOCADSearch/EE7D73C30F85271D862569BA004BC384?OpenDocument](http://rgl.faa.gov/Regulatory_and_Guidance_Library/rgAD.nsf/AOCADSearch/EE7D73C30F85271D862569BA004BC384?OpenDocument))

N/A

72-03-03 R3

10/15/1984

Wing Flap Actuators Jack Screw

([http://rgl.faa.gov/Regulatory and Guidance Library\rgad.nsf/AOCADSearch/11383ACCA8E3EF4E86256A34006319D9?OpenDocument](http://rgl.faa.gov/Regulatory_and_Guidance_Library/rgad.nsf/AOCADSearch/11383ACCA8E3EF4E86256A34006319D9?OpenDocument))

p/g/cw

83-22-06

11/8/1983

Aileron Hinge Pin

([http://rgl.faa.gov/Regulatory and Guidance Library\rgAD.nsf/AOCADSearch/4040907A5E39011B862569B9004D135D?OpenDocument](http://rgl.faa.gov/Regulatory_and_Guidance_Library/rgAD.nsf/AOCADSearch/4040907A5E39011B862569B9004D135D?OpenDocument))

N/A

< Previous 1 2 (?q=172k&makeModel=&type=Current&filter=&sort=effectiveDate&direction=desc&startRow=26)

Next > (?q=172k&makeModel=&type=Current&filter=&sort=effectiveDate&direction=desc&startRow=26)

Showing 1–25 of 48 airworthiness directives.

Page last modified: May 11, 2016 9:56:10 AM EDT

This page was originally published at: http://www.faa.gov/regulations_policies/airworthiness_directives/search/?q=172k

*1596.7
1453.1
143.3*

*10192.8
10314.0*

*1596.7
1474.4
122.0*



Federal Aviation Administration

Airworthiness Directives (ADs (Airworthiness Directives)) - Current Only

Search Results for "172k"

[« Back to Airworthiness Directives Main Page](#)

Search Results

AD No.

Effective Date

Subject

83-17-06

9/1/1983

Aileron Balance Weights

([http://rgl.faa.gov/Regulatory and Guidance Library/rgAD.nsf/AOCADSearch/E3038964F91329F7862569B9004D123A?OpenDocument](http://rgl.faa.gov/Regulatory_and_Guidance_Library/rgAD.nsf/AOCADSearch/E3038964F91329F7862569B9004D123A?OpenDocument))

NA B1 #

83-10-03

6/30/1983

Control Wheel Yoke Guide
Modification

([http://rgl.faa.gov/Regulatory and Guidance Library/rgAD.nsf/AOCADSearch/3D055F1F56F0553A862569B9004D0ED4?OpenDocument](http://rgl.faa.gov/Regulatory_and_Guidance_Library/rgAD.nsf/AOCADSearch/3D055F1F56F0553A862569B9004D0ED4?OpenDocument))

NA - STC

82-07-02

4/8/1982

Engine Crankcase Breather

([http://rgl.faa.gov/Regulatory and Guidance Library/rgAD.nsf/AOCADSearch/89D2E182A363570F862569B9004D3EDE?OpenDocument](http://rgl.faa.gov/Regulatory_and_Guidance_Library/rgAD.nsf/AOCADSearch/89D2E182A363570F862569B9004D3EDE?OpenDocument))

NA - m #

80-25-07 R1

9/24/1981

Oil Coolers

([http://rgl.faa.gov/Regulatory and Guidance Library/rgAD.nsf/AOCADSearch/C3CD2484103ACBC086256A3900683CE5?OpenDocument](http://rgl.faa.gov/Regulatory_and_Guidance_Library/rgAD.nsf/AOCADSearch/C3CD2484103ACBC086256A3900683CE5?OpenDocument))

NA - m #

81-16-09

8/13/1981

Elevator Control System

([http://rgl.faa.gov/Regulatory and Guidance Library/rgAD.nsf/AOCADSearch/79377FCF8E597F80862569B9004D3BF8?OpenDocument](http://rgl.faa.gov/Regulatory_and_Guidance_Library/rgAD.nsf/AOCADSearch/79377FCF8E597F80862569B9004D3BF8?OpenDocument))

NA - m #

81-15-03 (http://rgl.faa.gov/Regulatory and Guidance Library\rgAD.nsf/AOCADSearch/7BA6FD8A49736CF386256A34006250FF? OpenDocument)	7/20/1981 <i>C/cw</i>	Engine Inlet Air Filters
81-05-01 (http://rgl.faa.gov/Regulatory and Guidance Library\rgAD.nsf/AOCADSearch/591D97B6E7306E18862569B9004D3638? OpenDocument)	3/2/1981 <i>C/cw</i>	Fuel Tank Capacity
80-06-03 (http://rgl.faa.gov/Regulatory and Guidance Library\rgAD.nsf/AOCADSearch/590198B0F269BE9A862569BA004C0A70? OpenDocument)	4/21/1980 <i>NA m#</i>	Wing Flap Cable Clamp
80-07-03 (http://rgl.faa.gov/Regulatory and Guidance Library\rgAD.nsf/AOCADSearch/310F2AEF4708F659862569B9004D2F06? OpenDocument)	3/31/1980 <i>P/cw</i>	Oil Pressure
79-08-03 (http://rgl.faa.gov/Regulatory and Guidance Library\rgAD.nsf/AOCADSearch/D175D2296B42FCD686256A34006AA97C? OpenDocument)	6/6/1979 <i>P/cw</i>	Electrical System
77-12-08 (http://rgl.faa.gov/Regulatory and Guidance Library\rgAD.nsf/AOCADSearch/AB8B5C20D3FB408B86256A3400683BBE? OpenDocument)	6/27/1977 <i>NA not installed</i>	External Electrical Ground Power Receptacle
77-02-09 (http://rgl.faa.gov/Regulatory and Guidance Library\rgAD.nsf/AOCADSearch/3C62F9032CA7AE9B86256A3400683001? OpenDocument)	2/3/1977 <i>NA</i>	Wing Flap System
76-04-03 (http://rgl.faa.gov/Regulatory and Guidance Library\rgAD.nsf/AOCADSearch/6DE72C169605F8C886256A340066AB88? OpenDocument)	2/26/1976 <i>NA not installed</i>	ARC PA-500A Actuators

<u>74-08-01</u> http://rgl.faa.gov/Regulatory and Guidance Library/rgAD.nsf/AOCADSearch/540107CA6D7CDF7386256A320048CF24? OpenDocument	4/9/1974 <i>NA</i> <i>not installed</i>	Autopilot Servo Actuators
<u>74-06-02</u> http://rgl.faa.gov/Regulatory and Guidance Library/rgAD.nsf/AOCADSearch/5E9682BCE2C44C88862569990050FE97? OpenDocument	3/18/1974 <i>NA</i> <i>not installed</i>	AVCON Mufflers
<u>74-04-01</u> http://rgl.faa.gov/Regulatory and Guidance Library/rgAD.nsf/AOCADSearch/8560DC9CF2D3E59D86256A3400649047? OpenDocument	2/12/1974	Aft Fuselage Bulkhead Assembly
<u>73-23-07</u> http://rgl.faa.gov/Regulatory and Guidance Library/rgAD.nsf/AOCADSearch/65A7037C7EEE708086256A340064678E? OpenDocument	11/19/1973 <i>P/C/W</i>	Defective Spar Attachment Fittings
<u>73-17-01</u> http://rgl.faa.gov/Regulatory and Guidance Library/rgAD.nsf/AOCADSearch/EF7F12B764BA85FF86256A3400646090? OpenDocument	8/16/1973 <i>NA</i> <i>not installed</i>	Fuel Transfer Pump Placard
<u>72-07-02</u> http://rgl.faa.gov/Regulatory and Guidance Library/rgAD.nsf/AOCADSearch/2C7B32477D2A88A286256A340063355D? OpenDocument	3/25/1972 <i>P/C/W</i>	Selector Value Placard
<u>71-22-02</u> http://rgl.faa.gov/Regulatory and Guidance Library/rgAD.nsf/AOCADSearch/59E323F41F570CD786256E01005AD6B1? OpenDocument	11/9/1971 <i>P/C/W</i>	Cracks In Nose Gear Fork
<u>71-18-01</u> http://rgl.faa.gov/Regulatory and Guidance Library/rgAD.nsf/AOCADSearch/D17CE665960220AD86256A340062F3EA? OpenDocument	8/31/1971 <i>P/C/W</i>	Fuel Selector Valve Placard

69-15-03

8/20/1969

Muffler Assembly

[http://rgl.faa.gov/Regulatory and Guidance Library/rgAD.nsf/AOCADSearch/F1484C6E5D9F68CA86256A1C00749BB0?OpenDocument](http://rgl.faa.gov/Regulatory_and_Guidance_Library/rgAD.nsf/AOCADSearch/F1484C6E5D9F68CA86256A1C00749BB0?OpenDocument)

NA
Part

68-17-04

9/7/1968

Stall Warning System

[http://rgl.faa.gov/Regulatory and Guidance Library/rgAD.nsf/AOCADSearch/1B432556F74D37E786256A3400626E7A?OpenDocument](http://rgl.faa.gov/Regulatory_and_Guidance_Library/rgAD.nsf/AOCADSearch/1B432556F74D37E786256A3400626E7A?OpenDocument)

P/CW
NA

< Previous (?q=172k&makeModel=&type=Current&filter=&sort=effectiveDate&direction=desc&startRow=1)

1 (?q=172k&makeModel=&type=Current&filter=&sort=effectiveDate&direction=desc&startRow=1) 2 Next >

Showing 26-48 of 48 airworthiness directives.

Page last modified: May 11, 2016 9:56:10 AM EDT

This page was originally published at: http://www.faa.gov/regulations_policies/airworthiness_directives/search/?q=172k&makeModel=&type=Current&filter=&sort=effectiveDate&direction=desc&startRow=26



Federal Aviation Administration

Airworthiness Directives (ADs (Airworthiness Directives)) - Current Only Search Results for "0 320 e2d"

[« Back to Airworthiness Directives Main Page](#)

Search Results

Filter within results

Filter

AD No. ☐

Effective Date ☐

Subject ☐

2012-03-07

3/27/2012

Carburetor

([http://rgl.faa.gov/Regulatory and Guidance Library/rgAD.nsf/AOCADSearch/5650B8CD2CD80877862579AB00503BA4?OpenDocument](http://rgl.faa.gov/Regulatory_and_Guidance_Library/rgAD.nsf/AOCADSearch/5650B8CD2CD80877862579AB00503BA4?OpenDocument))

NA

2009-26-12

2/4/2010

Cylinder assemblies

([http://rgl.faa.gov/Regulatory and Guidance Library/rgAD.nsf/AOCADSearch/FD1C80194BA0B8DA8625769D00695ADA?OpenDocument](http://rgl.faa.gov/Regulatory_and_Guidance_Library/rgAD.nsf/AOCADSearch/FD1C80194BA0B8DA8625769D00695ADA?OpenDocument))

NA

2007-04-19R1

5/7/2007

SAP cylinder assemblies

([http://rgl.faa.gov/Regulatory and Guidance Library/rgAD.nsf/AOCADSearch/1426D6B55173B295862572B1004EC2D4?OpenDocument](http://rgl.faa.gov/Regulatory_and_Guidance_Library/rgAD.nsf/AOCADSearch/1426D6B55173B295862572B1004EC2D4?OpenDocument))

NA

2006-12-07

7/11/2006

ECi cylinder assemblies

([http://rgl.faa.gov/Regulatory and Guidance Library/rgad.nsf/AOCADSearch/076CBE0678C2D2398625718500504687?OpenDocument](http://rgl.faa.gov/Regulatory_and_Guidance_Library/rgad.nsf/AOCADSearch/076CBE0678C2D2398625718500504687?OpenDocument))

NA

2004-10-14

6/25/2004

Crankshaft gear

([http://rgl.faa.gov/Regulatory and Guidance Library/rgAD.nsf/AOCADSearch/9FA5E5F8683A0A4686256E9B004BC295?OpenDocument](http://rgl.faa.gov/Regulatory_and_Guidance_Library/rgAD.nsf/AOCADSearch/9FA5E5F8683A0A4686256E9B004BC295?OpenDocument))

due to O/H
on prop struck

<u>98-17-11</u> (http://rgl.faa.gov/Regulatory and Guidance Library/rgAD.nsf/AOCADSearch/ED3F1B9AF861486E8625684A004EE501?OpenDocument)	10/19/1998 NA	Crankshafts
<u>98-02-08</u> (http://rgl.faa.gov/Regulatory and Guidance Library/rgAD.nsf/AOCADSearch/E7B86DE103CB30E78625684D006644B5?OpenDocument)	3/30/1998 c/w o/H	Crankshaft
<u>98-01-06</u> (http://rgl.faa.gov/Regulatory and Guidance Library/rgAD.nsf/AOCADSearch/9F87A5E42C10900C86256A410065C0CD?OpenDocument)	2/13/1998 NA o/H	Carburetors
<u>97-15-11</u> (http://rgl.faa.gov/Regulatory and Guidance Library/rgad.nsf/AOCADSearch/F41AE8741C4E77CE8625684D00659858?OpenDocument)	8/12/1997 NA P#	Cylinder kits
<u>96-09-10</u> (http://rgl.faa.gov/Regulatory and Guidance Library/rgAD.nsf/AOCADSearch/5DE5ACBD6CBC8B2A8625684D00643AC1?OpenDocument)	7/15/1996 c/w o/H	Oil pump
<u>95-26-02</u> (http://rgl.faa.gov/Regulatory and Guidance Library/rgAD.nsf/AOCADSearch/C17889E92CF6B0F68625684D0063FA02?OpenDocument)	1/24/1996 NA	Aviation Gasoline
<u>93-19-04</u> (http://rgl.faa.gov/Regulatory and Guidance Library/rgAD.nsf/AOCADSearch/DA28338BF3FCB4C786256A410065BB2D?OpenDocument)	10/18/1993 NA c/H	Carburetors
<u>92-12-05</u> (http://rgl.faa.gov/Regulatory and Guidance Library/rgad.nsf/AOCADSearch/EB7F913B8170444C8625684A005E1FB9?OpenDocument)	7/10/1992 c/w o/H	Piston Pins

04-06 R1

([http://rgl.faa.gov/Regulatory and Guidance_Library/rgad.nsf/AOCADSearch/D17C07A9D76E6AAA8625684F006E5ADC?OpenDocument](http://rgl.faa.gov/Regulatory_and_Guidance_Library/rgad.nsf/AOCADSearch/D17C07A9D76E6AAA8625684F006E5ADC?OpenDocument))

5/28/1991

NA m#

Propeller Governor External Oil Line

87-10-06 R1

([http://rgl.faa.gov/Regulatory and Guidance_Library/rgAD.nsf/AOCADSearch/2345033EEBFB865986256842006B4839?OpenDocument](http://rgl.faa.gov/Regulatory_and_Guidance_Library/rgAD.nsf/AOCADSearch/2345033EEBFB865986256842006B4839?OpenDocument))

9/1/1989

NA m#

Rocker Arm Assembly

81-16-05

([http://rgl.faa.gov/Regulatory and Guidance_Library/rgAD.nsf/AOCADSearch/E4BD81E7943D55BB86256A3900683165?OpenDocument](http://rgl.faa.gov/Regulatory_and_Guidance_Library/rgAD.nsf/AOCADSearch/E4BD81E7943D55BB86256A3900683165?OpenDocument))

8/6/1981

q/h NA

Magnetos

80-06-05

([http://rgl.faa.gov/Regulatory and Guidance_Library/rgAD.nsf/AOCADSearch/C43E13FBCB95A098862569EE00658E47?OpenDocument](http://rgl.faa.gov/Regulatory_and_Guidance_Library/rgAD.nsf/AOCADSearch/C43E13FBCB95A098862569EE00658E47?OpenDocument))

3/28/1980

NA o/h

Magnetos

75-08-09

([http://rgl.faa.gov/Regulatory and Guidance_Library/rgAD.nsf/AOCADSearch/AE90399AB5340ABE86256E1200477661?OpenDocument](http://rgl.faa.gov/Regulatory_and_Guidance_Library/rgAD.nsf/AOCADSearch/AE90399AB5340ABE86256E1200477661?OpenDocument))

8/18/1977

NA o/h

Oil Pump Drive Shaft

73-23-01

([http://rgl.faa.gov/Regulatory and Guidance_Library/rgAD.nsf/AOCADSearch/534E4B43F97807DB86256E12004775A2?OpenDocument](http://rgl.faa.gov/Regulatory_and_Guidance_Library/rgAD.nsf/AOCADSearch/534E4B43F97807DB86256E12004775A2?OpenDocument))

1/13/1977

NA o/h

Piston Pin Assembly

69-24-03

([http://rgl.faa.gov/Regulatory and Guidance_Library/rgAD.nsf/AOCADSearch/670FCCEB061EB0FA86256A330055C0A0?OpenDocument](http://rgl.faa.gov/Regulatory_and_Guidance_Library/rgAD.nsf/AOCADSearch/670FCCEB061EB0FA86256A330055C0A0?OpenDocument))

11/29/1969

NA o/h

Carburetors

67-01-04

([http://rgl.faa.gov/Regulatory and Guidance_Library/rgAD.nsf/AOCADSearch/D2728366309A4FF886256A33006FEA2D?OpenDocument](http://rgl.faa.gov/Regulatory_and_Guidance_Library/rgAD.nsf/AOCADSearch/D2728366309A4FF886256A33006FEA2D?OpenDocument))

1/2/1967

NA p#

Oil Filters