

Aircraft Weight and Balance Revision

Tail Number: N4038B				Date: 08-17-18																																		
Prepared by: DEAN ROZEBOOM 1901 W GERMANN RD 3025 CHANDLER, AZ 85286				Work Order No: N/A																																		
				Type Certificate Data No: A18CE																																		
Aircraft Make: BELLANCA		Model: BL17-30A		Serial No: 76-30822																																		
		Time: 15:00																																				
Registered Owner: RAYMOND T HAVINS				Address: 1165 WEST DRIVE LAKESIDE, AZ 85929																																		
Maximum Weight 3325.00		CG Range FWD AFT																																				
As Received; Date of Previous Weight and Balance: 10-04-05		Useful Load: 1055.40		EW: 2269.60																																		
				EWCG: 17.34																																		
		Moment: 39,347.09																																				
Notes: AVOINICS INSTALLATION OF GARMIN GTX 335 TRNSPONDER, GARMIN SL 40 VHF COMM, JPI FS 450 FUEL FLOW																																						
				<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 60%;">Weight</th> <th style="width: 20%;">Arm</th> <th style="width: 20%;">Moment</th> </tr> </thead> <tbody> <tr> <td>REMOVED KING KX 170B VHF COMM P/N 069-1070-00, S/N 57756</td> <td style="text-align: center;">- 7.4</td> <td style="text-align: center;">-2.10</td> </tr> <tr> <td>REMOVED KING KI-201C VOR, P/N 066-3008-02, S/N 24793</td> <td style="text-align: center;">-2.8</td> <td style="text-align: center;">-2.10</td> </tr> <tr> <td>REMOVED KING KA-76A TRANSPONDER, P/N 066-1034-00, S/N</td> <td style="text-align: center;">-4.0</td> <td style="text-align: center;">-2.10</td> </tr> <tr> <td>INSTALLED GARMIN GTX 335 TRANSPONDER, P/N 011-03300-40, S/N</td> <td style="text-align: center;">4.2</td> <td style="text-align: center;">-2.10</td> </tr> <tr> <td>INSTALLED GARMIN SLK 40 VHF COMM, P/N 430-6040-203, 25814814</td> <td style="text-align: center;">2.0</td> <td style="text-align: center;">-2.10</td> </tr> <tr> <td>INSTALLED JPI FS 540 FUEL FLOW SYSTEM, P/N 450000, S/N 15601</td> <td style="text-align: center;">.20</td> <td style="text-align: center;">-2.10</td> </tr> <tr><td> </td><td> </td><td> </td></tr> <tr><td> </td><td> </td><td> </td></tr> <tr><td> </td><td> </td><td> </td></tr> <tr><td> </td><td> </td><td> </td></tr> </tbody> </table>		Weight	Arm	Moment	REMOVED KING KX 170B VHF COMM P/N 069-1070-00, S/N 57756	- 7.4	-2.10	REMOVED KING KI-201C VOR, P/N 066-3008-02, S/N 24793	-2.8	-2.10	REMOVED KING KA-76A TRANSPONDER, P/N 066-1034-00, S/N	-4.0	-2.10	INSTALLED GARMIN GTX 335 TRANSPONDER, P/N 011-03300-40, S/N	4.2	-2.10	INSTALLED GARMIN SLK 40 VHF COMM, P/N 430-6040-203, 25814814	2.0	-2.10	INSTALLED JPI FS 540 FUEL FLOW SYSTEM, P/N 450000, S/N 15601	.20	-2.10												
Weight	Arm	Moment																																				
REMOVED KING KX 170B VHF COMM P/N 069-1070-00, S/N 57756	- 7.4	-2.10																																				
REMOVED KING KI-201C VOR, P/N 066-3008-02, S/N 24793	-2.8	-2.10																																				
REMOVED KING KA-76A TRANSPONDER, P/N 066-1034-00, S/N	-4.0	-2.10																																				
INSTALLED GARMIN GTX 335 TRANSPONDER, P/N 011-03300-40, S/N	4.2	-2.10																																				
INSTALLED GARMIN SLK 40 VHF COMM, P/N 430-6040-203, 25814814	2.0	-2.10																																				
INSTALLED JPI FS 540 FUEL FLOW SYSTEM, P/N 450000, S/N 15601	.20	-2.10																																				
☒ As Calculated		Moment 39,332.70		New Empty Weight CG 17.38																																		
☐ As Weighed		Weight 2261.8		New Useful Load 1063.2																																		
Signature																																						
Repair Agency or License No: 3177219- IA																																						