

1. Approving Civil Aviation Authority / Country FAA / United States		2. AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3 AIRWORTHINESS APPROVAL TAG		3. Form Tracking No: ASI-175377	
4. Organization AIRCRAFT SPECIALTIES SERVICES, INC. PHONE: (918) 836-6872 2860 NORTH SHERIDAN ROAD FAX: (918) 836-4419 TULSA, OK 74115 FAA REPAIR STATION NO. DD2R764K				5. Work Order/ Contract/Invoice No. 272194	
6. Item:	7. Description:	8. Part Number:	9. Quantity	10. Serial Number	11. Status/Work
1.	LIFTER	530851	6	N/A	OVERHAUL

12 Remarks:

OVERHAULED IAW AS²I PROCESS 0009 REV. F DT: 29 JUN 2004

ADDITIONAL INSPECTION MAY BE REQUIRED PRIOR TO INSTALLATION

PART TRACKING NO: ASR-6-27-22

NOTE: AS²I = AIRCRAFT SPECIALTIES SERVICES, INC.

530851
LIFTER


13a. Certifies the items identified above were manufactured in conformity to <input type="checkbox"/> Approved design data and are in a condition for safe operation <input type="checkbox"/> Non-approved design data specified in Block 12		14a. <input checked="" type="checkbox"/> 14 CFR 43.9 Return to Service <input type="checkbox"/> Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.	
13b. Authorized Signature	13c. Approval/ Authorization No.	14b. Authorized Signature	14c. Approval Certificate No. DD2R764K
13d. Name (Typed or Printed)	13e. Date (dd/mmm/yyyy)	14d. Name (Typed or Printed) Harold Lehman	14e. Date (dd/mmm/yyyy) 27 JUL 2022


User/Installer Responsibilities

It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article.

Where the user/installer work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1.

Statements in Blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

1. Approving Civil Aviation Authority / Country FAA / United States		2. AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3 AIRWORTHINESS APPROVAL TAG			3. Form Tracking No: AS1-175378	
4. Organization AIRCRAFT SPECIALTIES SERVICES, INC. PHONE: (918) 836-6872 2860 NORTH SHERIDAN ROAD FAX: (918) 836-4419 TULSA, OK 74115 FAA REPAIR STATION NO. DD2R764K					5. Work Order/ Contract/Invoice No. 272194	
6. Item:	7. Description:	8. Part Number:	9. Quantity	10. Serial Number	11. Status/Work	
1.	HYDRAULIC UNIT	633697	8	N/A	OVERHAUL	
12. Remarks: OVERHAULED IAW AS2I PROCEDURE 99-001 REV. 2 DT: 10 AUG 2015 ADDITIONAL INSPECTION MAY BE REQUIRED PRIOR TO INSTALLATION PART TRACKING NO: S272194-5 NOTE: AS2I = AIRCRAFT SPECIALTIES SERVICES, INC.						
13a. Certifies the items identified above were manufactured in conformity to <input type="checkbox"/> Approved design data and are in a condition for safe operation <input type="checkbox"/> Non-approved design data specified in Block 12			14a. <input checked="" type="checkbox"/> 14 CFR 43.9 <input type="checkbox"/> Other regulation Return to Service specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.			
13b. Authorized Signature		13c. Approval/ Authorization No.		14b. Authorized Signature		14c. Approval/Certificate No.
						DD2R764K
13d. Name (Typed or Printed)		13e. Date (dd/mm/yyyy)		14d. Name (Typed or Printed)		14e. Date (dd/mm/yyyy)
				Harold Lehman		27 JUL 2022
User/Installer Responsibilities						
It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article.						
Where the user/installer work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1.						
Statements in Blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.						

1. Approving Civil Aviation Authority / Country FAA / United States		2. AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3 AIRWORTHINESS APPROVAL TAG			3. Form Tracking No: AS1-175375	
4. Organization AIRCRAFT SPECIALTIES SERVICES, INC. PHONE: (918) 836-6872 2860 NORTH SHERIDAN ROAD FAX: (918) 836-4419 TULSA, OK 74115 FAA REPAIR STATION NO. DD2R764K					5. Work Order/ Contract/Invoice No. 272194	
6. Item:	7. Description:	8. Part Number:	9. Quantity	10. Serial Number	11. Status/Work	
1.	CAMSHAFT	626608	1	N/A	REPAIRED	
12. Remarks: PERFORMED MAGNETIC PARTICLE INSPECTION IAW ASTM E1444/E1444M-22A DT: 01 JUL 2022 PERFORMED DIMENSIONAL CHECK IAW AS ² I REPAIR PROCEDURE 0812006 REV. 02 DT: 16 JAN 2018 GROUND LOBES IAW AS ² I REPAIR PROCEDURE 0812006 REV. 02 DT: 16 JAN 2018 APPLIED MANGANESE PHOSPHATE IAW AS ² I REPAIR PROCEDURE 0812006 REV. 02 DT: 16 JAN 2018 ADDITIONAL INSPECTION MAY BE REQUIRED PRIOR TO INSTALLATION PART TRACKING NO: S272194-2 NOTE: AS ² I = AIRCRAFT SPECIALTIES SERVICES, INC.						
<div style="font-size: 2em; opacity: 0.5; transform: rotate(-10deg);"> 626608 CAMSHAFT </div>						
13a. Certifies the items identified above were manufactured in conformity to <input type="checkbox"/> Approved design data and are in a condition for safe operation <input type="checkbox"/> Non-approved design data specified in Block 12				14a. <input checked="" type="checkbox"/> 14 CFR 43.9 Return to Service <input type="checkbox"/> Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.		
13b. Authorized Signature		13c. Approval/Authorization No.		14b. Authorized Signature		14c. Approval/Certificate No.
						DD2R764K
13d. Name (Typed or Printed)		13e. Date (dd/mm/yyyy)		14d. Name (Typed or Printed)		14e. Date (dd/mm/yyyy)
				Harold Lehman		27 JUL 2022
User/Installer Responsibilities						
<p>It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article.</p> <p>Where the user/installer work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1.</p> <p>Statements in Blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.</p>						

C. Yates

2194

1. Approving Civil Aviation Authority / Country FAA / United States	2. AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3 AIRWORTHINESS APPROVAL TAG	3. Form Tracking No: ASI-175488			
4. Organization AIRCRAFT SPECIALTIES SERVICES, INC. PHONE: (918) 836-6872 2860 NORTH SHERIDAN ROAD FAX: (918) 836-4419 TULSA, OK 74115 FAA REPAIR STATION NO. DD2R764K		5. Work Order/ Contract/Invoice No. 272194			
6. Item:	7. Description:	8. Part Number:	9. Quantity	10. Serial Number	11. Status/Work
1.	CRANKSHAFT	CONTINENTAL O-200 SUBASSEMBLY	1	N/A	REPAIRED

12 Remarks:

PERFORMED MAGNETIC PARTICLE INSPECTION IAW ASTM E1444/E1444M-22A DT: 01 JUL 2022
PERFORMED DIMENSIONAL CHECK IAW AS²I REPAIR SPECIFICATION 1004 DT: 30 SEP 2016
MEASURED ROD JOURNALS M020, MAIN JOURNALS GROUND M020 IAW AS²I REPAIR SPECIFICATION 1004 DT: 30 SEP 2016
GROUND OIL SEAL SURFACE IAW AS²I REPAIR SPECIFICATION 1004 DT: 30 SEP 2016
NITRIDE IAW AS²I PROCESS 0005 REV. 6 DT: 01 SEP 2005
CADMIUM PLATE AND BAKE PROPELLER FLANGE IAW AS²I REPAIR SPECIFICATION 1004 DT: 30 SEP 2016
POLISHED ROD AND MAIN JOURNALS IAW AS²I REPAIR SPECIFICATION 1004 DT: 30 SEP 2016
GROUND FLANGE IAW AS²I REPAIR SPECIFICATION 1004 DT: 30 SEP 2016
GROUND BEARING JOURNALS IAW AS²I STC NO. SE09002SC REV. 2 DT: 10 MAR 2006
REPAIRED PILOT IAW AS²I PROCESS 99-008 DT: 28 DEC 1999

ADDITIONAL INSPECTION MAY BE REQUIRED PRIOR TO INSTALLATION

PART TRACKING NO: S272194-1

NOTE: AS²I = AIRCRAFT SPECIALTIES SERVICES, INC.

13a. Certifies the items identified above were manufactured in conformity to <input type="checkbox"/> Approved design data and are in a condition for safe operation <input type="checkbox"/> Non-approved design data specified in Block 12		14a. <input checked="" type="checkbox"/> 14 CFR 43.9 Return to Service <input type="checkbox"/> Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.	
13b. Authorized Signature	13c. Approval/ Authorization No.	14b. Authorized Signature	14c. Approval/Certificate No. DD2R764K
13d. Name (Typed or Printed)	13e. Date (dd/mm/yyyy)	14d. Name (Typed or Printed) Harold Lehman	14e. Date (dd/mm/yyyy) 28 JUL 2022

User/Installer Responsibilities

It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article.

Where the user/installer work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1.

Statements in Blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

1. Approving Civil Aviation Authority / Country FAA / United States		2. AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3 AIRWORTHINESS APPROVAL TAG			3. Form Tracking No: ASI-175376	
4. Organization AIRCRAFT SPECIALTIES SERVICES, INC. PHONE: (918) 836-6872 2860 NORTH SHERIDAN ROAD FAX: (918) 836-4419 TULSA, OK 74115 FAA REPAIR STATION NO. DD2R764K					5. Work Order/ Contract/Invoice No. 272194	
6. Item:	7. Description:	8. Part Number:	9. Quantity	10. Serial Number	11. Status/Work	
1.	CONNECTING ROD	CONTINENTAL O-200 SUBASSEMBLY	4	N/A	REPAIRED	
12. Remarks: PERFORMED MAGNETIC PARTICLE INSPECTION IAW ASTM E1444/E1444M-22A DT: 01 JUL 2022 REPAIRED IAW AS ² I PROCESS 2000-05 REV 2 DT: 25 MAR 2003 ADDITIONAL INSPECTION MAY BE REQUIRED PRIOR TO INSTALLATION (IF INCLUDED, NO RETURN TO SERVICE DETERMINATION IS MADE FOR ROD BOLTS OR NUTS) PART TRACKING NO: S272194-3 NOTE: AS ² I = AIRCRAFT SPECIALTIES SERVICES, INC.						
13a. Certifies the items identified above were manufactured in conformity to <input type="checkbox"/> Approved design data and are in a condition for safe operation <input type="checkbox"/> Non-approved design data specified in Block 12			14a. <input checked="" type="checkbox"/> 14 CFR 43.9 <input type="checkbox"/> Other regulation Return to Service specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.			
13b. Authorized Signature		13c. Approval/ Authorization No.		14b. Authorized Signature		14c. Approval/Certificate No. DD2R764K
13d. Name (Typed or Printed)		13e. Date (dd/mmm/yyyy)		14d. Name (Typed or Printed) Harold Lehman		14e. Date (dd/mmm/yyyy) 27 JUL 2022
User/Installer Responsibilities						
It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article.						
Where the user/installer work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1.						
Statements in Blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.						

1. Approving Civil Aviation Authority / Country FAA / United States		2. AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3 AIRWORTHINESS APPROVAL TAG			3. Form Tracking No: ASI-175379	
4. Organization AIRCRAFT SPECIALTIES SERVICES, INC. PHONE: (918) 836-6872 2860 NORTH SHERIDAN ROAD FAX: (918) 836-4419 TULSA, OK 74115 FAA REPAIR STATION NO. DD2R764K					5. Work Order/ Contract/Invoice No. 272194	
6. Item:	7. Description:	8. Part Number:	9. Quantity	10. Serial Number	11. Status/Work	
1.	GEAR	CONTINENTAL O-200 SUBASSEMBLY	7	N/A	INSPECTED	

12. Remarks:

PERFORMED MAGNETIC PARTICLE INSPECTION IAW ASTM E1444/E1444M-22A DT: 01 JUL 2022

ADDITIONAL INSPECTION MAY BE REQUIRED PRIOR TO INSTALLATION

PART TRACKING NO: S272194-6

4 CYLINDER INTERNAL


13a. Certifies the items identified above were manufactured in conformity to <input type="checkbox"/> Approved design data and are in a condition for safe operation <input type="checkbox"/> Non-approved design data specified in Block 12		14a. <input checked="" type="checkbox"/> 14 CFR 43.9 Return to Service <input type="checkbox"/> Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.	
13b. Authorized Signature	13c. Approval/ Authorization No.	14b. Authorized Signature	14e. Approval/Certificate No. DD2R764K
13d. Name (Typed or Printed)	13e. Date (dd/mm/yyyy)	14d. Name (Typed or Printed) Harold Lehman	14e. Date (dd/mm/yyyy) 27 JUL 2022

User/Installer Responsibilities

It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article.

Where the user/installer work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1.

Statements in Blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

1. Approving Civil Aviation Authority/Country: FAA/United States		2. <div style="text-align: center; font-weight: bold; font-size: 1.2em;">AUTHORIZED RELEASE CERTIFICATE</div> FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG			
3. Form Tracking Number: DIV #13800		4. Organization Name and Address: DIVCO, INC., 28206 N. SHERIDAN ROAD, TULSA, OK 74115 (DB2R762K)			
6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:
1	CONT O-200 ACCY CASE	CASTING # 6726	1	N/A	REPAIRED
12. Remarks: CLEAN, INSPECT, REPAIRED (2) DRIVE GEAR HOLES AND CUT OIL PRESSURE SEAT REPAIRED PER DIVCO APPROVED PROCESS SPECS 77-002 REV 6 18 JULY 2017 DATE COMPLETED: 26/JUL/2022 DIV #13800 WORK SPECIFIED IN BLOCKS 14/12 WAS CARRIED OUT IN ACCORDANCE WITH EASA PART 145 AND WITH RESPECT TO THAT WORK THE COMPONENT IS CONSIDERED READY FOR RELEASE TO SERVICE UNDER EASA PART 145 APPROVAL NUMBER EASA 145-5286					
13a. Certifies the items identified above were manufactured in conformity to: <input type="checkbox"/> Approved design data and are in a condition for safe operation. <input type="checkbox"/> Non-approved design data specified in Block 12.		14a. <input checked="" type="checkbox"/> 14 CFR 43.9 Return to Service Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.			
13b. Authorized Signature:	13c. Approval/Authorization No.:	14b. Authorized Signature:	14c. Approval/Certificate No.:	14d. Name (Typed or Printed):	14e. Date (dd/mm/yyyy):
			DB2R762K	DARLY WAYNE DOTSON	26/JUL/2022
User/Installer Responsibilities					
It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1. Statements in Blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.					

1. Approving Civil Aviation Authority/Country: FAA/United States		2. <div style="text-align: center; border: 1px solid black; padding: 5px; margin: 5px 0;"> AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG </div> 3. Form Tracking Number: WDC # 128506 4. Organization Name and Address: DIVCO, INC., 2806 N. SHERIDAN ROAD, TULSA, OK 74115 (DB2R762K) 5. Work Order/Contract/Invoice Number: INVOICE #135146			
6. Item: 1	7. Description: CONT O-200 CRANKCASE	8. Part Number: CASTING # 6795	9. Quantity: 1	10. Serial Number: MATCH # 5A188	11. Status/Work: REPAIRED
12. Remarks: CRANKCASE REPAIRED PER DIVCO APPROVED PROCESS SPECS 77-002 REV 6, 18 JULY 2017 DATE COMPLETED: 30/JUL/2021 WDC #129506 WORK SPECIFIED IN BLOCKS 11/12 WAS CARRIED OUT IN ACCORDANCE WITH EASA PART 145 AND WITH RESPECT TO THAT WORK THE COMPONENT IS CONSIDERED READY FOR RELEASE TO SERVICE UNDER EASA PART 145 APPROVAL NUMBER EASA 145-5286					
13a. Certifies the items identified above were manufactured in conformity to: <input type="checkbox"/> Approved design data and are in a condition for safe operation. <input type="checkbox"/> Non-approved design data specified in Block 12.		14a. <input checked="" type="checkbox"/> 14 CFR 43.9 Return to Service Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.			
13b. Authorized Signature:	13c. Approval/Authorization No.:	14b. Authorized Signature: 	14d. Name (Typed or Printed): DARYLE WAYNE DOTSON	14e. Date (dd/mm/yyyy): 26/JUL/2022	14c. Approval/Certificate No.: DB2R762K
User/Installer Responsibilities					
<p>It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1. It is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1. Statements in Blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.</p>					



INVOICE

INVOICE NO.	212369
DATE	11/04/21
ACCOUNT #	

BILL TO:


Yuliana Vannik
 1243 Manet Dr
 Sunnyvale CA 94087
 Tel: 318-502-0507

SHIP TO:

Charles Yates
 1717 Crescent Rd
 Waterproof, LA 71375

P.O. NUMBER	DATE SHIPPED	SHIP VIA	COL	PP	FOB POINT	TERMS
0-200-1103	11/04/21	Fed Ex	X		Dallas, TX	CC
PART NUMBER	DESCRIPTION	ORDER QTY	SHIP QTY	UNIT PRICE	AMOUNT	
SA10200-A20P	Cylinders New 1	4	4			
	SN: 20000005774 1					
	SN: 20000005775 1					
	SN: 20000005776 1					
	SN: 20000005780 1					
Xfgt	Handling Fee 2	1	1			
Xfgt	Outbound Freight 3	1	1			
	Total Due					

Thank You

1. Approving Civil Aviation Authority/Country: FAA/UNITED STATES		2. AUTHORIZED RELEASE CERTIFICATE FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG		3. Form Tracking Number: PS-00018319	
4. Organization Name and Address: Superior Air Parts 621 S. Royal Lane, Suite 100, Coppell, TX 75019, USA				5. Work Order/Contract/Invoice Number: SO-00006475	
6. Item		7. Description	8. Part number	9. Quantity	10. Serial number
001	CYL ASSY. WITH VALVES & PISTON		SA10200-A20P	6	20000005774 — 20000005775 — 20000005776 — 20000005778 — 20000005779 — 20000005780 —
11. Status/Work NEW					
12. Remarks AIRWORTHINESS APPROVAL					
13a. Certifies the items identified above were manufactured in conformity to: <input checked="" type="checkbox"/> Approved design data and are in a condition for safe operation. <input type="checkbox"/> Non-approved design data specified in Block 12.			14a. <input type="checkbox"/> 14 CFR 43.9 Return to Service <input type="checkbox"/> Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in block 11 and described in Block 12 was accomplished in accordance with Title 12, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.		
13b. Authorized Signature: 		13c. Approval/Authorization No: PQ0060SW		14b. Authorized Signature:	
13d. Name(Typed or Printed): Darryl Harlos		13e. Date(dd/mm/yyyy): 17 Aug 2021		14c. Approval Certificate No:	
				14d. Name(Typed or Printed):	
				14e. Date(dd/mm/yyyy):	
User/Installer Responsibilities It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1. Statements in Blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.					

NSN: 0052-00-012-9005

ORIGINAL

F.A.A. Repair Station No. DD2R764K

WORK ORDER NO.

272194



QUAN.	PART NO. & DESCRIPTION	S/N
8	HYDRAULIC SOCKETS	*
6	530851 LIFTERS	ASR-6-27-22
1	HOUSING UNIT	NAD
1	ALUM PLUG	NAD*
1	0200 CRANKSHAFT	S272194-1
1	626608 CAMSHAFT	S272194-2
4	0200 RODS	S272194-3
2	530851 LIFTERS	S272194-4
8	633697 HYD. UNITS	S272194-5
1	CONT'L INT STEEL	S272194-6

NAME CHARLES YATES		[017268]	
ADDRESS 1717 CRESCENT RD		DATE IN 04/11/2022	DATE SHIPPED 07/28/2022
CITY WATERPROOF	STATE LA 71375		
PHONE (318) 502-0507	P.O. VERBAL	SHIP VIA UPS GROUND	TERMS: AMER EXPRESS

ITEM NO.	QUAN.	WORK DESCRIPTION	UNIT PRICE	TOTAL
1	8EA	HYDRAULIC SOCKETS		
		*REFURBISH PUSHROD SOCKET	6.00	48.00
2	6EA	CONTINENTAL LIFTERS		
		*INSP. VISUALLY, DIMENSIONALLY & BY MPI		
		WEAR FACES REGROUND TO FAA APPV. DATA	40.00	240.00
3	1EA	CONT. UNIT		
		*NO AIRWORTHINESS WAS DETERMINED	n/c	n/c
4	1EA	ALUM PLUG		
		*NO AIRWORTHINESS WAS DETERMINED	n/c	n/c
5	1EA	CONTINENTAL CRANKSHAFT		
		*MAG. INSP. RODS M020 FROM PREV GRIND		
		GROUND MAINS M020, RENIT., CAD. PLATE.	683.00	683.00
		*ALL WORK PERFORMED IN ACC. WITH STC		
		NO. SE09002SC	n/c	n/c

PART NO. & DESCRIPTION	PRICE	TOTAL
1 630651-DOWEL	28.51	28.51
1 SA24770-PLUG	3.02	3.02
4 SA530192-BUSHING	29.17	116.68
Less 10%		(14.82)

Page: 1

CONTINUED....

Remit to: Aircraft Specialties Services, Inc.
Tulsa International Airport
2860 North Sheridan Road
P.O. Box 582553
Tulsa, Oklahoma 74158
(918) 836-6872 • 1-800-826-9252 • FAX (918) 836-4419

TOTAL LABOR
TOTAL PARTS
FREIGHT
TAX

TOTAL

ORIGINAL

PART NO. & DESCRIPTION S/N

PART NO. & DESCRIPTION PRICE TOTAL

Remit to:	
Aircraft Specialties Services, Inc.	
Tulsa International Airport	
2860 North Sheridan Road	
P.O. Box 582553	
Tulsa, Oklahoma 74158	
(918) 836-6872 • 1-800-826-9252 • FAX (918) 836-4419	
TOTAL LABOR	TOTAL PARTS
FREIGHT	TAX
TOTAL	

Page: 2

CONTINUED....

6	1 EA	CONTINENTAL CAMSHAFT	*REPAIR OIL SEAL AS NECESSARY.	n/c	314.00
			*REPAIR FLANGE AS NECESSARY.	n/c	314.00
			*REPAIRED PILOT IN ACC. W/ A/C SPEC.		
			PROCEDURE 99-008	590.00	590.00
			*INSTALLED DOWEL	30.00	30.00
6	1 EA	CONTINENTAL CAMSHAFT			
7	4 EA	CONTINENTAL RODS	*4 CYL CAMSHAFT-RECOND PER A/C SPEC FAA	216.00	216.00
			APP. PROC & INSP TO MFG O/H CRITERIA		
			*RODS- MAGNAFLUXED, REBUSHED AND INSP.		
8	2 EA	CONTINENTAL LIFTERS	IN ACC. W/O/H MANUAL &/OR A.S.S. APPL	108.00	432.00
			*LIFTERS - REJECTED	n/c	
9	8 EA	CONT'L HYDRAULIC UNITS	*CLEANED, INSPECTED, O/H I/A/W AIRCRAFT	n/c	
			SPECIALTIES PROCEDURE 99-001	35.00	280.00

ITEM NO. QUAN.

WORK DESCRIPTION

UNIT PRICE TOTAL

NAME		CHARLES YATES		[0177268]	
ADDRESS		1717 CRESCENT RD		DATE IN	04/11/2022
CITY		WATERPROOF		STATE	LA
PHONE		(318) 502-0507		P.O.	VERBAL
SHIP VIA		UPS		GROUND	AMER EXPRESS
TERMS:					

AIRCRAFT SPECIALTIES SERVICES

F.A.A. Repair Station No. DD2R764K

WORK ORDER NO.

272194

ORIGINAL

PART NO. & DESCRIPTION

S/N

PART NO. & DESCRIPTION PRICE TOTAL

F.A.A. Repair Station No. DD2R764K

WORK ORDER NO.

272194

AIRCRAFT
SPECIALTIES
SERVICES

NAME

CHARLES YATES

[017268]

ADDRESS

1717 CRESCENT RD

DATE IN 04/11/2022

DATE SHIPPED 07/28/2022

CITY

WATERPROOF

STATE

LA 71375

PHONE

(318) 502-0507

P.O.

VERBAL

SHIP VIA

UPS GROUND

TERMS:

AMER EXPRESS

ITEM
NO.

QUAN.

WORK DESCRIPTION

UNIT PRICE

TOTAL

10 1LT 4 CYL. INTERNAL STEEL

*4 CYL. INT. STEEL - MAGNAFLUXED IN

ACC. WITH OVERHAUL MANUAL

65.00

65.00

THANK YOU FOR YOUR BUSINESS !

Remit to: Aircraft Specialties Services, Inc.
Tulsa International Airport
2860 North Sheridan Road
P.O. Box 582553
Tulsa, Oklahoma 74158
(918) 836-6872 • 1-800-826-9252 • FAX (918) 836-4419

TOTAL LABOR 2898.00
TOTAL PARTS 133.39
FREIGHT 157.10
TAX

TOTAL

3188.49

**AIRCRAFT
SPECIALTIES
SERVICES**

INVOICE NO: 215584

INVOICE DATE: 07/28/2022

ORIGINAL

B
I [021912]
L CHARLES YATES
L 1717 CRESCENT ROAD
T WATERPROOF, LA 71375
O

S
H
I CHARLES YATES
P 1717 CRESCENT ROAD
T WATERPROOF, LA 71375
O

(318) 502-0507

Sales Person: DW

S.O. # 207944

SHIP DATE: 07/28/2022

SHIP VIA: W/SHOP

P.O. # VERBAL

TERMS: VISA

ORDER QUAN.	SHIP QUAN.	B/O QUAN.	PART NUMBER & DESCRIPTION	LIST	UNIT PRICE	TOTAL
8	8	652421	/NUT	11.53	7.59	60.72
16	16	652422	/NUT	8.93	6.24	99.84
8	8	MS24665-227	/COTTER PIN	0.26	0.15	1.20
4	4	SA22532	/SCREW	9.13	5.20	20.80
4	4	SA22534	/SCREW	12.57	7.16	28.64
8	8	SA24804	/NUT	9.48	5.40	43.20
1	1	SA24890-A5	/GASKET SET MAJOR OVER	251.17	142.99	142.99
1	1	SA530019	/SEAL	57.19	32.56	32.56
2	2	SA530058 M20	/BEARING	171.00	118.50	237.00
8	8	SA530213	/ROD BOLT	35.19	20.03	160.24
2	2	SA530851	/LIFTER BODY	291.58	170.33	340.66

Remit to:

Aircraft Specialties Services, Inc.
Tulsa International Airport
2860 North Sheridan Road
P.O. Box 582553
Tulsa, Oklahoma 74158

TOTAL PARTS:

FREIGHT &
HANDLING:

TAX:

(918) 836-6872 • 1-800-826-9252 • FAX (918) 836-4419

TOTAL:

CONTINUED...

Products sold by **Aircraft Specialties Services, Inc.** are subject to the terms of any and all original manufacturer's warranty (warranties) that may apply. **Aircraft Specialties Services, Inc.** provides no warranties regarding such products, including merchantability, fitness for a particular purpose or eligibility. Please consult the manufacturer for support questions.

A

F.A.A. Repair Station No. DD2R764K

AIRCRAFT SPECIALTIES SERVICES

INVOICE NO: 215584
INVOICE DATE: 07/28/2022

ORIGINAL

B
I [021912]
L CHARLES YATES
L 1717 CRESCENT ROAD
T WATERPROOF, LA 71375
O
(318) 502-0507

S
H
I CHARLES YATES
P 1717 CRESCENT ROAD
T WATERPROOF, LA 71375
O
Sales Person: DW

S.O. # 207944

SHIP DATE: 07/28/2022

SHIP VIA: W/SHOP

P.O. # VERBAL

TERMS: VISA

ORDER QUAN.	SHIP QUAN.	B/O QUAN.	PART NUMBER & DESCRIPTION	LIST	UNIT PRICE	TOTAL
4	4		SA633141 /WASHER	51.77	29.47	117.88
2	2		SA633398 M20 /BEARING	47.56	28.50	57.00
1	1		SA637083 /SPRING - OIL PRESSUR	15.68	8.92	8.92
8	8		SA639640 M20 /BEARING	43.13	28.50	228.00
2	2		SA643233 M20 /BEARING	46.05	28.50	57.00

THANK YOU FOR YOUR BUSINESS !
RETURNS MAY BE SUBJECT TO RESTOCKING FEE
PARTS ELIGIBILITY TO BE VERIFIED BY INSTALLER

Remit to:

Aircraft Specialties Services, Inc.
Tulsa International Airport
2860 North Sheridan Road
P.O. Box 582553
Tulsa, Oklahoma 74158

TOTAL PARTS: 1636.65

FREIGHT &
HANDLING:

TAX:

TOTAL: 1636.65

(918) 836-6872 • 1-800-826-9252 • FAX (918) 836-4419

Products sold by Aircraft Specialties Services, Inc. are subject to the terms of any and all original manufacturer's warranty (warranties) that may apply. Aircraft Specialties Services, Inc. provides no warranties regarding such products, including merchantability, fitness for a particular purpose or eligibility. Please consult the manufacturer for support questions.

AIRCRAFT SPECIALTIES SHOP
2860 NORTH SHERIDAN ROAD
TULSA, OK 74115
918-836-6872

SHOP

Date: 07/28/2022 04:58:27 PM

CREDIT CARD SALE

AMERICAN EXPRESS

CARD NUMBER: *****2000 K

TOTAL AMOUNT: \$4,825.14

APPROVAL CD: 147464

RECORD #: 000

CLERK ID: asstrowland

CUST CODE: 017268

INVOICE #: 272194-207944

X

CHARLES YATES

I AGREE TO PAY THE ABOVE TOTAL AMOUNT
ACCORDING TO THE CARD ISSUER AGREEMENT
(MERCHANT AGREEMENT IF CREDIT VOUCHER)

Thank you for your business!

AIRCRAFT SPRUCE & SPECIALTY CO.

P.O. BOX 4000 - 225 AIRPORT CIRCLE, CORONA, CA 92878
 CUSTOMER SERVICE (800) 861-3192 FAX(951) 372-0555
 TOLL FREE ORDER LINE (877) 477-7823

809431
 S EVERSULL CORP
 01 TRACEMONT RD
 LD BOYCE, LA 71409
 TO

S KEN EVERSULL
 H1 TRACEMONT RD
 I BOYCE, LA 71409
 P
 T
 O

NOTE: ANY SHORTAGES MUST BE REPORTED WITHIN 10 DAYS

BACKORDERED PRODUCTS WILL SHIP AS SOON AS AVAILABLE

ORDER NO.		INVOICE NO.	CUST P.O. NO.	SHIP VIA	TERMS	DATE SHIPPED		
4313102		7025376		UPS COMM GROUND	CREDIT CARD	03/30/23		
QUANTITY SHIPPED	BACK ORDERED	DESCRIPTION		PRICE	DISCOUNT	NET PRICE	TAX X	EXTENSION
1		10-24625 MITCHELL TACHOMETER						
		D1-112-5025						
		SERIAL NUMBERS: 32406						
	12	54779-25 04-00366 U TYPE						
		TINNERMAN 239192001						
12		54780-10 04-00367 U TYPE						
		TINNERMAN A1348-8Z-1D						
12		08915-25 A1787-10Z-1D "U" TYPE						
		NAS395 (A1787-10Z-1)						
	1	15510-0320 10-16600 TACH CABLE						
		32" LEFT LAY						
SUBTOTAL		TAX	MISC.CHARGE	FREIGHT	PAID WITH ORDER		BALANCE DUE	

BESTGUNS@EARTHLINK.NET
 318-793-8728

CERTIFICATE OF CONFORMANCE

The products on this invoice have been obtained through authorized manufacturers or distributors and to the best of our knowledge fully meet all applicable specifications. There may be products on this invoice which are not approved for use on FAA type certificated aircraft. Purchaser is responsible for determining suitability of any part purchased from Aircraft Spruce for installation on their certificated or experimental aircraft.

Certified By: Jim Irwin, President

WAIVER OF LIABILITY & INDEMNIFICATION AGREEMENT

Inasmuch as Aircraft Spruce has no opportunity to supervise the manufacture, installation, or maintenance of the parts supplied by it, nor any opportunity to participate in the design or manufacture of the various certified and homebuilt aircraft in which its parts are utilized, the purchaser by placing this order and accepting merchandise from Aircraft Spruce agrees that all material purchased will be used solely at the purchaser's risk and that the purchaser will indemnify and hold Aircraft Spruce, its owners and employees, free and harmless from loss, liability, or damage resulting from claims brought by reasons of any alleged failure or defect of any part or parts supplied by Aircraft Spruce.

NOTICE

Weight and balance or operating limitation changes shall be entered in the appropriate aircraft record. An alteration must be compatible with all previous alterations to assure continued conformity with the applicable airworthiness requirements.

8. Description of Work Accomplished


(If more space is required, attach additional sheets. Identify with aircraft nationality and registration mark and date work completed.)

Nationality and Registration Mark

Date

Crankshaft S/N S2721941 was ground .020" undersize per S.T.C. SE09002SC by Aircraft Specialties Services, Inc. CRS# DD2R764K

Work order 272194



DATE 07/28/07

Authorized signature

Two copies of this form and an 8130-3 are furnished to comply with FAR 43.9. When the crankshaft is installed in an engine complete blocks 4, 5, 6 and 7 on this form. When the engine is installed on an aircraft, complete blocks 1 and 2 and forward a copy to the local FAA FSDO. Maintain the original with the engine record.

Crankshaft installed in engine model _____

S/N _____ Date _____ per STC number SE090002SC

***** END *****

☐ Additional Sheets Are Attached



US Department
of Transportation
Federal Aviation
Administration

MAJOR REPAIR AND ALTERATION
(Airframe, Powerplant, Propeller, or Appliance)

Form Approved
OMB No. 2120-0020
11/30/2007

Electronic Tracking Number

For FAA Use Only

INSTRUCTIONS: Print or type all entries. See Title 14 CFR §43.9, Part 43 Appendix B, and AC 43.9-1 (or subsequent revision thereof) for instructions and disposition of this form. This report is required by law (49 U.S.C. §44701). Failure to report can result in a civil penalty for each such violation. (49 U.S.C. §46301(a))

1. Aircraft	Nationality and Registration Mark	Serial No.	
	Make	Model	Series
2. Owner	Name (As shown on registration certificate)	Address (As shown on registration certificate)	
		Address _____	
		City _____	State _____
		Zip _____	Country _____

3. For FAA Use Only

4. Type		5. Unit Identification			
Repair	Alteration	Unit	Make	Model	Serial No.
<input type="checkbox"/>	<input type="checkbox"/>	AIRFRAME	_____	(As described in Item 1 above)	_____
<input type="checkbox"/>	<input type="checkbox"/>	POWERPLANT	_____	_____	_____
<input type="checkbox"/>	<input type="checkbox"/>	PROPELLER	_____	_____	_____
<input type="checkbox"/>	<input type="checkbox"/>	APPLIANCE	Type _____	_____	_____
			Manufacturer _____		

6. Conformity Statement

A. Agency's Name and Address		B. Kind of Agency	
Name _____	_____	<input type="checkbox"/> U. S. Certificated Mechanic	<input type="checkbox"/> Manufacturer
Address _____	_____	<input type="checkbox"/> Foreign Certificated Mechanic	C. Certificate No. _____
City _____	State _____	<input type="checkbox"/> Certificated Repair Station	
Zip _____	Country _____	<input type="checkbox"/> Certificated Maintenance Organization	

D. I certify that the repair and/or alteration made to the unit(s) identified in item 5 above and described on the reverse or attachments hereto have been made in accordance with the requirements of Part 43 of the U.S. Federal Aviation Regulations and that the information furnished herein is true and correct to the best of my knowledge.

Extended range fuel per 14 CFR Part 43 App. B <input type="checkbox"/>	Signature/Date of Authorized Individual _____
--	--

7. Approval for Return to Service

Pursuant to the authority given persons specified below, the unit identified in item 5 was inspected in the manner prescribed by the Administrator of the Federal Aviation Administration and is ☐ Approved ☐ Rejected

BY	FAA Flt. Standards Inspector	Manufacturer	Maintenance Organization	Persons Approved by Canadian Department of Transport
	FAA Designee	Repair Station	Inspection Authorization	Other (Specify) _____

Certificate or Designation No. _____	Signature/Date of Authorized Individual _____
---	--

United States Of America
Department of Transportation - Federal Aviation Administration

Supplemental Type Certificate

Number SE09002SC

This Certificate is issued to Aircraft Specialties Services, Inc.
P.O. Box 582553
Tulsa, OK 74158

*certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part * of the * Regulations.*

Original Product Type Certificate Number : [see FAA Approved Model List (AML)]

Make : for list of approved models and

Model : applicable airworthiness regulations]

Description of Type Design Change: Regrind Teledyne Continental crankshafts, to .020" undersize on crankpin and main journals according to Aircraft Specialties Services, Inc. Drawing No. 1010, Rev. C, dated 12/01/2004, or later FAA approved revision.

Limitations and Conditions: Compatibility of this design change with previously approved modifications must be determined by the installer. If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

(See continuation sheet 3 of 3)

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application : January 22, 1993

Date reissued :

Date of issuance : April 04, 1995

Date amended : January 17, 1997; March 10, 2006,
Rev. 2



By direction of the Administrator

(Signature)
S. Frances Cox
Manager, Special Certification Office
Southwest Region

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.

Divco, Inc.

2806 N. Sheridan Rd.
Tulsa, OK 74115

Invoice

Account #	Date	Invoice #
14357	7/26/2022	135146

Bill To
YATES, C 1717 CRESENT RD WATERPROOF, LA 71375

Ship To
YATES, C 1717 CRESENT RD WATERPROOF, LA 71375

P.O. Number		Terms	Phone #	Via	Price Level
		VISA/MASTERCARD			
Quantity	Item Code	Description	Price Each	Amount	
1	K-EXCHANGE	CRANKCASE EXCHANGE- CONT O-200	1,095.00	1,095.00	
	NOTE	WDC 128506, M/N 5A188, C/N 6795 SEE FAA FORM 8130-3 FOR REPAIR DETAILS			
1	FREIGHT	SHIPPING & HANDLING CHARGES (F.O.B. DIVCO)	254.19	254.19	
			Total	\$1,349.19	

FINANCE CHARGES WILL APPLY ON
INVOICES MORE THAN 30 DAYS

Phone #	Fax #
918 836-9101	918 835-4801

Web Site
www.Divcoinc.com

Divco, Inc.

2806 N. Sheridan Rd.
Tulsa, OK 74115

Invoice

Account #	Date	Invoice #
14357	7/26/2022	135147

Bill To
YATES, C 1717 CRESENT RD WATERPROOF, LA 71375

Ship To
YATES, C 1717 CRESENT RD WATERPROOF, LA 71375

P.O. Number		Terms	Phone #	Via	Price Level
		VISA/MASTERCARD			
Quantity	Item Code	Description	Price Each	Amount	
1	MACTD NOTE	ACCESSORY CASE - MISC. MACHINE WORK- CONT O-200 DIV 13800, C/N 6726 SEE FAA FORM 8130-3 FOR REPAIR DETAILS FREIGHT ON DIVCO	225.00	225.00	
			Total	\$225.00	

FINANCE CHARGES WILL APPLY ON
INVOICES MORE THAN 30 DAYS

Phone #	Fax #
918 836-9101	918 835-4801

Web Site
www.Divcoinc.com



520 W. Kearney Blvd.
Fresno, CA 93706-2598

Phone # (559) 237-4863
Fax # (559) 237-2703
E-mail contactus@fresnoairpartsco.com

Invoice

Date	Invoice #
7/27/2022	29251

Bill To	Ship To
STEPUNIN, YURY 1243 MANETY DR. SUNNYVALE, CA 94087	STEPUNIN, YURY 1243 MANETY DR. SUNNYVALE, CA 94087

Customer Phone	P.O. No.	Terms	Ship Date	Ship Via	Resale #
408-857-9485	ONLINE#17488	ONLINE CC	7/27/2022	US Mail	


Qty	Item	Description	Price	Amount
4	21477	Seal, Cylinder Base	1.50	6.00
1	352030	Retainer, Generator Drive	8.75	8.75
1	Lord Mount Assy.	Lord Mount Assy. (J3608-1)	157.50	157.50
1	A-65 RC	Rear Case Nut Set	9.50	9.50
8	21274	Connector, Push Rod Housing (Old Style)	0.75	6.00
1	538999	Bolt, Starter	11.50	11.50
1	C-150	Engine Mount Bolt Set	22.50	22.50
	PO SHIPPING	USPS Package 1 Tracking #: 9470111202527870962650	29.46	29.46

		Subtotal	\$251.21
ALL CLAIMS MUST BE MADE WITHIN 10 DAYS AFTER RECEIPT OF GOODS. A 15% HANDLING CHARGE WILL BE MADE UNLESS RETURNED ON ACCOUNT OF BEING DEFECTIVE OR ERROR ON OUR PART.		Sales Tax (7.25%)	\$16.08
		Payments/Credits	-\$267.29
		Total	\$267.29
		Balance Due	\$0.00

The 500^{hr} Inspection & Certification Service

Utilizing over **25 years** of Slick and CMI/Bendix magneto overhaul experience, Kelly Aerospace Energy Systems has developed a detailed **35 point checklist** that complies with all applicable AD's, service bulletins, and Slick and CMI Master Service Manuals to ensure a complete inspection of your magneto.

- Over 30 new parts included in every inspection
- 72 hour turn time



\$675



D2000/D3000

\$350



20/200/1200 & 4300/6300
Non-Impulse coupling

\$375



200/1200 & 4300/6300
Impulse coupling

Call us Today at 334.286.8551
KellyAerospace.com

Complete / Return this Flyer
for **Free**
UPS Ground Return Freight.