

NAME/
SIGNATURELICENCE:
AME or
AMO/ACA

12-19-22 TACH 3644.8

Installed repaired/overhauled turbo LW-46264
S/N H-WHK00179. Runup adjusted.

Eldon Holtz APP 3617647

12-19-22 TACH 3644.8

Changed oil filter and oil. C/w AD 80-04-03R2 by
using aeroshell 15W50 oil

Eldon Holtz APP 3617647

2-20-23 TACH 3655.7 Replaced mag with overhauled mag.
P/N 10-682555-13 S/N H 149810 CR. App checked good.

Eldon Holtz APP 3617647

5-15-23 TACH 3656.0 compression upper 60 and lower 70's. Inspected
exhaust & intake systems. No oil change due at this
time

Eldon Holtz APP 3617647

Date 5-15-23 Aircraft Total Time 3656.0I Certify That This POWER PLANT Has

Been Inspected In Accordance With An

ANNUAL

Inspection And Been

Determined To Be In Airworthy Condition.

Eldon Holtz

Signature

APP 3617647

Certificate No.

6-18-23 TACH 3658.0 C/w AD 8023-09-09 Exhaust pipe V Band
by visual no defects found.

Eldon Holtz APP 3617647