

NTSB Identification: LAX76DVA20 14 CFR Part 91 General Aviation

Aircraft: BOEING B75, registration: N68488

LOCATION AIRCRAFT DATA FILE DATE INJURIES FLIGHT PILOT DA F S M/N PURPOSE

3-

3007 75/10/12 NR.KETTLEMAN CITY, CA BOEING B75

TIME - 1330

N68488

CR- 0 0 1 COMMERCIAL

COMMERCIAL, AGE 4 PX- 0 0 0 ASSOC CROP CTL ACTIVITY TOTAL HOURS, 12

DAMAGE-

SUBSTANTIAL OT- 0 0 0

TYPE, NOT INSTRUMENT

RATED.

NAME OF AIRPORT - SALYER FARMS

DEPARTURE POINT

INTENDED DESTINATION

KETTLEMAN CITY, CA LOCAL

TYPE OF ACCIDENT

GROUND-WATER LOOP-SWERVE COLLIDED WITH: OBJECT

PROBABLE CAUSE(S)

PHASE OF OPERATION LANDING: ROLL LANDING: GO-AROUND

PILOT IN COMMAND - IMPROPER OPERATION OF BRAKES AND/OR FLIGHT CONTROLS

FACTOR(S)

AIRPORTS/AIRWAYS/FACILITIES - AIRPORT CONDITIONS: OTHER

MISCELLANEOUS ACTS, CONDITIONS - AIRCRAFT CAME TO REST IN WATER

SPECIAL DATA

TOTAL HOURS IN CROP CONTROL - 3800

KIND OF CROP - COTTON

PILOT' S SEAT BELT -UNKNOWN/NOT REPORTED

CRASH HELMET - AVAILABLE USED CRASH BAR - NOT INSTALLED

TERRAIN-TYPE -ROLLING

KIND OF OPERATION - DEFOLIATION (LIQUID)

TYPE OF CHEMICAL USED - LIQUID CHEMICAL-TOXIC

GOGGLES - USED

COCKPIT CRASHPAD - INSTALLED

TANK/HOPPER-LOCATION - FORWARD OF PILOT ELEVATION-AREA BEING TREATED-FEET - 300

REMARKS- SWERVED ON LDG, ATTMPTD GO ARND.L WG STRUT HIT SPRAYER, THEN HIT PWR POLE & CANAL.NO BRAKE MALF.

Full narrative is not available