

<b>AD NOTES COMPLIANCE RECORD</b>
-----------------------------------

AD#	Applicable S.B. # & Subject	Date & Hours @ Comp.	Method of Compliance	One Time	Recurring	Next Comp. @ Hrs/Date	Authorized Signature & Number
84-26-02	Paper induction air filters	2/19/2016 @ 936.5 hobbs	P/C/W		X	1436.5 hobbs	CarverAero LLC dba Revv Aviation CGFR811C
2000-01-16	Detect and correct cracks and corrosion in the exhaust system	12/9/2023 @ 1126.6 hobbs	C/W para (b)(c)(e)(f) Para(b) due again at 1176.6 hobbs Para(c) due again by 10/2024 Para(d) due at 1605.7 hobbs Para(e) due again by 10/2024 Para(f) due again by 1626.6 hobbs		X	1176.6 hobbs	CarverAero LLC dba Revv Aviation CGFR811C
2007-05-15	To prevent failure of the starter adapter assembly and or crankshaft gear	2798.6 T.T	P/C/W by inspection I/A/W part 2.		X	2898.6 T.T	CarverAero LLC dba Revv Aviation CGFR811C
2016-17-08	Elevator Trim Tab Assembly Parts Attachment Hardware Security	12/9/2023 @ 1126.6 hobbs	C/W by inspection		X	12/2024 or 1236.6 hobbs	CarverAero LLC dba Revv Aviation CGFR811C
2017-06-03	Combustion Heater Deterioration and Fire Hazard	12/9/2023 @ 1126.6 hobbs	C/W by pressure decay test		X	12/2025 or 1376.6 hobbs	CarverAero LLC dba Revv Aviation CGFR811C
2018-03-03 R1	Lower Forward Carry Through Spar Cap Integrity		Due at 12,000hr T.T		X	12,000hr T.T	CarverAero LLC dba Revv Aviation CGFR811C

*B. Coletta 12-6-23*



### AD NOTES COMPLIANCE RECORD

AD#	Applicable S.B. # & Subject	Date & Hours @ Comp.	Method of Compliance	One Time	Recurring	Next Comp. @ Hrs/Date	Authorized Signature & Number
72-02-01	Propeller attachment nuts	01/18/197 2	N/A by S/N	X			CarverAero LLC dba Revv Aviation CGFR811C
72-03-04	Crankcase vent line ice	02/04/197 2	N/A by S/N	X			CarverAero LLC dba Revv Aviation CGFR811C
72-03-07	Landing gear failure	02/09/197 2	N/A by S/N	X			CarverAero LLC dba Revv Aviation CGFR811C
72-11-05	Auxiliary fuel cell leaks	06/02/197 2	N/A by S/N	X			CarverAero LLC dba Revv Aviation CGFR811C
72-14-08 R1	Flexible hose assemblies	09/04/198 1	New lines installed meeting TSO C53D	X			CarverAero LLC dba Revv Aviation CGFR811C
73-07-04	Bendix Magnetos	10/11/197 3	Superseded by 94-01-03 R2	X			CarverAero LLC dba Revv Aviation CGFR811C
73-13-08	Turbochargers	06/27/197 3	N/A by S/N	X			CarverAero LLC dba Revv Aviation CGFR811C
73-22-01 R1	Fuel in wing leading edge	05/29/197 8	N/A by S/N	X			CarverAero LLC dba Revv Aviation CGFR811C
74-20-01	Main landing gear trunnion	09/25/197 4	N/A by S/N	X			CarverAero LLC dba Revv Aviation CGFR811C
74-26-09	Bendix magnetos	12/24/197 4	N/A by overhaul date.	X			CarverAero LLC dba Revv Aviation CGFR811C
75-09-13	Turbocharger oil inlet adapters	04/24/197 5	C/W at engine overhaul.	X			CarverAero LLC dba Revv Aviation CGFR811C
75-23-08 R5	Engine exhaust system	11/04/198 6	Superseded by 2000-01-16	X			CarverAero LLC dba Revv Aviation CGFR811C
76-04-03	ARC PA-500A actuators	01/12/197 9	Modified per SL AV75-10	X			CarverAero LLC dba Revv Aviation CGFR811C
76-08-02 R2	Wing tip nose cap	06/18/197 6	C/W by visual inspection	X			CarverAero LLC dba Revv Aviation CGFR811C
76-13-07	Fork bolts	07/07/197 6	Replacement of bolts 5/8 due 5000hrs ATT	X			CarverAero LLC dba Revv Aviation CGFR811C
77-09-02	Windshield inspection	05/09/097 7	C/W by replacement of the windshield	X			CarverAero LLC dba Revv Aviation CGFR811C
77-13-22 R1	Crankcase cracks	07/22/197 7	C/W at engine overhaul.	X			CarverAero LLC dba Revv Aviation CGFR811C
78-09-07 R3	Bendix magnetos	01/17/198 3	Superseded by 96-12-07	X			CarverAero LLC dba Revv Aviation CGFR811C
78-13-05	Improperly installed seats	07/05/197 8	C/W by visual inspection	X			CarverAero LLC dba Revv Aviation CGFR811C
79-05-09	Oil pressure relief valve	03/12/197 9	C/W at engine overhaul.	X			CarverAero LLC dba Revv Aviation CGFR811C
80-09-11	Starter torsional separation damper	04/03/198 0	Never sent to Western Skyways INC	X			CarverAero LLC dba Revv Aviation CGFR811C
81-09-09	Stewart Warner heaters	05/08/198 1	Superceded by AD 2017-06-03	X			CarverAero LLC dba Revv Aviation CGFR811C
81-24-06	Fuel pump	11/23/198 1	C/W at engine overhaul.	X			CarverAero LLC dba Revv Aviation CGFR811C
82-13-01	Bendix magnetos	06/28/198 2	N/A by overhaul date.	X			CarverAero LLC dba Revv Aviation CGFR811C



AD#	Applicable S.B. # & Subject	Date & Hours @ Comp.	Method of Compliance	One Time	Recurring	Next Comp. @ Hrs/Date	Authorized Signature & Number
84-26-02	Paper induction air filters	2/19/2016 @ 936.5 hobbs	P/C/W		X	1436.5 hobbs	CarverAero LLC dba Revv Aviation CGFR811C
86-13-04 R3	Cylinder assemblies	02/24/1988	C/W at engine overhaul.		X		CarverAero LLC dba Revv Aviation CGFR811C
87-21-02 R1	Fuel filler openings	06/16/1989	P/C/W by SL me 84-31		X		CarverAero LLC dba Revv Aviation CGFR811C
88-03-06	Oil filter	02/05/1988	N/A type not installed.		X		CarverAero LLC dba Revv Aviation CGFR811C
90-02-13	Main landing gear	02/05/1990	C/W by new style bearing installed		X		CarverAero LLC dba Revv Aviation CGFR811C
91-19-03	Champion oil filter	09/29/1991	N/A type not installed.		X		CarverAero LLC dba Revv Aviation CGFR811C
92-16-18	Seat structural assembly	09/10/1992	N/A type not installed.		X		CarverAero LLC dba Revv Aviation CGFR811C
93-10-02	Cylinder valve retainer	08/12/1993	C/W at engine overhaul.		X		CarverAero LLC dba Revv Aviation CGFR811C
94-01-03 R2	Teledyne/Bendix magnetos	06/28/1995	N/A by unit serial no#.		X		CarverAero LLC dba Revv Aviation CGFR811C
94-06-09	Teledyne/Bendix magnetos	03/09/1994	N/A by overhaul date.		X		CarverAero LLC dba Revv Aviation CGFR811C
94-14-12	Low octane detonation	N/A	Superseded by 95-21-15		X		CarverAero LLC dba Revv Aviation CGFR811C
95-21-15	Engine teardown and analytical inspect.	11/28/1995	N/A by N-Number		X		CarverAero LLC dba Revv Aviation CGFR811C
96-12-07	Prevent magneto failure and subsequent engine failure	07/18/1996	Superseded by 2005-12-06		X		CarverAero LLC dba Revv Aviation CGFR811C
97-01-13	Fuel, oil, or hydraulic hose	02/03/1997	P/C/W new hose installed at overhaul		X		CarverAero LLC dba Revv Aviation CGFR811C
98-04-28	Severe Icing Conditions	03/13/1998	P/C/W by revising POH with icing info		X		CarverAero LLC dba Revv Aviation CGFR811C
98-17-11	Crankshafts	10/19/1998	C/W at engine overhaul.		X		CarverAero LLC dba Revv Aviation CGFR811C
99-19-01	Crankshaft failure	09/30/1999	C/W at engine overhaul.		X		CarverAero LLC dba Revv Aviation CGFR811C
2000-01-16	Detect and correct cracks and corrosion in the exhaust system	12/9/2023 @ 1126.6 hobbs	C/W para (b)(c)(e)(f) Para(b) due again at 1176.6 hobbs Para(c) due again by 10/2024 Para(d) due at 1605.7 hobbs Para(e) due again by 10/2024 Para(f) due again by 1626.6 hobbs		X	1176.6 hobbs	CarverAero LLC dba Revv Aviation CGFR811C
2004-08-10	Prevent loss of engine power	05/05/2004	N/A New Cylinders Installed		X		CarverAero LLC dba Revv Aviation CGFR811C
2005-12-06	Prevent failure of the magneto impulse coupling assembly	07/19/2005	N/A by overhaul date.		X		CarverAero LLC dba Revv Aviation CGFR811C
2005-14-11	Maintenance by Southern California Propeller Service	08/17/2005	N/A propeller not serviced by facility in AD text.		X		CarverAero LLC dba Revv Aviation CGFR811C
2005-20-04	Prevent failure of the starter adapter assembly and or crankshaft gear	11/01/2005	Superseded by 2007-05-15		X		CarverAero LLC dba Revv Aviation CGFR811C



AD#	Applicable S.B. # & Subject	Date & Hours @ Comp.	Method of Compliance	One Time	Recurring	Next Comp. @ Hrs/Date	Authorized Signature & Number
2005-20-25	Prevent failure of the avionics bus circuit breaker switch	11/09/2005	N/A type not installed.	X			CarverAero LLC dba Revv Aviation CGFR811C
2007-05-15	To prevent failure of the starter adapter assembly and or crankshaft gear	2798.6 T.T	P/C/W by inspection I/A/W part 2.		X	2898.6 T.T	CarverAero LLC dba Revv Aviation CGFR811C
2008-08-17	To prevent hazardous amounts of carbon monoxide from entering the cabin, an increase in under-cowl temperatures hampering engine and accessory function, and loss of tailpipe retention	05/06/2008	N/A by part no#.	X			CarverAero LLC dba Revv Aviation CGFR811C
2009-24-51	To address rapid wear on the face of hydraulic lifters	N/A	Superseded by 2009-24-52	X			CarverAero LLC dba Revv Aviation CGFR811C
2009-24-52	To address rapid wear on the face of hydraulic lifters	N/A	Superseded by 2010-11-04	X			CarverAero LLC dba Revv Aviation CGFR811C
2010-11-04	To prevent excessive hydraulic lifter wear	06/16/2010	N/A by engine overhaul date	X			CarverAero LLC dba Revv Aviation CGFR811C
2011-13-03	To prevent seizure of the turbocharger turbine			X			CarverAero LLC dba Revv Aviation CGFR811C
2012-03-06	To prevent an in-flight shutdown due to a failed fuel servo diaphragm	02/24/2012	N/A by engine overhaul date	X			CarverAero LLC dba Revv Aviation CGFR811C
2014-03-03	AFM - Placard, Prohibit Flight Into Known Icing Conditions	04/07/2014	C/W (g) (1)	X			CarverAero LLC dba Revv Aviation CGFR811C
2016-07-24	Elevator Trim Tab Assembly Parts Attachment Hardware Security	04/26/2016	superseded by 2016-17-08	X			CarverAero LLC dba Revv Aviation CGFR811C
2016-16-12	ECI Class 71 or Class 76 Cylinder Assembly Failures	09/15/2016	N/A type not installed.	X			CarverAero LLC dba Revv Aviation CGFR811C
2016-17-08	Elevator Trim Tab Assembly Parts Attachment Hardware Security	12/9/2023 @ 1126.6 hobbs	C/W by inspection		X	12/2024 or 1236.6 hobbs	CarverAero LLC dba Revv Aviation CGFR811C
2017-06-03	Combustion Heater Deterioration and Fire Hazard	12/9/2023 @ 1126.6 hobbs	C/W by pressure decay test		X	12/2025 or 1376.6 hobbs	CarverAero LLC dba Revv Aviation CGFR811C
2018-03-03	Lower Forward Carry Through Spar Cap Integrity	02/28/2018	Superseded by 2018-03-03 R1	X			CarverAero LLC dba Revv Aviation CGFR811C
2018-03-03 R1	Lower Forward Carry Through Spar Cap Integrity		Due at 12,000hr T.T		X	12,000hr T.T	CarverAero LLC dba Revv Aviation CGFR811C
2020-16-11	Cross-Flow Cylinder Assemblies Integrity			X			CarverAero LLC dba Revv Aviation CGFR811C
2022-16-03	S-1200 Series Magnetos Roller Bearings Improper Lubricatio	8/15/2022	N/A by unit serial no#	X			CarverAero LLC dba Revv Aviation CGFR811C
2022-16-03	S-1200 Series Magnetos Roller Bearings Improper Lubricatio	8/15/2022	N/A by unit serial no#	X			CarverAero LLC dba Revv Aviation CGFR811C
2023-02-12	Intake Valve Failures	2/17/2023	N/A by overhaul date	X			CarverAero LLC dba Revv Aviation CGFR811C
2023-04-08	Crankshaft Assembly Counterweight Retaining Rings in the Counterweight Groove			X			CarverAero LLC dba Revv Aviation CGFR811C
2023-05-16	Improper Installation of Counterweight Retaining Rings	3/15/2023	N/A by overhaul date	X			CarverAero LLC dba Revv Aviation CGFR811C
2023-09-09	Failures of Spot-Welded, Multi-Segment V-Band Couplings	07/17/2023	N/A type not installed.	X			CarverAero LLC dba Revv Aviation CGFR811C