


**SENSE NICH THREE BLADE COMPOSITE
AIRCRAFT PROPELLER
INSTALLATION AND OPERATION INSTRUCTIONS
FOR ROTAX ENGINES**

DOC#: 3B0R5 Installation Instructions rev-C-2018-10-02.doc

ATTENTION: Failure to follow these instructions will void all warranties, expressed and implied. Mounting difficulties, vibration, and/or failure can result with improper assembly of the propeller blades and hub parts.

CAUTION: Rotating propellers are particularly dangerous. Extreme caution must be exercised to prevent severe bodily injury or death.

11

Hobbs: 1075.8 Total Time: 1075.8 Engine TT: 1075.8 Prop TT: 89
I certify this prop has been inspected in accordance with the manufacturers
 maintenance and inspection procedures for an Annual condition inspection and was
 found to be in a condition for safe operation.
 Stephen M Leo AP3678028 

Information on this subject is available from the following sources: