



Airworthiness Directives

Aircraft / Component

P/N: EC-130T2	Manufacture Date: 9/5/2019 12:00:00 AM	Registration: LV-IYU	Date of Last Processed Utilization: 3/5/2024 00:00
S/N: 8705	Manufacturer: AIRBUS	Model: EC-130T2	TSN: 263,30
Desc.: AIRBUS		Variable #: 	CSN: 424,00
		Line #: 	

Filter: AD's EQUIPO LV-IYU

Aircraft / Component	AD	Description	Issued Date / Rev.	Cat.	Type	Accomplishment Method	Status	Interval	Last Accomplishment		Expiration Control			
			Effectiv. Date		Class	Accomplishment Remarks			Date Work Record	Value at Accompl.	Date	Total Accumulated	Expiration	Remaining
AIRBUS	AD 2009-0278.		22/12/2009		Appliance		N/A							
EC-130T2	Fire Protection – Portable Halon 1211 Fire Extinguishers – Identification / Replacement		0							N/A	N/A	N/A	UNK	
LV-IYU	ATA: 						Remarks: N/A P/N no instalado							
AIRBUS	AD 2011-0103.	Equipment / Furnishings – Emergency Locator Transmitter (ELT) Antenna – Modification / Replacement - Chelton Limited SB 02/2011 Issue 1	27/5/2011	MOD	Appliance		N/A							
EC-130T2			0							N/A	N/A	N/A	UNK	
LV-IYU	ATA: 25		27/5/2011				Remarks: N/A P/N No instalado							
AIRBUS	AD 2013-0020.	Am Safe Repair Station Reference Document N. E512615 Rev. B , dated 16 Sept 2013.	4/7/2014		Appliance		Closed	AD 2013-0020 (One Time)						
EC-130T2	TR-37999		4			****		6 Months	17/12/2019	39,80	FH	N/A	N/A	N/A
LV-IYU	ATA: 25		11/7/2014					(-0/+0)	OT-2019-9345	75,00	FC			
							Remarks: Verificar Intervalo y aplicabilidad de esta AD 2013-0020							

>> = Lower level Task | P) = Parent Task | C) = Child Task | R) = Reference Task