



N 2314	
Front <input type="checkbox"/>	Rear <input type="checkbox"/>
Left <input type="checkbox"/>	Right <input type="checkbox"/>

AMERITECH INDUSTRIES, INC
Where Performance Begins...®

PROPELLER LOGBOOK

Ameritech Industries, Inc.
dba: American Propeller Service

FAA REPAIR STATION #NO3R717L

www.ameritech-aviation.com
sales@ameritech-aviation.com

20208 Charlanne Drive
Redding, California 96002, U.S.A.
(530) 221-4470 / (800) 292-7767

PROPELLER MAINTENANCE RECORDS

Log No. _____
Aircraft Registration No. N 231U
Propeller Manufacturer M^cCauley
Hub Model 2A34C216
Hub Serial No. 800260
Blade Design No. G-90DHB-16E
Blade Serial No's.
1. YJ 26064
2. YJ 26065
3. _____
4. _____
5. _____
6. _____

Pitch Range:
Low 14.7° High 33.0°
Feather _____ Reverse _____

Governor Manufacturer _____
Model No. _____
Serial No. _____

For current TBO's call: 1.800.292.7767

DESCRIPTION OF WORK PERFORMED

SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK

DATE 4/2/14 TSN TSO 0.0



AMERITECH INDUSTRIES DBA
AMERICAN PROPELLER SERVICE
REPAIR STATION NO. N03R717L
20208 CHARLANNE DRIVE
REDDING, CA 96002 USA

WORK ACCOMPLISHED Complete Overhaul

MODEL NO. 2A34C216

SERIAL NO. 800260

THE AIRCRAFT AND/OR COMPONENT IDENTIFIED ABOVE WAS REPAIRED AND INSPECTED IN ACCORDANCE WITH CURRENT FEDERAL AVIATION REGULATIONS AND IS APPROVED FOR RETURN TO SERVICE. PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS AGENCY UNDER

REPAIR ORDER # 17742-03-2014

DATED: 04-02-2014

SIGNED

[Signature]
(AUTHORIZED INDIVIDUAL)

TONY MARINKOVICH

1361.5 Q Hobbs 1023.5

4/17/2014

Hobbs: 1

Installed pro

This certify
to be in airw

[Signature]

an Propeller Service

RELEASE CERTIFICATE

AIRWORTHINESS APPROVAL TAG

3. Form Tracking Number:

5. Work Order/Contract/Invoice
Number:

17742-03-2014

3/20/20

Hobbs:

Inspected

This certi
to be in ai

[Signature]

Eligibility:*

10. Quantity:

1

11. Serial/Batch Number:

Blade: YJ26064, YJ26065
Hub: 800260

12. Status/Work:

OVERHAULED

4/29/2016

Hobbs: 11

Inspected IAV

This certify th
to be in airworthy condition.



[Signature]

19. ☒ 14 CFR 43.9 Return to Service

☐ Other regulation specified in Block 13

Certifies that unless otherwise specified in block 13, the work identified in Block 12 and described in Block 13 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.

Eric Niedrauer A&P 2783808 IA

DATE	TSN	TSO	DESCRIPTION OF WORK PERFORMED SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
4/2/14		0.0	 <p>AMERITECH INDUSTRIES DBA AMERICAN PROPELLER SERVICE REPAIR STATION No. N03R717L 20208 CHARLANNE DRIVE REDDING, CA 96002 USA</p> <p>WORK ACCOMPLISHED <u>Complete Overhaul</u></p> <p>MODEL NO. <u>2A34C216</u></p> <p>SERIAL NO. <u>800260</u></p> <p>THE AIRCRAFT AND/OR COMPONENT IDENTIFIED ABOVE WAS REPAIRED AND INSPECTED IN ACCORDANCE WITH CURRENT FEDERAL AVIATION REGULATIONS AND IS APPROVED FOR RETURN TO SERVICE. PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS AGENCY UNDER REPAIR ORDER # <u>17742-03-2014</u></p> <p>DATED: <u>04-02-2014</u></p> <p>SIGNED:  TONY MARINKOVICH (AUTHORIZED INDIVIDUAL)</p>
1361.5	Q	Hobbs 1023.5	

4/17/2014 N231U McCauley 2A34C216 S/N 800260
Hobbs: 1023.5 TTP: 1361.5 TSPOH: 0

Installed propeller on N231U after overhaul by American Propeller in WO 17742.

This certify that this PROPELLER has been inspected in accordance with an ANNUAL inspection and was determined to be in airworthy condition.




Eric Niedrauer A&P 2783808 IA

3/20/2015 N231U McCauley 2A34C216 S/N 800260
Hobbs: 1066.3 TTP: 1404.3 TSPOH: 42.8

Inspected IAW Part 43 Appendix D checklist.

This certify that this PROPELLER has been inspected in accordance with an ANNUAL inspection and was determined to be in airworthy condition.



Eric Niedrauer A&P 2783808 IA






4/29/2016 N231U McCauley 2A34C216 S/N 800260
Hobbs: 1106.2 TTP: 1444.2 TSPOH: 82.7

Inspected IAW Part 43 Appendix D checklist.

This certify that this PROPELLER has been inspected in accordance with an ANNUAL inspection and was determined to be in airworthy condition.



Eric Niedrauer A&P 2783808 IA

DATE	TSN	TSO	DESCRIPTION OF WORK PERFORMED SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
			4/04/2017 N231U McCauley 2A34C216 S/N 800260 Hobbs: 1157.8 TTP: 1495.8 TSPOH: 134.3 Inspected IAW Part 43 Appendix D checklist. This certify that this PROPELLER has been inspected in accordance with an ANNUAL inspection and was determined to be in airworthy condition.  Eric Niedrauer A&P 2783808 IA
			4/20/2018 N231U McCauley 2A34C216 S/N 800260 Hobbs: 1216.4 TTP: 1554.4 TSPOH: 192.9 Inspected IAW Part 43 Appendix D checklist. This certify that this PROPELLER has been inspected in accordance with an ANNUAL inspection and was determined to be in airworthy condition.  Eric Niedrauer A&P 2783808 IA
			4/20/2018 N231U McCauley 2A34C216 S/N 800260 Hobbs: 1266.9 TTP: 11604.9 TSPOH: 243.4 Inspected IAW Part 43 Appendix D checklist. This certify that this PROPELLER has been inspected in accordance with an ANNUAL inspection and was determined to be in airworthy condition.  Eric Niedrauer A&P 2783808 IA
			4/20/2018²⁰ N231U McCauley 2A34C216 S/N 800260 Hobbs: 1304.4 TTP: 1649.4 TSPOH: 287.9 Inspected IAW Part 43 Appendix D checklist. This certify that this PROPELLER has been inspected in accordance with an ANNUAL inspection and was determined to be in airworthy condition.  Eric Niedrauer A&P 2783808 IA
			3/24/2021 N231U McCauley 2A34C216 S/N 800260 Hobbs: 1337.6 TTP: 1682.8 TSPOH: 321.3 Inspected IAW Part 43 Appendix D checklist. Installed new prop governor McCauley D-20309-21 s/n 190357. This certify that this PROPELLER has been inspected in accordance with an ANNUAL inspection and was determined to be in airworthy condition.  Eric Niedrauer A&P 2783808 IA

Eric Niedrauer A&P 2783808 IA