

N 153TA

Front ☒

Rear ☐

Left ☐

Right ☐



AMERITECH INDUSTRIES, INC

Where Performance Begins...®

PROPELLER LOGBOOK

Ameritech Industries, Inc.

dba: American Propeller Service

FAA REPAIR STATION #NO3R717L

www.ameritech-aviation.com

sales@ameritech-aviation.com

**20208 Charlanne Drive
Redding, California 96002, U.S.A.
(530) 221-4470 / (800) 292-7767**


N 153TA

Front ☒

Rear ☐

Left ☐

Right ☐



AMERITECH INDUSTRIES, INC
Where Performance Begins...®

PROPELLER LOGBOOK

Ameritech Industries, Inc.
dba: American Propeller Service

FAA REPAIR STATION #NO3R717L

www.ameritech-aviation.com
sales@ameritech-aviation.com

20208 Charlanne Drive
Redding, California 96002, U.S.A.
(530) 221-4470 / (800) 292-7767

PROPELLER MAINTENANCE RECORDS

Log No. _____

Aircraft Registration No. N153TA

Propeller Manufacturer MCCAULEY

Hub Model B3D36C431-C

Hub Serial No. 010768

Blade Model No. H 80VSA-1

Blade Serial No's.

1. VB54011

2. VB54012

3. VB54027

4. _____

5. _____

6. _____

Pitch Range:

Low 14.9° High/Latch 31.7°

Feather _____ Reverse _____

Governor Manufacturer _____

Model No. _____

Serial No. _____

For current TBO's call: (800) 292-7767

[illegible]

N153TA 04-02-14 TTAf & Tach: 2144.7 SPOH: 0.0

Installed prop this date on to Cessna 182 N153TA S/N 18281053. Opps
and leak check good.....

Robert Scott W/K A&P 2719327



N153TA 08-15-14 Tach: 2167.3 SPOH: 22.6

I certify this prop has been inspected I/A/W a 100 hr / annual inspection within the scope & detail of FAR 43 appendix D and was determined to be in airworthy condition.....

Ken Kerstetter A&P 3462897



N153TA 07-15-15 Tach: 2233.5 SPOH: 88.8

I certify this prop has been inspected I/A/W a 100 hr / annual inspection within the scope & detail of FAR 43 appendix D and was determined to be in airworthy condition.....✓...../

Robert Scott  A&P 2719327



N153TA 07-28-16 Tach: 2312.6 SPOH: 167.9

I certify this prop has been inspected I/A/W a 100 hr / annual inspection within the scope & detail of FAR 43 appendix D and was determined to be in airworthy condition.....

Robert Scott W/C A&P 2719327

[illegible]

N153TA 07-25-17 Tach: 2381.7 SPOH: 237.0

I certify this prop has been inspected I/A/W a 100 hr / annual inspection within the scope & detail of FAR 43 appendix D and was determined to be in airworthy condition.....

Robert Scott [Signature] A&P 2719327



N153TA 07-11-18 Tach: 2435.0 SPOH: 290.3

I certify this prop has been inspected I/A/W a 100 hr / annual inspection within the scope & detail of FAR 43 appendix D and was determined to be in airworthy condition.....

Samuel W. Taflinger *Samuel W. Taflinger* A&P 3319389



N701FA 02-24-2018 Tach : 203.0 TTAF: 710.8

Removed prop and installed after repair by American Propeller (see FAA form 8130-3). Ground run ops and leak check good...

Robert Scott [Signature] A&P 2719327



N153TA 07-19-19 Tach: 2489.8 SPOH: 345.1

I certify this prop has been inspected I/A/W a 100 hr / annual inspection within the scope & detail of FAR 43 appendix D and was determined to be in airworthy condition.....

Robert Scott A&P 2719327



N153TA 07-17-20 Tach: 2535.4 SPOH: 390.7

I certify this prop has been inspected I/A/W a 100 hr / annual inspection within the scope & detail of FAR 43 appendix D and was determined to be in airworthy condition.....✓

Robert Scott A&P 2719327



N153TA 09-06-22 Tach: 2643.8 SPOH: 499.1

I certify this prop has been inspected I/A/W a 100 hr / annual inspection within the scope & detail of FAR 43 appendix D and was determined to be in airworthy condition.....

Robert Scott  A&P 2719327



N153TA 08-01-21 Tach: 2581.8 SPOH: 437.1

I certify this prop has been inspected I/A/W a 100 hr / annual inspection within the scope & detail of FAR 43 appendix D and was determined to be in airworthy condition.....✓

Robert Scott A&P 2719327