

HARTZELL

PROPELLER LOGBOOK

PROPELLER MODEL PHC-334F-1RF

PROPELLER S/N FP 30968

LOGBOOK # _____

PROPELLER MAINTENANCE RECORD

Position Front

PITCH RANGE

Propeller Model PHC-534F-1RF

High/Feather _____

Propeller S/N FP 30968

Start Lock _____

Blade Design _____

Low _____

Blade S/N's

Reverse _____

No. 1 K 09727

No. 2 K 09656

No. 3 K 09730

No. 4 _____

No. 5 _____

No. 6 _____

Aircraft Manufacturer Mooney Aircraft Co.

Aircraft Model M20R

S/N 29-0341

Registration N 341PS

Spinner Assembly Part No. _____

Date: 1-3-07

Hobbs: 369.5

Propellor Log entry for N341PS

Annual Inspection

Inspect this propellor as per Mooney Aircraft maintenance manual inspection guide. Lubricate with Aeroshell 6 grease.

All work was performed as per Mooney Aircraft maintenance manual, Hartzell owners manual and FAR 43.

I certify that this propellor has been inspected in accordance with an Annual Inspection and has been determined to be in airworthy condition.

James T. Miller A & P DIA 59766555

PROP MODEL:
PROP S/N:
REG NO: 341PS
WORK ORDER:
1714-01-2008



Premier Aircraft Service, Inc.

5540 NW 23rd Avenue Hanger 14
Fort Lauderdale, FL 33309
Phone: (954) 334-2393

DATE: 1/10/2008
A/C TSN: 487.7
PROP TT: 487.7
TACH: 487.7

Prop Entries

C/W100 HR INSPECTION ON THIS PROPELLER IAW FAR 43 APPENDIX D AND INSPECTION PROCEDURES CALLED OUT IN MOONEY M20R M/M.

A&P 2761974

MECH ADRIAN ARIAS

SIGNATURE

I certify this propeller has been inspected in accordance with an Annual inspection and found in airworthy condition on this date. Approved for return to service on this date. THIS RELEASE IN NO WAY CERTIFIES FUTURE AIRWORTHINESS

DATE: 1/10/2008

SIGNED:

Jack Wesley Dale, IA: 456967085

Work Order: 1714-01-2008

Printed by EBis 3 (datcomedia.com)

Propeller
TSN TSO

A/C
Hrs

Description of all operations pertaining to Airworthiness Directives,
Service Documents, Overhaul, Major or Minor Repair, and Inspection

PROP MODEL:
PHC-J3YF-1RF
PROP S/N: FP3096B
REG. NO: 341PS
WORK ORDER:
2693-01-2009



Premier Aircraft Service, Inc.

5540 NW 23rd Avenue Hanger 14
Fort Lauderdale, FL 33309
Phone: (954) 334-2393

DATE: 2/6/2009
A/C TSN: 532.5
PROP TT: 532.5
TACH: 532.5

Prop Entries

C/W 100 HR INSPECTION ON THIS PROPELLER IAW FAR 43 APPENDIX D AND INSPECTION PROCEDURES CALLED OUT
IN M20R M/M CHAPTER 5

A&P 2738632
MECH CHRISTOPHER BARCENAS

SIGN:

I certify this propeller has been inspected in accordance with an ANNUAL INSPECTION and found in airworthy condition on this date. Approved for return
to service on this date. THIS RELEASE IN NO WAY CERTIFIES FUTURE AIRWORTHINESS

DATE: 2/6/2009

SIGNED:

JONATHAN RANNEY, IA: 2773257

Work Order: 2693-01-2009

Printed by EBis 3 (datcomedia.com)

PROP MODEL:
PHC-J3YF-1RF
PROP S/N: FP3096B
REG. NO: N341PS
WORK ORDER:
2062-11-2009



Mooney Airplane Company, Inc.

Repair Station No. CRS# MPYR456X
165 Al Mooney Road North
Kerrville, TX 78028
Phone: 830-792-2911

DATE: 3/2/2010
A/C TSN: 678.8
PROP TT: 678.8
TACH: 678.8

Prop Entries

(8) Performed 100 hr inspection in accordance with Mooney M20R service manual and Hartzell Owner's manual No. 115N Greased hub with Aeroshell #6..(26) Removed deep gouges from 2 of 3 blades and dressed 3rd blade to match..(102) Reinstalled prop in correct position with new C-3317-228 oring. Performed propeller dynamic balance to .078 IPS.

I certify that this Propeller installed on N341PS has been inspected in accordance with a 100 hour inspection and is determined to be in Airworthy condition. Pertinent details of the repair are on file at this repair station under EBis 3 Work Order No. 2062-11-2009.

DATE: 3/2/2010

SIGNED:

Work Order: 2062-11-2009

Brian Kendrick
Certified Repair Station No. CRS# MPYR456X

Printed by EBis 3 (datcomedia.com)

e	Propeller TSN TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspection
---	----------------------	------------	---

PROP MODEL:
PHC-J3YE-1RF
PROP S/N: FP3096B
REG. NO: 341PS
WORK ORDER:
4206-03-2011



Premier Aircraft Service, Inc.

Repair Station No. 9PRR402B
5540 NW 23rd Avenue Hanger 14
Fort Lauderdale, FL 33309
Phone: (954) 334-2393

DATE: 4/1/2011
A/C TSN: 835.3
PROP TT: 835.3
TACH: 835.3

Prop Entries

(5) C/W ANNUAL INSPECTION ON THIS PROPELLER IAW FAR 43 APPENDIX D USING MOONEY M20R M/M CHAPTER 5 INSPECTION CHECKLIST AS A GUIDE. ADS CHECKED THROUGH 2011-05.

MAINTENANCE RELEASE: IN REFERENCE TO THE WORK PERFORMED, THIS AIRCRAFT, AIRFRAME, AIRCRAFT ENGINE, PROPELLER, AND / OR APPLIANCE WAS REPAIRED AND INSPECTED I.A.W. CURRENT REGULATIONS OF THE FEDERAL AVIATION ADMINISTRATION AND IS APPROVED FOR RETURN TO SERVICE. ALL WORK WAS PERFORMED IAW CURRENT APPLICABLE AIRCRAFT, ENGINE, OR APPLIANCE MAINTENANCE MANUALS AND INSTRUCTIONS. PERTINENT DETAILS ARE ON FILE AT THIS REPAIR STATION OFFICE.

DATE: 4/1/2011

SIGNED:

Work Order: 4206-03-2011

Adrian Arias
Certified Repair Station No. 9PRR402B

Printed by EBis 3 (datcomedia.com)

Date: 8 March, 2012

S/N: FP3096B

Propeller: Hartzell

Tach Time: 897.2

Model: PHCI3YF-1RF

Total Time: 897.2

Lubricated hub with Aeroshell #6 in accordance with Hartzell maintenance instructions. Dressed leading edges of all three blades to remove minor nicks and abrasions. I certify that this Propeller has been inspected in accordance with an annual inspection and has been determined to be in airworthy condition.

Stanley D. Wheeler 3131314 IA

Stanley D Wheeler

PROPELLER LOGBOOK ENTRY

N341PS MOONEY Model M20R S/N 29-0341 JUNE 7, 2013

HARTZELL HC-C2YR-1BF S/N CH17178.

Total Aircraft Time: 946.8

PTSMOH: _____

Tach Time: 946.8

C/W ANNUAL INSPECTION ON THIS PROPELLER IAW FAR 43 APPENDIX D
USING MOONEY M20R M/M CHAPTER 5 INSPECTION CHECKLIST AS A GUIDE.
ADs CHECKED THROUGH CURRENT ON ATP NAVIGATOR.

In reference to the work performed this aircraft airframe, propeller, engine and/or appliance was repaired and inspected IAW current regulations of Federal Aviation Administration and is approved to return to service. All work was performed IAW current applicable Airframe, engine or appliance Maintenance manuals and instructions

[Signature]

Propeller

TSN TSC

PROP MODEL:
PHC-JSYF-1RF
PROP S/N: FP3096B
REG. NO. 341PS
WORK ORDER:
5997-03-2014



Premier Aircraft Service, Inc.

Repair Station No. 9PRR402B
5540 NW 23rd Avenue Hanger 14
Fort Lauderdale, FL 33309
Phone: (954) 334-2393

DATE: 3/21/2014
A/C TSN: 960.6
PROP TT: 960.6
TACH: 960.6

atives,
spections.

Prop Entries

(5) C/W ANNUAL INSPECTION ON THIS PROPELLER IAW FAR 43 APPENDIX D USING M20R M/M CHAPTER 5 INSPECTION CHECKLIST AS A GUIDE. ADs CHECKED THROUGH CURRENT ON ATP.... (34) PAINTED FACE OF PROPELLER FLAT BLACK PER HARTZELL O/M 115N.

I CERTIFY THIS PROPELLER HAS BEEN INSPECTED IAW AN ANNUAL INSPECTION AND FOUND IN AIRWORTHY CONDITION ON THIS DATE. APPROVED FOR RETURN TO SERVICE ON THIS DATE.

DATE: 3/21/2014

SIGNED:

Rich Quires
Certified Repair Station No. 9PRR402B

Work Order: 5997-03-2014

Printed by EBis 3 (datcomedia.com)



South Texas Aircraft, LLC.
Propeller Log

N341PS 04/13/2015

Tach : 1113.5 PTSN: 1113.5

C/W 100hr inspection, reference FAR 43 appendix (d) & Hartzell service / maintenance manuals. Verified AD compliance to 04/13/2015. No new applicable AD's found at this time. A complete AD summary was furnished to aircraft owner and is part of aircraft permanent records. Run up ops check, ok. *I certify that this propeller has been inspected in accordance with a 100hr inspection and was determined to be in airworthy condition at this time.*

A&P 3584134

James Gibbs

05/05/2016

N341PS

100 hour inspection:

TT 1,184.2

Researched all airworthiness directives through Bi weekly. I certify that this propeller assembly has been inspected in accordance with an Annual Inspection and was determined to be in airworthy condition at this time. Inspection data: Hartzell Owners, Maintenance, Manual 300 & Appendix D to title 14 CFR part 43.



Gregory W. Groves 3466323 A&P

For Sundance Aircraft Maintenance LLC

5/5/16
Date

JB Aviation Management, Inc.

5112 Greenwood Rd · Wonder Lake, IL 60097 · 815-648-2642

N #: 341PS Propeller Log Entry

Prop: Hartzell PHC-J3YF-1RF Serial #: FP3096B Tach: 1237.9 Prop TT: 1237.9 Date: 01 APR 17

Completed annual inspection IAW FAR 43 Appendix D & Manufacturer's Service Manual 100 Hr / Annual Inspection Section & performed routine service requirements as specified by the aircraft manufacturer. The following work was performed:

1. Serviced prop hub with Aeroshell 6 grease.
2. Cleaned, inspected, and dressed propeller blades.
3. All AD's checked and determined to be complied with at this time.

I certify that this Propeller has been inspected in accordance with an Annual Inspection and was determined to be in an airworthy condition.

END


Brian Spiro

A&P/IA #2826898

JB Aviation Aircraft Maintenance, Inc.

5112 Greenwood Rd · Wonder Lake, IL 60097 · 815-648-2642

N #: N341PS Propeller Log Entry

Prop: Hartzell PHC-J3YF-1RF Serial #: FP3096B Tach: 1266.5 SPOH: 1266.5 Date: 26 APR 18

Completed annual inspection IAW FAR 43 Appendix D & Manufacturer's Service Manual Annual Inspection Section & performed routine service requirements as specified by the aircraft manufacturer. The following work was performed:

1. Cleaned, inspected, and dressed propeller blades.
2. Serviced prop hub with Aeroshell 6 grease.

I certify that this Prop has been inspected IAW an Annual Inspection and was determined to be in an airworthy condition.

END


Brian Spiro

A&P/IA #2826898

JB Aviation Aircraft Maintenance, Inc.

5112 Greenwood Rd · Wonder Lake, IL 60097 · 815-648-2642

N #: **N341PS** Propeller Log Entry


Prop: Hartzell PHC-J3YF-1RF Serial #: FP3096B Tach: 1278.7 SPOH: 1278.7 Date: 01 MAY 2019

Completed annual inspection IAW FAR 43 Appendix D & Manufacturers Service Manual Annual Inspection Section & performed routine service requirements as specified by the aircraft manufacturer. The following work was performed:

1. Cleaned, inspected, and dressed propeller blades.
2. Serviced prop hub with Aeroshell 6 grease.

I certify that this Prop has been inspected IAW an Annual Inspection and was determined to be in an airworthy condition.

-----END-----


Troy Schlote

A&P/IA #3590247

MYERS AVIATION, INC. OSHKOSH, WI

PROPELLER LOG ENTRY - N341PS

September 1, 2021


Hobbs 1269.4


Tach 1281.1

Prop TSN 1492.5

SPOH 263.4

Annual inspection completed this time and date. Inspected, lubed hub, and dressed blades.


Steve J. Myers AP3521097IA

Date	Propeller TSN TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.																	
			<u>Satnan Avionics</u>																	
			Joe Foss Field Sioux Falls SD																	
			Propeller Log																	
<table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 12.5%;">DATE</th> <th style="width: 17.5%;">MAKE/MODEL</th> <th style="width: 12.5%;">TACH / HOBBS</th> <th style="width: 12.5%;">TOTAL TIME</th> <th style="width: 12.5%;">SPOH</th> <th style="width: 17.5%;">REGISTRATION</th> <th style="width: 15%;">SERIAL NUMBER</th> </tr> </thead> <tbody> <tr> <td>1/6/23</td> <td>HARTZELL PCH-J34F-1RF</td> <td>1274.9</td> <td>1274.9</td> <td>1274.9</td> <td>N431PS</td> <td>FP309GB</td> </tr> </tbody> </table>							DATE	MAKE/MODEL	TACH / HOBBS	TOTAL TIME	SPOH	REGISTRATION	SERIAL NUMBER	1/6/23	HARTZELL PCH-J34F-1RF	1274.9	1274.9	1274.9	N431PS	FP309GB
DATE	MAKE/MODEL	TACH / HOBBS	TOTAL TIME	SPOH	REGISTRATION	SERIAL NUMBER														
1/6/23	HARTZELL PCH-J34F-1RF	1274.9	1274.9	1274.9	N431PS	FP309GB														
<p>I certify this propeller has been inspected IAW an annual inspection and was found to be in an airworthy condition at this time. Details on file at this agency. W.O.# 4921</p>																				
<p>Signed <u></u> AP # <u>3565899</u></p> <p style="margin-left: 100px;">Dale Ebbinga</p>																				