


DATE	RECORDING TACH TIME	TODAYS FLIGHT	TOTAL TIME IN SERVICE	DESCRIPTION OF INSPECTIONS, TESTS, REPAIRS AND ALTERATIONS ENTRIES MUST BE ENDORSED WITH NAME, RATING AND CERTIFICATE NUMBER OF MECHANIC OR REPAIR FACILITY. (SEE BACK PAGES FOR OTHER SPECIFIC ENTRIES.)
2023				<p>Minor: <sup>Hardware</sup> rust; surface corrosion on Alum. CWAD;</p> <p>67-03-01 heat exch. 72-03-03 R3 Flap screw Jack</p> <p>98-01-06 2 piece venturi 2011-10-09 seat tracks</p> <p>ELT Function CROK</p> <p>I certify this Aircraft/Engine has been inspected IAW an 100 hr/Annual Inspection and was determined to be in an Airworthy Condition. Eric O. Sawyer A&amp;P 3521645 IA</p> 
July 9	114.8		5911.52	

THIS ELT EQUIPPED WITH MERL, INC. ALKALINE BATTERY PACK P/N BP-1015 APPROVED TSO C-91

REPLACE BY **JAN 24**

Battery weight: 1.5 lbs.



MERL, INC. (203) 237 - 8811  
1777 N. Colony Rd. P.O. Box 188  
Meriden, CT USA 06450