2001-2015



The Standard AIRCRAFT LOG

ASA-SA-1

Aircraft Record General Information		Mental Service Consulty of
Manufacturer PIPER Serial 18-7305264	Model PA 28-180 Registration Number 110	
Date of Manufacture		
Engine(s) currently installed:		
Manufacturer Ly COMUNE Model	0-360-A4A Serial	L-29419-36A
Manufacturer Model	Serial _	
Propeller(s) currently installed:	4	55
Manufacturer SENISENIICH	Model 76EM8\$	5-0-60
HUB Model Serial		
Blade ModelSerial	Serial	Serial
Blade Model Serial	Serial	

YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
2/2/01	PEPLA NEW.	(E)	PANEL ED OK	POSCHNE 625012838 AGP
*3/2/01	->			Piper PA28-180 N16484 Installed Gamin GA56 GPS antenna for GPS295 GPS/Map. Equipment installed in accordance with manufactures installation manual and AC43-13-18 and AC43-13-24
				This aircraft was inspected in accordance with applicable maintenance rules and current FAA Regulations. With regards to this work performed, this aircraft is approved for return service.
				ABLE AVIONICS 12659 Osborne Street Pacoima, CA 91331 (818) 896-9471 F.A.A. Repair Station YA2R312L
				Paul B. Byrne 3/2/01 Date

YEAR: O1 DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
3-27	23829			
	REPLA	CED	LEPT	WHEEL FAIRING BRACKET PN 63370-04.
	RE SE	DENA	RIGHT	BRAKE ACTUATING CYLINDER & REPLACED
	8	RAKE	PADS	
	RESER	0 3 J4	LEFT	T GEAR STRUM AND SERVICED WITH NEGLY
	=	rung) .	6
	REPL	DOED	cu	CK. \$ \$972264006
				0001
5-01		REMO	IED ANT	PEPLACED RUDDER ASSEMBLY WITH NEW,
		ART	# 653	42-002 PERMINI AND BALANCE RUDDER
				2 papril 40 ste

YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
FEB1,2002	2468,06	3.1.6	DATE: FET	1 this PIRCRAFT has been inspected in accordance with a ANNUAL inspection
	(2) (3)	1		ermined to be in airworthy condition. Mech, All No. 2204056
14	4 4110	47	COMPLIE	DWITH FAR 91.207(d) BY INSPECTION GOPERATIONAL
	63/6	55	CHECK	OF ECT. INSPECTION DUE NEXT ANNUAL DWITH AD 75-24-02 BY INSPECTION OFFER SEATS.
		170 13		TATAL MINISTER.
	29.254	9 Ex		The state of the second st
		1	P (2)	

EAR: RECORD TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
	SE THAT	11 140 4	ACTORS MELON MENT IN THE RESIDENCE OF THE PARTY OF THE PA
24 Mo.	PITOT STA	TIC,	
ALTIMETE	R, TRANSP	ONDER	
CER	TIFICATION	4	
	the Altimete		
	Reporting E		
	been perform		
Tested to 2	000	14	
Date 5-	9-02	4	
Signed 7	no n	ganes	THE ALLACT STORES SPECIAL BOTTOM OF THE SECOND SECTION OF THE SECOND SEC
	Station #WZ	Section of the second of the s	
/818	'S AVIONIC	194//	
(010	100.330		
115			

YEAR: O_2_ DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.) REPLACED LEFT MAIN TURE WUTH
6-11	2502,33			new Stockstrated Men men
22503	2583.71		certify that th	S-03 TACH. 2583.71 S AIRCRAFT has been inspected in accordance with a ANNUAL Inspection
		COMPL	HIWOSI	ADTS-24-02 BYINSPECTION OF REARSEATS; DUE 2-29-04 H AD 99-24-10 BY INSPECTION OF STAND BY VACUUM
		REA	SISTEM- ALED E	LT WITH AMERI-VING AVENUE OVER A CHRIST
	Contraction		16:31	H: 337 ON FIVE WITH DETAILS (THIS DATE) EVERY YEAR 91.207(1) BY INSPECTION AND OPERATIONAL.

-	RECOLLERATE	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
DATE	2626.49	r Prael	y Palgo	ACCOMPUSHED S.B. NO. 1131 DYE PEN
1-20	100	,ev	HAR AZ	INSPECTION, DO DOZZAJOG
			KYARAT.	DE 17764006
JANSOF	4/263	9.45	REMOVE	ED AIRCRAFT BATTERY WE PLACED WITH
1	1	41	NEW	GILL G-35. Partine A9P625012838
39-04	2644.66		BATE MAR	CH 9,2004 TACH. 2644.66
	1564		certify that	this AIRCRAFT has been inspected in accordance with a ANNUAL insspection
	Tooks.		and was delen	without to be in elementhy condition. Mech. 1807264056
		COMPU	EDWITHE!	R 91.20767BY INSPECTIONS OPERATIONAL CHECK-OF ELT
		THE	MARCH	2005, REPLACED ELT BATTERIES WITH NEW DURACELL, DUE
		COMPLY	ED WITH	AD75-24-02 BY INSPECTION OF PEAR SEATS-CIC
		D	E MA	UN 2005. Continued ->

YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
3-9-04	2644.66	COMPL	IEO WIT	HAD 99-24-10 BY INSPECTION OF VACUUM LINES AND
	continued	9		FITTINGS OF STANDBY VACUUM SYS. DUB MARZOS
4.016	SSITA	REPLA		ET WHEEL BRAKE PADS WITH NEW.
		REPLA	CED IN	ET AIRFILTER BA105 WITH NEW
38	30000	REPLA	CED VA	CUUMFILTER B3-5-1 WITHNEW
			CANADA STATE OF THE STATE OF TH	THEROUS-B-17BY OVERHAUL OF PROPELLER DIVE
		BY	Execuín	EPPOP. (EUGR595N), PARTH 76EM855-0-60,
135	125-2 555	56	JAC#1	2920K. REINSTALLED PROPELLER INLACCORDANCE
<u>r 131</u>	ED _D. 184/	WIT	H PIPER	AND SENSENICH SERVICE INSTRUCTIONS.
100 July	MATERIAL CA		04/29/10	TO THE PARTY OF TH
2) (123 P. J. A. S. J. A. J. A. S. J. J. A. S. J. A.	1/2/15	1012450	ALLEY YOU AND A PROPERTY OF THE PROPERTY OF TH
	A Dunie			

AR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
30	2649.	48	REPL	ACED ELECTRIC FUEL PUMP
70			WIT	H NEW PART # 35328-800
		11 37	OP	5 V O.K. # 1000
		Ca		The service of the se
		2 6	,	en dismeinal perional isontile des
		7	hand of	Bas I spirite in a company of the co
				n Since the sent the
				1 2 2 2 1 702 siso 1
				THE RESERVE OF THE PROPERTY OF
				WERE S AMORIOS I

YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Re Facility. (See back pages for other specific entries.)
W	4 4		Liber	的对于2014年,任中全年1972年, 该年 第1996
a to	certify that and Altitude ests required 413 have ested to 2 ate 6	the Altin Reporting by FAR been per	SPONDER ION heter System g Equipment 91.411 and formed. 7 0 ft.	SEPT, 3, 04 CHANGED ELECTRIC FUEL PUMP NITH NEW PAPPONTO PAPPO

RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Entries must be en	Inspections, Tests, Repadorsed with Name, Rating an pages for other specific entries	d Certificate N	Iterations Number of Technician or F
Amer	ican A	viation	14 14 11			Airframe
16425 V	anowen S	t.	N-number:	N16484	Date:	April 12, 2005
Van Nuy (818) 78	rs, CA 914 5-7285	106	Model No: Serial No:	Piper PA28-180 28-7305264	Tach:	2693.67
Complie Complie system. Complie ELT batt Replaced	d with AD d with AD Due in 12 d with FA tery due M I left navig	75-24-02 to 199-24-10 to 199-24-10 to 199-24-10 to 199-24-10 to 199-207(d) 199-24-10 to 199-24-10 to 199-24-10 to 199-207(d) 199-24-10 to 199-24-10	by visual inspection by visual inspection nonths. by inspection and bulb, 1512, with no	of rear seats: Okay. Due of vacuum lines and sad operational check of ELT.	e next Annodle fittings Γ. Due next	ual inspection. of standy by vacuum t annual inspection.

VE _	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Refereility. (See back pages for other specific entries.)
-22-05	2705.83			REPLACED VACUUM PUMP WITH NE UNIT PAPTIGOSS
				UNIT DAPTIGOSE
				30100
3-72-0	to			REPLACED STARTER CONTACTOR WITH
				NEW KIT P# 767-394
				200000000000000000000000000000000000000
				60101
				The second secon

AR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Entries must be endorsed with	ns, Tests, Repairs and Alter Name, Rating and Certificate Num ner specific entries.)		
· W	American Aviation 16425 VANOWEN STREET, VAN NUYS, CA (818) 785-7285						
	N	IANUFACT	TURER	New Piper	REGISTRATION	N16484	
	N	ODEL NU	MBER	PA28-180	DATE	May 10, 2006	
	S	ERIAL NU	MBER	28-7305264	TACH	2733.73	
		d with <i>FA</i> n.	R91.207	2 calendar months. (d) by inspection and operation IA 2264056	tional check of ELT. Due	next annual	
100				112201000	0.0		
06	2736				SCC YOUND PUMP	S/N. 35/43	
16					SCC YOUND PUND	S/N. 35143	

.

.

-

-

YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
DATE				I CERTIFY THE ALTIMETER, STATIC SYSTEM, PRESSURE
				ALTITUDE REPORTING SYSTEM, AND TRANSPONDER HAS
TONE				BEEN TESTED AND INSPECTED AND FOUND TO COMPLY
				WITH FAR 91.411 APP. E AND FAR 91.413, APP. F OF PART 43.
				ALTIMETER TESTED TO: 15.000
				DATE: 7-5-86
				SIGNATURE: OCITAL
				SKY WEST INSTRUMENTS FAA REP.
				STA. # AK4R053M
				CABLE AIRPORT UPLAND, CA 91786
	1 1000			
				The state of the s

YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Entries must be endorsed with Facility. (See back pages for or	ons, Tests, Repairs and Alterations Name, Rating and Certificate Number of Technician or Repair other specific entries.)
UPLAND I CERTIF ACCORD RETURN FILE AT	, CA 91786 FA Y THAT THIS ANCE WITH TO SERVICE THIS FACILIT	A APPROV AIRFRAM ANNUAL II OTHER D Y.	E HAS BEEN SPECTION A ETAILS OF T	CABLE AIRPORT, TATION AJ4R052M INSPECTED IN IND APPROVED FOR HIS INSPECTION ARE ON TAC 2776, 91 472, 59	CHADTS-24-02 VIATHOR OF READ SEATS CKOK C/WAD99-24-10 VIA VISINSPOFF, TTING FOR STAND-BY VAC, SYSTEM CR GOOD. AD95-26-13 PLW 8-30-00 TACH 2304.32 (AT ENG, CHANGE) RAD BRAKE LININGS ON LH MLG WITH NEW,
OPLA I certif OF FAF ELT DAT	ND, CA 91786 by that the ELT 1 R Section 91.20 BATTERY	FAA APPR has been ins 7(d) and was 7 DUE D TAC <u>277</u>	OVED REPAIR pected in accord s found to be in ATE 3 ~ 0 691 NAME	AC. CABLE AIRPORT R STATION AJ4R052M dance with the requirements satisfactory condition. 9 WO# 9305	

-

YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Re Facility. (See back pages for other specific entries.)
				I CERTIFY THE ALTIMETER, STATIC SYSTEM, PRESSURE
4400		A. S.		ALITOUL KETOKING SYSTEM AND TO
STATE			316	TO THE MIND TO GOVE
GUE				WITH FAR 91.411 APP. E AND FAR 91.413, APP. F OF PART 43.
				ALTIMETER TESTED TO: 15,000
		31333	3 - 31-52 5	DATE: 7 / DE FT.
150		A TOTAL		
1363				SIGNATURE:
	NO HOLD	5318 3		SKY WEST INSTRUMENTS FAA REP.
11	3 2548	W. J	32 081	STA. # AK4R053M
		4 1/2 1/2		CABLE AIRPORT UPLAND, CA 91786
1 0				OT EAND, CA 91/86
-08			1	2100 DOLOT 1011- 2011 C D
				simple vertila (and comples)
				ith ralis on his Poland
				50 11115 - 0 59 - 1111111111111111111111111111111111
	100		4	19 10 SI My SI Winente # All 40000

YEAR:	RECORDING TODAY'S TOT	Description of Inspections, Tests	, Repairs and Alterations
100		111 1 1 1 22 2 1	Certificate Number of Technician or Repair
DATE	8-25-08 In	stalled Comant CII21	
2AV	Can Antenna.	Installed Icom partable	
	interface, Ins	fall new Cabin speaker	
Tanal	tested all Eq	Installed Icom portable fall new Cabin speaker and found and found airworthy ABHX+1+R923K	
	units to be a	airworthy AB#XTITAJAK	
	N16484	Maintenance Release	
	accordance with current Fe	dece identified was repaired and inspected in ederal Aviation Regulations and was approved ment details of the repair are on file at this	
- 110		1	
	Authorized Signature	wy you	
	Date 8-25-08	Recorded Time M/H	
	Pacific Coast Radio	1749 W. 13th Street	
- 3000	CTS # XXHR912K	Upland, CA 91786	

Description of Inspections, Tests, Repairs and Alterations YEAR: RECORDING TODAY'S TOTAL Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair TACH FLIGHT TIME IN TIME SERVICE Facility. (See back pages for other specific entries.) DATE 5163 A095-26-02 N-A VIA H HOSES ARE T\$0 C 53 A0 FOOTHILL AIRCRAFT SALES & SERVICE, INC. CABLE AIRPORT, UPLAND, CA 91786 FAA APPROVED REPAIR STATION AJ4R052M C/WAD 75-24-02 VIA VIS INSP. I CERTIFY THAT THIS AIRFRAME HAS BEEN INSPECTED IN ACCORDANCE WITH ANNUAL INSPECTION AND APPROVED FOR RETURN TO SERVICE. OTHER DETAILS OF THIS INSPECTION ARE OF REAR SEATS CK GOOD. ON FILE AT THIS FACILITY. ADGG-24-10 VIA VIS, INSO. WO# 9924 DATE 8-1-08 TAC 2846.15 OF STO-134 VAL SYSTEM T.T. A/C 28410. 15 ENG. T/T 541.83 CK OK. R+R BOTH TRIM Foothill AIRCRAFT SALES & SERVICE, INC., CABLE AIRPORT BARNEL BUSIHINGS WITH UPLAND, CA 91786 FAA APPROVED REPAIR STATION AJ4R052M I certify that the ELT has been inspected in accordance with the requirements of FAR Section 91.207 (d) and was found to be in satisfactory condition. ELT BATTERY DUE DATE 3-09 WO# 9924 DATE 8-1-08 TAC 2846, 15 NAME &m Wall

YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspec Entries must be endorsed v Facility. (See back pages for	tions, Tests, Repairs and Alterations vith Name, Rating and Certificate Number of Technician or Repair r other specific entries.)
UPLAND, I CERTIFY ACCORDA RETURN FILE AT T	CA 91786 FAA THAT THIS A ANCE WITH AN TO SERVICE. (HIS FACILITY	APPROVE AIRFRAME NNUAL INS OTHER DET	D REPAIR ST HAS BEEN PECTION AN TAILS OF THE	CABLE AIRPORT, ATION AJ4R052M INSPECTED IN ID APPROVED FOR IS INSPECTION ARE ON TAC 2862. 31 544.83 587.99	CHAD75-24-02 VIA VIS.INSP. OF REAN SEATS CK GOOD, CHNAD99-24-ID VIA INSP OF STAND-BY VAC. SYSTEM CIL GOOD RAR BOTH MLG TINES WITH NEW. CHNAD95-26-13 VIA INSTALLING 2 NEW OIL COOLER HOSES:
certify th	at the ELT has	been inspe	eted in accord	C. CABLE AIRPORT STATION AJ4R052M ance with the requirements a satisfactory condition. W/O	

2876,95 Hrs SEPT Date: 2010 S Tach Time: 24

FAA Reg: N- 16 484

inspected as defined under Title 14 CFR - Parts 91 & 43, along with all other applicable FARs, manufacturers maintenance manuals and check-lists. All lube points were attended to, per manufactures maintenance lubrication charts. I CERTIFY THAT THIS PROPELLER WAS INSPECTED INSPECTION AND HAS BEEN DETERMINED TO BE IN AN IN ACCORDANCE WITH REQUIREMENTS OF AN ANNUAL AIRINORTHY CONDITION AT THIS TIME AND DATE AND RETURNED TO SERVICE:

Charles L. "Roy" Downing - 1/A A & P 1882364

Prp TSOH: @EM Hrs Prop T/T: 2876.9 Hrs 76.93 Hrs 572.6 Hrs Tach Time: 2 Date: 20 10 Eng TSOH:

Afrm T/T: 2876.9 Hrs Eng T/T: 2876.9 Hrs FAA Reg: N- 16484

Wing Airframe was attended to, per manufactures maintenance lubrication charts. maintenance manuals and check-lists. All lube points were This Air Vehicle Tike \(\mathcal{L}_1 \in \mathcal{L}_1 \in \mathcal{L}_2 \) Wing Airframe inspected as defined under Title 14 CFR - Parts 91 & 43, along with all other applicable FARs, manufacturers

I CERTIFY THAT THIS AIRFRAME WAS INSPECTED IN ACCORDANCE WITH REQUIREMENTS OF AN ANNUAL INSPECTION AND HAS BEEN DETERMINED TO BE IN AN AIRWORTHY CONDITION AT THIS TIME AND DATE AND RETURNED TO SERVICE:

Charles L. "Roy" Downing - 1/A A & P 1882364

		8		
YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
9-184	o FAC	N, D	276.93	ACAMON CONTRACTOR CONT
-		SALESTAN	12000000	SERVICED LAWA 100 INSPECTION. EN
				AD 75-24 02 - VISUAL INERECTION OF BEAR SENTE
				3-11. ALL CONTROLS LUEGO, HORSONTALTAR
				THER SCREW LUBRA!
				THE CONTRACTOR AND SAME
			ō	AND AD CHAPTER TREDER UPLAND, CA DEL
-				
_				

long with all other applicable FARs, manufacturers Parts ! SOH:

ittended to, per manufactures maintenance lubrication charts I CERTIFY THAT THIS AIRFRAIME WAS INSPECTED naintenance manuals and check-lists. All lube points were **DETERMINED TO BE IN ACCORDANCE WITH REQUIREMENTS NSPECTION AND**

1882 Ö

Inspections, Tests, Repairs and Alterations
Indorsed with Name, Rating and Certificate Number of Technician or Repair
Indoped pages for other specific entries.)

Thus Actually (NSPECTED AND

THIS ACREPATT (NSPECTED AND

SERVICES LAW A 100 MR INSPECTION

CW AD 75-24-02 13CEGION OF

READ SEAT. AD 99-3440 STAND

BY VACUUM ZYSEM FUEL PANOL2

1403FS REFLICED OF ALL CONTROLS

LUBS ELEVATOR THE TALK

SCREW LUBED, ELT REPORTED INE

10-13

YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repairs. Facility. (See back pages for other specific entries.)
	0.00	5018	a Tak	Series Court Visit Court
	Cally Comments	1 -0.01	0.12	
	- 3 32	1	- 3-12	EVICE HOLD TO THE PERSON OF TH
	nin,	5 . FF	O.F.C.	TOTAL SALES STATE OF THE SALES S
3 341	\$ 35kg	B 19	D. 1	also being the second of the s
	10000	1900	13,00 \$	
1133	7 31 7	EV. 9		
46			639	Id wast 7
	July 1			
156	1987 14	33 8	3. S.	

YEAR: RECORDING TODAY'S TOTAL Description of Inspection	ons, Tests, Repairs and Alterations
Date: 2013 MAR 1 FAA Reg: N- 16484	Name, Rating and Certificate Number of Technician or Repair her specific entries.)
Tach Time: 2925. (Hrs Afrm T/T: 2925. (Hrs Eng TSOH: 640.8 Hrs Eng T/T: 2925. Hrs Prop TSOH: 0Em Hrs Prop T/T: 2925. Hrs	THU AIRCRAFT INSPECTED
This Air Vehicle FINED Wing Airframe was inspected as defined under Title 14 CFR - Parts 91 & 43,	(NSFECTED, CW AD-75 2402
along with all other applicable FARs, manufacturers maintenance manuals and check-lists. All lube points were attended to, per manufactures maintenance lubrication charts.	PEHR SEM AD 99 24410 STANDER
I CERTIFY THAT THIS AIRFRAME WAS INSPECTED IN ACCORDANCE WITH REQUIREMENTS OF AN ANNUAL INSPECTION	BRAK HOSES REPLACED ALL
AND HAS BEEN DETERMINED TO BE IN AN AIRWORTHY CONDITION AT THIS TIME AND DATE AND RETURNED TO SERVICE:	TRIM JACK SCREW LUBED
Roll of 3	ELT DUE, 10-13.
Charles L. "Roy" Downing – I/A A & P 1882364	Al 53439, 2081

YEAR: RECORDING TODAY'S TOTAL

EAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Ins Entries must be endors	sed with Name, Rat	ing and Certifica	chnician or Repair
ATE				Facility. (See back pag	es for other specific	entries.)	
	MAKE: PIPER MODEL: PA-28-180 S/N: 28-7305264 REG. NO: 16484 WORK ORDER: 14505-07-2013		Re 174	pothill Aircraft Sales & Service, pair Station No. AJ4R052M 49 W 13Th St land, CA 91786 one: 909-985-1977	Inc.	DATE: 7/23/2013 A/C TSN: 2929.6 TACH: 2929.6	
	Airframe Entr	ies					
3.60	MAINS WITH I NEW,THEN R FITTINGS. OP	RAKE LININ NEW. REPA EINSTALLE S. CK. NO L L S WITH N E	GS ON BOTH I CK WHEEL BE D PROPELLER EAKS NOTED. EW MS1251B5	TUBE (3) INSTALLED NEW MAINS WITH NEW (5) REF EARINGS (6) REPLACED A L (7) WORKED PRIMER SE (9) CAW AD 2013 02 13 BY STURN BARRELS (11) CA T IS OVER .20	PLACED BRAKE DIS ALTERNATOR BELT EVERAL TIMES, TIG	CS ON BOTH WITH HTENED	
3 ST		IRCRAFT 164 as of the Feder	at Waterini Describ	d/ repaired in accordance with the ations and was found Airworthy for Order No. 14505-07-2013, Dated		ance manual and nent details of the	
	DATE: 7/23/2013		SIGNED:	Money	/ Work Ore	der: 14505-07-2013	
			Don Wade Certified Repair	Station No. AJ4R052M	Printed by EBis 3	3 (datcomedia.com)	
		1450	1300	E BRANCO CONTRACTOR			
		Contract of the Contract of th					

.

nd Alterations Foothill Aircraft Sales & Service, Inc. DATE: 8/23/2013 MAKE: PIPER A/C TSN: 2937.82 MODEL: PA-28-180 icate Number of Technician or Repair Repair Station No. AJ4R052M TACH: 2937.82 S/N: 28-7305264 1749 W 13Th St REG. NO: 16484 Upland, CA 91786 WORK ORDER: Phone: 909-985-1977 14581-08-2013 Airframe Entries (1) INSTALL HOBBS METER, AND OIL PRESSURE SWITCH. Maintenance Release I certify that the AIRCRAFT 16484 was repaired in accordance with the manufactoures maintenance manual and current - FARs rules of the Federal Aviation Regulations and was jound Airworthy for return to service. Pertinent details of the repair are on file at this repair station under Work Order No. 14881-08-2013, Dated 8/23/28/13. DATE: 8/23/2013 SIGNED: Work Order: 14581-08-2013 Don Wade Printed by EBis 3 (datcomedia.com) Certified Repair Station No. AJ4R052M 1 of 1

R:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE Descrip Entries m	nust be endorsed with Name, Rating and Certific	d Alterations ate Number of Technician or Repair
E			MAKE: PIPER MODEL: PA-28-180 S/N: 28-7305264 REG. NO: 16484 WORK ORDER: 14595-09-2013 Airframe Entries (2) UPDATED WEIGH REMOVED MAIN WH	Foothill Aircraft Sales & Service, In Repair Station No. AJ4R052M 1749 W 13Th St Upland, CA 91786 Phone: 909-985-1977 HT AND BALANCE FOR SKYTEC STARTER AND HEEL FAIRINGS. (SEE NEW W & B SHEET)	TACH: 2938.21
			current FARs rules of the	FT 16484 was inspected/ repaired in accordance with the respected Aviation Regulations and was found Airworthy for repair station under Work Order No. 14595-09-2013, Dated 9	eturn to service. Pertinent details of the
				Mike Hartman Certified Repair Station No. AJ4R052M	Printed by EBis 3 (datcomedia.com)
		odel #35		aircraft battery and replaced with n	

EAR:	R MAKE: PIPER T MODEL: PA-28-180 T S/N: 28-7305264 REG. NO: 16484 WORK ORDER: 14673-10-2013	Repair Station No. AJ4R0 1749 W 13Th St Upland, CA 91786 Phone: 909-985-1977	Sales & Service, Inc.	DATE: 10/25/2013 A/C TSN: 2978.3 TACH: 2978.3	ions er of Technician or Repair
	Airframe Entries				
	(1) COMPLIED WI	TH 50 HOUR INSPE	CTION.		
	current FARs rules of	RAFT 16484 was inspe the Federal Aviation Reg		the manufactoures maintenance manual and for return to service. Pertinent details of the ted 10/25/2013.	
	DATE: 10/25/2013	SIGNED: \	XVIII ing	Work Order: 14673-10-2013	
	DATE: 10/25/2013	Don Wade	air Station No. AJ4R052M	Work Order: 14673-10-2013 Printed by EBis 3 (datcomedia.com)	
	DATE: 10/25/2013	Don Wade	air Station No. AJ4R052M		
	DATE: 10/25/2013	Don Wade	air Station No. AJ4R052M		
	DATE: 10/25/2013	Don Wade	air Station No. AJ4R052M		
	DATE: 10/25/2013	Don Wade	air Station No. AJ4R052M		
	DATE: 10/25/2013	Don Wade	air Station No. AJ4R052M		

YEAR:	RECORD! TACH	MAKE: PIPER MODEL: PA-28-180	Foothill Aircraft Sales & Service, Inc.	DATE: 11/8/2013 A/C TSN: 2986.23	hnician or Repair
DATE	TIME	S/N: 28-7305264 REG. NO: 16484 WORK ORDER: 14691-11-2013	Repair Station No. AJ4R052M 1749 W 13Th St Upland, CA 91786 Phone: 909-985-1977	TACH: 2986.23	
		Airframe Entries			
		(1) REPLACED LI M.M CHAPTER 3 PA28-180 M.M CH	H MAIN TIRE WITH RETREAD BY DRESSER TIRE 2 (2) RESEALED RH MAIN BRAKE CALIPER AN HAPTER 32.	6.00X6-6PLY IAW PIPER PA28-180 D BLED BRAKE SYSTEM IAW PIPER	
		Maintenance Release I certify that the AIRCRAFT 16484 was repaired in accordance with the manufactoures maintenance manual and current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair station under Work Order No. 14691-11-2013, Dated 11/8/2013. DATE: 11/8/2013 SIGNED: Work Order: 14691-11-2013			
			Joe Caliva Certified Repair Station No. AJ4R052M	Printed by EBis 3 (datcomedia.com)	
			1 of 1		

YEAR: DATE	RECORDIN TACH TIME	MAKE: PIPER MODEL: PA-28-180 S/N: 28-7305264 REG. NO: 16484 WORK ORDER: 14694-11-2013	Foothill Aircraft Sales & Service, Inc. Repair Station No. AJ4R052M 1749 W 13Th St Upland, CA 91786 Phone: 909-985-1977	DATE: 11/12/2013 A/C TSN: 2989.2 TACH: 2989.2	nician or Repair	
		Airframe Entries				
		(1) REMOVED, CLEANED, TESTED AND REINSTALLED #1 CYL LOWER SPARK PLUG. INSTALLED NEW INTAKE GASKET IN #3 CYL				
		Maintenance Release I certify that the ENGI rules of the Federal A file at this repair station				
		DATE: 11/12/2013	SIGNED: pile latto	Work Order: 14694-11-2013		
			Mike Hartman Certified Repair Station No. AJ4R052M	Printed by EBis 3 (datcomedia.com)		
			1 of 1			

YEAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repairs
FAR 91.4 with FAR transpond	hat the altimeter system has been 111 and FAR 91. R 43 Appendix E der tests and inspected to: 20, 20, 20, 20, 20, 20, 20, 20, 20, 20,	and F; altimeterions.	nspected as per nd to comply eter and	Facility. (See back pages for other specific entries.)
1/49 W. I.	ast Radio CRS X 8 th St. A 91786 (909) 98			

				J. Altovations
YE	MAKE: PIPER MODEL: PA-28-180	Foothill Aircraft Sales & Service, Inc.	DATE: 1/6/2014 A/C TSN: 3024.42 TACH: 3024.42	Alterations Ite Number of Technician or Repair
DA	S/N: 28-7305264 REG. NO: 16484 WORK ORDER: 14778-12-2013	Repair Station No. AJ4R052M 1749 W 13Th St Upland, CA 91786 Phone: 909-985-1977	TACH. 3024.42	27AG
	Airframe Entries			
	SECTION III INSPE	ISPECTION ON THIS AIRFRAME IAW FAR 43 AF CTION CHECKLIST AS A GUIDE. C/W FAR 9/1.2 CK. ELT BATTERY EXPIRATION DATE 9/2015. A PLACED BOTH HINGE PINS ON ENTRY DOOR TH NEW.	ADS CHECKED THROUGH	
	per the manufactures m Airworthy for return to s 14778-12-2013, Dated	1,110	Aviation Regulations and was found pair station under Work Order No.	
_	DATE: 1/6/2014	SIGNED: JASH V Lab	Work Order: 14778-12-2013	
		Joe Caliva Certified Repair Station No. AJ4R052M	Printed by EBis 3 (datcomedia.com)	
_		1 of 1		
_				

YEAR: DATE	RECORDING TACH TIME	MODEL: PA-28-180 S/N: 28-7305264 REG. NO: 16484 WORK ORDER: MODEL: PA-28-180 A/C TSN: 3024.42 TACH: 3024.42 TACH: 3024.42	ician or Repair
		14794-01-2014 Opinin, CA 91788 Phone: 909-985-1977 Airframe Entries (1) REMOVED DG 1U262-003-14 S/N T48581K INSTALLED OVERHAULED 1U262-003-14 S/N T547833K, GROUND RUN, SYSTEM CHECKS GOOD.	
		Maintenance Release I certify that the AIRCRAFT 16484 was repaired in accordance with the manufactoures maintenance manual and current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair station under Work Order No. 14794-01-2014, Dated 1/9/2014.	
		DATE: 1/9/2014 SIGNED: Work Order: 14794-01-2014 Joe Calive Certified Repair Station No. AJ4R052M Printed by EBis 3 (datcomedia.com)	
		1 of 1	

YEAR:	RI MAKE PIPER Southill Airgray Color 2	
DATE	TJ MAKE: PIPER MODEL: PA-28-180 TI S/N: 28-7305264 REG. NO: 16484 WORK ORDER: 14875-02-2014 MAKE: PIPER MODEL: PA-28-180 Foothill Aircrest Soles & Corvice, Inc. PAGE: 3/11/2014 A/C TSN: 3067.92 TACH: 3067.92 TACH: 3067.92 TACH: 3067.92 TACH: 3067.92	r of Technician or Repair
	Airframe Entries	
	(1) COMPLIED WITH 50 HOUR INSPECTION. CHECKED FLIGHT CONTROL OPERATIONS, BRAKE FLUID, TIRE PRESSURES, AND OVERALL CONDITION. GROUND RUN, SYSTEMS CHECK GOOD (3) REPLACED TIRE WITH RECAP, AND REPLACED TUBE WITH NEW (4) REPLACED STALL WARNING LAMP WITH NEW (5) INSTALL FUEL SHUT OFF VALVE COVER PLATE (7) REPLACED OLD FUEL SELECTOR VALVE WITH NEW PIPER FUEL VALVE, S/N 11648. FILLED BOTH FUEL TANKS, NO LEAKS NOTED, OPS. CK. GOOD.	
	Maintenance Release I certify that the AIRCRAFT 16484 was inspected/ repaired in accordance with the manufactoures maintenance manual and current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair station under Work Order No. 14875-02-2014, Dated 3/11/2014. DATE: 3/11/2014 SIGNED: Work Order: 14875-02-2014 Don Wade	
	Certified Repair Station No. AJ4R052M Printed by EBis 3 (datcomedia.com)	
	1 of 1	

Foothill Aircraft Sales & Service, Inc.

Repair Station No. AJ4R052M 1749 W 13Th St Upland, CA 91786 Phone: 909-985-1977 DATE: 6/18/2014 A/C TSN: 3123.15 TACH: 3123.15

CAS WALLEY

nd Alterations

ficate Number of Technician or Repair

Airframe Entries

(1) C/W ANNUAL/100 INSPECTION ON THIS AIRCRAFT IAW FAR 43 APPENDIX D USING PIPER M.M SECTION III INSPECTION CHECKLIST AS A GUIDE. ELT BATTERY EXPIRATION DATE SEP 2015. ADS CHECKED THROUGH 08/28/2013. REPLACED AIR INDUCTION FILTER WITH NEW.... (4) REPLACED ALTERNATOR BRACKET AFTER REPAIR, REINSTALLED ALTERNATOR AND SET BELT TENSION.... (5) C/W AD75-24-02 REAR SEAT LEGS PER SERVICE LETTER #763, REAR SEAT CHECK GOOD.... (6) REPLACED LANDING LIGHT WIRE IN LOWER COWLING WITH NEW.

Maintenance Release

I certify that the aircraft and/or component(s) on 16484 was repaired and inspected in accordance with a Annual inspection per the manufactures maintenance manual and current FARs rules of the Federal Aviation Regulations and was found 15033-06-2014, Dated 6/18/2014.

DATE: 6/18/2014

SIGNED:

Joe Caliva

Work Order: 15033-06-2014

Certified Repair Station No. AJ4R052M

Printed by EBis 3 (datcomedia.com)

EAR:	MAKE: PIPER MODEL: PA-28-180 S/N: 28-7305264 REG. NO: 16484 WORK ORDER:	Foothill Aircraft Sales & Service, Inc. Repair Station No. AJ4R052M 1749 W 13Th St Upland, CA 91786	DATE: 7/28/2014 A/C TSN: 3177.5 TACH: 3177.5	ations ber of Technician or Repai
AIE	15088-07-2014	Phone: 909-985-1977		
	Airframe Entries			
	FLUID, TIRE PRESS	H 50 HOUR INSPECTION. CHECKED FLIGHT C FURES, AND OVERALL CONDITION. GROUND RAKE LININGS WITH NEW P/N 066-105.	CONTROL OPERATIONS, BRAKE RUN, SYSTEMS CHECK GOOD (3)	
	Maintenance Release I certify that the AIRCRA	FT 16484 was inspected/ repaired in accordance with t	the manufactoures maintenance manual and	
	repair are on the at this r	e Federal Aviation Regulations and was found Airworthy epair station under Work Order No. 15088-07-2014, Date	for return to service. Pertinent details of the ed 7/28/2014.	
	repair are on file at this r	e Federal Aviation Regulations and was found Airworthy epair station under Work Order No. 15088-07-2014, Date SIGNED:	for return to convice Destinant details of the	
	repair are on the at this r	e Federal Aviation Regulations and was found Airworthy epair station under Work Order No. 15088-07-2014, Date	for return to service. Pertinent details of the ed 7/28/2014.	
	repair are on the at this r	e Federal Aviation Regulations and was found Airworthy epair station under Work Order No. 15088-07-2014, Date SIGNED:	for return to service. Pertinent details of the ed 7/28/2014. Work Order: 15088-07-2014	
	repair are on the at this r	e Federal Aviation Regulations and was found Airworthy epair station under Work Order No. 15088-07-2014, Date SIGNED:	for return to service. Pertinent details of the ed 7/28/2014. Work Order: 15088-07-2014	
	repair are on the at this r	e Federal Aviation Regulations and was found Airworthy epair station under Work Order No. 15088-07-2014, Date SIGNED:	for return to service. Pertinent details of the ed 7/28/2014. Work Order: 15088-07-2014	

**

EAR:	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Tec Facility. (See back pages for other specific entries.)	hnician or Re
	Advanta LOG IDa N16484		- cary 2014	errill Ave. Box 20 Hangar A-240 Chino, CA 91710 VZKR081Y WO# 6551 AC TT 3109.9 PIPER PA-28-180 TACH 3109.9	Pg 1 / 1
			raft: Audio		
	- For more	informati	ion, see FAA	GMA 340, Garmin GNS 430 form 337. Dated 07/22/14	
	Mark Krue		7		
		THE REAL PROPERTY.		Committee of the Commit	

	Weight / Balance & Equi Advantage Avionics 7000 Merrill Ave. Box 2 Chino, CA 91710 Tel:	- VZKR081Y), Hangar A-240	me, Rating and Certificate Number of Technician or Rep specific entries.)		
	ort Garza Alta Loma Drive ho Cucamonga, CA 91701-4028	A/C S A/C Se WO WE	Make: PIPE Model: PA-2 erial #: 28-73 Ref #: 6551 3 Date: Jun-0 B ID #: 435	8-180 305264	
Previous data taken from	n document dated Sep-04-2013 Previou	s useful load = 988.00			
Model # REMOVED ITEMS ———	Description Previou	(LB/IN) Weight s data -> 1462,00	CG/Arm 86.55	Moment 126533.60	
AUDIO PANEL COM 810 NAV 121	AUDIO PANEL COM NAV	-1.20 -2.90 -3.00	57.00 57.00 57.00	-68.40 -165.30 -171.00	
REMOVED SUB TOTAL	3 Items @	-7.10	57.00	-404.70	
GI 106A	Course Deviation Indicator GI 1064	1.40	57.00	79.80	
GMA 340	Garmin Audio Panel GMA 340	1.70	57.00	96.90	
GNS 430	GPS/NAV/COM GNS 430	6,70	57,00	381,90	
INSTALLED SUB TOTAL	3 Items @	9.80	57.00	558.60	
It is the responsibility of the	NEW USEFUL LOAD = 985.30 e data is calculated data based on most curr aircraft owner/operator and the pilot to insur nce are the responsibility of the aircraft owner	e that the aircraft is properly	86,49 d, loaded, All subs	126687,50 sequent	

	INC TORAVIO TOTAL	The second secon	
MAKE: PIPER MODEL: PA-28-180	Foothill Aircraft Sales & Service, Inc.	DATE: 8/28/2014	nd Alterations
S/N: 28-7305264 REG. NO: 16484 WORK ORDER: 15140-08-2014	Repair Station No. AJ4R052M 1749 W 13Th St Upland, CA 91786 Phone: 909-985-1977	A/C TSN: 3222.76 TACH: 3222.76	icate Number of Technician or Repa
Airframe Entries			
(1) C/W ANNUAL SECTION III INSP	100 INSPECTION ON THIS AIRCRAFT IAW FAR 4 PECTION CHECKLIST AS A GUIDE. ELT BATTERY FUGH 08/27/2014.	3 APPENDIX D USING PIPER M.M. EXPIRATION DATE 9/ 2015. ADS	
Maintenance Release	e aft and/or component(-) - 40.00		
per the manufactures Airworthy for return to 15140-08-2014, Date	aft and/or component(s) on 16484 was repaired and inspecte maintenance manual and current FARs rules of the Federal poservice. Pertinent details of the repair are on file at this repaired 8/28/2014.	d in accordance with a Annual inspection Aviation Regulations and was found	
10170-00-2014, Date	0 8/28/2014.	air station under Work Order No.	
DATE: 8/28/2014	SIGNED: Joh //	Work Order: 15140-08-2014	
	1.11	all station under Work Order No.	
	SIGNED: Joh / Colla	Work Order: 15140-08-2014	
	SIGNED: Joh / Colla	Work Order: 15140-08-2014	
	SIGNED: Joh / Colla	Work Order: 15140-08-2014	
	SIGNED: Joh / Colla	Work Order: 15140-08-2014	

MAKE: PIPER MODEL: PA-28-180 S/N: 28-7305264 REG. NO: 16484 WORK ORDER: 15185-10-2014

Foothill Aircraft Sales & Service, Inc.

Repair Station No. AJ4R052M 1749 W 13Th St Upland, CA 91786 Phone: 909-985-1977 DATE: 10/6/2014 A/C TSN: 3272.76 TACH: 3272.76

d	A	te	ra	ti	O	ns
						-

cate Number of Technician or Repair

Airframe Entries

(1) COMPLIED WITH 50 HOUR INSPECTION ON AIRCRAFT.

Maintenance Release

I certify that the AIRCRAFT 16484 was repaired in accordance with the manufactoures maintenance manual and current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair station under Work Order, No. 15185-10-2014, Dated 10/6/2014.

In Wand

DATE: 10/6/2014

SIGNED:

Work Order: 15185-10-2014

Don Wade

Certified Repair Station No. AJ4R052M

Printed by EBis 3 (datcomedia.com)

EAR:	RECORDING TACH TIME	TODAY'S TOTAL Description of Inspections, Tests, Repairs and Alterations					
ATE		MAKE: PIPER MODEL: PA-28-180 S/N: 28-7305264 REG. NO: 16484 WORK ORDER: 15236-11-2014 Airframe Entries Foothill Aircraft Sales & Service, Inc. DATE: 11/7/2 A/C TSN: 3320 TACH: 3320 TACH: 3320 A/C TSN: 3320 TACH: 3320 Airframe Entries	ian or Repair				
		(1) C/W ANNUAL INSPECTION ON THIS AIRFRAME IAW FAR 43 APPENDIX D USING PIPER M.M. SECTION III INSPECTION CHECKLIST AS A GUIDE. ELT BATTERY EXPIRATION DATE 9/2015. ADS CHECKED THROUGH 11/07/2014. REPLACED AIR INDUCTION FILTER WITH NEW. CLEANED, INSPECTED, AND GREASED MAIN WHEEL BEARINGS. Maintenance Release I certify that the aircraft and/or component(s) on 16484 was repaired and inspected in accordance with a Annual inspection per the manufactures maintenance manual and current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair station under Work Order No. 15236-11-2014, Dated 11/7/2014.					
		DATE: 11/7/2014 SIGNED: Work Order: 15236-11-20 Joe Calive Printed by EBis 3 (datcomedia.com					
1		1 of 1					

YEAR: DATE	RECORDING TACH TIME	TODAY'S FLIGHT	MAKE: PIPER MODEL: PA-28-180 S/N: 28-7305264 REG. NO: 16484 WORK ORDER: 15301-12-2014 Airframe Entries	Foothill Aircraft Sales & Service, Inc. Repair Station No. AJ4R052M 1749 W 13Th St Upland, CA 91786 Phone: 909-985-1977 TH 50 HOUR INSPECTION. CHECKED FLIGHT CONSSURES, AND OVERALL CONDITION (5) INSTAL	DATE: 12/19/2014 A/C TSN: 3375.55 TACH: 3375.55 TACH: 3375.55 NTROL OPERATIONS, BRAKE LED A NEW TRANSPONDER	pair
				RAFT 16484 was inspected/ repaired in accordance with the the Federal Aviation Regulations and was found Airworthy for is repair station under Work Order No. 15301-12-2014, Dated SIGNED: Don Wade Certified Repair Station No. AJ4R052M		
				1 of 1		

YEAR: DATE	RECORDING TACH TIME	MAKE: PIPER MODEL: PA-28-180 FI S/N: 28-7305264 REG. NO: 16484 WORK ORDER: 15330-01-2015	Foothill Aircraft Sales & Service, Inc. Repair Station No. AJ4R052M 1749 W 13Th St Upland, CA 91786 Phone: 909-985-1977	DATE: 1/9/2015 A/C TSN: 3391.61 TACH: 3391.61	or Repai
		Airframe Entries (2) ELT TESTED F	PER 91.207(d). DUE AGAIN 01-2016		
		Maintenance Release I certify that the AIRCI FARs rules of the Fed are on file at this repair	RAFT 16484 was repaired in accordance with the manufactorial Aviation Regulations and was found Airworthy for return station under Work Order No. 15330-01-2015, Dated 1/9/	ctoures maintenance manual and current in to service. Pertinent details of the repair (2015)	
		DATE: 1/9/2015	SIGNED: And Parts	Work Order: 15330-01-2015	
			Mike Hartman Certified Repair Station No. AJ4R052M	Printed by EBis 3 (datcomedia.com)	
			1 of 1		

RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Facility. (See back pages for other specific entries.)	
LOG ID# 20	98 04-Ju	7000 Merrill ine-2014 W 05264 PIP	I Ave. Box 20 Hangar A-240 Chino, CA 91710 VZKR081Y /O# 6551 AC TT 3109.9 PER PA-28-180 TACH 3109.9	Pg 1 / 1
Removed fro Audio panel	m aircraft	t:		
Installed in Garmin GMA				
			orm 337. Dated 07/10/14	
Mark Kruege				
- Taraba (1) 379 (1) (1)	March Street			Milita wiele

	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Techn Facility. (See back pages for other specific entries.)
L(OG ID# 2100	15-Januar	ry-2015 VVO	PA-28-180 TACH 3395.7 Pg 1
				l installed Garmin GTX 327.
OF	FAR 43.	TO MOT OTTOTAL	I LEST VIND I	INSPECTION. WALT FOUND TO COMPLY WITH FAR 91.413 AND APPENDIX F
01-	FAR 43.			#: 83750525 .
Per	FAR 43.			
Per	formed on M			
Per	formed on M			

A Children of the Control of the Con

YEAR: DATE	RECORDING TACH TIME	MAKE: PIPER MODEL: PA-28-180 S/N: 28-7305264 REG. NO: 16484 WORK ORDER: 15357-01-2015 Airframe Entries (1) C/W ANNUAL/ INSPECTION CHI Maintenance Release I certify that the aircra	Maintenance Release I certify that the AIRCF current FARs rules of	RAFT 16484 was inspected/	N. CHECKED FLIGHT CON CONDITION.	DATE: 12/19/2014 A/C TSN: 3375.55 TACH: 3375.55 TROL OPERATIONS, BRAKE manufactoures maintenance manual and eturn to service. Pertinent details of the 2/19/2014.
		per the manufactures Airworthy for return to	DATE: 12/19/2014	SIGNED	Vall zall	Work Order: 15301-12-2014
		15357-01-2015, Date DATE: 1/30/2015		Don Wade Certified Repair Sta	ation No. AJ4R052M	Printed by EBis 3 (datcomedia.com)
				1 of 1		

RECORDING TACH TIME	Maintenance Release	Foothill Aircraft Sales & Service, Inc. Repair Station No. AJ4R052M 1749 W 13Th St Upland, CA 91786 Phone: 909-985-1977 100 INSPECTION ON THIS AIRCRAFT IAW FAR 43 APF ECKLIST AS A GUIDE. If and/or component(s) on 16484 was repaired and inspected in accomminate manual and current FARs rules of the Federal Aviation of the Pederal Aviation	ecordance with a Annual inspection
		Don Wade Certified Repair Station No. AJ4R052M	Printed by EBIS 3 (datcomedia.com)

CEDVIC	nce of Maior Repairs and Major Alte	rations To
MAKE: PIPER MODEL: PA-28-180 S/N: 28-7305264 REG. NO: 16484 WORK ORDER: 15410-02-2015 Airframe Entries	Foothill Aircraft Sales & Service, Inc. Repair Station No. AJ4R052M 1749 W 13Th St Upland, CA 91786 Phone: 909-985-1977	DATE: 2/26/2015 A/C TSN: 3476 TACH: 3476
(1) COMPLIED WIT	TH 50 HOUR INSPECTION. CHECKED FLIGHT COSSURES, AND OVERALL CONDITION. GROUND DOOR SEAL WITH NEW (4) REPLACE ATTITU	ONTROL OPERATIONS, BRAKE RUN, SYSTEMS CHECK GOOD (3) DE GYRO WITH OVERHAULED ONE
Maintenance Release I certify that the AIRCR FARs rules of the Fode	AFT 16484 was repaired in accordance with the manufact	
are on file at this repair DATE: 2/26/2015	station under Work Order No. 15410-02-2015, Dated 2/26/	toures maintenance manual and current a to service. Pertinent details of the repair //2015.
are of the at this repair	SIGNED: SIGNED: SIGNED:	Work Order: 15410-02-2015
are of the at this repair	station under Work Order No. 15410-02-2015, Dated 2/26/	/2015.
are of the at this repair	SIGNED: Joe Caliva	Work Order: 15410-02-2015

YEAR:	TOTAL TIME IP SERVII	Refere	ence of Major Repairs and Major Alte	rations To	A STATE OF THE STA
DATE	MAKE: MODEL S/N: 28 REG. N WORK	PIPER .: PA-28-180 -7305264 IO: 16484 ORDER: 03-2015	Foothill Aircraft Sales & Service, Inc. Repair Station No. AJ4R052M 1749 W 13Th St Upland, CA 91786 Phone: 909-985-1977	DATE: 4/8/2015 A/C TSN: 3517.98 TACH: 3517.98	47.0
	(1) C/	TION III INSP	INSPECTION ON THIS AIRFRAME IAW FAR 43 AF ECTION CHECKLIST AS A GUIDE. ELT BATTERY UGH 4/08/2015. REPLACED BOTH LEFT AND RIG	EXPIRATION DATE 9/2015. ADS	
	I certif per the Airwor 15457	manufactures	aft and/or component(s) on 16484 was repaired and inspecte maintenance manual and current FARs rules of the Federal properties. Pertinent details of the repair are on file at this rep	Aviation Regulations and was found	
	DATE	410/2010	Joe Caliva Certified Repair Station No. AJ4R052M	Printed by EBis 3 (datcomedia.com)	
				£	
			1 of 1		

SER	TAL IE IN RVICE	MAKE: PIPER MODEL: PA-28-180 S/N: 28-7305264 REG. NO: 16484	Foothill Aircraft Sales & Service, Inc. Repair Station No. AJ4R052M	DATE: 5/14/2015 A/C TSN: 3579.76 TACH: 3579.76
DATE		WORK ORDER: 15541-05-2015	1749 W 13Th St Upland, CA 91786 Phone: 909-985-1977	
		Airframe Entries		
			TH 50 HOUR INSPECTION. CHECKED FLIGHT COSURES, AND OVERALL CONDITION. GROUND I	
		current FARs rules of t	RAFT 16484 was inspected/ repaired in accordance with the Federal Aviation Regulations and was found Airworthy f	or return to service. Pertinent details of the
		repair are on file at this DATE: 5/14/2015	s repair station under Work Order No. 15541-05-2015, Date	ed 5/14/2015.
		repair are on file at this	repair station under Work Order No. 15541-05-2015, Date	ed 5/14/2015.
		repair are on file at this	Signed: Signed	Work Order: 15541-05-2015
		repair are on file at this	Signed: Signed	Work Order: 15541-05-2015
		repair are on file at this	Signed: Signed	Work Order: 15541-05-2015

YEAR:	A.D. NUMBER	TOTAL TIME IN SERVICE	Airworthiness Directives Chronological Listing of Compliance and Method of Compliance	1270
DATE				
				A STATE OF THE PARTY OF THE PAR
T. III				
- 3				
1000				
2	LE BUSE W			

	A.D.		***	The second secon
	NUMBER	MAKE: PIPER MODEL: PA-28-180	Foothill Aircraft Sales & Service, Inc.	DATE: 6/17/2015
-		S/N: 28-7305264		A/C TSN: 3618.36
		REG. NO: 16484 WORK ORDER:	Repair Station No. AJ4R052M 1749 W 13Th St	TACH: 3618.36
		15592-06-2015	Upland, CA 91786 Phone: 909-985-1977	
-		Airframe Entries		
		VACUUM REGUL	100 INSPECTION ON THIS AIRCRAFT IAW FAR A ECTION CHECKLIST AS A GUIDE. ELT BATTERY UGH 06/15/2015. REPLACED AIR INDUCTION FIL ATOR FILTER P/N ARB3-5-1 (6) C/W AD75-24-0 AR SEAT CHECK GOOD (7) C/W AD 99-24-10 S	TER WITH NEW (4) REPLACED
		Maintenance Release I certify that the aircra per the manufactures	ft and/or component(s) on 16484 was repaired and inspecte	ed in accordance with a A
		15592-06-2015, Dated	service. Pertinent details of the repair are on file at this rep d 6/17/2015.	air station under Work Order No
		DATE: 6/17/2015	SIGNED:	
			Joe Caliva	Work Order: 15592-06-2015
+			Certified Repair Station No. AJ4R052M	Printed by EBis 3 (datcomedia.com)
			- The state of the	(and a control
+				
			1 of 1	

EAR:	MAKE: PIPER MODEL: PA-28-180	Foothill Aircraft Sales & Service, Inc.	DATE: 7/9/2015 A/C TSN: 3669.9	
ATE	S/N: 28-7305264 REG. NO: 16484 WORK ORDER: 15637-07-2015	Repair Station No. AJ4R052M 1749 W 13Th St Upland, CA 91786 Phone: 909-985-1977	TACH: 3669.9	31/10
	Airframe Entries			
	(1) COMPLIED W FLUID, TIRE PRE	TH 50 HOUR INSPECTION. CHECKED FLIGHT CONTROL SSURES, AND OVERALL CONDITION. GROUND RUN, SY	L OPERATIONS, BRAKE YSTEMS CHECK GOOD. —	
	current FARS rules of	RAFT 16484 was inspected/ repaired in accordance with the manufathe Federal Aviation Regulations and was found Airworthy for return to repair station under Work Order No. 15637-07-2015, Dated 7/9/201	lo soprise Destinant datails of the	
	DATE: 7/9/2015	SIGNED:	Work Order: 15637-07-2015	
		Joe Caliva Certified Repair Station No. AJ4R052M	Printed by EBis 3 (datcomedia.com)	
4				
		1 of 1		

YEAR:	TOT, TIMI	MAKE: PIPER MODEL: PA-28-180	Foothill Aircraft Sales & Service, Inc.	DATE: 8/5/2015 A/C TSN: 3716.1	
DATE	SER	S/N: 28-7305264 REG. NO: 16484 WORK ORDER: 15666-08-2015	Repair Station No. AJ4R052M 1749 W 13Th St Upland, CA 91786 Phone: 909-985-1977	TACH: 3716.1	
		SECTION III INSP	100 INSPECTION ON THIS AIRCRAFT IAW FAR 43 ECTION CHECKLIST AS A GUIDE. ELT BATTERY	EXPIRATION DATE 09/2015. ADs	tional Equipment otional Equipment quired–Exchanged for 0 equired–Exchanged for 0
		Maintenance Release	UGH 08/06/2015 (6) C/W AD 75-24-02 REAR SEAPASS MOUNT WITH NEW. strain of the str		tional Equipment ptional Equipment quired-Exchanged for 0 equired-Exchanged for 0
		per the manufactures	maintenance manual and current FARs rules of the Federal service. Pertinent details of the repair are on file at this repair	Aviation Regulations and was found	tional Equipment otional Equipment quired—Exchanged for 0p oquired—Exchanged for 0p
			Joe Caliva Certified Repair Station No. AJ4R052M	Printed by EBis 3 (datcomedia.com)	tional Equipment otional Equipment quired—Exchanged for Open equired—Exchanged for Open
					tional Equipment ptional Equipment quired—Exchanged for Opin quired—Ex
			1 of 1		ional Equipment stional Equipment quired—Exchanged for Option quired—Exchanged for Option

EAR:	TOTAL TIME IN	MAKE: PIPER	Foothill Aircraft Sales & Service	e, Inc. DATE: 10/1/2015	Appendig to the same
- TE	SERVICE	MODEL: PA-28-180 S/N: 28-7305264 REG. NO: 16484	Repair Station No. AJ4R052M 1749 W 13Th St	A/C TSN: 3814.71 TACH: 3814.71	
ATE		WORK ORDER: 15762-09-2015	Upland, CA 91786 Phone: 909-985-1977		uipment
		Airframe Entries			quipment xchanged for Optional
		(1) C/W ANNUAL INS	SPECTION ON THIS AIRFRAME IAW FAR 43 AF	PPENDIX D USING PIPER M.M.	Exchanged for Optiona
		FUNCTIONAL CHEC CHECKED THROUG	CK. REPLACED ELT BATTERIES WITH NEW, EXIST 10/01/2015. REPLACED AIR INDUCTION FILE	EXPIRATION DATE 12/2018 ADS	uipment quipment xchanged for Optional Exchanged for Optional
		per the manufactures ma	1 . / /	al Aviation Regulations and was found	uipment quipment xchanged for Optional Exchanged for Optional
$\overline{}$	Traves at the	DATE: 10/1/2015	SIGNED: Jet Vla	Work Order: 15762-09-2015	uipment
	S. C. San Street, St. Co.		111	Printed by EBis 3 (datcomedia.com)	quipment
			Joe Caliva Certified Repair Station No. AJ4R052M		xchanged for Optional exchanged for Optional
			Joe Caliva Certified Repair Station No. AJ4R052M		

YEAR:

MA
MC
S/N
DATE


WC
150

Ai

(1)
FL
RI
BI
Occurrer

D/-

MAKE: PIPER MODEL: PA-28-180 S/N: 28-7305264 REG. NO: 16484 WORK ORDER: 15818-11-2015



Repair Station No. AJ4R052M 1749 W 13Th St Upland, CA 91786 Phone: 909-985-1977 DATE: 11/2/2015 A/C TSN: 3866 TACH: 3866

Airframe Entries

(1) COMPLIED WITH 50 HOUR INSPECTION. CHECKED FLIGHT CONTROL OPERATIONS, BRAKE FLUID, TIRE PRESSURES, AND OVERALL CONDITION. GROUND RUN, SYSTEMS CHECK GOOD.... (3) REPLACED LEFT MAIN TIRE TUBE WITH NEW A/H 6.00X6, 6PLY.... (4) REPLACED RIGHT AND LEFT BRAKE LININGS WITH NEW.

Maintenance Release

I certify that the AIRCRAFT 16484 was inspected/ repaired in accordance with the manufactoures maintenance manual and current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair station under Work Order No. 15818-11-2015, Dated 11/2/2015.

DATE: 11/2/2015

SIGNED: Chula Be can

Work Order: 15818-11-2015

Christopher Byars
Certified Repair Station No. AJ4R052M

Printed by EBis 3 (datcomedia.com)

Ition of Optional Equipment noval of Optional Equipment tion of Required-Exchanged for Option noval of Required-Exchanged for Option

tion of Optional Equipment loval of Optional Equipment tion of Required–Exchanged for Option loval of Required–Exchanged for Option

tion of Optional Equipment oval of Optional Equipment tion of Required-Exchanged for Option oval of Required-Exchanged for Option

tion of Optional Equipment oval of Optional Equipment tion of Required—Exchanged for Option oval of Required—Exchanged for Option

tion of Optional Equipment oval of Optional Equipment tion of Required-Exchanged for Option oval of Required-Exchanged for Option

tion of Optional Equipment oval of Optional Equipment tion of Required–Exchanged for Option oval of Required–Exchanged for Option

Notes

Advantage Avionics 7000 Merrill Ave. Box 20 Hangar A-240 Chino, CA 91710 VZKR081Y LOG ID# 2260 07-December-2015 WO# 7169 AC TT 3914.7 N16484 S/N 28-7305264 PIPER PA-28-180 TACH 3914.7

Pg 1/1

Page #: 1

Removed Narco Com 810 and installed in its place GTR 225 Com.

Mark Krueger

Weight / Balance & Equipment List Revision

Advantage Avionics - VZKR081Y

7000 Merrill Ave. Box 20, Hangar A-240 Chino, CA 91710 Tel: 909-606-0220

A/C Tail #: N16484 Register Name: Robert Garza

Name 2 : Address 1 : 8979 Alta Loma Drive

Address 2:

City, State, PC: Rancho Cucamonga, CA 91701-4028

A/C Make: PIPER A/C Model: PA-28-180

A/C Serial #: 28-7305264 WO Ref #: 7169

WB Date: Dec-04-2015

WB ID #: 502

Previous data taken from document dated Jan-15-2015 Previous useful load = 984.57

Description	(LB/IN)	Weight	CG/Arm	Moment
Part #				
	r revious data ->	1405,43	86.48	126729.11
COM		0.00		
COM 810		-3.20	57.00	-182.40
1 Item @		-3.20	57.00	-182.40
		1 2000		
GTR 225A		3.06	57.00	174.42
1 Item @		0.00		
		3.06	57.00	174.42
NEW USEFUL LOAD = 984.7		1465.29	86.48	126721.13
data i palaulata duluta birili				120121.10
	Part # COM COM 810 1 Item @ Com Radio GTR 225A 1 Item @ NEW USEFUL LOAD = 984.7	Part # Previous data -> COM COM 810 1 Item @ Com Radio GTR 225A 1 Item @ NEW USEFUL LOAD = 984.71	Part # Previous data -> 1465.43 COM	Part # Previous data -> 1465.43 86.48 COM

es	MAKE PAIPER	Foothill Aircraft Sales & Service, Inc.	
	MODEL PAZ8-180	Repair Station No. AJ4R052M	
	REG # 11/6494	1749 W. 13th St	
	WORK ORDER	Upland, CA 91786	
		909 985-1977	
	DATE /2/01/2015		
	Airframe Entries		
		TRANSPONDED HAS BEEN TESTED AS BEQUIDED BY FAR OF ALL AND	
	WAS FOUND TO COMPLY	TRANSPONDER HAS BEEN TESTED AS REQUIRED BY FAR 91.413 AND	
	WAS FOUND TO COMPLY WAS FO	WITH FAR. APPENDIX F.	
	#2 TRANSPONDER		
	I CERTIFY THAT THE ALTIMET	TER AND ALTITUDE REPORTING EQUIPMENT HAVE BEEN TESTED AS	
	REQUIRED BY FAR 91.411.	AND WERE FOUND TO COMPLY WITH FAR 43, APPENDIX F	
	PILOTS ALT. TO: 20,000	FT. #1 ENCODER TO: ZO.000 FT	
	STANDBY ALT. TO:	FT. #2 ENCODER TO: FT.	
	Material		
	Maintenance Release		
	rules of Federal Aviation Regulation	ons and was found Airworthy for return to source. Portion of the manual and current FARs	
7747	file at this repair station under Wor	ons and was found Airworthy for return to service. Pertinent details of the repair are on ork Order No.	
	DATE 12/01/2015		
	DATE / L/U///U/	SIGNED ()	
	DAIE	SIGNED CLAM III	
	DAIE	The ball	
	DAIE	Joe Caliva Certified Repair Station No. AJ4R052M	

N 16484

6-8-06

Aero Accessories, Inc. warrants that the Tempest Dry Air Pumps or Tempest Auxiliary Pumps sold by it are free from defects in material and workmanship. The warranty covers the AA3215CC and AA3216CW series new pumps for period of (3) years or 1300 hours from the time of installation or for a period of (4) years from the date of manufacture whichever occurs first. Aero Accessories' warranty covers the AA240 and the AA400 series of new dry air pumps for a period of (1) year or 500 hours from the time of installation or for period of (4) years from date of manufacture whichever occurs first.

Aero Accessories' warranty covers the AA4A2-1 and AA4A3-1 Tempest auxiliary pumps for a period of 2 years or 250 hours from the time of installation or (3) years from the date of manufacture whichever occurs first.

Aero Accessories' obligation under this warranty is limited to the replacement of any product which is returned for warranty consideration and upon inspection by Aero Accessories, Inc. is found to be defective in material or workmanship.

Torest 2756.

S/N 39143

