

ASA-SA-1

gistere	MAKE MOBILEY MODEL MZO	Foothill Aircraft Sales & Service, Inc. Repair Station No. AJ4R052M
	REG # N7164V WORK ORDER	1749 W. 13th St Upland, CA 91786
	DATE 07/13/2016	909 985-1977
	Airframe Entries (1) I CERTIFY THAT THE ATC TRANSPONDER H. WAS FOUND TO COMPLY WITH FAR. APPEND #1 TRANSPONDER	AS BEEN TESTED AS REQUIRED BY FAR 91.413 AND DIX F.
•	#2 TRANSPONDER	REPORTING EQUIPMENT HAVE BEEN TESTED AS
•	PILOTS ALT. TO: Za/600 FT. STANDBY ALT. TO: FT.	#1 ENCODER TO: Z4000 FT #2 ENCODER TO: FT.
e	Maintenance Release I Certify that the AIRCRAFT - was inspected in accordance rules of Federal Aviation Regulations and was found Air file at this repair station under Work Order No. DATE	ce with the manufactures maintenance manual and current FARs worthy for return to service. Pertinent details of the repair are on
e	100	e Caliva ertified Repair Station No. AJ4R052M

MAKE: MOONEY Foothill Aircraft Sales & Service, Inc. DATE: 11/3/2018 MODEL: M20F A/C TSN: 3754.3 S/N: 22-0073 Repair Station No. AJ4R052M TACH: 3754 3 REG. NO: 7164V 1749 W 13Th St WORK ORDER: Upland, CA 91786 17580-10-2018 Phone: 909-985-1977 Airframe Entries (1) C/W ANNUAL INSPECTION ON THIS AIRFRAME IAW FAR 43 APPENDIX D USING MOONEY M20F. M M CHAPTER 5 INSPECTION CHECKLIST AS A GUIDE. C/W FAR 91,207 D ELT INSPECTION AND FUNCTIONAL CHECK. ELT BATTERY EXPIRATION DATE 07-2019. ADs CHECKED THROUGH 11-2018. REPLACED AIR INDUCTION FILTER WITH NEW P/N BA-6305.... (4) C/W AD 2015-19-07 FUEL INJECTION LINES INSPECTION IAW LYCOMING S/B 342F. NO DEFECTS NOTED AT THIS TIME. NEXT INSPECTION DUE IN 100 HRS OR NEXT ANNUAL WHICHEVER COMES FIRST (5) C/W AD 76-07-12R1 BENDIX IGNITION SWITCHES BY OPERATIONAL CHECK IAW BENDIX S/B 583, NO DEFECTS NOTED AT THIS TIME. NEXT INSPECTION DUE IN 100 HRS.... (7) C/W AD 73-21-01 LUBRICATION OF ALL FLIGHT CONTROL SYSTEM AND LANDING GEAR ROD ENDS IAW MOONEY S/B M20-155.... (10) REPLACED ENCODER WITH NEW ACK A30.5. LEAK TEST GOOD (11) REPLACED NOSE TIRE AND TUBE WITH NEW Maintenance Release I certify that the aircraft and/or component(s) on 7164V was repaired and inspected in accordance with a Annual inspection per the manufactures maintenance manual and current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair station under Work Order No. 17580-10-2018, Dated 11/3/2018.

DATE: 11/3/2018

Adrian Arias

Certified Repair Station No. AJ4R052M

1 of 1

Work Order: 17580-10-2018

Printed by EBis 3 (datcomedia.com)

Notes

YEAR DATE: 12/20/2019 Foothill Aircraft Sales & Service, Inc. MAKE: MOONEY A/C TSN: 3778.8 20 MODEL: M20F TACH: 3778.8 Repair Station No. AJ4R052M S/N: 22-0073 DATE 1749 W 13Th St REG. NO: 7164V Upland, CA 91786 WORK ORDER: Phone: 909-985-1977 18196-12-2019 Airframe Entries (1) C/W ANNUAL INSPECTION ON THIS AIRFRAME IAW FAR 43 APPENDIX D USING MOONEY M20F MM CHAFTER 5 INSPECTION CHECKLIST AS A GUIDE. C/W FAR 91.207 D ELT INSPECTION AND FUNCTIONAL CHECK, ELT BATTERY EXPIRATION DATE 12-2022. ADs CHECKED THROUGH 12-2019. REPLACED AIR INDUCTION FILTER WITH NEW P/N BA-6305.... (5) C/W AD 76-07-12R1 BENDIX IGNITION SWITCHES BY OPERATIONAL CHECK IAW BENDIX S/B 583. NO DEFECTS NOTED AT THIS TIME. NEXT INSPECTION DUE IN 100 HRS.... (6) C/W AD 73-21-01 LUBRICATION OF ALL FLIGHT CONTROL SYSTEM AND LANDING GEAR ROD ENDS IAW MOONEY S/B M20-155.... (8) REPLACED LH AND RH FUEL CAP O-RINGS WITH P/N MS29513-338 AND M29513-010 (QTY 2ea)... (9) REPLACED LH AND RH FUEL QTY AND TYPE PLACARDS WITH P/N 150080-055.... (10) REPLACED RH CALIPER O-RING WITH NEW MS28775-224 BLED SYSTEM IAW MOONEY M.M OPS AND LEAK CHECKED GOOD. Maintenance Release I certify that the aircraft and/or component(s) on 7164V was repaired and inspected in accordance with a Annual inspection per the manufactures maintenance manual and current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair station under Work Order No. 18196-12-2019, Dated 12/20/2019 DATE: 12/20/2019 SIGNED Work Order: 18196-12-2019 Adrian Arias Printed by EBis 3 (datcomedia.com) Certified Repair Station No. AJ4R052M 1 of 1

			MAKE: MOONEY	YEAR
2 80 12 8 1 8 8	Inc. DATE: 3/29/2019 — A/C TSN: 3763.4	Foothill Aircraft Sales & Service	MODEL: M20F	20
	TACH: 3763.4	Repair Station No. AJ4R052M 1749 W 13Th St Upland, CA 91786 Phone: 909-985-1977	S/N: 22-0073 REG. NO: 7164V WORK ORDER: 17810-03-2019	DATE
			Airframe Entries	
	AD 77-17-04 BY REMOVING BOTH UND. DUE AGAIN 500 HOURS.	TCH WIRE PILOT SIDE (2) C/W P BOTH SHAFTS. NO CRACKS FO	(1) REPAIRED BROKEN PTT SV CONTROL YOKES. DYE PEN IN TACH 4263.4	
	e manufactoures maintenance manual and return to service. Pertinent details of the 3/29/2019.	inspected/ repaired in accordance with the Regulations and was found Airworthy for Work Order No. 17810-03-2019, Date	current FARs rules of the Federal Avia	
	Work Order: 17810-03-2019	mil Anti	DATE: 3/29/2019 SIGN	
	Printed by EBis 3 (datcomedia.com)	artman d Repair Station No. AJ4R052M		
		repair Station No. A341002M	Celtil	
				- 10 mm
				B. Carlotte B.

tions YEAR mber of Technician or DATE: / /_ MAKE: MOONEY Foothill Aircraft Sales & Service, Inc. 20 A/C TSN: 3812.31 MODEL: M20F Repair Station No. AJ4R052M TACH: 3812.31 S/N: 22-0073 DATE 1749 W 13Th St REG. NO: 7164V Upland, CA 91786 WORK ORDER: Phone: 909-985-1977 18687-01-2021 Airframe Entries (1) C/W ANNUAL INSPECTION ON THIS AIRFRAME IAW FAR 43 APPENDIX D USING MOONEY M20F M.M CHAPTER 5 INSPECTION CHECKLIST AS A GUIDE. C/W FAR 91.207 D ELT INSPECTION AND FUNCTIONAL CHECK, ELT BATTERY EXPIRATION DATE 12-2022. ADs CHECKED THROUGH 01/2021. REPLACED AIR INDUCTION FILTER WITH NEW P/N BA-6305.... (5) SECURED HANGER BLOCK FOR EXHAUST PIPE.... (7) INSTALLED CORRECT TYPE FIRE BOTTLE.... (10) SECURED HARDWARE AT CROSS MEMBER FOR COWL FLAP CONTROL (11) REPLACED RIGHT TIRE WITH NEW (13) REMOVED AND CLEANED RIGHT BRAKE CALIPER. NO DAMAGE NOTED. INSTALLED WITH NEW PACKING AND SECURED (14) SECURED LEFT NAV LIGHT LENS AND COVER (16) REMOVED SURFACE CORROSION AND PAINTED ELEVATOR CONTROL ARMS.... (17) TIGHTENED SET SCREW AT PILOT'S YOKE CONTROL (18) TIGHTENED HARDWARE AT RIGHT AND LEFT YOKE TUBE ATTACHMENT BLOCKS AT "Y" COLUMN.... (20) COMPLIED WITH AD 2015-19-07 BY VISUAL INSPECTION OF ALL INJECTOR LINES AND CLAMPS. CHECKED GOOD PER AD INSTRUCTION. NEXT DUE AT 3912.31 HRS TACH TIME.... (21) IGNITION SWITCH OPS CHECKED GOOD PER AD 76-07-12 R1 INSTRUCTION. NET DUE AT 3912.31 HRS TACH TIME.... (22) COMPLIED WITH AD 73-21-01 BY LUBRICATING FLIGHT CONTROL SYSTEM PER AD INSTRUCTION. NEXT DUE AT 3912.31 HRS. TACH TIME.... (23) COMPLIED WITH AD 75-23-04 PART II BY LUBRICATING LANDING GEAR ACTUATOR. NEXT DUE AT 3912.31 HRS TACH TIME.... (24) C/W PITOT STATIC / TRANSPONDER TEST... (25) APPLIED ANTI-CHAFE TAPE AT TOP COWL. 1 of 2

		Nions
DATE	Maintenance Release I certify that the aircraft and/or component(s) on 7164V was repaired and inspected in accordance with a Annual inspection per the manufactures maintenance manual and current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair station under Work Order No. 18687-01-2021, Dated 1/29/2021.	nber of Technician or
	DATE: SIGNED: Work Order: 18687-01-2021 Abraham Abel Printed by EBis 3 (datcomedia.com)	
	Certified Repair Station No. AJ4R052M	

tions YEAR DATE: 3/8/2022 Foothill Aircraft Sales & Service, Inc. nber of Technician or MAKE: MOONEY 20 A/C TSN: 3825.26 MODEL: M20F TACH: 3825.26 Repair Station No. AJ4R052M S/N: 22-0073 DATE 1749 W 13Th St REG. NO: 7164V Upland, CA 91786 WORK ORDER: Phone: 909-985-1977 19260-02-2022 Airframe Entries (1) C/W ANNUAL INSPECTION ON THIS AIRFRAME IAW FAR 43 APPENDIX D USING MOONEY M20F M.M CHAPTER 5 INSPECTION CHECKLIST AS A GUIDE. C/W FAR 91,207 D ELT INSPECTION AND FUNCTIONAL CHECK. ELT BATTERY EXPIRATION DATE 12-2022. ADs CHECKED THROUGH 01/2021. REPLACED AIR INDUCTION FILTER WITH NEW P/N BA-6305.... (4) AD 75-09-08 TO DETECT CRACKED ENGINE MOUNT MEMBERS C/W BY VISUAL INSPECTION IAW MOONEY S/B M20-192, NO DEFECTS NOTED AT THIS TIME. NEXT INSPECTION DUE IN 100 HRS.... (6) C/W AD 76-07-12 BENDIX IGNITION SWITCH BY OPERATIONAL CHECK IAW BENDIX S/B 583. NO DEFECTS NOTED AT THIS TIME NEXT INSPECTION DUE IN 100 HRS.... (7) C/W AD 73-21-01 TO PREVENT CORROSION AND/OR MISRIGGING IN THE FLIGHT CONTROL AND LANDING GEAR SYSTEMS BY LUBRICATION WITH SILICONE TYPE LUBRICANT.... (8) REPLACED LH AND RH FUEL CP O-RINGS.... (9) INSTALLED OVERSIZE NLG TRUSS BUSHING AND REPLACE NOSE STEERING ROD END IAW MOONEY M20F M.M. OPS CHECKED GOOD (11) REPLACED VACUUM REGULATOR FILTER (12) REPLACED AIR FILTER WITH P/N BA-6305.... (14) REPLACED AIRCRAFT BATTERY WITH NEW RG-35A 1 of 2

RECORDING TODAY	Description of Insp	ections, Tests, Repairs and Alte	rations mber of Technician or		
Airworthy for return to s 19260-02-2022, Dated	I certify that the aircraft and/or component(s) on 7164V was repaired and inspected in accordance with a Annual inspection per the manufactures maintenance manual and current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair station under Work Order No. 19260-02-2022, Dated 3/8/2022.				
DATE: 3/8/2022	SIGNED:	Work Order: 19260-02-2022			
	Adrian Arias Certified Repair Station No. AJ4R052M	Printed by EBis 3 (datcomedia.com)			
	2 of 2				

-

-

-

