

PROPELLER LOGBOOK

McCauley
1A103-TCM 6958
S/N LA-005

PROPELLER MODEL 1A103-TCM 6958

PROPELLER S/N LA-005


N 714XB
HARTZELL


Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.

Date
Propeller
TSN
TSO
Hrs
A/C


PROP MODEL: 1A103TCM6958
PROP S/N: LA005
REG NO: N714XB
WORK ORDER: 7327
DATE: 12/17/2008
SIGNED: 
Mike Tertune, A&P: 2180478 IA
Printed by Ebis 3 (datcommedia.com)
DATE: 12/17/2008
A/C TSN: 9353
PROP TT: 4987
TSPOH: 1567
TACH: 9353

100 Hour Inspection complied with on Propeller. Prop dressed and painted
This Propeller was inspected in accordance with a 100 Hour Inspection, was found to be in an airworthy condition and is approved to return to service.
Pertinent details are listed above and are on file at this facility under this work order.
100 Hour Inspection complied with on Propeller. Prop dressed and painted
PROP ENTRIES
PROP MODEL: 1A103TCM6958
PROP S/N: LA005
REG NO: N714XB
WORK ORDER: 7382
DATE: 4/28/2009
A/C TSN: 9453
PROP TT: 5097
TSPOH: 1667
TACH: 9453

DATE: 4/28/2009
SIGNED: 
Mike Tertune, A&P: 2180478 IA
Printed by Ebis 3 (datcommedia.com)
Work Order: 7382

PROP MODEL: 1A103TCM6958
PROP S/N: LA005
REG NO: N714XB
WORK ORDER: 7427
DATE: 7/2/2009
SIGNED: 
Mike Tertune, A&P: 2180478 IA
Printed by Ebis 3 (datcommedia.com)
DATE: 7/2/2009
A/C TSN: 9553
PROP TT: 5197
TSPOH: 1767
TACH: 9553

100 Hour Inspection complied with on Propeller. Prop dressed and painted
This Propeller was inspected in accordance with a 100 Hour Inspection, was found to be in an airworthy condition and is approved to return to service.
Pertinent details are listed above and are on file at this facility under this work order.
100 Hour Inspection complied with on Propeller. Prop dressed and painted
PROP ENTRIES
PROP MODEL: 1A103TCM6958
PROP S/N: LA005
REG NO: N714XB
WORK ORDER: 7508
DATE: 10/28/2009
A/C TSN: 9654
PROP TT: 5298
TSPOH: 1868
TACH: 9654

DATE: 10/28/2009
SIGNED: 
Mike Tertune, A&P: 2180478 IA
Printed by Ebis 3 (datcommedia.com)
Work Order: 7508



Directives,
Inspections.

WORK ACCOMPLISHED I.A.B. 4 w A.D. 2010-04-05

MODEL NO.

1A103TCM6958

SERIAL NO.

LAD005

THE AIRCRAFT AND/OR COMPONENT IDENTIFIED ABOVE WAS REPAIRED
AND INSPECTED IN ACCORDANCE WITH CURRENT FEDERAL AVIATION
REGULATIONS AND IS APPROVED FOR RETURN TO SERVICE.
PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS AGENCY UNDER
REPAIR ORDER # 12004-03-2010
DATED: 03-23-2010
SIGNED: *T. J. W. P. P.*
TODD MARINKOVICH (AUTHORIZED INDIVIDUAL)

PROF MODEL: 1A103TCM6958
PROP S/N: LA005
REG NO: N714XB
WORK ORDER: 7580
Mike's Aero, Inc.
PO Box 431
Angwin, CA 94508
Phone: 707-965-2411
TACH 9754
A/C TSN 9754
PROP TT 5398
TSPOH 1968
DATE 3/29/2010

100 Hour inspection complied with on Propeller. Prop dressed and painted. AD 2010-04-05 McCauley Propeller 1A103TCM (3-10-2010) Inspection for hub cracks complied with. Removed propeller on LA-005 from N714XB for inspection at American McCauley ASB221E. Next due at 10,504 tach and total time (750 hrs).
Propeller Service and reinstalled afterward. Installed utilizing bolts, mylar gasket and reinforcement plate kit B4622-43 per
This Propeller was inspected in accordance with a 100 Hour inspection, was found to be in an airworthy condition and is approved to return to service.
Pertinent details are listed above and are on file at this facility under this work order.

DATE: 3/29/2010
SIGNED: *T. J. W. P. P.*
Mike Terhune, A&P: 2180478 IA
Printed by EBis 3 (datcomedia.com)
Work Order: 7580

PROF MODEL: 1A103TCM6958
PROP S/N: LA005
REG NO: N714XB
WORK ORDER: 7631
Mike's Aero, Inc.
PO Box 431
Angwin, CA 94508
Phone: 707-965-2411
TACH: 9856
A/C TSN: 9856
PROP TT: 5500
TSPOH: 2070
DATE: 6/24/2010

100 Hour inspection complied with on Propeller. Prop dressed and painted
This Propeller was inspected in accordance with a 100 Hour inspection, was found to be in an airworthy condition and is approved to return to service.
Pertinent details are listed above and are on file at this facility under this work order.

DATE: 6/24/2010
SIGNED: *T. J. W. P. P.*
Mike Terhune, A&P: 2180478 IA
Printed by EBis 3 (datcomedia.com)
Work Order: 7631

PROF MODEL: 1A103TCM6958
PROP S/N: LA005
REG NO: N714XB
WORK ORDER: 7677
Mike's Aero, Inc.
PO Box 431
Angwin, CA 94508
Phone: 707-965-2411
TACH: 9853
A/C TSN: 9853
PROP TT: 5597
TSPOH: 2167
DATE: 9/13/2010

100 Hour inspection complied with on Propeller. Prop dressed and painted. AD 2010-04-05 due at 10,504 tach and total time (due every 750 hrs)
This Propeller was inspected in accordance with a 100 Hour inspection, was found to be in an airworthy condition and is approved to return to service.
Pertinent details are listed above and are on file at this facility under this work order.

DATE: 9/13/2010
SIGNED: *T. J. W. P. P.*
Mike Terhune, IA: 2180478 IA
Printed by EBis 3 (datcomedia.com)
Work Order: 7677

Date
TSN
Pro

PROP MODEL: 1A103TCM6958
PROP S/N: LA005
REG NO: N714XB
WORK ORDER: 7737
DATE: 2/1/2011
SIGNED: *[Signature]*
Mike Terhune, A&P: 2180478 IA
Mike's Aero, Inc.
PO Box 431
Angwin, CA 94508
Phone: 707-965-2411
TSPCH: 2268
PROP TT: 5698
A/C TSN: 10054
DATE: 2/1/2011
TACH: 54

100 Hour inspection complied with on Propeller. Prop dressed and painted. AD 2010-04-05 due at 10,504 tach and total time (due every 750 hrs)
This Propeller was inspected in accordance with a 100 Hour inspection, was found to be in an airworthy condition and is approved to return to service
Pertinent details are listed above and are on file at this facility under this work order.

DATE: 2/1/2011
SIGNED: *[Signature]*
Mike Terhune, A&P: 2180478 IA
Mike's Aero, Inc.
PO Box 431
Angwin, CA 94508
Phone: 707-965-2411
WORK ORDER: 7784
PROP MODEL: 1A103TCM6958
PROP S/N: LA005
REG NO: N714XB
TSPCH: 2368
PROP TT: 5798
A/C TSN: 10154
DATE: 5/4/2011
TACH: 154

100 Hour inspection complied with on Propeller. Prop dressed and painted. AD 2010-04-05 due at 504 tach and total time (due every 750 hrs)
This Propeller was inspected in accordance with a 100 Hour inspection, was found to be in an airworthy condition and is approved to return to service
Pertinent details are listed above and are on file at this facility under this work order.

DATE: 5/4/2011
SIGNED: *[Signature]*
Mike Terhune, A&P: 2180478 IA
Mike's Aero, Inc.
PO Box 431
Angwin, CA 94508
Phone: 707-965-2411
WORK ORDER: 7784
PROP MODEL: 1A103TCM6958
PROP S/N: LA005
REG NO: N714XB
TSPCH: 2464
PROP TT: 5894
A/C TSN: 10250
DATE: 9/21/2011
TACH: 250

100 Hour inspection complied with on Propeller. Prop dressed and painted. AD 2010-04-05 due at 504 tach and total time (due every 750 hrs). Propeller removed from N714XB for engine overhaul and reinstalled afterward.
This Propeller was inspected in accordance with a 100 Hour inspection, was found to be in an airworthy condition and is approved to return to service
Pertinent details are listed above and are on file at this facility under this work order.

DATE: 9/21/2011
SIGNED: *[Signature]*
Mike Terhune, A&P: 2180478 IA
Mike's Aero, Inc.
PO Box 431
Angwin, CA 94508
Phone: 707-965-2411
WORK ORDER: 7823
PROP MODEL: 1A103TCM6958
PROP S/N: LA005
REG NO: N714XB
TSPCH: 2569
PROP TT: 5899
A/C TSN: 10355
DATE: 12/20/2011
TACH: 355

100 Hour inspection complied with on Propeller. Prop dressed and painted. AD 2010-04-05 due at 504 tach and total time (due every 750 hrs). (149 to go)
This Propeller was inspected in accordance with a 100 Hour inspection, was found to be in an airworthy condition and is approved to return to service.
Pertinent details are listed above and are on file at this facility under this work order.

DATE: 12/20/2011
SIGNED: *[Signature]*
Mike Terhune, A&P: 2180478 IA
Mike's Aero, Inc.
PO Box 431
Angwin, CA 94508
Phone: 707-965-2411
WORK ORDER: 7907
PROP MODEL: 1A103TCM6958
PROP S/N: LA005
REG NO: N714XB
TSPCH: 2663
PROP TT: 6093
A/C TSN: 10449
DATE: 4/19/2012
TACH: 449

100 Hour inspection complied with on Propeller. Prop dressed and painted. AD 2010-04-05 due at 504 tach and total time (due every 750 hrs). 55 hours to go.
This Propeller was inspected in accordance with a 100 Hour inspection, was found to be in an airworthy condition and is approved to return to service.
Pertinent details are listed above and are on file at this facility under this work order.

DATE: 4/19/2012
SIGNED: *[Signature]*
Mike Terhune, A&P: 2180478 IA
Mike's Aero, Inc.
PO Box 431
Angwin, CA 94508
Phone: 707-965-2411
WORK ORDER: 7949
PROP MODEL: 1A103TCM6958-1.5
PROP S/N: LA005
REG NO: N714XB
TSPCH: 2663
PROP TT: 6137
A/C TSN: 10493
DATE: 5/18/2012
TACH: 483

AD 2010-04-05 McCauley Propeller 1A103TCM (3-10-2010) inspection for hub cracks complied with. Removed propeller for Overhaul at American Propeller Service and reinstalled afterward. Installed utilizing Bolt, gasket and reinforcement plate kit B4622-43 per McCauley ASB221E. Next due at 1243 tach, 11,243 total time (750 hrs).
This Propeller was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details are listed above and are on file at this facility under this work order.

DATE: 5/18/2012
SIGNED: *[Signature]*
Mike Terhune, A&P: 2180478 IA
Work Order: 7965
Printed by EBis 3 (datcomedia.com)



less Directives,
r, and Inspections.

WORK ACCOMPLISHED *COMPLETE OVERHAUL*

MODEL NO. *1A103 TCM6958*

SERIAL NO. *LA005*

THE AIRCRAFT AND/OR COMPONENT IDENTIFIED ABOVE WAS REPAIRED
AND INSPECTED IN ACCORDANCE WITH CURRENT FEDERAL AVIATION
REGULATIONS AND IS APPROVED FOR RETURN TO SERVICE.

REPAIR ORDER # *15152-05-2012*

DATED: *05-17-2012*

SIGNED *TODD MARKOVICH*

(AUTHORIZED INDIVIDUAL)

DATE: 6/29/2012
A/C TSN: 15827
PROP TT: 6188
TSPOH: 51
TACH: 1537

PROP MODEL: 1A103-6958
PROP S/N: LA-005
REG NO: N24932
WORK ORDER: 7986

Mike's Aero, Inc.

PO Box 431
Angwin, CA 94508
Phone: 707-965-2411

100 Hour inspection complied with on Propeller. Prop dressed and painted. This propeller installed onto N24932 at aircraft tach 1537.

This Propeller was inspected in accordance with a 100 Hour inspection, was found to be in an airworthy condition and is approved to return to service. Pertinent details are listed above and are on file at this facility under this work order.

Work Order 7986

Printed by EBIS 3 (datcomedia.com)

Date
Propeller TSN TSO
A/I Hr

5/15/12
6131 Prop
443 tach

Prop Entries

PROP MODEL: 1A103TCM6958-1.5
PROP S/N: LA-005
REG NO: N714XB
WORK ORDER: 7984

Mike's Aero, Inc.

PO Box 431
Angwin, CA 94508
Phone: 707-965-2411

Removed propeller sn LA-005 for installation onto N24932 and reinstall back onto N714XB. Prop times were advanced 9 hours of use.

DATE: 7/6/2012

SIGNED *Mike's Aero, Inc.*

Mike's Aero, Inc.

Work Order: 7984

Printed by EBIS 3 (datcomedia.com)

Prop Entries

PROP MODEL: 1A103TCM6958-1.5
PROP S/N: LA-005
REG NO: N714XB
WORK ORDER: 7986

Mike's Aero, Inc.

PO Box 431
Angwin, CA 94508
Phone: 707-965-2411

DATE: 7/20/2012
A/C TSN: 10556
PROP TT: 8209
TSPOH: 72
TACH: 556

100 Hour inspection complied with on Propeller. Prop dressed and painted. AD 2010-04-05 due at 1234 tach 11,234 total time (due every 750 hrs).

This Propeller was inspected in accordance with a 100 Hour inspection, was found to be in an airworthy condition and is approved to return to service. Pertinent details are listed above and are on file at this facility under this work order.

Work Order: 7996

Printed by EBIS 3 (datcomedia.com)

DATE: 6/7/2013	SIGNED: <i>Mike Terhune</i>	Mike Terhune, A&P: 2180478 IA	Printed by EBis 3 (datacommedia.com)
Work Order: 8127			
This Propeller was inspected in accordance with a 100 Hour Inspection, was found to be in an airworthy condition and is approved to return to service.			
Pertinent details are listed above and are on file at this facility under this work order.			
(due every 750 hrs.)			
100 Hour Inspection complied with on Propeller. Prop dressed and painted. AD 2010-04-05 due at 1234 tach 11,234 total time			
Prop Entries			
PROF MODEL: 1A103TCM6958-1.5	PROF S/N: LA-005	REG NO: N714XB	WORK ORDER: 8127
PO Box 431 Angwin, CA 94508 Phone: 707-965-2411			
Mike's Aero, Inc.			
DATE: 6/7/2013 A/C TSN: 10839 PROP TT: 6492 TSPH: 355 TACH: 839			
Printed by EBis 3 (datacommedia.com)			
Work Order: 8165			
This Propeller was inspected in accordance with a 100 Hour Inspection, was found to be in an airworthy condition and is approved to return to service.			
Pertinent details are listed above and are on file at this facility under this work order.			
(due every 750 hrs.)			
100 Hour Inspection complied with on Propeller. Prop dressed and painted. AD 2010-04-05 due at 1234 tach 11,234 total time			
Prop Entries			
PROF MODEL: 1A103TCM6958-1.5	PROF S/N: LA-005	REG NO: N714XB	WORK ORDER: 8165
PO Box 431 Angwin, CA 94508 Phone: 707-965-2411			
Mike's Aero, Inc.			
DATE: 6/4/2013 A/C TSN: 10939 PROP TT: 6592 TSPH: 455 TACH: 939			
Printed by EBis 3 (datacommedia.com)			

DATE: 11/21/2012	SIGNED: <i>Mike Terhune</i>	Mike Terhune, A&P: 2180478 IA	Printed by EBis 3 (datacommedia.com)
Work Order: 8047			
This Propeller was inspected in accordance with a 100 Hour Inspection, was found to be in an airworthy condition and is approved to return to service.			
Pertinent details are listed above and are on file at this facility under this work order.			
(due every 750 hrs.)			
100 Hour Inspection complied with on Propeller. Prop dressed and painted. AD 2010-04-05 due at 1234 tach 11,234 aircraft total time			
Prop Entries			
PROF MODEL: 1A103TCM6958-1.5	PROF S/N: LA-005	REG NO: N714XB	WORK ORDER: 8047
PO Box 431 Angwin, CA 94508 Phone: 707-965-2411			
Mike's Aero, Inc.			
DATE: 11/21/2012 A/C TSN: 10649 PROP TT: 6302 TSPH: 165 TACH: 649			
Printed by EBis 3 (datacommedia.com)			
Work Order: 8088			
This Propeller was inspected in accordance with a 100 Hour Inspection, was found to be in an airworthy condition and is approved to return to service.			
Pertinent details are listed above and are on file at this facility under this work order.			
(due every 750 hrs.)			
100 Hour Inspection complied with on Propeller. Prop dressed and painted. AD 2010-04-05 due at 1234 tach 11,234 total time			
Prop Entries			
PROF MODEL: 1A103TCM6958-1.5	PROF S/N: LA-005	REG NO: N714XB	WORK ORDER: 8088
PO Box 431 Angwin, CA 94508 Phone: 707-965-2411			
Mike's Aero, Inc.			
DATE: 2/28/2013 A/C TSN: 10741 PROP TT: 6394 TSPH: 257 TACH: 741			
Printed by EBis 3 (datacommedia.com)			

active inspections.

(AUTHORIZED INDIVIDUAL)

TODD MARINKOVICH

12-30-2014

18882-12-2014

THE AIRCRAFT AND/OR COMPONENT IDENTIFIED ABOVE WAS REPAIRED AND INSPECTED IN ACCORDANCE WITH CURRENT FEDERAL AVIATION REGULATIONS AND IS APPROVED FOR RETURN TO SERVICE. PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS AGENCY UNDER REPAIR ORDER #

LA 005

1A103 TCM6958

W.A.D. 2010-04-05

AMERITECH INDUSTRIES DBA
AMERICAN PROPELLER SERVICE
REPAIR STATION NO. N03R717L
20208 CHARLANNNE DRIVE
REDDING, CA 96002 USA



Printed by EBis 3 (datcommedia.com)

Work Order: 8344

Mike Terhune, A&P: 2180478 LA

DATE: 9/12/2014

This Propeller was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details are listed above and are on file at this facility under this work order.

Propeller dressed and painted.

Prop Entries

PROP MODEL: 1A103TCM6958-1.5
PROP S/N: LA-005
REG. NO: N714XB
WORK ORDER: 8344

Mike's Aero, Inc.

PO Box 431
Angwin, CA 94508
Phone: 707-965-2411

DATE: 9/12/2014
A/C TSN: 11178
PROP TT: 6831
TSPCH: 694
TACH: 1178

Printed by EBis 3 (datcommedia.com)

Work Order: 8293

Mike Terhune, A&P: 2180478 LA

DATE: 6/20/2014

This Propeller was inspected in accordance with a 100 Hour inspection, was found to be in an airworthy condition and is approved to return to service. Pertinent details are listed above and are on file at this facility under this work order.

(due every 750 hrs)

100 Hour inspection complied with on Propeller. Prop dressed and painted. AD 2010-04-05 due at 1234 tach 11,234 total time

Prop Entries

PROP MODEL: 1A103TCM6958-1.5
PROP S/N: LA-005
REG. NO: N714XB
WORK ORDER: 8293

Mike's Aero, Inc.

PO Box 431
Angwin, CA 94508
Phone: 707-965-2411

DATE: 6/20/2014
A/C TSN: 11128
PROP TT: 6781
TSPCH: 644
TACH: 1128

Printed by EBis 3 (datcommedia.com)

Work Order: 8223

Mike Terhune, A&P: 2180478 LA

DATE: 1/30/2014

This Propeller was inspected in accordance with a 100 Hour inspection, was found to be in an airworthy condition and is approved to return to service. Pertinent details are listed above and are on file at this facility under this work order.

(due every 750 hrs)

100 Hour inspection complied with on Propeller. Prop dressed and painted. AD 2010-04-05 due at 1234 tach 11,234 total time

Prop Entries

PROP MODEL: 1A103TCM6958-1.5
PROP S/N: LA-005
REG. NO: N714XB
WORK ORDER: 8223

Mike's Aero, Inc.

PO Box 431
Angwin, CA 94508
Phone: 707-965-2411

DATE: 1/30/2014
A/C TSN: 11025
PROP TT: 6678
TSPCH: 541
TACH: 1025

Date
Pr
TSN

DATE: 5/28/2015
SIGNED: *[Signature]*
Mike Ternune, A&P: 2180478 IA
Printed by EBis 3 (datamedia.com)

Work Order: 8450

100 Hour inspection complied with on Propeller. Prop dressed and painted. AD 2010-04-05 due at 724 tach 11,949 aircraft total time (due every 750 hrs).

This Propeller was inspected in accordance with a 100 Hour inspection, was found to be in an airworthy condition and is approved to return to service.

Pertinent details are listed above and are on file at this facility under this work order.

Prop Entries
PROP MODEL: 1A103TCM6958-15
PROP S/N: LA-005
REG. NO: N714XB
WORK ORDER: 8450
Phone: 707-965-2411
Angwin, CA 94508
PO Box 431
Mike's Aero, Inc.

DATE: 8/3/2015
SIGNED: *[Signature]*
Mike Ternune, A&P: 2180478 IA
Printed by EBis 3 (datamedia.com)

Work Order: 8485

100 Hour inspection complied with on Propeller. Prop dressed and painted. AD 2010-04-05 due at 724 tach 11,949 aircraft total time (due every 750 hrs).

This Propeller was inspected in accordance with a 100 Hour inspection, was found to be in an airworthy condition and is approved to return to service.

Pertinent details are listed above and are on file at this facility under this work order.

Prop Entries
PROP MODEL: 1A103TCM6958-15
PROP S/N: LA-005
REG. NO: N714XB
WORK ORDER: 8485
Phone: 707-965-2411
Angwin, CA 94508
PO Box 431
Mike's Aero, Inc.

DATE: 11/1/2015
SIGNED: *[Signature]*
Mike Ternune, A&P: 2180478 IA
Printed by EBis 3 (datamedia.com)

Work Order: 8388

100 Hour inspection complied with on Propeller. Prop d time (due every 750 hrs).

This Propeller was inspected in accordance with a 100 Hour inspection, was found to be in an airworthy condition and is approved to return to service.

Pertinent details are listed above and are on file at this facility under this work order.

Prop Entries
PROP MODEL: 1A103TCM6958-15
PROP S/N: LA-005
REG. NO: N714XB
WORK ORDER: 8388
Phone: 707-965-2411
Angwin, CA 94508
PO Box 431
Mike's Aero, Inc.

DATE: 2/18/2015
SIGNED: *[Signature]*
Mike Ternune, A&P: 2180478 IA
Printed by EBis 3 (datamedia.com)

Work Order: 8406

100 Hour inspection complied with on Propeller. Prop d time (due every 750 hrs).

This Propeller was inspected in accordance with a 100 Hour inspection, was found to be in an airworthy condition and is approved to return to service.

Pertinent details are listed above and are on file at this facility under this work order.

Prop Entries
PROP MODEL: 1A103TCM6958-15
PROP S/N: LA-005
REG. NO: N714XB
WORK ORDER: 8406
Phone: 707-965-2411
Angwin, CA 94508
PO Box 431
Mike's Aero, Inc.

1. Approving Civil Aviation Authority/Country: **FAA/UNITED STATES**

2. AUTHO **FAA**

4. Organization Name and Address:  Ameritech Inc. 20208 Charla Redding, CA



6. Item:	7. Description:	8. F
1	McCauley Propeller	Prop: McCauley Hub: 1A103 TC Blade:

12. Remarks:

Inspected track, angle and balance. Complied with Airworthiness D found. Next action due in 750 hours T.I.S. Complied with Service E

DATE: 11/1/2015
A/C TSN: 11199
PROP TT: 6852
TSPOH: 715
TACH: 1199

13a. Certifies the items identified above were manufactured in

100 Hour Inspection complied with on Propeller. Prop dressed and painted. AD 2010-04-05 due at 724 tach 11,949 aircraft total	DATE: 5/20/2016	SIGNED: 	Mike Tetune, A&P: 2180478 1A	Printed by EBis 3 (datcommedia.com)	Work Order: 8629
This Propeller was inspected in accordance with a 100 Hour Inspection, was found to be in an airworthy condition and is approved to return to service. Permitt details are listed above and are on file at this facility under this work order.					
100 Hour Inspection complied with on Propeller. Prop dressed and painted. AD 2010-04-05 due at 724 tach 11,949 aircraft total					
time (due every 750 hrs).					
Prop Entries	100 Hour Inspection complied with on Propeller. Prop dressed and painted. AD 2010-04-05 due at 724 tach 11,949 aircraft total				
PROP MODEL:	1A103TCM6958-15				
PROP S/N:	LA-005				
REG NO:	N714XB				
WORK ORDER:	8666				
PO Box:	431				
Angwin, CA:	94508				
Phone:	707-965-2411				
TACH:	498				
TSPCH:	1239				
PROP TT:	7376				
A/C TSN:	11723				
DATE:	8/5/2016				
Printed by EBis 3 (datcommedia.com)	Work Order: 8629				
Mike Tetune, A&P: 2180478 1A	Printed by EBis 3 (datcommedia.com)				
SIGNED: 	DATE: 8/5/2016				
Mike Tetune, A&P: 2180478 1A	Work Order: 8666				
Printed by EBis 3 (datcommedia.com)	100 Hour Inspection complied with on Propeller. Prop dressed and painted. AD 2010-04-05 due at 724 tach 11,949 aircraft total				

[illegible]

1714XB 10/17/17 722 tach, 11

1. Approving Civil Aviation Authority/Country: FAA/UNITED STATES		2. AUTHORIZED RELEASE FAA Form 8130-3, AIRWORTHINESS	
4. Organization Name and Address:		 Ameritech Industries dba American Propeller Service 20208 Charlanne Drive Redding, CA 96002 USA	
6. Item:	7. Description:	8. Part Number:	9. Q
1	McCauley propeller	Prop: McCauley propeller Hub: 1A103 TCM6958 Blade:	1
12. Remarks: Complied with Airworthiness Directive 2010-04-05, dated 03-10-2010 by inspection and rework as per Ser T.I.S. No further work performed.			
13a. Certifies the items identified above were manufactured in conformity to:			14a. ☐ Certified and
☐ Approved design data and are in condition for safe operation.			9/16/17


3 (datcomedia.com)
Work Order: 8801

DATE/01/19/2017
A/C TSN: 11941
PROP TT: 7594
TSPOH: 1457
TACH: 722

100 Hour Inspection complied with on Propeller. Prop dressed and painted. AD 2010-04-05 due at 724 tach 11,949 aircraft total time (127 hrs to go)

This Propeller was inspected in accordance with a 100 Hour Inspection, was found to be in an airworthy condition and is approved to return to service

Pertinent details are listed above and are on file at this facility under this work order

SIGNED  Mike Terhune, A&P 2180478 IA

DATE: 3/6/2017

Work Order: 8744

Printed by EBIS 3 (datcomedia.com)

DATE: 7/13/2017


Work Order: 8807

Printed by EBIS 3 (datcomedia.com)

100 Hour Inspection complied with on Propeller. Prop dressed and painted. AD 2010-04-05 due at 724 tach 11,949 aircraft total time (due every 750 hrs) 27 hrs to go

This Propeller was inspected in accordance with a 100 Hour Inspection, was found to be in an airworthy condition and is approved to return to service

Pertinent details are listed above and are on file at this facility under this work order

SIGNED  Mike Terhune, A&P 2180478 IA

DATE: 7/13/2017


Work Order: 8807

Printed by EBIS 3 (datcomedia.com)

100 Hour Inspection complied with on Propeller. Prop dressed and painted. AD 2010-04-05 due at 724 tach 11,949 aircraft total time (due every 750 hrs) 27 hrs to go

This Propeller was inspected in accordance with a 100 Hour Inspection, was found to be in an airworthy condition and is approved to return to service

Pertinent details are listed above and are on file at this facility under this work order

SIGNED  Mike Terhune, A&P 2180478 IA

DATE: 7/13/2017

Work Order: 8807

Printed by EBIS 3 (datcomedia.com)

DATE: 3/6/2017
A/C TSN: 11822
PROP TT: 7475
TSPOH: 1338
TACH: 597
ss Directives,
and Inspections.

[illegible]

Date	Propeller	TSN	TSO	A/C	Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
10/11/17		7594	1457			 AMERITECH INDUSTRIES DBA AMERICAN PROPELLER SERVICE REPAIR STATION NO. N03R71ZL 20208 CHARLANNE DRIVE REDDING, CA 96002 USA 4w A.P. 2010-04-05 1A103 Tcm6958 6A005 THE AIRCRAFT AND/OR COMPONENT IDENTIFIED ABOVE WAS REPAIRED AND INSPECTED IN ACCORDANCE WITH CURRENT FEDERAL AVIATION REGULATIONS AND IS APPROVED FOR RETURN TO SERVICE. PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS AGENCY UNDER REPAIR ORDER # 22058-09-2017 DATED: 10-04-2017 SIGNED: <i>Todd Marinikovich</i> (AUTHORIZED INDIVIDUAL) FORM LB01

