

DATE

HC



# VAN BORTEL AIRCRAFT INC<sup>TM</sup>

4912 S. Collins St., Arlington, TX 76018

FAA CRS VNFR171L

**N319CS TACH & TOTAL 401.8 H.M. 453.5 DATE 7/5/2017 W.O. SV5165**

PROPELLER S/N: 150866

PERFORMED A 100 HOUR INSPECTION IN ACCORDANCE WITH FAR 43 WITH REFERENCE TO CESSNA MAINTENANCE MANUAL 206HMM20. AD'S CHECKED THROUGH 2017-14.

I CERTIFY THIS PROPELLER HAS BEEN INSPECTED IN ACCORDANCE WITH A 100 HOUR/ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION. PERTINENT DETAILS OF THE REPAIRS ARE ON FILE AT THIS REPAIR STATION UNDER THIS WORK ORDER.

*Paul Park*  
PAUL PARK, CHIEF INSPECTOR

 SIGNATURE,  
TYPE  
R


# VAN BORTEL AIRCRAFT INC<sup>TM</sup>

4912 S. Collins St., Arlington, TX 76018

FAA CRS VNFR171L

**N319CS TACH & TOTAL 782.4 H.M. 868.0 DATE 7/9/2018 W.O. SV5591**


PROPELLER S/N: 150866

PERFORMED A 100 HOUR INSPECTION IN ACCORDANCE WITH FAR 43 WITH REFERENCE TO CESSNA MAINTENANCE MANUAL 206HMM20. REPLACED #2 BLADE DEICE BOOT P/N: B-40245-53 S/N: 66351 AND RETAINING STRAP P/N: B-40251. AD'S CHECKED THROUGH 2018-14.

I CERTIFY THIS PROPELLER HAS BEEN INSPECTED IN ACCORDANCE WITH A 100 HOUR/ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION. PERTINENT DETAILS OF THE REPAIRS ARE ON FILE AT THIS REPAIR STATION UNDER THIS WORK ORDER.

*Paul Park*  
PAUL PARK, CHIEF INSPECTOR

## MAINTENANCE RECORD

DATE	TOTAL TIME IN SERVICE		DESCRIPTION OF THE WORK PERFORMED	AUTHORIZED SIGNATURE, CERTIFICATE TYPE & NUMBER
	HOURS	10THS		
			<b>PROPELLER</b> McCauley S/N: 150866. Date: 12-27-18 A/C Registration: 319CS Tach: 906. H.M. 1002.0	
			Performed a 100 hrs. inspection in accordance with Far43 with reference to Cessna maintenance manual 206HMM20. All AD'S checked and up to date.  I certify this propeller has been inspected in accordance with a 100 hrs. /annual inspection and was determined to be in airworthy condition.	
			 David Thibodeaux Flying T Repair Station, LLC, SJNR1521 WO # 745	