DATE	T					RCRAF"		М	NATURE,
	НО	N319CS	4912 S. Collii TACH & TO	ns St., Arlington, AL 1118.0	TX 76018 H.M. 1233.9	FAA CR DATE 2/17/2	S VNFR171L 2020 W.O.	SV6085	[YPE
-		PROPELLER PERFORMED A REPLACED #2 BI L CERTIFY THIS PE	S/N: 150866 100 HOUR INSPECTION LADE DEICE BOOT P/N ROPELLER HAS BEEN IN	N IN ACCORDANCE I: B-40245-53 WITH NI	WITH FAR 43 WITH F EW RETAINING STRAP RDANCE WITH A 100	EFERENCE TO CESSNA P/N: B-40251. AD'S CH HOUR/ANNUAL INSPEC S REPAIR STATION UND	MAINTENANCE MIECKED THROUGH	MANUAL 206HMM20. I 2020-04. DETERMINED TO BE IN	
		PAUL PARK, CH	JEF INSPECTOR						
- 1	1		- 1					L	
		PROPELLER S, PERFORMED A 100 CHECKED THROUGH	4912 S. Collins TACH & TOT /N; 150866 HOUR INSPECTION IN GH 2021-09.	St., Arlington, TAL 1395.5 ACCORDANCE WITH	X 76018 H.M. 1531.4 H FAR 43 WITH REFERE	FAA CRS DATE 4/19/ NCE TO CESSNA MAINT	VNFR171L 2021 W.C TENANCE MANUA ON AND WAS DET	L 206HMM21. AD'S	a.
-	+	AIRWORTHY CONI	DITION, PERTINENT DET	AILS OF THE REPAIRS	ARE ON FILE AT THIS	REPAIR STATION UNDER	this work orde	ER.	
	L	PAUL PARK, CHIEF	INSPECTOR	12					
		0			0			0	
			ža				**= =	ಪ	
		0			0			0	
				MAIN	TENANCE REC	ORD			-,
DATE	IN S	TAL TIME SERVICE RS 10THS	DESCRIPTION OF THE WORK PERFORMED CERTIFICA				AUTHORIZED SIG CERTIFICATE & NUMBE	TYPE	
	O7/01/2022 N319CS B3D36C432/80 VSA-1 S/N:150866 PTT:1620.3 Complied with a 100hr inspection IAW FAR43 with reference to Cessna 206H maintenance manual. Inspected and dressed prop blades as required. Inspected hub, clamps, back plate, spinner, deicer boots/wiring/connections and propeller attach bolts per McCauley service manual. All applicable AD's have been conformity checked & complied with through this date I certify that this Propeller has been inspected IAW a 100 hr/Annual inspection and was determined to be in an AIRWORTHY condition. Richard W. Harvey								
	dre pro wit	ssed prop blad peller attach be h through this	100hr inspection I les as required. In olts per McCauley date I certify that	AW FAR43 with aspected hub, classified service manual. this Propeller I	n reference to Cesamps, back plate All applicable Al has been inspect	sna 206H mainten spinner, deicer be o's have been conf ed IAW a 100 hr/	ance manual. I cots/wiring/conformity checked Annual inspec	nnections and d & complied tion and was	
	dre pro wit	ssed prop blad peller attach be h through this ermined to be	100hr inspection I les as required. In olts per McCauley date I certify that	AW FAR43 with aspected hub, classified service manual. this Propeller I	n reference to Cesamps, back plate All applicable Al has been inspect	sna 206H mainten spinner, deicer be o's have been conf ed IAW a 100 hr/	ance manual. I pots/wiring/con formity checked Annual inspect A&P3061908	nnections and d & complied tion and was BIA	S-sister s
	dre pro wit	ssed prop blad peller attach be h through this	100hr inspection I les as required. In olts per McCauley date I certify that	AW FAR43 with aspected hub, classified service manual. this Propeller I	n reference to Cesamps, back plate All applicable Al has been inspect	sna 206H mainten spinner, deicer be o's have been conf ed IAW a 100 hr/	ance manual. I cots/wiring/conformity checked Annual inspec	nnections and d & complied tion and was BIA	
	dre pro wit	ssed prop blad peller attach be th through this ermined to be wo: 17944	100hr inspection I les as required. In olts per McCauley date I certify that in an AIRWOR	AW FAR43 with aspected hub, classervice manual. this Propeller In the condition.	reference to Cesamps, back plate All applicable Al has been inspect Richard V	ssna 206H mainten spinner, deicer be D's have been confe ed IAW a 100 hr/A V. Harvey	ance manual. I pots/wiring/con formity checked Annual inspect A&P3061908 Propeller · pa	nnections and d & complied tion and was BIA age 1 of 1	
	dre pro wit	ssed prop blad peller attach be h through this ermined to be	100hr inspection I les as required. In olts per McCauley date I certify than e in an AIRWOR? Coastal Skie	AW FAR43 with aspected hub, classervice manual. this Propeller In the condition.	reference to Cesamps, back plate All applicable Al has been inspect Richard V	ssna 206H mainten spinner, deicer be D's have been confe ed IAW a 100 hr/A V. Harvey	ance manual. I pots/wiring/con formity checker Annual inspect A&P3061908	nnections and d & complied tion and was BIA age 1 of 1	
	dre pro wit	ssed prop blad peller attach be the through this ermined to be wo: 17944 N319CS TACH: 151 Complied w Appendix D.	100hr inspection I les as required. In olts per McCauley date I certify than e in an AIRWORT Coastal Skie 12.9 TS ith 100 hour inspe checked all applic	AW FAR43 with aspected hub, classervice manual. this Propeller IFHY condition. SMX LLC. 17910 SN: 1512.9 ction in accordar able AD's through	Richard V Airfield Ln · Pearlan he with Cessna h this date.	ssna 206H mainten spinner, deicer be D's have been confed IAW a 100 hr/2 W. Harvey	ance manual. I pots/wiring/con formity checked Annual inspect A&P3061908 Propeller · pa 31150 September 13, e Manual and	nnections and d & complied tion and was BIA ———————————————————————————————————	
	dre pro wit	ssed prop blad peller attach be th through this e ermined to be Wo: 17944 N319CS TACH: 151 Complied w Appendix D. I certify this	100hr inspection I les as required. In olts per McCauley date I certify than e in an AIRWORT Coastal Skie 12.9 TS ith 100 hour inspe checked all applic	AW FAR43 with aspected hub, classervice manual. this Propeller IFHY condition. SMX LLC. 17910 SN: 1512.9 ction in accordar cable AD's through inspected in accordance i	Richard V Airfield Ln · Pearlan Airfield Ln · Pearlan Accordance with a	ssna 206H mainten spinner, deicer be D's have been confed IAW a 100 hr/2 W. Harvey	ance manual. I pots/wiring/con formity checked Annual inspect A&P3061908 Propeller · pa 31150 September 13, e Manual and	nnections and d & complied tion and was BIA ———————————————————————————————————	