







MAINTENANCE RECORD

DATE	TOTAL TIME IN SERVICE		DESCRIPTION OF THE WORK PERFORMED	AUTHORIZED SIGNATURE, CERTIFICATE TYPE & NUMBER
	HOURS	10THS		
			<div style="display: flex; justify-content: space-between; align-items: center;"> <div>    </div> <div style="text-align: center;"> <u>Aircraft Maintenance Record</u> </div> <div> 3 Cessna Blvd. Wichita, KS 67215 316-517-8270 CRS #X07R071Y </div> </div> <div style="text-align: center; margin-top: 5px;">  </div> <div style="display: flex; justify-content: space-between; margin-top: 10px;"> <div> Model T206 Ser. No. T20609219 </div> <div> Registration No. N319CS Total Time 195.3 hrs. </div> <div> Date 29 SEP 2016 Total Landings N/A </div> </div> <ol style="list-style-type: none"> Complied with Lycoming Engine Service Bulletin 627 Replaced #2 Cylinder assy. P/N 16A22541 S/N 120736 with new S/N 122967, Replaced 2ea. Spark plug RHB37E with new. Replaced Alternator P/N 9910592-3 S/N H-P111037 with new S/N H-Q041775. Adjusted Engine Mixture Lean IAW M/M 73-00-01. Adjusted Aft Door Latch IAW M/M 52-30-00. Replaced Engine Oil Filter, Changed Engine Oil Re-Serviced with XC Aviation 20W50. Replaced Cargo Door Seal P/N R581573 with new. Replaced #2 Exhaust Cylinder Pipe P/N 40B22318 with new. Replaced #6 Intake Pipe O-ring P/N 42E22422 with new. Replaced L/H Center Door Scuff Plate P/N 1211527-19 with new. <p>Pertinent details on file under TAIRS WO No. T206009219</p> <p>I certify that with respect to work performed, this aircraft was repaired and inspected in accordance with Cessna T206 Maintenance Rev.19, and current FAA regulations and is approved for return to service, pending a successful check flight.</p> <p>Authorized Signature _____ Daniel L. Hobbs for Textron Aviation Inc. Repair Station</p>	

MAINTENANCE RECORD

DATE	TOTAL TIME IN SERVICE		DESCRIPTION OF THE WORK PERFORMED	AUTHORIZED SIGNATURE, CERTIFICATE TYPE & NUMBER
	HOURS	10THS		
			<div style="display: flex; justify-content: space-between; align-items: center;"> <div>    </div> <div style="text-align: center;"> <u>Aircraft Maintenance Record</u> </div> <div> 3 Cessna Blvd. Wichita, KS 67215 316-517-8270 CRS #X07R071Y </div> </div> <div style="text-align: center; margin-top: 5px;">  </div> <div style="display: flex; justify-content: space-between; margin-top: 10px;"> <div> Model T206 Ser. No. T20609219 </div> <div> Registration No. N319CS Total Time 195.9 hrs. </div> <div> Date 29 SEP 2016 Total Landings N/A </div> </div> <ol style="list-style-type: none"> Complied with '30 minute Run In' IAW Lycoming S/B 627, Ops check good. <p>Pertinent details on file under TAIRS WO No. T20609219</p> <p>I certify that with respect to work performed, this aircraft was repaired and inspected in accordance with T206 Maintenance Manual Rev. 19, and current FAA regulations and is approved for return to service.</p> <p>Authorized Signature _____ Daniel L. Hobbs for Textron Aviation Inc. Repair Station</p>	