


MAINTENANCE RECORD




6304 N. Cedar Ave, Lubbock, TX 79403 Phone: 806-747-5101 Fax: 806-767-8000

Date: 6/25/2021 N-319CS Make: CESSNA Model: T206H
S/N: T20609219 HOBS: 1548.3
Removed and replaced Avionics master switch P/N S3443-1-1. Ops check good at this time.

The aircraft, airframe, aircraft engine, propeller, or appliance identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details are on file at this repair station under Work Order No. A23228 Date 6/25/2021
Signed:  (CRS#4B0R190D)

AUTHORIZED SIGNATURE,
CERTIFICATE TYPE
& NUMBER

MAINTENANCE RECORD

DATE	TOTAL TIME IN SERVICE		DESCRIPTION OF THE WORK PERFORMED	AUTHORIZED SIGNATURE, CERTIFICATE TYPE & NUMBER
	HOURS	10THS		
			<p><u>07/01/2022 N319CS Cessna T206H S/N:T20609219 AFTT: 1620.3</u></p> <p>Complied with an Annual inspection IAW FAR 43 with reference to Cessna 206H maintenance manual. Opened panel and inspection covers. Lubed control pulleys, rod ends, bell cranks and hinges. Cleaned inspected and repacked wheel bearings. Op's checked Aircraft electrical system. Inspected control cables for damage/wear and proper tension. Op's checked and serviced aircraft brake system with fluid as required. Installed new regulator filter ARB-3-51 and Vacuum filter RAD9-18-1. IAW AD84-26-02 the Induction air filter P/N:P197268 is due for replacement at AFTT:1895.5. ELT OP's checked IAW FAR 91-207 D (1-4). ELT battery expiration date 06/2028. Complied with the one year essential & Cross feed diode test, Amsafe restraints diagnostic test and inspection, Standby battery capacity test & recharge. Completed the 2 year ACU over volt test. Completed ICA inspections for Kelly A/C system, Flint wing tips, Micro VG's, Aerocet Cargo pod, & Knots 2U Flap Gap seals. I certify that this AIRFRAME has been inspected IAW an ANNUAL INSPECTION and was determined to be in an Airworthy condition.  A&P3061908IA Richard W. Harvey</p>	