		MAINTENANCE RECORD		
DATE	TOTAL TIME IN SERVICE HOURS 10THS	Beegles A/C Model 72024 AFTT / 494	AUTHORIZED SIGNAT CERTIFICATE TYP & NUMBER	
		A/C SN/ZOLO9219 N#/J3190  The transponder tests and inspections required by 14CFR91.4130  have been performed and found to comply with part 43 Appendix  and is approved for return to service.	a)	
		M/N. Germin P/N: S/N: 8913025  Date: 7-22-2023 W/O# 13292 Inspector: Child Ext  Beegles Aircraft Service CRS# BX4R092M	g Link	
				•
<del></del>				-
				_
				rijeniji ingestrasis
DATE	Quality	REPAIR STATION BX4R092M (970) 353-9200 www.beeglesaircraft.com	SIGNATU ATE TYPE MBER	•
:	06-23-23 A	635 AIRPORT ROAD - WELD COUNTY AIRPORT - GREELEY, COLORADO 80631 FTT 1494.60 Tach 1494.60 Hobbs 1639.70 N319CS	sn T20609219	
	tailcone mou	ed aircraft for repair access: Removed aft baggage interior anted systems as required. Removed rudder and LH & RF	l elevators. Repaired	
	assembly pn	placed RH bulkhead pn 1212425-5 at Station 138.00. Rep 1211651-6 at Stations 112.00 to 152.00. Replaced RH st .00 to 124.00. Replaced RH channel pn 1211436-7 at Sta	ringer pn 1211692-13 at	
	Replaced RF 1212416-6 a	H stringer pn 1212416-10 at Stations 124.00 to 208.00. Ret Stations 132.00 to 209.00. Replaced RH aft side skin pn 8.00. Replaced aft belly skin pn 1211650-7 at Stations 11	placed RH stringer pn 1211650-4 at Stations	
	Replaced RF tailcone skin 1211716-2 a	I tailcone side skin pn 1212400-22 at Stations 138.00 to 2 pn 1212400-2 at Stations 138.00 to 194.00. Replaced RF t Stations 124.00 to 152.00. Replaced aft window retained	08.00. Replaced upper I aft baggage shelf pn skin pn 1211650-2 at	Phone Wilder Holler Inches
	Stations 112 door assemb 050. Repaire	.00 to 138.00. Reinstalled aft cabin windows as required. ly pn 1211673-26. Replaced air conditioner elastomeric bd rudder: Replaced trailing edge skin pn 1231001-3. Repl	Replaced aft cabin ushings pn (3) N83-aced static wick base	Transfer of the second
	pn C592001-	-0205. Replaced tip pn GF0731606-04. Performed painted painted aft tailcone to match as required. Repainted rudden	l static balance check. ———	