

Page No.

DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED —
				SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
TOTALS brought forward from previous page				

ORLANDO AIRCRAFT SERVICES 601 HUMPHRIES AVE. ORLANDO EXECUTIVE AIRPORT ORLANDO, FL
 LOG ID# 12323 29-December-2022 WO# 121688-0 Pg 1 / 1
 N583PU S/N 2043 CIRRUS SR20

ENGINE LOG

FLY HOBBS: 5497.5

OIL DRAINED, FILTER REMOVED AND CUT OPEN. NO VISUAL CONTAMINATES NOTED. ENGINE SERVICED WITH 8QTS
 PHILLIPS 20W50X/C AND NEW AA108-2 OIL FILTER INSTALLED & SAFETIED. ENGINE RUN-UP. LEAK AND
 OPERATIONAL CHECKS GOOD.

A&P 7630954 ALBERTO RODRIGUEZ

Date

12/29/22



Freedom Aviation
 310 Hangar Road
 Lynchburg, VA 24502
 (434) 237-3342
 CRS# BGSR439C


Date: 2/24/2023, Aircraft: N583PU, Type: SR20, S/N: 2043, Tach: 5560.5, WO#: F23-1197

Engine Entries

Ran engine, drained oil and took sample. Removed and cut filter, no metal noted. Installed new filter P/N AA48108-2 and serviced engine with 8 qts of Phillips 20W50 X/C IAW Cirrus SR20 AMM 12-10. Ran engine, ops/leak check good.

Maintenance Release

The aircraft and/or component(s) as listed above was repaired in accordance with current Federal Aviation Regulations. Pertinent details are on file at this repair station.


 JOE LEONARD CRS# BGSR439C

Topflight Aircraft Maintenance
 48162 F Street
 Belleville Michigan 48111
 517 320-0893

Make: LYCOMING

Model: IO-360-ES

Tail: N583PU

S/N:

Hours: Tach: 5601.1 Hobbs: 7373.0

Drained oil and removed filter, Checked for contaminants, none found at this time. Installed new oil filter PN: AA48108-2 and service with 6 qts of Phillips 20W-50. Sent sample to BlackStone. No Leaks at this time. -----End-----

Signed:

Name: Patrick Stewart

Cert: A&P 3103433 IA

Date: 06/21/2023

SUB-TOTALS