

Date	Propeller		A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
	TSN	TSO		
9 Sep 2004	-0-	-0-	1945.0	Installed this prop on Bellanca N6650V.
1 Aug 2006	95.1		2040.1	Lubed prop - Annual Inspection completed <i>Bobly Powell</i> 416530366 IFA
12 Sep 2007	163.1		2108.1	Lubed prop. Annual Inspection completed <i>Bobly Powell</i> 416530366 IFA

MODEL HC-H3V-1RF
S/N EC1726B
REG N6650V

AIR SPEED AIRCRAFT MAINTENANCE
927 FLIGHTLINE DR
DOTHAN, AL. 36303

DATE 12/11/09
HOBBS
TACH 2164.1
TSMOH 219.1

THIS AIRCRAFT AND/OR COMPONENT IDENTIFIED ABOVE WAS REPAIRED AND/OR INSPECTED IN ACCORDANCE WITH CURRENT FEDERAL AIR REGULATIONS AND WAS FOUND AIRWORTHY FOR RETURN TO SERVICE ONLY WITH RESPECT TO THE WORK PERFORMED. PERTINENT DETAILS ARE FOUND UNDER SHOP ORDER # 09-2960.

1. THIS PROPELLER HAS BEEN INSPECTED IN CONJUNCTION WITH AN ANNUAL INSPECTION

February 3, 2011 HMB: HC-C3YF-1RF SN: EC1726B
Overhauled propeller, shot peened blade knobs, painted and
statically balanced in accordance with Hartzell Manuals: 113,
133, 159, 202. All other curr svc info & ADs C/W as of this
date. An AD may apply to the install of the prop described
hereon. The installer is responsible for complete compliance
with any applicable installation A.D.

Maintenance Release (Complete Overhaul)

The aircraft propeller, or appliance identified above was overhauled
and inspected in accordance with Regulations of the Federal Aviation
Agency and is approved for return to service. Pertinent details of the
Repair are on file at this repair station under Order Number 11-7099.

Signed , for AIR PROP SPECIALISTS,
INC. Certificate Number 1X4R274M, 3671 Industrial Park Drive,
Marianna, FL 32446

Date	Propeller	A/C	Description of all operations pertaining to Airworthiness Directives, including Propeller Overhaul, Major or Minor Damage, and Repairs
	MODEL HC-C3YF-1RF S/N EC1726B REG N6650V	ALLIANCE AVIATION 927 FLIGHTLINE DR DOTHAN, AL. 36303	DATE 02/08/11 TACH 2192.5 TSMOH 0
	THIS AIRCRAFT AND/OR COMPONENT IDENTIFIED ABOVE HAS BEEN REPAIRED AND/OR INSPECTED IN ACCORDANCE WITH CURRENT FEDERAL REGULATIONS AND WAS FOUND AIRWORTHY FOR RETURN TO SERVICE. PERTINENT DETAILS ARE ON FILE AT THIS AGENCY UNDER W/O.		
	REMOVED AND REINSTALLED PROP AFTER OVERHAUL BY OUTSIDE VENDOR.		
			<i>Rehash</i> <i>08372804</i>
23 Jul 2011	283.6	36.1	2228.6
27 Jul 2011			
	Removed Prop and gov after prop and gov adjustments were unable to increase max RPM. Awaiting bench test. <i>Prop rebuilt HTP 3160009</i>		
	Prop governor reindexed from an H to P. This fixed problem from previous entry. See Aircraft Log dated 27 Jul 11. <i>Charles T. Byrd</i> Owner/operator.		

N6650V

7-28-11

MODEL 17-30

TSO 36.1

REMOVED AND SENT PROP TO BE BENCH CHECKED,
REINSTALLED ONT A/C. OP CHECK GOOD IAW: HARTZELL
PROPELLORS OWNERS MANUAL 115N

AARON WALLS A&P 3160009

Aaron Walls

MODEL HC-C3YF-1RF ALLIANCE FLIGHT SUPPORT

S/N EC1726B
REG N6650V

927 FLIGHTLINE DR
DOTHAN, AL. 36303

DATE 05/17/12
TACH 2250.2
TSMOH

THIS AIRCRAFT AND/OR COMPONENT IDENTIFIED ABOVE HAS BEEN REPAIRED AND/OR INSPECTED IN ACCORDANCE WITH CURRENT FEDERAL REGULATIONS AND WAS FOUND AIRWORTHY FOR RETURN TO SERVICE. PERTINENT DETAILS ARE ON FILE AT THIS AGENCY UNDER W/O.

I CERTIFY THIS PROPELLER HAS BEEN INSPECTED IAW AN ANNUAL INSPECTION AND HAS BEEN DETERMINED TO BE AIRWORTHY AT THIS TIME


A73472804JA

MONARCH AVIATION MAINTENANCE INC.

619 AIR PARK RD., DEFUNIAK SPRINGS, FL 32435

N6650V, BELLANCA, 17-30, TSOH: ~~346-02~~
121.52, TACH: 2291.62, 6-24-2013

COMPLIED WITH ANNUAL INSPECTION IAW BELLANCA SERVICE MANUAL AND THIS PROPELLER HAS BEEN DETERMINED TO BE IN AN AIRWORTHY CONDITION. SEE AD LISTING FOR COMPLIANCE. MAINTENANCE CARRIED OUT ON THE AIRCRAFT IDENTIFIED ABOVE WAS CARRIED OUT AND INSPECTED IN ACCORDANCE WITH CURRENT REGULATIONS OF THE FAA ADMINISTRATION AND IS APPROVED FOR RETURN TO SERVICE. FOR RELEVANT DETAILS OF WORK CARRIED OUT ARE HELD ON FILE WO# 1304.



ERIC MENGELSON A&P 3026965 IA
AUTHORIZED SIGNATURE FOR MONARCH AVIATION MAINTENANCE INC.

Description of all operations pertaining to Airworthiness Directives,
Service Documents, Overhaul, Major or Minor Repair, and Inspections.

MONARCH AVIATION MAINTENANCE INC.

619 AIR PARK RD., DEFUNIACK SPRINGS, FL 32435

N6650V, BELLANCA 17-30, TSOH: 358.95, TACH: 2551.45, DATE: 7-8-2016

COMPLIED WITH ANNUAL INSPECTION IAW BELLANCA SERVICE MANUAL AND THIS PROPELLER HAS BEEN DETERMINED TO BE IN AN AIRWORTHY CONDITION. SEE AD LISTING FOR COMPLIANCE. MAINTENANCE CARRIED OUT ON THE AIRCRAFT IDENTIFIED ABOVE WAS CARRIED OUT AND INSPECTED IN ACCORDANCE WITH CURRENT REGULATIONS OF THE FAA ADMINISTRATION AND IS APPROVED FOR RETURN TO SERVICE. FOR RELEVANT DETAILS OF WORK CARRIED OUT ARE HELD ON FILE WO# 1979.



ERIC MENGELSON A&P 3026965 IA

AUTHORIZED SIGNATURE FOR MONARCH AVIATION MAINTENANCE INC.



MONARCH AVIATION MAINTENANCE INC.

619 AIR PARK RD., DEFUNIAK SPRINGS, FL 32435

N6650V, BELLANCA 17-30, TSOH: 459.42, TACH: 2651.92, DATE: 8-3-2017

**COMPLIED WITH ANNUAL INSPECTION IAW BELLANCA SERVICE MANUAL AND THIS PROPELLER
HAS BEEN DETERMINED TO BE IN AN AIRWORTHY CONDITION. SEE AD LISTING FOR COMPLIANCE.
MAINTENANCE CARRIED OUT ON THE AIRCRAFT IDENTIFIED ABOVE WAS CARRIED OUT AND
INSPECTED IN ACCORDANCE WITH CURRENT REGULATIONS OF THE FAA ADMINISTRATION
AND IS APPROVED FOR RETURN TO SERVICE. FOR RELEVANT DETAILS OF WORK CARRIED OUT
ARE HELD ON FILE WO# 2119.**



ERIC MENGELSON A&P 3026965 IA

AUTHORIZED SIGNATURE FOR MONARCH AVIATION MAINTENANCE INC.



Description of all operations pertaining to Airworthiness Directives,
Service Documents, Overhaul, Major or Minor Repair, and Inspections.
MONARCH AVIATION MAINTENANCE INC.

619 AIR PARK RD., DEFUNIAK SPRINGS, FL 32435

N6650V, BELLANCA 17-30, TSOH: 553.61, TACH: 2746.11, DATE: 9-7-2018

COMPLIED WITH ANNUAL INSPECTION IAW BELLANCA SERVICE MANUAL AND THIS PROPELLER
HAS BEEN DETERMINED TO BE IN AN AIRWORTHY CONDITION. SEE AD LISTING FOR COMPLIANCE.
MAINTENANCE CARRIED OUT ON THE AIRCRAFT IDENTIFIED ABOVE WAS CARRIED OUT AND
INSPECTED IN ACCORDANCE WITH CURRENT REGULATIONS OF THE FAA ADMINISTRATION
AND IS APPROVED FOR RETURN TO SERVICE. FOR RELEVANT DETAILS OF WORK CARRIED OUT
ARE HELD ON FILE WO# 2307.



ERIC MENGELSON A&P 3026965 IA

AUTHORIZED SIGNATURE FOR **MONARCH AVIATION MAINTENANCE INC.**



SOUTH COAST PROPELLER SERVICE, INC.
5750 DUROSE DRIVE, BESSEMER, AL 35022

205-426-7022
REPAIR STATION #S6PR302X

MAJOR OVERHAUL. BLADES REFINISHED. PARTS FLORESCENT PENETRANT
INSPECTED, MAGNAFLUXED, REPLATED & REPLACED WHERE REQUIRED.
PROPELLER TRACKED, BALANCED, SET ANGLES, GREASED AND PAINTED.
COMPLIES WITH AD'S & SB'S LISTED ON 8130-3 FORM.
BLADE S/N#S INSTALLED ARE: J98539, J98540, J98537

WORK ORDER # SR-13265
MODEL # HC-C3YF-1RF
BLADE MODEL # F8468A-8R

HUB SERIAL # EC1726B

DATE: 10/25/2019

JAMES M GAITHER,
GENERAL MANAGER



WO: 2489

Propeller - page 1 of 1



Eagle Aviation Maintenance - 619 Air Park Road - Defuniak Springs, FL 32435 - 850-951-2111

N6650V

Tach: 2822.78

October 28, 2019

TSOH: 0.01. REMOVED PROP FOR OVERHAUL. REINSTALLED PROPELLER AFTER OVERHAUL BY
SOUTH COAST PROPELLER SEE 8130.

With respect to the work performed, this propeller is approved for return to service. Details of work performed are on file with Eagle Aviation Maintenance under work order: 2489.

Eric Mengelson A&P 3026965



Description of all operations pertaining to Airworthiness Directives,
Service Documents, Overhaul, Major or Minor Repair, and Inspections.

WO: 2633

Propeller - Page 1 of 1



Eagle Aviation Maintenance Inc. • 619 Air Park Road • Delunyak Springs, FL 32435 • 850-951-0042

N6650V

tach: 2857.46

December 8, 2020

TSOH: 34.68. COMPLIED WITH ANNUAL INSPECTION IAW BELLANCA SERVICE MANUAL AND THIS PROPELLER HAS BEEN DETERMINED TO BE IN AN AIRWORTHY CONDITION. SEE AD LISTING FOR COMPLIANCE. MAINTENANCE CARRIED OUT ON THE AIRCRAFT IDENTIFIED ABOVE WAS CARRIED OUT AND INSPECTED IN ACCORDANCE WITH THE CURRENT REGULATIONS OF THE FAA ADMINISTRATION AND IS APPROVED FOR RETURN TO SERVICE.

With respect to the work performed, this Propeller is approved for return to service. Details of work performed are on file with Eagle Aviation Maintenance under work order: 2633.

Eric Mengelson IA 3026965

A handwritten signature in blue ink, appearing to read "EM", is written over a horizontal line.



Eagle Aviation Maintenance Inc. · 619 Air Park Road · Delunyak Springs, FL 32435 · 850-951-0042

N6650V

TACH: 2899.82

January 19, 2022

TSOH: 77.04

COMPLIED WITH ANNUAL INSPECTION IAW BELLANCA SERVICE MANUAL AND THIS PROPELLER HAS BEEN DETERMINED TO BE IN AN AIRWORTHY CONDITION. SEE AD LISTING FOR COMPLIANCE. MAINTENANCE CARRIED OUT ON THE AIRCRAFT IDENTIFIED ABOVE WAS CARRIED OUT AND INSPECTED IN ACCORDANCE WITH CURRENT REGULATIONS OF THE FAA ADMINISTRATION AND IS APPROVED FOR RETURN TO SERVICE.

With respect to the work performed, this Propeller is approved for return to service. Details of work performed are on file with Eagle Aviation Maintenance under work order: 2762.

Eric Mengelson IA 3026965

A handwritten signature in black ink, appearing to read "Eric Mengelson", written over a horizontal line.

wo: 2874

Propeller · page 1 of 1



Eagle Aviation Maintenance Inc. · 619 Air Park Road · Defuniak Springs, FL 32435 · 850-951-0042

N6650V

February 02, 2023

TACH: 2911.15

TSOH: 88.36

COMPLIED WITH ANNUAL INSPECTION IAW BELLANCA SERVICE MANUAL AND THIS PROPELLER HAS BEEN DETERMINED TO BE IN AN AIRWORTHY CONDITION. SEE AD LISTING FOR COMPLIANCE. MAINTENANCE CARRIED OUT ON THE AIRCRAFT IDENTIFIED ABOVE WAS CARRIED OUT AND INSPECTED IN ACCORDANCE WITH CURRENT REGULATIONS OF THE FAA ADMINISTRATION AND IS APPROVED FOR RETURN TO SERVICE.

With respect to the work performed, this Propeller is approved for return to service. Details of work performed are on file with Eagle Aviation Maintenance under work order: 2874.

Eric Mengelson IA 3026965

A handwritten signature in black ink, appearing to read "Eric Mengelson", is written over a horizontal line.