

THE
adlogTM

AIRCRAFT
MAINTENANCE
RECORDKEEPING
SYSTEM

Right #2



ENGINE MAINTENANCE RECORDS

Custom Airmotive, Inc.
FAA REPAIR STATION #DC2R763K
AIRCRAFT ENGINE SERVICE
2702 N. SHERIDAN, BLDG. B
TULSA, OK 74115
(918) 836-6836
FAX (918) 836-9431



ENGINE MAINTENANCE RECORDS

Log No. 2

Aircraft Registration No. N11AC

Engine Manufacturer Continental

Model IO-550-E1B

Serial No. 283378-R

Date installed on aircraft _____

Time Between Overhauls (TBO) _____ Hours

If used on multi-engine aircraft:

- | | |
|---|-------------------------------|
| <input checked="" type="checkbox"/> Right | <input type="checkbox"/> Left |
| <input type="checkbox"/> Front | <input type="checkbox"/> Rear |

(All applicable information must be filled in)



AEROTECH PUBLICATIONS INC.

P.O. Box 1359 / Southold, NY 11971-0965

DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
				TOTALS brought forward from previous page

ENGINE MAJOR OVERHAULED TO MANUFACTURERS SPECIFICATIONS

TT _____ TSMOH 2.1 (test run time only)
 MODEL IO-550-E (1) S/N 283378-R

The aircraft engine identified above was repaired and inspected in accordance with manufacturers specifications and current Regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details of the repairs are on file at this repair station under,

Work order number 24811

Dated 25 AUG 2015 Signed Marcel Lichter for

Custom Airmotive, Inc.
 2702 North Sheridan Road (Bldg. B)
 Tulsa, OK 74115 U.S.A.
 Ph. 918-836-6836 Fax 918-836-9431
 FAA Certified Repair Station DC2R763K

Fuel system, prop gov., tach gen., vac. pump, alternator & magnetos were also overhauled (see maint. release). Ignition harness & spark plugs are new. This engine is equipped with Factory new genuine CMI P/N 658592A2 steel bore cylinders.

Model IO-550-E S/N 283378-R WO# 24811 Total Time _____

A.D. # Method of compliance

86-13-04 N/A TO THESE NEW CYLINDERS.

88-03-06 N/A; HAS ORIGINAL SCREEN TYPE.

91-19-03 “ ”

93-08-17 C/W BY USE OF CORRECT PICK-UP TUBE.

93-10-02 N/A TO THESE NEW CYLINDERS MANUF. AUG 2015.

99-19-01 N/A TO THIS CRANKSHAFT S/N D219718N.

00-23-21 “ ”

04-08-10 N/A TO THESE CMI CYLINDERS.

07-04-19 N/A TO THESE CMI CYLINDERS.

09-19-07 C/W BY INSPECTION (AFFECTED CYLINDERS NOT INSTALLED).

10-11-04 N/A; AFFECTED P/N LIFTERS NOT INSTALLED.



12-03-06 N/A; AFFECTED PARTS NOT INSTALLED.

14-05-29 N/A TO THESE CMI CYLINDERS.

Signed Marcel Lichter for CRS# DC2R763K on 25 AUG 2015

SUB-TOTALS this page

TOTALS—Carry forward to next page

DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK
TOTALS brought forward from previous page				
<div style="display: flex; justify-content: space-between;"> wo: WO_0009 Engine R : page 1 of 1 </div> <div style="text-align: center;">  <p>WEST HOUSTON AERO Aircraft Service and Parts 18000 Groschke Rd Hanger 3E</p> </div> <p>West Houston Aero · 18000 Groschke Rd Ste 3E · Houston, TX 77084 · 713-724-5002 · N/A#: —</p> <hr/> <div style="display: flex; justify-content: space-between;"> <div> <p>N11AC HOBBS: 6062.8</p> </div> <div> <p>Continental, IO-550-E, S/N: 283378 SMOH: 39.2</p> </div> <div> <p>July 14, 2023</p> </div> </div> <p>POWERPLANT Annual Inspection - Work Performed:</p> <ol style="list-style-type: none"> 1. Engine run-up and compression check; all cylinders satisfactory. 2. Inspect engine, nacelle group, & exhaust system. Check magneto timing. Clean, gap, & test spark plugs. 3. Change oil & filter. Engine wash, run-up, & leak check. Serviced with (10 qt) Aeroshell W100 SAE 50 Oil. 4. Perform AD research. <p>I certify that this Engine has been inspected IAW an Annual Inspection, per 14 CFR 43 APPENDIX D and was determined to be in an airworthy condition. Details on file at West Houston Aero under work order: WO_0009</p> <div style="display: flex; justify-content: space-between; align-items: center;"> James Placette IA 3397518  </div>				
SUB-TOTALS this page				