

## AIRFRAME MAINTENANCE RECORD

AIRCRAFT SERIAL AND REGISTRATION

N29247

RECORD NUMBER

D5517-2-13

## **INSTRUCTIONS**

This record should be completed and maintained in accordance with FAA Federal Aviation Regulations 43.9, 43.11 and 91.417 and/or other prevailing government regulations.

Note: Record Service Bulletins and Airworthiness Directives in the back of this record as well as the appropriate Engine/Propeller/Avionics Maintenance Record.

Copyright © 1988



DATE TO IN HOU

MAKE. PIPER MODEL. 28RT201 \$/N: 28R7931195 REG. NO. N29247 WORK ORDER 9981



APR Aviation

Repair Station No. X6DR662I 120 Olmsted Way Monterey, CA 93940 Phone (831) 373-1511 DATE: 1/12/2005 A/C TSN: 3776.8 TACH: 3776.8

AUTHORIZED SIGNATURE, CERTIFICATE TYPE & NUMBER

Airframe Entries

REMOVED OLD BATTERY. SERVICED AND CHARGED NEW G-35 BATTERY. BATTERY INSTALLED.

This aircraft and/or component was repaired in accordance with current Federal Air Regulations and has been approved for return to service. Pertinent details of the repair are on file all files agency.

DATE: 1/12/2005

SIGNED: 4

Work Order 0081

Larry Davis
Certified Repair Station No. X6DR6621

Printed by EBis 3 (datcomedia.com)

MAKE: PIPER MODEL 28RT201 S/N 28RT931195 REG NO N29247 WORK ORDER 9910228



**APR Aviation** 

Repair Station No X6DR6621 120 Olmsted Way Monterey, CA 93940 Phone: (831) 373-1511 DATE: 6/6/2005 A/C TSN 3813 99 TACH 3813 99

Airframe Entries

REMOVED LEFT MAIN WHEEL ASSEMBLY FROM AIRCRAFT REPLACED TIRE WITH NEW 600 X 6 6PLY REPACKED BEARINGS BALANCED TIRE AND RE-INSTALLED ONTO AIRCRAFT

This aircraft and/or component was repaired in accordance with current Federal Air Regulations and has been approved for return to service. Pertinent details of the repair are on file at this agency.

DATE 6/6/2005

SIGNED

Work Order 9910228

Larry Davis
Certified Repair Station No. X6DR6621

Printed by EBis 3 (datcomedia com)

DATE	TOTAL	TIME	MAINTENANCE RECORD		
	IN SER	VICE	DESCRIPTION OF THE WORK PERFORMED		AUTHORIZED SIGNATURE, CERTIFICATE TYPE & NUMBER
			APR Aviation  120 Olmsted Way  Monterey CA 93940  866-373-3672  FAA CRS # X6DR6621  Wo # 910347 Reg # N09247 Hrs 3828-88  I Certify that the altimeter and static system tests required by FAR 91.411 have been performed. Performance was found to be in accordance with FAR 43 Appendix E. The altimeter/s have been tested to 20,000 ft.  The transponder in this aircraft was checked this date in accordance with FAR 91.413. Its performance was found to be in accordance with FAR 91.413. Its performance was found to be in accordance with FAR 91.413. Its performance was found to be in accordance with FAR 43 Appendix F. Test results are on file for transponder.  Make Collins M/N TOR-950 S/N 10907  INSP. Reduced:  Date 7-26-08		
DATE	TOTAL		MAINTENANCE RECORD		THORIZED SIGNATURE
	HOURS	_	MODEL 28RT201 A/C TSN:	D HECK TY worthy	THORIZED SIGNATURE, CERTIFICATE TYPE & NUMBER

MAINTENANCE RECORD						
DATE	TOTAL IN SER	VICE	DESCRIPTION OF THE WORK PERFORMED	AUTHORIZED SIGNATURE, CERTIFICATE TYPE & NUMBER		
			MAKE: PIPER MODEL: 2877201 SIN: 2887391195 REG. NO: N29247 WORK ORDER: 9910692  APR Aviation Repair Station No. X6DR662I 120 Olmsted Way Monterey, CA 93940 Phone (831) 373-1511  Airframe Entries FOUND OIL TEMP PROBE CONNECTOR BROKEN. INSTALLED NEW EYELET. OP'S CHECKED GOOD.			
			This aircraft and/or component was repaired in accordance with current Federal Air Regulations and has been approved for return to service. Pertinent details of the repair are on file at this agency.  DATE: 1/10/2006 SIGNED: Work Order: 9910692  Larry Davis Printed by EBis 3 (datcomedia.com)  Certified Repair Station No. X6DR6621			
DATE	TOTAL IN SEF HOURS	RVIC	MAKE: PIPER MODEL: PA-28RT-201T SR: 28F733198 REG. NO. N29247 WORK ORDER: 9910833  AIfframe Entries REMOVED BATTERY SERVICED, CHARGED, AND REINSTALLED.  This aircraft and/or component was repaired in accordance with current Federal Air Regulations and has been approved for return to service. Pertinent details of the repair are on file at this agency.  DATE: 4/20/2006  SIGNED:  Work Order: 9910833  Printed by EBis 3 (datcomedia.com	A NOWIDER		

	_		MAINTENANCE RECOR	D	
DATE	TOTAL IN SEF				HORIZED SIGNATURE, CERTIFICATE TYPE
	11100110				& NUMBER
		MAKE PIPER MODEL PA-28RT-201T S/N 28R7931195 REG NO N29247 WORK ORDER 9911110	APR Aviation, Inc.  Repair Station No. X6DR6621 120 Olmsted Way Monterey. CA 93940 Phone. (331) 373-1511	DATE 11/6/2006 A/C TSN 3907 25 TACH 3907 25	
		Airframe Entries			
		MANUALS REPLACED NU COMPRESSOR UNREPAIR IGNITION SWITCH TEST. O	INSPECTION IAW FAR 43 APPENDIX (d) AND AL JMBER ONE NAV LAST DIGIT WITH NEW P/N 42! ABLE. REPLACED COMPLETE TURBO CHARGE! DPS CHECK GOOD REMOVED COMPLETE EXF TERMINE THAT IT NEEDED TO BE REWORKED	953-31150 OPS CHECK GOOD TURBO R WITH NEWC/W AD 76-07-12 R1 BENDIX HAUST SYSTEM AND SENT OUT FOR	
		 REWORK REMOVE DEBF BEARINGS WITH NEW . CV 402-940 DRAINED AND R CORROSION BEHINED FUI UNITS GASKETS, REINSTA	TERMINE THAT IT NEEDED TO BE REVORKED.  INS FROM LEFT FUEL TANK DRAIN VALVE, OPS W PIPER SB #1156 REPLACEMENT OF NOSE GF EMOVED LEFT AND RIGHT FUEL TANKS TO CA EL TANKS NO CORROSION FOUND REPLACED ILLED FUEL TANKS AND FILLED WITH AVGAS. ILLED WITH AVGAS. IN W PIPER MANDATORY SB 940A INTSALLATION	CHECK GOOD REPLACED NOSE WHEEL EAR DRAG LINK BOLT WITH NEW BOLT PN W PIPER SB 1006 INSPECTION FOR D VENT LINE HOSES AND FUEL SENDING LEAK CHECK GOOD N/A TURBO	
		WIRE INSTALLED C/W PIF PIPER SB # 717 FUEL SELE EQUIPPED C/W SB 884 LG N/A AS EQUIPPED PER PA EQUIPPEDC/W SB 625A	MTCH ACTUATING TAB P/N 67210-008. PIPER PER SB 694 THROTTLE ROD END ATTACHMEN' ECTOR LINE INSPECTION, NO DEFECTS NOTIC DCK WIRING OF V-BAND CLAMPS WHEN EXHAI RKER HANNIFIN SB# 7063. PIPER SB#691A N/F FUEL AND VAPOR RETURN LINES SUPPORT.	T INSPECTION, NO DEFECTS NOTEDCW I.E PIPER SB#1136 N/A AS UST WAS REASSEMBLEPIPER SB# 1023 A AS EQUIPPEDPIPER SB# 1118 N/A AS REPLACED RIGHT TRIM CABLE PULLY	
		TO COMPLY WITH INSPEC	OOD PERFORMED FAR 91.207(D) ELT OPER- CTION AND OPERTIONAL CRITERIA. ELT BATTE FT BAFFLETORQUED BAGGAGE LOCK MOUN	ERY DUE 7-07. REPLACED BOTTOM COWL	
		condition	has been inspected in accordance with a ANNUAL	L inspection and was determined to be in airworthy  Work Order: 99111	
		DATE: 11/6/2006	SIGNED.  Larry Davis Certified Repair Station No. X6DR6621	Printed by EBis 3 (datcomedia.co	<del></del>



			MAINTENANC	E RECORD		
	MAKE PIPER MODEL PA-28rt-201T S/N 28R-7931195 REG NO N29247 WORK ORDER 393	Monterey Bay Aviation 130 Olmsted Way Monterey, CA 93940 Phone 831-373-3201	1	DATE 12/21/2007 A/C TSN 3975 99 TACH 3975 99		AUTHORIZED SIGNATURE, CERTIFICATE TYPE & NUMBER
	ACMM REPLACED RETRACTION/EXTE ACTUATOR CLIPS I 066-10500 REPLA	NNUAL INSPECTION I/A/W THE INSTRUMENT AIR FILTERS PN INSION TEST, NORMAL AND EIPN 451-848 & 6752-03, FUNCTI ACED LEFT MAIN BRAKE CALIPINSPECTION AND FUNCTION TI	SCOPE AND DETAIL OF FAR 43 APPEN AAD9-18-1 & ARB3-5-1 PERFORMED L/ MERGENCY . REPLACED NOSE GEAR ON TEST GOOD REPLACED BRAKE I ER O-RING WITH NEW P/N MS28775-22 ST, NO DEFECTS NOTED REPLACED	ANDING GEAR DOWN LIMIT SWITCH LINNINGS WITH NEW PN 2 AND BLED BRAKE CW		
	I certify this airframe condition  DATE 12/21/2007	SIGNED La	e with an annual inspection and was determined by the second of the seco	Work Order 393 ad by EBis 3 (datcomedia com)		INTEX 1.00 BOOK ENTRY REPLACEMENT DATE
Rem A&P Terry	h: 3963	ed battery (p/n G35). Pe	132 Powell Butte Hwy. T S/N: 28R-7931 W/O: 07-40942 formed operations check, no d  Professional Travel that works for	efects noted.	41) 388-00 EMBER-20	MATEX MICRAFT SAPPLIES, INC. 1005 15 19:505 10002  301 5 19:505 10002  300 547:8901  300 547:8901
DATE			MAINTENANC	E RECORD		
	IN SEF	S/N 28R-7931195 REG. NO: N29247 WORK ORDER: 914	Monterey Bay Aviation Repair Station No. DQCR259B 114 Airport Way Sullie A donterey, CA 93940		<sup>7</sup> February, 2009 IC TSN: 4011.18 TACH: 4011.18	AUTHORIZED SIGNATURE, CERTIFICATE TYPE & NUMBER
		Airframe Entries PERFORMED AN ANNUL DISASSEMBLED GASCC CHECK GOOD. REPLACE REPLACED UPPER TAIL NOSE GEAR ASSEMBLY RE-ASSEMBLED NOSE REMOVED OLD HYDRAI NITROGEN C/W FAR S	AL INSPECTION IAW FAR 43 APPENDIX DIATOR AND CLEANED SCREEN. REAS: ED VACUUM FILTER WITH NEW PIN AA NAV LIGHT BULLB WITH NEW PIN GE AND REPLACED NOSE GEAR TRUNNIC SEAR ASSEMBLY WITH NEW BOLTS PIN LIC FLUID FROM NOSE GEAR STRUT A 12 207 (D) ELT INSPECTION AND FINCT	D AND ALL APPLICABLE MAINTENANCE M SEMBLED WITH NEW GASKET P/N 462-049 D9-18-1 AND VALVE FILTER P/N ARB3-5-1. 1777. OPERATIONAL CHECK GOOD REM ON UPPER BEARINGS WITH NEW P/N 6702 N ANT-42A. GEAR OPERATIONAL CHECK G OND SERVICED WITH NEW 5606 FLUID AN TIONAL TEST, NO DEFECT NOTICE. NEXT 111.18 OR ANNUAL C/W AD76-07-12R-1 @ TACH 4111.18 OR ANNUAL PERFORM	0, LEAK  10VED 6-011 5000 D	
		I certify this airframe has b condition.	een inspected in accordance with an annu	al inspection and was detemined to be in an a	irworthy	
	<del> </del> .	DATE: 17 February, 2009	SIGNED:  Lawrence Davis Certified Repair Station No. DQCR28		k Order: 914 omedia.com)	
-						

		MAINTENANCE RECORD	
DATE	TOTAL TIME IN SERVICE HOURS 10THS	DESCRIPTION OF THE WORK PERFORMED	AUTHORIZED SIGNATURE, CERTIFICATE TYPE & NUMBER
		MAKE PIPER MODEL PA.28n-201T SN 28R-7931195 REG NO N29247 WORK ORDER 1113 Monterey Bay Aviation Report Superior	ns and has been
		approved for return to service in regards to the work performed above Perturent details are on file at the DATE 13 August, 2009 SIGNED	Work Order 1113
		Lawrence Davis Printed by Certified Repair Station No. DQCR259B	EBis 3 (datcomedia com)
tests by F/ Altim IAW Sign	required by FAR 91.411, a AR 91.413 have been performeter(s) tested to FAR 43 App. E on 6		S ds
DATE	TOTAL TIME	MAINTENANCE RECORD	
DATE	IN SERVICE HOURS 10THS	DESCRIPTION OF THE WORK PERFORMED	AUTHORIZED SIGNATURE, CERTIFICATE TYPE & NUMBER
		MAKE PIPER MODEL PA-26r-201T SIN 28R-7931195 REG NO: N29247 WORK ORDER: 1315  Aifframe Entries  PERFORMED AN ANNUAL INSPECTION I/A/W THE SCOPE AND DETAIL OF FAR 43 APPEN APPLICABLE MANUALS. REPLACED INSTRUMENT AIR FILTERS PN AAD9-18-1 & ARB3-5-1 AND REPACKED WHEEL BEARINGS PERFORMED LANDING GEAR RETRACTIONEXTENS EMERGENCY NO DEFECTS NOTED INSTALLED NEW ELT BATTERY PN BP-1026 C/W OPERATIONAL TEST, NO DEFECT NOTICE C/W AD76-07-12 R1 BENDIX IGNITION SWITC NO DEFECT NOTICE REPAIRED ENGINE CONTROL COVER IAW STANDARD PRACTICE SCAT TUBE WITH NEW  I certify this airframe has been inspected in accordance with an annual inspection and was determined to the support of the suppo	CLEAND, INSPECTED, SION TEST, NORMAL AND FAR 91 207 (D) ELT CH OPERATIONAL CHECK REPLACED DEFROST

		MAINTENANCE RECORD	
DATE	TOTAL TIME IN SERVICE HOURS 10THS	DESCRIPTION OF THE WORK PERFORMED	AUTHORIZED SIGNATURE, CERTIFICATE TYPE & NUMBER
		MAKE PIPER MODEL PA-28h-201T SIN 28R-7931195 REG NO N29247 WORK ORDER: 1810 Repair Station No. DQCR259B SIT-4 Airport Way Suite A Monterey. CA 93940 Phone. 831-375-2359  Airframe Entries REMOVED BATTERY AND CHARGED OVER NIGHT. CHECKED BATTERY AND FOUND TWO CELLS WASN'T TAKING CHARGE REPLACED BATTERY WITH NEW P/N G 35 S/N G02515648 CUSTOMER SUPPLIED BATTERY.  This aircraft and component was inspected or repaired in accordance with current federal air regulations and has been approved for return to service in regards to the work performer above. Pertinent details are on file at this agency.  DATE: 05 January, 2011  SIGNED:  Work Order: 16 Lawrence Davis Certified Repair Station No. DQCR259B	A
		MAINTENANCE RECORD	
DATE		Pacific Aircare Inc.  Watsonville Ca. CRS JP5R604X  N29247 TACH: 4121.14 TOTAL TIME: 4121.14  Annual Inspection completed this date IAW Pacific Aircare's FAA approved annual inspection form. Complied with FAR 91.207(d) ELT battery next due: May 2012.  C/W AD 93-05-06 Ignition switch by test. Removed and replaced #4 and #6 cylinders with new overhauled cylinder assemblies. Re-timed left and right magnetos to 20 deg BTDC. Installed missing nose gear stop with new, rigged IAW service manual. Replaced left and right main gear drag brace bushings and bolts with new IAW piper service manual, swung gear and ops ck good. Replaced sun visor supports with new. I certify this syframe has been inspected IAW an ANNUAL inspection and found to be in an airworthy transition.  Signed  Date: 08/23/2011	AUTHORIZED SIGNATURE, CERTIFICATE TYPE & NUMBER

	TOTAL	TIME	MAINTENANCE RECORD	
DATE	TOTAL IN SER HOURS	AUTHORIZED SIGNATURE, CERTIFICATE TYPE		
			I certify that the Altimeter, Static System, & Altitude Reporting tests required by FAR 91.411, and the Transponder tests required by FAR 91.411, and the Transponder tests required by FAR 91.413 have been performed IAW FAR 43 App E & F. Altimeter(s) tested to 2000 Ft. N29247 IAW FAR 43 App, E on 2001 Ft. N29247 Signed Date 2001 Time 41.42.36	3000 -25 4000 -25 8000 -30 8000 -40
				•
			MAINTENANCE RECORD	
DATE	TOTAL IN SER HOURS		DESCRIPTION OF THE WORK PERFORMED	AUTHORIZED SIGNATURE, CERTIFICATE TYPE & NUMBER
-13-12			REMOVED NARCO DRE-195 DME SYSTEM, INSTALLED IN WITH KA-43 FREQUENCY CONVERTER AND KA-58 HOLD ADAPTOR INDICATOR, NEW EMPTY WEIGHT 1972.12, NEW ECG 96-36	AND K1-266 DER
			121.88	
	-	-	Airmartronics, Avionics Div.	
			FAA Repair Station #BG3R395t	
	+	1		


			MAINTENANCE RECORD	
DATE	TOTAL IN SER HOURS	VICE	DESCRIPTION OF THE WORK PERFORMED	AUTHORIZED SIGNATURE, CERTIFICATE TYPE & NUMBER
			Piper PA-28RT-201T S/N:28R-7931195 TACH:4211.64 T.T.4211.64	
			Airframe: Performed an Annual Inspection in accordance with the scope and details of FAR 43 Appenddix D and all applicable manuals. Lube all flight controls, pullys and rodends. Complied with FAR 91.207 (D) ELT inspection and functional test, no defect	
			2015. Complied with AD13-02-13 Horizontal Stabilator Control Cables Inspection, no defect found, next due at 2/2021 or tach time 6211.64. Landing gear swung and checked for proper as a section.	
			no defect notice, lubed gear. Installed overhead vent cable clap and hold down. Replaced left main gear tire nwith new 600x6 6PR. Repacked landing gear wheel bearings.  I certify this aircraft was inspected in accordance with an annual inspected and has been determined.	
			inspected and has been determind to be in an airworthy condition.  Lawrence J. Davis A&P 2713370 IA.  Signed:  Date: 2/5/14	
			-	
D.177	T		MAINTENANCE RECORD	
DATE	IN SEE	RVICE	DESCRIPTION OF THE WORK PERFORMED	AUTHORIZED SIGNATURE, CERTIFICATE TYPE & NUMBER
	-		——— Piper Arrow N29247 ——— Tach:4249.25	
	-		Engine: Replaced sparkplugs with new P/N REM38E. Removed fuel injectors, cleaned and re-installed.Aircraft ran by owner, ops	
	-		checked good.  I certify this aircraft has been repaired in accordance with the current Federal Reg- ulations and has been approved for return	
			to service in regards to the work performed above.  Lawrence J. Davis A&P 2713370.  Signed:	

			MAINTENANCE RECORD	
DATE	TOTAL IN SER HOURS	VICE	DESCRIPTION OF THE WORK PERFORMED	AUTHORIZED SIGNATURE, CERTIFICATE TYPE & NUMBER
			Piper PA28-RT201T Tach:4251.73 T.T:4251.73 Airframe:Performed an Annual Inspection in accordance with the scope and details of FAR 43 Appenddix D and all applicable manuals.Lubed all flight control rod ends, pullys, and hinges. Complied with FAR 21.207 (D) ELT inspection and functional test,no defect notice. ELT battery was replaced with new, next inspection due April 2016 or Annual. Battery exspiration date June 2017. Re-packed landing gear wheel bearing, inspected wheel for defects none found. Swung gear for functional test, no defects notice. Replaced O-rings in brake calipers and bled brakes. Replaced vacuum air filters with new. I certify this aircraft has been inspected in accordance with an Annual Inspection and has been determined to be in an airworthy condition. Lawrence J. Davis A&P 2713870 IA. Sisned:  Date 4/1/2015.	

MAINTENANCE RECORD

DATE	TOTAL IN SER		* * * * * * * * * * * * * * * * * * *	AUTHORIZED SIGNATURE, CERTIFICATE TYPE
	HOURS	10THS	Piper PA-28RT-201T N29247	& NUMBER
	l	1	S/N:28R-7931195 T.T:4278.62	
	1		Tach: 4278.62	
			Performed an Annual Inspection in accordance with the scope and details of FAR 43 Appenddix D and	
		<del> </del>	all applicable manuals. Complied with AD76-07-12	
	1	1	by function test, no defect notice.Complied with	
		1	FAR 91.207 (D) ELT inspection and functional test,	
			no defects found Lube all flight controls rodends,	
			pullys and hinges. Removed landing gear wheels	
	Į.	1	inspected and re-packed bearings. Replaced vac-	
			uum and airfilters. Swung landing gear for functional	
	-	-	test, ops check good.	
	}		I certify this aircraft has been inspected in accord-	1
			ance with an Annual Inspection and has been det-	1
	1		ermined to be in an airworthy condition.	
			Lawrence J. Davis A&P 2713370 IA. Signed: Date: 6/1/2016.	
			Signed:Date: 6/1/2016.	
	1			
				55

MAINTENANCE REI						
DATE TOTAL TIME IN SERVICE DESCRIPTION OF THE WORK PE	Reads -1000 0 500 1500 2000					
Altimeter(s) tested to ARPRIT	Scale Con Altimete Add Scale Con Altimete Scale Con Al					
Northcoast Services crs WR3R955L Time 4301.93  Piper PA-28RT-201T S/N:28R-7931195 Tach:4301.93	N29247 T.T:4301.93 ———					
Performed an Annual Inspection in accordance with thescopem anddetailsof FAR 43 Appendix D and all applicable manuals. Complied with AD76-07-12 by functional test with no defects noticed. Replsaced ELTbattery with new. performed FAR 91.207.D ELT						
inspection and functional test, ops Lube all flight control rodends, pully Removed landing gear wheels, cle lubed and re-installed. Replaced n Replaced Garter Filter with new.	rs and hinges. ————————————————————————————————————					
I certify this aircratf has been inspo with an Annual Inspction and has to to be in an airworthy condition. Lawrence J. Devis A&P2 \13370 I/	been determined					
	ate: <u>5/30///</u> 2					
MAINTENANCE RECORD						
DATE TOTAL 1 IN SERV HOURS	AUTHORIZED SIGNATURE, CERTIFICATE TYPE & NUMBER					
Piper PA-28RT-201T N29247 S/N:28R-7931195 T.T:4313.48 Tach:4313.48						
Performed an Annual Inspection in accordance with the scope and details of FAR 43 Appendix D and all applicable manuals. Complied with AD76-07-12 by functional test with no defects noticed.						
Performed FAR 91.207.D ELT Battery condition, inspection and functional test, ops check good.  Lube all flight control rodends, pullys and hinges.  Removed landing gear wheels, cleaned, inspeced, lubed and re-installed. Replaced neumatic fiter new.						
I certify this aircraff has been inspcted in acordance with an Annual Inspction and has been determined to be in an airworthy condition						
Lawrence J. Davis A&P2713370 IA. Davis. Date 7-18						



RE.

MAKE. Piper MODEL PA 28RT-201T S/N: 28R-7931195 REG. NO N29247 WORK ORDER: 18366

## **Mather Aviation**

Repair Station No. CUXR041D 801 Airport Way Modesto, CA 95354 Phone: 209-577-6831

## Airframe Entries

Removed the Following:

OEM red Position light and attached Strobe

installed the following equipment.

uAv-1001856-002 S/N 1009378 in accordance with skyBeacon STC Installation Guide, Document # UAV-1002305-001 Rev F. Used existing OEM position light circuit and confirmed appropriate per AC43.1 3-B Chapter 11, Section 5&6.

Red position light was terminated to the skyBeacon position light wire (red wire) using Environmental Splice (Part # UAV-1001487-001) skyBeacon Ground wire (black wire) was terminated to airframe. Strobe high voltage excitation input power was disconnected from the strobe high voltage power supply. Strobe input power wire was terminated to the skyBeacon strobe wire (yellow wire) using environmental splice (Part # UAV-1001487-001 or equivalent) Placard installed above position light switch

1. Maintenance and Trouble Shooting Instructions: uAvionix Document # UAV-1002112-001 Rev A.

2. Airplane Flight Manual Supplement: uAvionix Document # UAV-1002112-001 Rev A.

3. Airworthiness Limitation: No additional Airworthiness Limitations

4. Weight and balance negligible and Equipment list revised

5. The above modification was found not to interfere with other installed systems and/or modifications and does not exceed 80% of Alternator output. No adverse interference to radios and navigation systems from RFI were found while operating skyBeacon during Configuration process. The installed ADS-B OUT system is shown to meet the equipment performance requirements of 14 CFR section 91-227. All work was accomplished Per A.C. 20-138A and para. 15; AC 43.13-1 B chapter 11 and chapter 12 and AC43.13-2B chapter 2, chapter 3, and paragraph 36, and described Manuals listed above. Installation is shown to meet the requirements of 14 CFR Section 91.228. Performed the ATC Transponder correspondence check Per FAR Part 43 appendix E (a) (c) and appendix F. All operational/functional/leak checks are good.

Modified Acrylic Lens to Fit Sky Beacon Blade. Sealed with RTV Sealant.

Finalized all paperwork and Authorized for Return to Service

Technicians Who Worked On The Items Listed Above: John Freitas, Robert Jackson

The above maintenance has been completed in accordance with current Federal Aviation Regulations.

I certify this airframe has been inspected in accordance with FAR 91.409(f)(3), has been found to be in an airworthy condition with respect to the work performed and is approved

Pertinent details are on file at Mather Aviation under the Work Order indicated in this logbook entry.

DATE: 1/24/2020

SIGNED

Work Order: 18366

Steve Hake

Certified Repair Station No. CUXR041D

Printed by EBis 3 (datcomedia.com)





DATE	IN SER	VICE		AUTHORIZED SIGNATURE, CERTIFICATE TYPE
	HOURS	10THS	Piper PA-28RT-201T N29247	& NUMBER
		1	S/N:28R7931195 T.T:4322.99	
			Tach:4322.99	
				1
			Performed an Annual Inspection within the scope and	
		1	details of FAR 43 Appendix D and all applicable man-	1
			uals. Complied with AD76-07-12 by functional test,no	1
		1	defect notice.Complied with FAR 91.207 D ELT insp-	1
		-	ection and functional test, ops check good. Battery	
			replacement date Sept.2021. Lubed all flight controls	
			rodends and pulleys.Removed landing gear wheels	1
			and cleaned, inspected and repacked bearing.	1
			Replaced brake linings with new and conditioned	<del></del>
10-6		1	brakes.Replaced induction airfilter with new BA-8.	1
			Replaced neumatic filter with new.	1
			I certify this Aircraft has been inspected in accord-	
			ance with an Annual Inspection and has been det-	
			ermind to be in an airworthy condition.	
			Lawrence J. Davis A&P 2713370 IA.	i
			Signed: Date:7/2/2020	1
			V	
	3			1
				l
411				

		MAINTENANCE RECORD	
DATE	TOTAL TIME IN SERVICE HOURS 10THS	DESCRIPTION OF THE WORK PERFORMED	AUTHORIZED SIGNATURE, CERTIFICATE TYPE & NUMBER
		Cutting Edge, 3600 Carol Kennedy Drive Hanger D, San Andreas CA 95249  Date: 08-09-2021 Logbook: Airframe Tail Number: N29247	
		Tach: 1703.1 Model: PA-28RT-201T Serial: 28R-7931195	
	Repairs	/ Maintenance	
	pe	ertify that the Altimeter(S) and Static system(S) test required by CFR 91.411 and insponder tests, including data correspondence, required by CFR 91.413, have been formed and found to comply with 14 CFR part 43, Appendix E and F.	
	Te	sted to: 20,000 feet. (Next due: 8/31/2023)	
	The wor regulation RETURI	k described on the above work order was performed in accordance with current ons of the FEDERAL AVIATION AGENCY. It is airworthy and is APPROVED FOR	
	Certifica	te: CEAR996D BTS Name: JASON KUBIAK	
	Sign:	Date: 08-09-2021	

		6		
			MAINTENANCE RECORD	
8/12/21	IN SEF	RVICE	DESCRIPTION OF THE WORK PERFORMED	AUTHORIZED SIGNATURE, CERTIFICATE TYPE & NUMBER
Jack:	435	1.73	Annual inspection Clw 1.A.W. FAR	43 (app.D) 4 Piper
	-		Maintenance Manual. checked + lubed all flight e	
			Caldles + Indeed Pulleys. checked + charged botte liquito. cleaned + Parked wheel Bearings - checked	Y · checical all
	-		91(207) d. orcay. Replaced Eli Battery Non- are @ 1	vov. 2023. O Press.
			Hear cheered Exhaust system. (3) Replaced wider thered widnestion system + tunto. (3) Replaced V	de file. Jacked
	-		Aircraft Performed Landing gear retraction check	
-			extensión check. Occay. @clw A.D. 97-01-01 R1 M for exacus. Occay. Oclw A.D. 2013-02-13 HOREZI. State Occay. Oclw A.D. 76-07-12 Sylon . D occay. Occay.	din L. Gear Brace control Syptem cenned fuel filler.
			I certify that this Alc has been inspected 1. A.w. An and has been determined to be in our worthing conditions	d'm
	,		SONI AVIACION	1 22 13023 A

	MAINTENANCE RECORD				
	DATE 2022	TOTAL IN SER HOURS	RVICE	DESCRIPTION OF THE WORK PERFORMED	AUTHORIZED SIGNATURE, CERTIFICATE TYPE & NUMBER
10	3 2022,	4 363	21	Annual inspection completed 1.1	
				And Piper Maintenance Manual. Checked + Lubad	al fran
				all lights. Okay. Replaced AIC Battery with seal	Dullank checked
				35Axc. 8140.41955200cleaned + Packed Main 1	lose wheel Bearings
				serviced TIRES WITH AIR. Checked Brake Pads. B	led Popul Brances
	- 1	- 1	- 1	+ Bernical Stake Resvoirs. Uchecked Eli I'A'W.	AR91(207) d.
-				oray Mac Gattery change due @ NOV 2023. B	Press. loak
	- 1	- 1		Enecked Exhaust system. & kay, 3 checked-	Turbo Charger-OKay
			Ģ	Enecked Exhaust sigstem. Bkay, 3 checked - Preplaced miduction fine & inspected miduction	supstem. 6
-	-		_	Keplaced vac. filler + central gyro file. 6 JA	exed Alc.
			- 1	Performed Landing gear retraction of emerger	ey extension
	- 1		- 1	check. Orcay. (7) Serviced NOSE SATUL WITH NITH	gen. Ocleaned
-				quel file. 9 clw A.D. 97.01-01 R. Landing as	DE Russ Das
	٠.	1	- 1	Cracks - OKCON TO CIWA-D. 2013 - 02 - 13 HORIZONA	2 Stabilatas
	1	1	1	control system for cracks. Oray. (1) CIWA.D.	76-07-12 ignition
				switch for operation. Oray. (12) Replaced Taxi lite	Bulb. GC 4509.

1 contity that this Alchas been inspected 1.A.w. Annual inspection + was determined to be in an unimy cordination.

MAINTENANCE RECORD				
2024.	IN SER	VICE		AUTHORIZED SIGNATURE, CERTIFICATE TYPE & NUMBER
1/2/2024	4371.	62	appendix D. of piper Maint. Manual checked	I.A.W.FAR 43
			Landing goon restaction chocket emergency es Checked Evi I.A.W. FAR al(207) d. Changed Evi	renced AIC. Performed Herron chanc. orcay Bostery News
			Jue @ feb. 2026. Pressure leak choked Exha modulation film. Serviced Brake Resport with 5606 h Checked Turbo charger for condition-8 Kay. Replace of marrected induction Eystem. Replaced vac. of	i duction and file
			Mose gear down lock actuator. cleaned fuel fill Landing gear Brace for cracks, okay, clw A.D. 2	6. CIWA.D.C17-01-018, 013-02-13 Horizontal
			Stablator control system for cracks - okay. clu A switch for operation - okay replaced travilite ? Certify war lites Alchae been inspect	f sulo.
			inspection + was determined to be in an word	y cordinon.