

TEXTRON Lycoming

652 Oliver Street
Williamsport, PA 17701 U.S.A.
717/323-6181

ENGINE LOG AND MAINTENANCE RECORD

RECORD OF TEXTRON LYCOMING 0-360-A1A L-36296-36A
MAKE MODEL SERIAL
FROM 7/28/98 19 — TO — 19 —
DETAILING TIME FROM 0.00 TO —
HOURS HOURS

SSP 1872-1

October 1994

ENGINE DESCRIPTION

Mfgr. TEXTRON LYCOMING	Place Williamsport, PA 17701	Date
Type RECIP	Model 0-360-A1A	Serial No. L-36296-36A
Rated H.P. 180	Max. H.P. 180	Weight (Dry)
Rated R.P.M. 2700	Max. R.P.M. 2700	Oil Pressure
Bore	Stroke	Displacement 360 Cu. In.
Compression Ratio 8.50/1	Supercharger Ratio N/A	
Reduction Gear Ratio NA		
Propeller	Hub Design	Hub Serial No.
Blade Design	Blade Serial No.	Blade Serial No.
Max. Hub H.P.	Max. Blade H.P.	
Pitch	Diameter	Length
Name LAIRD OWENS		
Address 24033 MOBILE ST WEST HILLS CA 91307		

ENGINE LOG

Serial No. _____

Date	Time		REPAIRS - ADJUSTMENTS - SERVICE - REMARKS	Signature	License Number
	Hrs	Min			
7/28/98			BREAK IN RUN ON STAND BY LYCOMING FOR 1.05 HRS. SEE TEST LOG FORM T-001 (4/95) — 98 ?		
2/1/99	0.00		ENGINE INSTALLED IN AIRCRAFT NS15L (RV-6)	R. B. Wynn	12634
4-24-00	0.00		DRAINED PRESERVATIVE OIL, CLEANED PLUGS + ADDED AERISHELL 100 MINERAL OIL PER LYCOMING RECOMMENDATIONS	R. B. Wynn	12634
	00.0		Page Total		
			Brought Forward		
			Total to Date		

All Repair Data Must Bear the Endorsement of a
Certificated Mechanic, and his Rating and
Certificate Number MUST be Shown.

ENGINE LOG

Serial No. _____

Date	Time		REPAIRS - ADJUSTMENTS - SERVICE - REMARKS	Signature	License Number
	Hrs	Min			
4-24-00	00.0		CONVERTED FROM CONSTANT SPEED TO FIXED PITCH PROP PER LYC SI 1435-9-25-86	R. Owens	ASP 1263422
4-25-00	00.1		INITIAL GROUND LOW POWER RUN	R. Owens	ASP 1263422
5-22-00	00.2		FULL POWER RUN 2125 RPM STATC	R. Owens	ASP 1263422
6-4-00	3.1		OIL + FILTER CHANGED AEROSHELL 100 MINERAL OIL	R. Owens	ASP 1263422
6-20-00	26.1		OIL + FILTER CHANGED AEROSHELL 100 MINERAL	R. Owens	ASP 1263422
6-28-00	26.1		ROTATED SPARK PLUGS TOP/BOT SAME CYL	R. Owens	ASP 1263422
Page Total			All Repair Data Must Bear the Endorsement of a Certificated Mechanic, and his Rating and Certificate Number MUST be Shown.		
Brought Forward					
Total to Date					

License
Number

ASP
1263422

ASP
1263422

ENGINE LOG

Serial No. _____

Date	Time		REPAIRS - ADJUSTMENTS - SERVICE - REMARKS	Signature	License Number
	Hrs	Min			
7-14-00	51.6		CHANGED OIL/FILTER AEROSHELL 100 PLUS	R. Brown	A-P 1263422
9-27-00	101	.2	CHANGED OIL/FILTER AEROSHELL 100 PLUS	R. Brown	A-P 1263422
12-2-00	147	.8	CHANGED OIL/FILTER (AEROSHELL 100) AEROS. PLUS	R. Brown	A-P 1263422
12-2-00	147	.8	ROTATED SPARK PLUGS TOP TO BOTTOM - SAME CYL	R. Brown	A-P 1263422
2-5-01	155	.7	SERVICED AIR INTAKE FILTER		
			DIFF COMP TEST #1-74, #2-76, #3-74, #4-75/80		
			TIMED MAGS PER LYC REOM. 25° BT L+R		
			REPLACED OIL (AEROSHELL 100 PLUS) + FILTER		
			COMPLETED ENGINE CONDITION INSPECTION +	R. Brown	
2-5-01	155	.7	DETERMINED TO BE AIRWORTHY, RETURNED TO SERVICE	A-P	1263422
			Page Total		
			Brought Forward		
			Total to Date		

All Repair Data Must Bear the Endorsement of a
Certificated Mechanic, and his Rating and
Certificate Number MUST be Shown.

ENGINE LOG

Serial No. _____

Date	Time		REPAIRS - ADJUSTMENTS - SERVICE - REMARKS	Signature	License Number
	Hrs	Min			
4-27-01	199	4	CONVERTED ENGINE FROM FIXED PITCH TO CONSTANT SPEED PROP PER LYC SI 1435 dtd 9-25-86. INSTALLED M'CAULEY GOVERNOR & OIL TRANSFER TUBE, COMPLIES WITH AD 39-6427 & AD 39-6915. CHANGED OIL/FILTER - AEROSHELL 100 PLUS GROUND RUN & ADJ GOV 2650 STATIC RPM. DETERMINED TO BE AIRWORTHY AFTER TEST FLIGHT		
4-27-01	199	4	RETURNED TO SERVICE	<i>R. B. Calmof</i>	A+P 1263422
Page Total			All Repair Data Must Bear the Endorsement of a Certificated Mechanic, and his Rating and Certificate Number MUST be Shown.		
Brought Forward					
Total to Date					

License
Number

A-P
1263422

A-P
1263422

A-P
1263422

A-P
1263422

R. B. Calmof
1263422

a

ENGINE LOG

Serial No. _____

Date	Time		REPAIRS - ADJUSTMENTS - SERVICE - REMARKS	Signature	License Number
	Hrs	Min			
6-1-01	253	1	CHANGED OIL/FILTER - REPAIRED BROKEN R.H. EXH TAILPIPE HANGER TUBE + LARD BT WIRE	Rb Owens	APP 1263422
7-21-01	302	0	CHANGED OIL/FILTER, NEW EXH. TAILPIPE HRS INSTALLER WASHERS AT F.W. TO RAISE ENG CTRL	Rb Owens	APP 1263422
			ROTATED SPARK PLUGS Top-Bottom	"	"
9/10/01	349	6	CHANGED OIL/FILTER w/ Aeroshell 100+	Lanid Owens	REPAIRMAN/OWNER 1263422
12-07-01	399	3	CHANGED OIL/FILTER	Rb Owens	APP 1263422
			ROTATED PLUG TOP/BOTTOM + GAP SET 0.018"	"	"
			SERVICED AIR INTAKE FILTER	"	"
			Page Total		
			Brought Forward		
			Total to Date		

All Repair Data Must Bear the Endorsement of a Certificated Mechanic, and his Rating and Certificate Number MUST be Shown.

ENGINE LOG

Serial No. _____

Date	Time		REPAIRS - ADJUSTMENTS - SERVICE - REMARKS	Signature	License Number
	Hrs	Min			
3-1-2002	432	7	CLEANED CARB FUEL FILTER. ROTATED & GAPPED SPARK PLUGS TOP-TO-BOTTOM		
"			COMPLETED CONDITION INSPECTION & FOUND IN		
"			A CONDITION FOR SAFE OPERATION.	RB Owens	ATP 1263422
3-20-02	450	1	CHANGED OIL & FILTER W/ AEROSHELL 100+ (air filter)		REPAIRMAN COST #2643976
6-03-02	49		CHANGED OIL/FILTER. CLEANED, GAPPED (0.018),	RCO	
"			ROTATED PLUGS. PERFORMED 500 HR INSP ON MAGS		
"			PER SUCK SB 82-80 C + L-1363B.		
"			COMPR. CHECK 1/73/80 2/73/80 3/73/80 4/73/80		
"			COMPLETED 100 HR INSPECTION PER REPORT	ATP 1263422	
6-03-02	498	9	DTD 6-3-02, ENCL IS AIRWORTHY & RELEASED TO SERVICE	RB Owens	
			Page Total	All Repair Data Must Bear the Endorsement of a Certificated Mechanic, and his Rating and Certificate Number MUST be Shown.	
			Brought Forward		
			Total to Date		

Signature	License Number
ATP	1263422
ATP	1263422
"	"
"	"
REPAIRMAN/	
OWENS	2643976
ATP	1263422
"	"
"	"

nt of a

ENGINE LOG

Serial No. _____

Date	Time		REPAIRS - ADJUSTMENTS - SERVICE - REMARKS	Signature	License Number
	Hrs	Min			
9-25-02	5	9	COMPLETED 100 HR INSPECTION PER REPORTS. OIL/FILTER CHANGED PLUGS CLEANED, GAPPED & ROTATED TOP/BOTTOM COMPRESSION 1/3/80 2/4/80 3/12/80 4/25/80 MAG TIMING CHECKED 25° BTC REPLACED A/C MOUNTING HARDWARE	R B Owens	A+P 1263422
12-8-02	6	0	OIL/FILTER CHANGED, PLUG ROTATED / GAPPED	R B Owens	A+P 1263422
3/18/03	7	0	OIL/FILTER CHANGED, PLUGS CLEANED, GAPPED & ROTATED TOP-BOTTOM & #2 FOR 3 CHECKED MAG TIMING @ 25° BTC	R B Owens	A+P 1263422
Page Total			All Repair Data Must Bear the Endorsement of a Certificated Mechanic, and his Rating and Certificate Number MUST be Shown.		
Brought Forward					
Total to Date					

ENGINE LOG

Serial No. _____

Date	Time		REPAIRS - ADJUSTMENTS - SERVICE - REMARKS	Signature	License Number
	Hrs	Min			
4-1-03	706	0	CLEANNED CARB FUEL FILTER SCREEN. ROTATED	R. B. Dwyer	A+P 1263422
"			+ GAPPED SPARK PLUGS (TOP - BOTTOM + CYL 2-3)	A+P	
"			COMP. CHECK (COLD) 73/80 - 74/80 - 74/80 - 75/80	1263422	
"			OIL / FILTER CHANGED		
"			COMPLETED CONDITION INSPECTION PER		
"			APPEND D OF FAR 43 AND FOUND TO BE IN		
4-1-03			A CONDITION FOR SAFE OPERATION.	R. B. Dwyer	A+P 1263422
5-16-03	724	3	CHANGED FILTER/OIL TO AEROSHELL 100 PLUS.	R. B. Dwyer	A+P 1263422
			CLEANNED PUMP INLET SCREEN		
7-17-03	763	2	CHGD OIL / FILTER 7QAS ASHELL 100 PLUS	R. B. Dwyer	A+P 1263422
			Page Total	All Repair Data Must Bear the Endorsement of a Certificated Mechanic, and his Rating and Certificate Number MUST be Shown.	
			Brought Forward		
			Total to Date		

License
Number

A+P
1263422

A+P
1263422

A+P
1263422

of a

ENGINE LOG

Serial No. _____

Date	Time		REPAIRS - ADJUSTMENTS - SERVICE - REMARKS	Signature	License Number
	Hrs	Min			
10-15-03	50	00	CHGD OIL/FILTER - 7QTS AEROSHELL 100 Plus		
+	765	3	CUT OPEN FILTER FOUND NO METAL OR CARBON		
	815	3	ADJ + LUBED CARB HT CONTROL CABLE -		
			LUBED ALL ENG CONTROL ROD ENDS R6 Oliver	APR	1263422
			TACH CHG IN A/C REMOVED @ 765.3 HRS		
12-20-03	97.2		OIL/FILTER CHANGED. 7QTS AERO SH 100 +		
+	763	0	TIGHTENED LOCKER BOX COVER SCREWS		
TT	860.5		REPAIRED AIR Baffle CRACK AT #1 CYL. R6 Oliver	APR	1263422
			Page Total		
			Brought Forward		
			Total to Date		

All Repair Data Must Bear the Endorsement of a
Certificated Mechanic, and his Rating and
Certificate Number MUST be Shown.

Date	H
4-14-04	7
	1
TOTAL	9
5-7-04	
TOTAL	
5-14-04	

ENGINE LOG

Serial No. _____

Date	Time		REPAIRS - ADJUSTMENTS - SERVICE - REMARKS	Signature	License Number
	Hrs	Min			
4-14-04	763.0		INSTALLED 8 NEW CHAMPION SPARK PLUGS OEM		
	141.3		INSTALLED NEW RED SILICONE ROCKERBOX GASKETS.		
TOTAL	914.3		CHANGED OIL/FILTER. 7 QTS AS 100 PLUS. CLEANED FUEL CARB SCREEN + OIL PUMP SCREEN. CHECKED L/R MAG TIMING. LOBED CONTROLS. COMPRESSION Δ PRES CHK 1) 72/80 2) 75/80 3) 72/80 4) 75/80		
5-7-04	763.0		OIL/FILTER CHANGED. FILTER HAS		
	140.8		METAL FLAKES.		
TOTAL	953.8				
5-14-04			REMOVED ENGINE + SENT TO LYCAN FOR IRAN		
			Page Total		
			Brought Forward		
			Total to Date		

All Repair Data Must Bear the Endorsement of a
Certificated Mechanic, and his Rating and
Certificate Number MUST be Shown.

License
Number

3422

3422

ENGINE LOG

Serial No.

Date	Time		REPAIRS - ADJUSTMENTS - SERVICE - REMARKS	Signature	License Number
	Hrs	Min			
			LYCOMING O-360-EXP S/N L-36296-36A IRAN DUE TO METAL CONTAMINATION, LESS FUEL SYSTEM, WITH THE FOLLOWING PARTS INSTALLED: 1EA 75439-1 MOH GASKET, 1EA STD-1211 PLUG, 1EA STD-2246 CRANKBOLT, 8EA 18M19389 BRG, 8EA SL75061 BOLT, AEL12186 NUT, 1EA LW-18840R CAMSHAFT, 8EA 72877R TAPPET, 2EA 18A19441 BRG, 18D23135 BRG, 1EA 1028-B BALL, 3EA LW-31H0.88 BOLT, 1EA STD-2168 NUT, 1EA STD RING, 1EA STD-1221 RING, 4EA STD-1821 HOSE, 8EA 6203 CLAMP, 4EA 69603 HOSE, 8EA CLAMP, 8EA 60009 KEY, 8EA 17C21191 KEY, 4EA 17C19386 CAP, 4EA AEL14077-1 PIN, 4E NFS PISTON, 4EA SL3601-SC RING SET, 4EA AEL13790 RKR SHAFT, 8EA AEL12892 BU 8EA REM38E SPARKPLUG, 1EA M4004 HARNESS, 2EA K3318-4 BRG KIT, 2EA K3215 B 2EA K3984 CAPACITOR, 4EA M3040 WEDGE, 1EA K3822 U/S BLOCK/GEAR ASM, 1E MAGNETO S/N 98070580, 1EA 4373 MAGNETO S/N 98061046. PORT POLISH & FLOW BA CYLINDERS. COMPLY WITH PERTINENT A.D.'S & S.B.'S. TEST RUN 1 ½ HR INFORMATION ON FILE AT LY-CON REBUILDING CO. REFERENCE W.O. 51433		
FOR USE IN EXPERIMENTAL AIRCRAFT ONLY					
LY-CON REBUILDING CO. 8231 W. Doe Avenue Visalia, CA 93291 (559)651-1070					

FOR USE IN EXPERIMENTAL AIRCRAFT ONLY

LY-CON REBUILDING CO. 8231 W. Doe Avenue Visalia, CA 93291 (559)651-1070

9. DIGITAL TACH FOR TT ADD 763.

ENGINE LOG

Serial No. _____

Date	Time		REPAIRS - ADJUSTMENTS - SERVICE - REMARKS	Signature	License Number
	Hrs	Min			
7-31-04	190	8	INSTALLED REBUILT ENGINE	R B Owens	ASP 1263422
9-6-04	206	0	NEW SPARK PLUGS; OIL/FILTER CHANGE	R B Owens	ASP 1263422
12-22-04	250	0	OIL / FILTER CHANGE 7QTS A.S. 100	R B Owens	1263422
5-1-2005	290	0	REPLACED SPARK PLUGS WITH CLEANED/GAPPED CH. REM 38E		
(TT 1053-0)			CLEANED FUEL/OIL SCREENS. RE-TIMED MAGS TO 25° BTC		
			CHANGED OIL/FILTER: 7QTS AEROSHELL 100 ST. MINERAL OIL		
			SEE ANNUAL CONDITION INSPECTION REPORT DTD 5-1-2005 FOR		
			FURTHER MAINTENANCE ACTIONS PER FAR 43 APP D. ENGINE		
			FOUND TO BE IN SAFE ^{OPERATING} CONDITION. 73/80 75/80 76/80 73/80 COOL		
			R B Owens ASP 1263422		
			Page Total	All Repair Data Must Bear the Endorsement of a Certificated Mechanic, and his Rating and Certificate Number MUST be Shown.	
			Brought Forward		
			Total to Date		

Date

5-23-0.
7-12-05

29 Aug 05

9-17-
10-1-
10-1-

ENGINE LOG

Serial No. _____

Date	Time		REPAIRS - ADJUSTMENTS - SERVICE - REMARKS	Signature	License Number
	Hrs	Min			
5-23-05	322	1	CHG OIL + FILTER - SWITCHED TO 100 PLUS	R. Owens	1263422
7-12-05	334	1	CAG OK + FILTER - TAT 100 +	R. Owens	1263422
9 AUG 05	347.9		DYNAMICALLY BALANCED PROPELLER ASSY. FINAL READING 0.04 IPS. SEE ALSO HARD COPY RECORD THIS DATE.		
9-17-05	357	0	REPLACED VERNI THERM OIL TEMP	R. Owens	1263422
10-1-05	361	0	REPLACED B+C ALT WITH NEW B+C ALT	R. Owens	1263422
10-1-05	361	0			

License Number

A/P
1263422

A/P
1263422

1263422

38E

TC

24L OIL

85 FOR

ENGINE

73/80 COOL

of a

ENGINE LOG

Serial No. _____

Date	Time		REPAIRS - ADJUSTMENTS - SERVICE - REMARKS	Signature	License Number
	Hrs	Min			
5-06-06	405.7	-	(1168) INSTALLED + TIMED <u>RE BUILT MASS</u> RE BUILT RE BUILT SPARK PLUGS PER AERO ACCESSORIES + AIRCRAFT SPARK PLUGS	RL Owens	1263422
6-1-06	415.8		(1178) CLEANED FUEL + OIL SCREEN CHANGED OIL/FILTER = 7 QTS AEROSHELL PLUS SEE ANNUAL CONDITION INSPECTION REPORT DTD 6-7-06 FOR MAINTENANCE ACTIONS PER FOR 43 APP D COMP R CHECK ① 76/80 ② 72/80 ③ 67/80 ④ 75/80 COLD FOUND TO BE IN CONDITION FOR SAFE FLIGHT RETURNED TO SERVICE RL Owens		1263422
Page Total			All Repair Data Must Bear the Endorsement of a Certificated Mechanic, and his Rating and Certificate Number MUST be Shown.		
Brought Forward					
Total to Date					

RE CHECKED
HOT AS
76/80
RLO
4-30-06

ENGINE LOG

Serial No. _____

Date	Time		REPAIRS - ADJUSTMENTS - SERVICE - REMARKS	Signature	License Number
	Hrs	Min			
8-7-06	443	4	CHGD OIL/FILTER AFTER OSH	R. B. Wenzel	1263422
2-22-07	494	5	CHGD OIL/FILTER/SPARK PLUGS	R. B. Wenzel	1263422
6-1-07	525	7	CHGD OIL/FILTER/SPARK PLUGS + CLEANED OIL/FUEL SCREEN, SEE ANNUAL COND. INST. REPORT DTD 6-1-07.		
			COMP. CHK 76/80, 77/80, 77/80, 76/80	R. B. Wenzel	1263422
8-5-07	580	1	OIL/FILTER CHGD	R. B. Wenzel	1263422
10-29-07	600	1	RESET "E" GAP - BOTH MAGS + R.C.D. AERO ACCESS.	R. B. Wenzel	1263422
2-26-08	627	7	CHANGED OIL, FILTER + CLEANED SCREEN	R. B. Wenzel	1263422
6-2-08	651	8	CLEANED + GAPPED PLUGS - RETIMED T 15° TDC SEE COND. INST. REPORT	R. B. Wenzel	1263422
			Page Total		
			Brought Forward		
			Total to Date		

All Repair Data Must Bear the Endorsement of a Certificated Mechanic, and his Rating and Certificate Number MUST be Shown.

OLD TACH 763.0

new 763

ENGINE LOG

Serial No. _____

Date	Time		REPAIRS - ADJUSTMENTS - SERVICE - REMARKS	Signature	License Number
	Hrs	Min			
01-11-2013	9	10.1	BOTH MAGS 500 HR INSP BY AERO ACCESSORIES TIMED 25° BTC	R. Owens	APP 1263422
6-21-2013	9	24.1	REPLACED FUEL PUMP WITH NEW	R. Owens	APP 1263422
11-01-2013	9	39.9	COMPLETED CONDITION INSPECTION REPORT ^{SEE}	R. Owens	APP 1263422
12-01-2014	9	88.8	COMPLETED CONDITION INSPECTION REPORT ^{SEE}	R. Owens	APP 1263422
01/01/17	10	83.3	COMPLETED CONDITION INSPECTION REPORT ^{SEE}	R. Owens	APP 1263422
5/1/18	11	08.5	COMPLETED CONDITION INSPECTION REPORT ^{SEE}	L. Owens	REPAIRMAN 2462643976
8/1/19	11	21.1	COMPLETED CONDITION INSPECTION ^{SEE} MAINT REPORT L. Owens	L. Owens	REPAIRMAN 2462643976
	+	763.0	ORIGINAL TACH TIME BEFORE REPLACEMENT		
		1884.1	TTSN		
8/1/19	18	84.1	OLL & FUTER AEROSHAW W100+ L. Owens		2643976
			Page Total	All Repair Data Must Bear the Endorsement of a Certificated Mechanic, and his Rating and Certificate Number MUST be Shown.	
			Brought Forward		
			Total to Date		

ENGINE LOG

Serial No. _____

License Number
 APP
 1263422
 APP
 1263422
 APP
 1263422
 APP
 1263422
 APP
 1263422
 REPAIRMAN
 2462643976
 REPAIRMAN
 2643976

2643976

Date	Time		REPAIRS - ADJUSTMENTS - SERVICE - REMARKS	Signature	License Number
	Hrs	Min			
10/1/20	1902	13	COMPLETED CONDITION INSPECTION OIL & FILTER AEROSHAW 100+. NEW INTAKE COUPLERS & GASKETS, DRAIN BACK HOSES, EXHAUST GASKETS REPLACED. SEE MAINT. REPORT	L. Owen	2643976
			CH 48110-1 FILTER		2643976
6/10/21	1908	1	R & R OIL FILTER AEROSHAW 100+	L. Owen	2643976
1/1/22	1967	4	CONDITION INSPECTION, OIL & FILTER AEROSHAW 100+, + NEW VALVE COVER GASKETS NEW K&N P/N 3450 INSTALLED + REPAIRED FRESH AIR BOX SEE MAINTENANCE REPORT	L. Owen	2643976
	65	1	Page Total		
	1902	3	Brought Forward		
	1967	4	Total to Date		

All Repair Data Must Bear the Endorsement of a
 Certificated Mechanic, and his Rating and
 Certificate Number MUST be Shown.

OLD TAX 763.0

ENGINE LOG

Serial No.

Date			Time		REPAIRS - ADJUSTMENTS - SERVICE - REMARKS	Signature	License Number
Date			Hrs	Min			
1-25-22	1969	9			CLEANED & GAPPED PLUGS	L. OWENS	2643976
7-25-22	2003	4			R&R OIL/FILTER 100+ AEROSHELL + P/U AA 43110-2 TEMPEST FILTER	L. Owen	2643976
2-1-23	2012	0			R&R 100+ AEROSHELL ROTATED PLUGS TOP TO BOTTOM. #1 75/80 #2 74/80 #3 76/80 #4 77/80 CLEAN AIR FILTER - SEE MAINTENANCE REPORT	L. Owen	2643976
Page Total					All Repair Data Must Bear the Endorsement of a Certificated Mechanic, and his Rating and Certificate Number MUST be Shown.		
Brought Forward							
Total to Date							

ENGINE LOG

Serial No.

[illegible]

License
Number

DATE _____

Service Bulletins, Letters, Instructions & A D Notes

SLICK MAG LA MODEL 4373 S/N 93061045 CAP M2989

RA .. 4370 S/N 98070580

BOTH MAGS INSPECTED + REPAIRED PER SLICK 500 HR INSP
5-06-06

ENGINE

Mac's Maintenance 4111 Airport Drive Lawrenceburg, TN 38464 931-797-3375
N515L Van's RV-6 S/N: 22923 AFTT: 2029.8 Tach: 1264.5 Date: 04/01/2024
Engine: Lyc Model: O-360-A1A S/N: L-36296-36A TSN: 2029.8 TSO: N/A

Completed a 100 hour & Annual conditional service and inspection i/a/w FAR Part 43, appendix D.

No new or recurring AD's due at this time. See AD Compliance Listing for complete AD sign off.

- 1: Drained oil, removed & inspected filter (no metal found), installed new filter p/n AA48110-2, torqued & safetied filter, serviced with 8 qts Aeroshell 100 Plus.
 - 2: Cleaned and inspected sparkplugs, installed with new gaskets p/n 6800084(M-674), lubed threads with anti-sieze & torqued as required. Installed & tightened leads as required.
 - 3: Cleaned fuel filters and screens.
 - 4: Compression Check: 1- 75/80 2- 76/80 3- 71/80 4- 72/80
 - 5: Removed, cleaned & inspected fuel injector nozzles. Lubed threads with high temp thread sealer & installed fuel injector nozzles. Torqued nozzles & attached nozzle lines, tightened as required.
 - 6: Repaired right side aft engine baffle crack, stop drilled & installed doubler.
 - 7: Cleaned & lubed K&N air filter.
 - 8: Removed & installed engine for engine mount repair. Tightened & secured hardware, lines & cables.
 - 9: Removed & installed engine mount after weld repair & installation of truss plates by welding at lower left & right strut housings & engine mount tubes. Cleaned inspected repaired areas. Primed & painted repaired areas
Tightened & secured hardware.
 - 10: Replaced alternator belt, installed new belt. Adjusted, tightened & secured hardware.
- Engine ground run, op and leak checked good. I certify that this work has been accomplished and inspected reference applicable maintenance manuals and/or instructions and was determined to be in airworthy condition at this time. I certify that this engine has been inspected in accordance with a 100 hour & Annual conditional inspection and was determined to be in airworthy condition at this time. End.