

HARTZELL

PROPELLER LOGBOOK

PROPELLER MODEL HC-CAVR-1BFP / F7497

PROPELLER S/N N5619B

LOGBOOK # _____

PROPELLER MAINTENANCE RECORD

Position _____

Propeller Model _____

Propeller S/N _____

Blade Design _____

Blade S/N's

No. 1 _____

No. 2 _____

No. 3 _____

No. 4 _____

No. 5 _____

No. 6 _____

Spinner Assembly Part No. _____

PITCH RANGE

High/Feather _____

Start Lock _____

Low _____

Reverse _____

Aircraft Manufacturer _____

Aircraft Model _____

S/N _____


Registration _____

N9298V TACH: 4550.16 ACTT Prop.TSN: 373.86 Date: 8/3/2016

Serviced propeller with AeroShell #6 grease. ADs checked.

I certify this Propeller has been inspected in accordance with an annual inspection and was determined to be in an AIRWORTHY condition.

California Aero Marketing LLC T 760.731.2614
2155 - F South Mission Road F 760.203.0422
Fallbrook, California 92028-4404

 Jeff W. Holstein
A&P 3180354 IA

David McCoy AP 3615278

B&G Aviation LLC

Georgetown Texas 78628 ph 512-864-7632

N9892V

AC TT: 4636.92


SN# NS619B

Tach: 4636.92

Date 10/5/2018

TT prop: 460.62

I certify that this propeller has been inspected in accordance with a 100hr inspection
In accordance with part 43 appendix d and was determined to be in airworthy condition.
This aircraft is approved for return to service in
regards to Work performed.


Bradley Gray A&P 3135226

aining to Airworthiness Directives,
for or Minor Repair, and Inspections.

B&G Aviation LLC

Georgetown Texas 78628 ph 512-864-7632

N9298V

AC TT: 4650.6

SN# NS619B

Tach: 4650.6

Date 10.8.2019

TT prop: 474.3

I certify that this propeller has been inspected in accordance with a 100hr inspection
In accordance with part 43 appendix d and was determined to be in airworthy condition.
This aircraft is approved for return to service in
regards to Work performed.


Bradley Gray A&P 3135226**B&G Aviation LLC**

Georgetown Texas 78628 ph 512-864-7632

N9298V

AC TT: 4669.83


SN# 690067

Tach: 4669.83

Date 10-7-2020

TSN: 493.53

I certify that this propeller has been inspected in accordance with a 100hr inspection
In accordance with part 43 appendix d and was determined to be in airworthy condition.
This aircraft is approved for return to service in
regards to Work performed.


David McCoy AP 3675278**B&G Aviation LLC**

Georgetown Texas 78628 ph 512-864-7632

N9298V

AC TT: 4673.63


SN# 690067

Tach: 4673.63

Date 4-13-2022

TT prop: 497.33

I certify that this propeller has been inspected in accordance with a 100hr inspection
In accordance with FAR part 43 appendix d and was determined to be in airworthy condition.


David McCoy AP 3675278

HARTZELL PROPELLER INC.
One Propeller Place
Piqua, Ohio 45356-2634 U.S.A.
Telephone: 937.778.4200
Telex: 4332032
Fax: 937.778.4391

HARTZELL

PROPELLER LOGBOOK

PROPELLER MODEL HC-C2YR-1BFP/F7497

PROPELLER S/N N5619B

LOGBOOK # _____