

PROPELLER MODEL PAC-J341F-IN

PROPELLER S/N NJ 1473B




LOGBOOK #____




PositionONE	PITCH RANGE
Propeller Model PHC-J3YIF-IN	High/Feather
Propeller S/N NJ 1473B	Start Lock
Blade Design N7605CB	Low
Blade S/N's No. 1	Reverse
No. 2 B4940	Aircraft Manufacturer Circus Design Con
No. 3 B4946	Aircraft Model <u>SR22</u>
No. 4	S/N 4457
No. 5	Registration N8851L
No. 6	
Spinner Assembly Part No	

Scanned with CamScanner

Date	Prop	eller TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
Olis/rt	0.0	N/A	0.0	I have Dynamically Balanced Propeller IAW Hartzell Propeller Owner's Manual 145 Rev. 16 dated Nov/16 Section: 61-00-45 on 3/15/2017 (DATE). The location of the Weight(s) are None degree And are None gram(s). Section: 61-00-45 on 3/15/2017 (DATE). The location of the Weight(s) are location of the Weight(s) are location of the Weight(s) are location. PC 338CE



Date			A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.		
				Date: 08/09/2017 Fit: 196.0 Tach: 198.6 Horizon Avionics, Inc. 2445 E. General Aviation Drive, Suite C, Alcoa, TN 37701. Tel: (865) 980-7858 Fax: (865) 980-7701 PROP LOG ENTRY CW 100Hr Inspection IAW FAR 43 App D with Ref to SR22 AMM 05-20. CW AD research through Bi-Weekly 2017-16 none due at this time. MAINTENANCE RELEASE I certify that this Prop has been insp IAW an 100Hr Insp & was determined to be in an Airworthy condition. Pertinent Details Are On File Under Work Order No. M4494. Signed: Cert. No: APJW3SY/A Date: 8/9// For Horizon Avionics, Inc.		



Page 2

	Prop Entries		MN 55811 118-788-3049					
\pm	(8) Performed an annual inspection of this propeller in accordance with Cirrus Aircraft SR-22 AMM 05-20 inspection checklist. (31) I certify that this propeller has been inspected in accordance with an annual inspection and was determined to be in an airworthy condition.							
_	This eleviewed the file on this aircraft and the accompanying discrepancy forms. The aircraft, airframe, aircraft engine, properlier or appliance dentified was reparted inspected in accompance with current lens, rements of the Federal Avapton Administration and is approved for return to service. Perther details of mis work order are on file at this Centified Repair Station CRS / DERESS /							
	DATE: 3.21.2018	SIGNED:	'Wo	rk Order: TYS 19694-03-2018				
		Print Feliman Destited Repair Station ()		by EBis 3 (datcomedia.com)				
	4							
E.								
-	حرت							
THE OHIO	STATE UNIVERSITY AIRPO 0 West Case Road Hgr. 3	ORT	THE OHIO STATE UNIVERSITY A	IRPORT				

Scanned with CamScanner





THE OIIIO STATE UNIVERSITY AIRPORT 2160 West Case Road Hgr. 3 Columbus, Ohlo 43235-2526

CRS# IKBRO28F
Date: 5/6/2019 Work Order #: AM09121

N#: 88511.

Aircraft Make/Model: Curus SR22

Serial #: 4457

Propeller Make/Model: Hartzell PHC-J3Y31F-1N

Serial#: NJ1473B

Flight Meter; 453.3

Propeller T.T.: 453.3

Propeller Log:

 Complied with a Propeller 100hr Inspection using Cirrus SR22/22T AMM P/N 13773-002 Chapter 5 Inspection Guide Revision 1 dated 12/27/2017 and other current data.

I certify that this Propeller has been inspected in accordance with 100 hour inspection and was determined to be in airworthy condition. All applicable A D.'s checked thru 2019-09

Prop TSMOH: NEW

"Maintenance Release"

The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and was found airworthy for return to service. Pertinent details of the repair are on file at this agency.

Signature

for CRS# IKBR028F





THE OHIO STATE UNIVERSITY AIRPORT

2160 West Case Road Hgr. 3 Columbus, Ohio 43235-2526 CRS# IKBRO28F

Date: 5/14/2020

Work Order #: AM09898

N#: 8851L

Aircraft Make/Model: Cirrus SR22

Serial #: 4457

Propeller Make/Model: Hartzell PHC-J3Y1F-1N

Serial#: NJ1473B

Flight Meter: 520.4

TSMOH:NEW

Propeller T.T.: 520.4

Propeller Log:

 Complied with a Propeller 100hr Inspection using Cirrus SR22/22T AMM P/N 13773-002 Rev. 3 Chapter 5 Inspection Guide and other current data.

I certify that this Propeller has been inspected in accordance with 100 hour inspection and was determined to be in airworthy condition. All applicable A.D.'s checked thru 2020-10

"Maintenance Release"


The aircraft and/or component identified above was repaired and inspected in accordance with current Federal Aviation Regulations and was found airworthy for return to service. Pertinent details of the repair are on file at this agency

Signature:

_____ for

for CRS# IKBR028F

ate				operations pertaining to Airworthiness Directives, s, Overhaul, Major or Minor Repair, and Inspections.
I in cl	2160 Columb CR Date: 08/05/2021 Work Aircraft Make/Model: Cir Propeller Make/Model: Ha Tach. Time: 580.2 P Propeller Log: 1. Complied with a Chapter 5 Inspect current data. certify that this Propelle ispection and was determine the detection and was determined the detection and components.	Propeller TSMOH: Propeller TSMOH: Propeller 100hr Inspinon Guide Revisional Propeller 100hr Inspinon Guide Revisio	8 N#: N8851L Serial#: 4457 F-1N Serial#: NJ1473B New Propeller TT: 580.2 Section using Cirrus SR22/22T AMM 80 dared 04 Sep 2018 and other 3 dated 16/Jan/2020 Steed in accordance with 100 hour hy condition. All applicable A.D.'s lease" we was repaired and inspected in lations and was found airworthy for	



Scanned with CamScanner

ite	Prop TSN	eller TSO	A/C Hrs	Description of all operations pertain Service Documents, Overhaul, Major	
	wo	: INV_8917	,		Propeller - page 1 of 1
			PF Flyers In	nc 12 Ramseur Ct - Greenville, SC 29607 - 864-252-4289 - C	CRS#: Y3FR325Y
		851L IGHT TIM	E: 621.1	Hartzell, PHC-J3Y1F-1N, S/N: NJ1473B HOBBS: 821.7	June 08, 2023
	Com guide dete	plied with e. I certify rmined to	n an annu y that this be in airw	al inspection IAW FAR 43 (d) referencing Cirrus SR 3 propeller has been inspected in accordance with a corthy condition	annual inspection and was
	John	Pruden /	A&P/IA 35	03331	
	la.		1 1		