## CHUSHON AIRCRAFT INC.

OCTOBER 7, 2019 MU-2B-40 S/N 403SA N600JE ACTT:6499.8 HOBBS: 528.3 LEFT ENGINE S/N P-36054C LETT: 6436.5 TSO: 724.7



COMPLIED WITH 100/200 HOUR INSPECTION I/A/W THE MITSUBISHI INSPECTION GUIDE AND THE HONEYWELL INSPECTION GUIDE. SOAP SAMPLE TAKEN.

I CERTIFY THAT THIS ENGINE HAS BEEN INSPECTED AND FOUND TO BE IN AIRWORTHY CONDITION. 1



## APRIL 12, 2023


MU-2B-40 S/N 403SA N600JE ACTT:6560.7 HOBBS: 589.2 LEFT ENGINE S/N P-36054C LETT: 6497.4 TSO: 785.6

## CHUSHON AIRCRAFT INC.



COMPLIED WITH 100/200 HOUR, 600 HOUR INSPECTION I/A/W THE MITSUBISHI INSPECTION GUIDE AND THE HONEYWELL INSPECTION GUIDE. COMPLIED WITH AD2020-26-14. INSTALLED PPC LEVER KIT, P/N APD-PPC-SRA2PCK, IN LH ENGINE PPC LEVER. FUEL NOZZLES CLEANED & FLOW CHECKED BY JET AIR GROUP.

I CERTIFY THAT THIS ENGINE HAS BEEN INSPECTED AND FOUND TO BE IN AIRWORTHY CONDITION,



1117 111