

HARTZELL

PROPELLER LOGBOOK

PROPELLER MODEL HC-C34R-4BNX

PROPELLER S/N B33261B

LOGBOOK # _____

PROPELLER MAINTENANCE RECORD

Position _____

Propeller Model HC-C34R-4BNX

Propeller S/N B33261B

Blade Design NC8302-7X1

Blade S/N's

No. 1 C0311

No. 2 C0327

No. 3 C0328

No. 4 _____

No. 5 _____

No. 6 _____

Spinner Assembly Part No. _____

PITCH RANGE

High/Feather 31.0[±]1.0

Start Lock NA

Low 12.5[±]1.0

Reverse NA

Aircraft Manufacturer _____

Aircraft Model _____

S/N _____

Registration _____

[illegible]

SOUTHEAST AERO SERVICES, INC. 800-692-2091
EXTRA FLUGZEUGPRODUKTIONS EA-300/LT N916AG S/N LT052


22 November 2019 Tach Time .5 hrs Propeller TSNEW 0.0

Hartzell HC-C3YR—4BNX/NC8302-7X1 Assembly/Propeller Serial No: B33261B

- 1.) Installed 0.0hrs Since New Hartzell Propellers Spinner and propeller HC-C3YR—4BNX/NC8302-7X1 Assembly/Propeller Serial No: B33261B IAW Hartzell Manual No. 145 Rev. 18 Aircraft Weight and balance as well as Equipment list revised.
- 2.) Inspected IAW a 100hr/Annual Inspection IAW Hartzell Manual No. 145 Rev 18. Servicing with Aeroshell 6 Grease. No defects noted.
- 3.) Complied with Ad Summary thru Revision 2019-23 See AD log for more information. No ADs at this time.
- 4.) Installed spinner.

I certify that this propeller has been inspected in accordance with the scope and detail of Appendix D to Part 43, and found to be in a condition for safe operation this date.

Royce J Blankenship A&P 3556184 IA




SOUTHEAST AERO SERVICES, INC. 800-692-2091
EXTRA FLUGZEUGPRODUKTIONS EA-300/LT N916AG S/N LT052

25 November 2019

I certify that that the prescribed flight test hours have been completed with Hartzell HC-C3YR- Propeller & Spinner installed and the aircraft was found to be controllable throughout all Advanced Category maneuvers listed as the International Aerobatic Club Official Aerobatic Figures. No hazardous operating characteristics or design features were found. Aircraft has been determined to be in safe condition for continued operation.

Douglas L. Vayda A&P 2694036 IA



Date

Southeast Aero Services Inc.

St Augustine, FL.

Phone (904) 824-1899/Fax (904) 824-6334

Hartzell HC-C3YR-4BNX

s/n:B33261B

N916AG

1-5-2021 Tach:36.2hrs. Hobbs:41.9hrs. Prop Total Time:35.7hrs. Completed 12 month condition inspection in accordance with 14 CFR43 Appendix D with references to Chapters 4 and 5 EA-300LT Service Manual EA-0D702 and Hartzell I.C.A. this date. AD's checked thru FAA Bi-Weekly 2020-26 with no AD's due at this time.

I certify this Propeller has been inspected in accordance with a 12month Condition Inspection and was determined to be in Airworthy condition at this time.

Bryan M Wood A&P3216290

Southeast Aero Services Inc.

St Augustine, FL.

Phone (904) 824-1899/Fax (904) 824-6334

Hartzell HC-C3YR-4BNX

s/n:B33261B

N916AG


12-1-2021 Tach:64.7hrs. Hobbs:76.7hrs. Prop Total Time:64.2hrs. Completed 12month condition inspection in accordance with 14 CFR43 Appendix D with references to Chapters 4 and 5 EA-300LT Service Manual EA-0D702 and Hartzell I.C.A. this date. AD's checked thru FAA Bi-Weekly 2021-24 with no AD's due at this time. Serviced hub with Aeroshell #6.


I certify this Propeller has been inspected in accordance with a 12month Condition Inspection and was determined to be in Airworthy condition at this time.


Bryan M Wood A&P3216290

Propeller Time 105.9, Engine Time 106.4 & Aircraft Total Time 125.7 29 December 2022
Completed 100-hour inspection per MAINTENANCE MANUAL EXTRA 300LT Doc. No: EA-
0D702. I certify that this propeller was inspected IAW a 100-hour inspection and was
determined to be in an airworthy condition.

Ian MacMahon A&P 4209284





Date	Propeller		A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
	TSN	TSO		
				<p>PROP MODEL: HC-C3YR-4BNX PROP S/N: B33261B REG. NO: 916AG WORK ORDER: 20298-01-2024</p> <p>Foothill Aircraft Sales & Service, Inc. Repair Station No. AJ4R052M 1749 W 13Th St Upland, CA 91786 Phone: 909-985-1977</p> <p>DATE: 1/10/2024 A/C TSN: 158.5 PROP TT: 158 TACH: 158.5</p> <p>Prop Entries</p> <p>(3) C/W ANNUAL/100HR INSPECTION ON THIS PROPELLER IAW FAR 43 APPENDIX D USING EXTRA 300 LT M.M CHAPTER 5 INSPECTION CHECKLIST AS A GUIDE. ADs CHECKED</p> <hr/> <p>Maintenance Release I certify that the PROPELLER on 916AG was inspected in accordance with an 100hr./Annual inspection per the manufactoures maintenance manual and current FARs rules of the Federal Aviation Regulations and was found Airworthy for return to service. Pertinent details of the repair are on file at this repair station under Work Order No. 20298-01-2024, Dated 1/10/2024.</p> <p>DATE: 1/10/2024 SIGNED:  Work Order: 20298-01-2024</p> <p>Mike Hartman Certified Repair Station No. AJ4R052M</p> <p>Printed by EBis 3 (datcomedia.com)</p>