

Veteran Aero Services

(914) 374-3308

A/C N7789M Model Mooney M20c S/N 20-0023

TACH 3226.75 TOTAL 3226.75 Engine 1426.75 Date 11/5/2021

1. Performed Annual Inspection per Mooney 100 Hour annual checklist.
2. Oil changed. Replaced CH48110 filter, no debris found, removed, cleaned and reinstalled case drain screen.
3. Compressions checked as follows:
4. #1 78/80 #2 77/80 #3 76/80 #4 79/80
5. Verified Mag timing of both Mags set to 25 Degrees BTDC per Lycoming service manual
6. Removed, cleaned, verified gap, rotated top to bottom and reinstalled 8 (ea) spark plugs per Lycoming service manual.
7. Inspected exhaust and verified no cracks at this time per Lycoming service manual.

All AD's complied with via Airworthiness directive report dated 11/5/2021 provided to aircraft owner.

I certify this engine to have been inspected in accordance with an annual inspection checklist and found to be in airworthy condition at this time.

Joseph McMillan A&P 30812091A

Date 11/5/2021

Veteran Aero Services

(914) 374-3308

A/C N7789M Model Mooney M20C S/N 20-0023

TACH 3421.22 ENG 1621.22 SMOH Date 10/1/2022

1. Performed Annual Inspection per Mooney 100 Hour annual checklist.
2. Oil changed. Replaced CH48110-2 filter, no debris found.
3. Compressions checked as follows:
4. #1 72/80 #2 76/80 #3 75/80 #4 73/80
5. Set and verified Mag timing of both Mags to 25 Degrees BTDC per Lycoming service manual
6. Removed, cleaned, verified gap, rotated top to bottom and reinstalled 8 (ea) spark plugs per Lycoming service manual.
7. Inspected exhaust and verified no cracks at this time per Lycoming service manual.

All AD's complied with via Airworthiness directive report dated 10/1/2022 provided to aircraft owner.

I certify this engine to have been inspected in accordance with an annual inspection checklist and found to be in airworthy condition at this time.

Joseph McMillan A&P 30812091A

Date 10/1/2022