MAKE: Flight Design MODEL: CTsw S/N: 06-12-13 REG NO. N542LL

utterbilt Aero Services

www.cutterbiltaeroservices.com cuttterbilt@gmail.com 530-586-8566

DATE: 21 Aug 2023 HOBBS: 1469.2

TACH:

TTSN: 1469.2

Work Order: 2023040

AIRFRAME ENTRIES

Performed an Annual Condition Inspection IAW Flight Design CTSW maintenance manual AU01002000 and checklist in chapter 3. Complied with ELT inspection and test IAW FAR 91.207d. Adjusted tire pressures to 39psi. Completed SD check. I certify that this aircraft has been inspected in accordance with an Annual Condition Inspection and was determined to be in condition for safe operation.

The aircraft, component identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details of this repair or inspection are on file under the above W.O. number.

DATE: 21 Aug 2023 SIGNED:

Anthony D. Cutter A&P/IA 3717632

MAKE: Rotax MODEL: 912 ULS S/N: 5.647.614 REG NO. N542LL

Cutterbilt Aero Services www.cutterbiltaeroservices.com

> cuttterbilt@gmail.com 530-586-8566

DATE: 21 Aug 2023 HOBBS: 1469.2

TACH: TTSN: 1469.2 TSMOH:

Work Order: 2023040

ENGINE ENTRIES

Performed an Annual Condition Inspection IAW Flight Design CTSW maintenance manual AU01002000 and Rotax MML-912 and check list in chapter 5. Checked magnetic plug and removed oil filter and cut it open to check for contaminants, no metal or defects noted. Installed new oil filter P/N 825-016. Performed cylinder inspection and differential compression check #1-100%, #2-100%, #3-100%, #4-98% at test pressure 80psi. Performed operational leak and functional test, no defects noted. Completed SD check. I certify that this engine has been inspected in accordance with an Annual Condition Inspection and was determined to be in condition for safe operation.

The aircraft, component identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details of this repair or inspection are on file under the above W.O. Amber.

DATE: 21 Aug 2023 SIGNED:

Anthony D. Cutter A&P/IA 3717632

MAKE: Neuform

MODEL: CR3-65-47-101.6

REG NO. N542LL

Cutterbilt Aero

www.cutterbiltaeroservices.com cuttterbilt@gmail.com 530-586-8566

DATE: 21 Aug 2023 HOBBS: 1469.2

TACH:

TTSN: 1469.2 TSMOH:

Work Order: 2023040

PROPELLER ENTRIES

Performed an Annual Condition Inspection IAW Flight Design CTSW maintenance manual AU01002000 and checklist in chapter 3. Completed SD check. I certify that this propeller has been inspected in accordance with an Annual Condition Inspection and was determined to be in condition for safe operation.

The aircraft, component identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is approved for return to service. Pertinent details of this repair or inspection are on file under the above W.O. number.

DATE: 21 Aug 2023 SIGNED:

Anthony D. Cutter A&P/IA 3717632