

8010V

HARTZELL

PROPELLER LOGBOOK

PROPELLER MODEL PHC-J3VF-1RF/F7694

PROPELLER S/N FP2491B

LOGBOOK # _____

THIS SERVICE RECORD shall accompany the propeller equipment at all times. When equipment is installed as part of an Aircraft or engine, this record shall be maintained concurrently with and become a part of the Aircraft and Engine Service Records.

PROPELLER MAINTENANCE RECORD

Position _____

PITCH RANGE _____

Propeller Model PHC-53XF-1RF/F7694

High/Feather _____

Propeller S/N FP2491B

Start Lock _____

Blade Design 3 Blade F7694

Low _____

Blade S/N's

Reverse _____

No. 1 591168

No. 2 591167

No. 3 591167

No. 4 _____

No. 5 _____

No. 6 _____


Aircraft Manufacturer Citrus

Aircraft Model SR22

S/N 0677

Registration _____

Spinner Assembly Part No. _____

Date	Propeller		A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
	TSN	TSO		
8-18-03	0.1		0.1	I have Dynamically Balanced Propeller IAW Hartzell Propeller Owner's Manual 115N Rev. 7 dated Oct/02 Section: 61-00-15 on <u>8-18-03</u> (DATE). The location of the Weight(s) are <u>N/A</u> degree And are <u>N/A</u> gram(s). Placard P/N A-2803 is installed on propeller hub.  (Sign/Stamp) Cirrus Design Corporation, PC 338CE


Attitude Aviation

299 W. Jack London Blvd., Livermore, CA 94550

N8140V Hartzell S/N: _____
 Total Time: 170.1 Tach: 170.1 March 5, 2004
 This is a permanent part of the Propeller records.
 1) Performed the following maintenance / service / repair items:
 *Removed minor nicks & scratches from blade leading edges. Lubricated propeller hub.
 3) Inspected Propeller per Cirrus Service Manual.
 I certify that this Propeller has been inspected in accordance with an 100 Hour Inspection and has been
 determined to be in airworthy condition.
 Thomas J. Kristof 283442926 A&P

Attitude Aviation


299 W. Jack London Blvd., Livermore, CA 94550

N8140V Hartzell S/N: _____
 Total Time: 270.1 Tach: 270.1 May 13, 2004
 This is a permanent part of the Propeller records.
 1) Performed the following maintenance / service / repair items:
 *Removed minor nicks & scratches from blade leading edges. Lubricated propeller hub.
 3) Inspected Propeller per Cirrus Service Manual.
 I certify that this Propeller has been inspected in accordance with an 100 Hour Inspection and has been
 determined to be in airworthy condition.
 Thomas J. Kristof  283442926 A&P

STERLING

145 JOHN GLENN DRIVE
 CONCORD, CA. 94520
 T: (925) 676-2100 F: (925) 676-5580

I CERTIFY THAT THIS PROP HAS BEEN INSPECTED IAW
 ANNUAL INSPECTION AND WAS DETERMINED TO BE IN
 AIRWORTHY CONDITION.

SIGNED:  DATE: 09-10-04
 MICHAEL J BRUNO, IA2585871
 TTIS: 369.7 TSMOH: _____ REG.# N 81404

West Valley Flying Club

Date: 02-10-05 Tach : 439 ACTT: 439

Inspected propeller 50 hour IAW Cirrus SR22 MM
 checklist. I certify this propeller to be in airworthy condition

Peter Kolenko A&P 558833476 

West Valley Flying Club

Date: 04-01-05 Tach : 471 ACTT: 471

N# 8140v

Inspected propeller IAW Cirrus SR-22MM 100HR MM Checklist

STEPHEN E Ball
Stephen E Ball 027463798

West Valley Flying Club

DATE: 07-27-05 ACTT:577 TACH:577

Inspected propeller using Cirrus SR22 100hr MM Checklist as a guide. Dressed propeller.

This propeller is airworthy.

Eric Zapata A&P 2806335

Eric Zapata

West Valley Flying Club

DATE: 06-03-05 ACTT:521 TACH:521

Inspected propeller using Cirrus SR-22 50hr MM Checklist as a guide. Dressed propeller.

This propeller is airworthy.

Eric Zapata A&P 2806335

Eric Zapata

West Valley Flying Club

Date: 07/27/05

ACTT: 577

Tach: 577

Annual inspection completed using the Cirrus 100 Hr checklist.

As a guide. A/C test flown "OK" This Propeller is Airworthy.

Kevin Pinger A&P574543772IA

Kevin Pinger

7 SEP 05	T=623			clw insp of propeller per Cirrus 50 hr MM - Marked 2734691

West Valley Flying Club

Date: 11/11/05 TACH:669 ACTT: 669

Inspected prop using Cirrus SR22 100HR MM checklist as a guide. This propeller is airworthy

Feroz Khan A&P 604158361

Feroz Khan

20 Jan 06 T=715 ACTT=715

Inspected propeller using Cirrus 50 hr MM AS a GUIDE
This propeller is AIRWORTHY.

Marked Kelly 2734691

"WRITING Below entered in error


Marked Kelly
2734691


Replaced LH MAN gear brake line (lower) during repair

Date	Propeller TSN TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
STERLING 145 JOHN GLENN DRIVE CONCORD, CA. 94520 T: (925) 676-2100 F: (925) 676-5580 IFY THAT THIS PROP HAS BEEN INSPECTED IAW L INSPECTION AND WAS DETERMINED TO BE IN RTHY CONDITION. <i>Lisa Tyler</i> DATE: <u>7/21/06</u> LISA TYLER, FA623016610 <u>27.4</u> TSMOH: <u>—</u> REG.# <u>N 8140V</u>			

145 JOHN GLENN DRIVE
CONCORD, CA. 94520
T: (925) 676-2100 F: (925) 676-5580

SIGNED: Lisa Tyler DATE: 7/21/06
LISA TYLER, PA623016610
TTIS: 727.4 TSMOH: — REG.# N 8140V

PROP MODEL: PHC-JSYF-1RF PROP S/N: FP2491B REG. NO: 8140V WORK ORDER: 3078-04-2007	 Top Gun Aviation, Inc. 6100 S. Lindbergh St. Stockton, CA 95206 Phone: 209-983-8082	DATE: 4/24/2007 A/C TSN: 946.8 PROP TT: 946.8 TACH: 946.8
Prop Entries (18) Removed excess tape from spinner forward bulkhead.... (21) Dressed propeller blades, painted faces, treated de-ice boots with 303, and lubed hub with Aeroshell #6.... (54) Completed 100hr/Annual inspection.		
I certify that this PROPELLER is airworthy with respect to the work performed.		
DATE: 4/24/2007	SIGNED:  Mark T. Rouch, IA: 568531421 IA	Work Order: 3078-04-2007 Printed by EBis 3 (datacomedia.com)

PROP MODEL: PHC-JSYF-1RF PROP S/N: FP2491B REG. NO: 8140V WORK ORDER: 3607-04-2008	Top Gun Aviation, Inc. 6100 S. Lindbergh St. Stockton, CA 95206 Phone: 209-983-8082	DATE: 5/16/2008 A/C TSN: 1208.9 PROP TT: 1208.9 TACH: 1208.9
Prop Entries (18) Cleaned of tape adhesive from prop cylinder and adjusted spinner fit with shim tape.... (19) Dressed propeller, painted propeller face and lubricated prop.... (26) Completed 100hr/Annual inspection.		
I certify that this PROPELLER is airworthy with respect to the work performed.		
DATE: 5/16/2008	SIGNED:  Thomas W. Richard, IA: 547493873	Work Order: 3607-04-2008 Printed by EBis 3 (datacomedia.com)

Top Gun Aviation, Inc.

DATE 4/24/2007
A/C TSN 946.8
PROP TT 946.8
TACH 946.8

Prop Entries

Prop Entries

(18) Removed excess tape from spinner forward bulkhead.... (21) Dressed propeller blades, painted faces, treated de-ice boots with 303... and lubed hub with Aeroshell #6.... (54) Completed 100hr/Annual inspection.

I certify that this PROPELLER is airworthy with respect to the work performed

DATE: 4/24/2007

SIGNED

Mark T. Rouch, IA: 566531421 IA

Work Order: 3078-04-2007

Printed by EBis 3 (datacomedia.com)

PROP MODEL:
PHC-JBYF-1RF
PROP S/N: FP2491B
REG. NO: 8140V
WORK ORDER:
3507-04-2008

Top Gun Aviation, Inc.

DATE 5/16/2008
A/C TSN 1208 9
PROP TT 1208 9
TACH 1208 9

Prop Entries

(18) Cleaned of tape adhesive from prop cylinder and adjusted spinner fit with shim tape.... (19) Dressed propeller, painted propeller face and lubricated prop.... (26) Completed 100hr/Annual inspection.

I certify that this PROPELLER is airworthy with respect to the work performed

DATE: 5/16/2008

SIGNED:

Thomas W. Richard, IA 547493873

Work Order: 3607-04-2008

Printed by EBis 3 (datamedia.com)

Date

TS

PROP MODEL
PHC-33YF-1RF
PROP S/N: FP2491B
REG NO: 8140V
WORK ORDER
3993-04-2009

Top Gun Aviation, Inc.

6100 S. Lindbergh St
Stockton, CA 95206
Phone: 209-983-8082

DATE: 4/23/2009
A/C TSN: 1413 1
PROP TT: 1413 1
TACH: 1413 1 TS.

Prop Entries

(20) Dressed the propeller blades, painted faces, lubed hub with Aeroshell #6, treated de-ice boots with 303.... (36) Completed
100hr/Annual inspection.

I certify that this PROPELLER is airworthy with respect to the work performed.

DATE: 4/23/2009

SIGNED:

Thomas W. Richard, IA: 547493873

Work Order: 3993-04-2009

Printed by EBis 3 (datamedia.com)


Propeller Logbook Entry

Date: 07-13-12
Tach: 1902.9
TT Since O/Haul: 1902.9
TT Since New: 1902.9

Aircraft: N8140V
Type: 2003 Cirrus SR22
Serial Number: 0677
Propeller Model #:
Propeller Serial #:

Filed nick out of leading edge of one propeller blade.

Signed


Dan Miller, A&P2615827IA