

# JORDAN PROPELLER SERVICE, INC.

103 East Rhapsody San Antonio, Texas 78216

Certificated Repair Station No. EK2R797K

PROPELLER S/N 980446 HAS BEEN OVERHAULED

I/A/W McCauley Manuals MPC500, BOM100-7 & SPM100-6.

C/W Service Bulletins 119A, 227B (Torque Decal Installed) and Service Letters

1989-2C, 2000-02, 2002-24B & 2014-01E.

PERTINENT DETAILS ON FILE UNDER WORK ORDER NUMBER 17840

SIGNED *Gary L. Jordan* DATE 06-01-16

MECHANIC MAKING INSTALLATION ON A/C MUST C/W FAR 43.9

Year: _____	Total Time in Service	Description
Date: _____		
Next Inspection Due: _____	Time Since Overhaul	
		Mech. Cert. # or Repair Station # _____

B&G Aviation LLC

Georgetown Texas 78628 ph 512-864-7632

N574JD ACTT:1841.1  
SN# 980446 HRM: 1841.1  
Date 8/15/2016 TT prop: 1841.1 TSO: 0.0

I certify that this propeller has been inspected in accordance with a 100hr inspection  
In accordance with part 43 appendix d and was determined to be in airworthy condition.  
Work accomplished as follows

- 1. Reinstalled this propeller after overhaul  
This aircraft is approved for return to service in  
regards to Work performed.

  
Bradley Gray A&P 3135226

EPAIRS AND ALTERATIONS ☐

Due:	Overhaul	Mec
Year: _____	Total Time in Service	De:
Date:		
Next Inspection Due:	Time Since Overhaul	Mec

B&G Aviation LLC

Georgetown Texas 78628 ph 512-864-7632

N574JD ACTT:1943.1  
SN# 980446 Tach: 1943.1  
Date 5/3/2017 RH TSO prop: 102.0

I certify that this propeller has been inspected in accordance with a 100hr inspection  
In accordance with part 43 appendix d and was determined to be in airworthy condition.  
Work accomplished as follows

This aircraft is approved for return to service in  
regards to Work performed.

  
Bradley Gray A&P 3135226

# B&G Aviation LLC

Georgetown Texas 78628 ph 512-864-7632

N574JD

ACTT:2030.5

SN# 980446

H.M:2030.5


Date 7-20-2018

TTOP: 2030.5

RH Prop

SMOH: 189.4

I certify that this propeller has been inspected in accordance with a 100hr inspection  
In accordance with part 43 appendix d and was determined to be in airworthy condition.  
This aircraft is approved for return to service in  
regards to Work performed.

  
David McCoy AP 3615278

Next Inspection Due:	Time Since Overhaul	Mech.
Year: _____	Total Time in Service	Desc
Date: _____		
Next Inspection Due:	Time Since Overhaul	Mech.

# B&G Aviation LLC

Georgetown Texas 78628 ph 512-864-7632

N574JD

RH

SN#980446

Date 7-25-2019


ACTT:2086.7

H.M.:2086.7

TT prop:2086.7

SMOH: 245.6

I certify that this propeller has been inspected in accordance with a 100hr inspection  
In accordance with part 43 appendix d and was determined to be in airworthy condition.  
This aircraft is approved for return to service in  
regards to Work performed.

  
David McCoy AP 3615278

# 100 HR & 21 AND INSPECTIONS REPAIRS AND ALTERATIONS ☐

## B&G Aviation LLC

Georgetown Texas 78628 ph 512-864-7632

N574JD ACTT:2163.1

SN# 980446 Tach: 2163.1

Date 9/18/2020 RH TSO prop: 322.0

I certify that this propeller has been inspected in accordance with a 100hr inspection  
In accordance with part 43 appendix d and was determined to be in airworthy condition.

Work accomplished as follows

This aircraft is approved for return to service in  
regards to Work performed.

Bradley Gray A&P 3135226

## B&G Aviation LLC

Georgetown Texas 78628 ph 512-864-7632

N574JD ACTT:2171.8

SN# 980446 EDM Tach: 6.2

Date 9-9-2021 RH TT prop: 2171.8  
SMOH: 330.7

I certify that this propeller has been inspected in accordance with a 100hr inspection  
In accordance with FAR part 43 appendix d and was determined to be in airworthy condition.

David McCoy AP 3615278

		Mech
Year: _____	Total Time in Service	Des
Date: _____		
Next Inspection Due: _____	Time Since Overhaul	Mech

☐ **HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS**

PROP MODEL (R)  
3AF32C523  
PROP S/N (R) 980446  
REG NO: N574JD  
WORK ORDER: 12841



**Turbine Aircraft Services, LLC.**

Repair Station No. TBWR469X  
7101 Millionaire Drive, Hangar 21  
Bethany, Oklahoma 73008  
Phone: 405-491-8995

DATE: 06 July, 2022  
A/C TSN: 2197.7  
PROP TT (R): 2197.7  
TSPCH (R): 356.6  
HOBBS: 2197.7

**Right Prop Entries**

- (9) Completed a 100 hour propeller inspection in accordance with the PA-34-220T series maintenance manual 100 hour checklist P/N 761-888 Dated September 30, 2018 and utilizing 14 CFR 43 Appendix (D) in scope and detail to inspect this Aircraft.
- (92) Right propeller blades blended for minor nicks.

The aircraft and/or component(s) on N574JD was repaired and/or inspected in accordance with current Federal Aviation Regulations and was found Airworthy for return to service with regard to work performed on this work order. "Pertinent details of the inspection/repair are on file at this Repair Station No. TBWR469X under Work Order No. 12841 Dated 06 July, 2022

DATE: 06 July, 2022

SIGNED:

James C. Morphey  
Certified Repair Station No. TBWR469X

Work Order: 12841

Printed by EBis 3 (datcomedia.com)

Date:

Next Inspection  
Due:

Time Since  
Overhaul

Mech. Cert. # or Repair Station #

# HUB & BLADE INSPECTIONS, REPAIRS AND ALTERATIONS ☐

Year: \_\_\_\_\_

Date: \_\_\_\_\_

Next Inspection  
Due: \_\_\_\_\_

PROP MODEL (R):  
3AF32C523  
PROP S/N (R): 980446  
REG NO: N574JD  
WORK ORDER: 13085



## Turbine Aircraft Services, LLC.

Repair Station No. TBWR469X  
7101 Millionaire Drive, Hangar 21  
Bethany, Oklahoma 73008  
Phone: 405-491-8995

DATE: 04 August, 2023  
A/C TSN: 2260.3  
PROP TT (R): 2260.3  
TSPOH (R): 419.2  
HOBBS: 2260.3

### Right Prop Entries

(8) Completed a 100 hour propeller inspection in accordance with the PA-34-220T series maintenance manual 100 hour checklist P/N 761-888 Dated September 30, 2018 and utilizing 14 CFR 43 Appendix (D) in scope and detail to inspect this Aircraft.

Year: \_\_\_\_\_

Date: \_\_\_\_\_

Next Inspection  
Due: \_\_\_\_\_

The aircraft and/or component(s) on N574JD was repaired and/or inspected in accordance with current Federal Aviation Regulations and was found Airworthy for return to service with regard to work performed on this work order. "Pertinent details of the inspection/repair are on file at this Repair Station No. TBWR469X under Work Order No. 13085 Dated 04 August, 2023

DATE: 04 August, 2023

SIGNED: \_\_\_\_\_

James C. Morpew  
Certified Repair Station No. TBWR469X

Work Order: 13085

Printed by EBis 3 (datcomedia.com)

Year: \_\_\_\_\_

Date: \_\_\_\_\_

Next Inspection  
Due: \_\_\_\_\_