


**DESCRIPTIONS OF ALL OPERATIONS  
PERTAINING TO AIRWORTHINESS DIRECTIVES,  
SERVICE BULLETINS, SERVICE LETTERS,  
& MINOR ADJUSTMENTS**

DATE	TACH	DESCRIPTION OF WORK	SIGNATURE
30 Aug 22		<p>Overhauled (1) propeller m/n C2A34C204-C s/n 799247 c/w s/b 119A, 227B, s/1 98-8B. Set blade angles in accordance with STC SA01581AT. Oil filled, painted and balanced. Bld. Dwg.# G-90DCB-8 #1) BK162 #2) BK240. <b>H &amp; H PROPELLER SERVICE, INC.</b> <b>3439 S. AVIATION DR.</b> <b>BURLINGTON, NC 27215</b> <b>FAA REPAIR STATION PS4R451M</b> <b>1-800-334-6437</b></p>	

Model	2A34C204C	<i>Interstate Turbine Management</i>	Date	11/14/22
S/N	799247	2700 Fort Trenholm Rd.	Tach	0.0
Reg #	N4582E	Johns Island, SC 29455	PTT	1108.5
WO#	22-099		PTSOH	0.0

Propeller: C/W Annual Inspection IAW Cessna 182 Series Service Manual Checklist. C/W STC# SA01581AT. Removed McCauley Prop 2A34C204C, SN# 799247. Sent to H & H Prop Service for O/H and STC# SA01581AT compliance, Ref WO#25728. Received and installed same Prop as removed with new Oring. Installed new Prop Gov PN# D-20309-1, SN# 220319. C/W ground run. Leak/Ops checks satisfactory. Tach replaced at this time reading 1108.5. New Tach, 0.0.

I CERTIFY THIS PROPELLER HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION.



3541816 A&P IA

Model	2A34C204C	<i>Interstate Turbine Management</i>	Date	3/1/24
S/N	799247	2700 Fort Trenholm Rd.	Tach	44.2
Reg #	N4582E	Johns Island, SC 29455	PTT	1152.7
WO#	24-029		PTSOH	44.2

Propeller: C/W Annual Inspection IAW Cessna 182 Series Service Manual Checklist. C/W ground run. Leak/Ops checks satisfactory.

I CERTIFY THIS PROPELLER HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION.



3541816 A&P IA