## **PROPELLER** MAINTENANCE RECORDS

AIRCRAFT MAINTENANCE MAINTENANCE RECORDKEEPING SYSTEM

adlog



## PROPELLER MAINTENANCE RECORDS

Log No. / Propeller Manufacturer McGzuley Hub Model 1890cm Blade Design No. 7148 Blade Serial No's. 3. \_ Pitch Range: High \_\_\_\_\_ \_\_\_\_ Low \_\_\_\_ Feather \_\_\_ \_\_ Reverse \_\_\_\_ Governor Manufacturer \_ Model No. \_ Serial No. \_ Date installed on aircraft 4/16/1947 Time Between Overhauls (TBO) \_ If used on multi-engine aircraft: ☐ Right ☐ Left ☐ Front ☐ Rear



(All applicable information must be filled in)

AEROTECH PUBLICATIONS INC

E	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH RECORDING METER TIME	CRIPTION OF WORK PERFORMED— RTIFICATE NO. OF PERSON PERFORMING WORK			
				TOTALS brought forward from previous page			
1.9	1860.0±	unk.	New. "0"	Sent prop to propshop after mud	strike.		
				It was found to be 18" out of track. A	lo other		
		W (0.1		damage. Reinstalled with new bolts and a			
		new factory supplied double bulkhead	Spinner.				
				Repainted face of 6 lades with Slat back paint,			
				Ocar mhistre			
				HAP 1365235 IA			
				Propeller Log			
		-	Ae 55	ora 51 Aviation Services  O Airway Blvd Livermore CA, 54551			
		Date:8/1/	16 N941	TSOH:1893.3 (ESTIMATED)			
		Inspect	formed On The ed this <i>prop</i> d propeller. (	eller in accordance with Fact to the least that this			
			lar hac hool	checked torque of propeller botts. I corary inspection inspected in accordance with ANNUAL inspection be in airworthy condition.			
		Michae	el Town AP5518	316330IA			
1		Milona					
1		Engine	Continental Mod				
		I certif	y that this propell	ch: 41.57 TSOH: 41.57  er has been inspected in accordance with an Annual inspection per FAR Part 43			
		- 1	Pickacl Hard Flagella A&P 3	determined to be in airworthy condition. END.			
	1		Solid AGP 3	172/0/ IA			



			the state of the s	-
DATE	TOTAL TIME IN SERVICE	TOTAL TIME SINCE OVERHAUL	TACH OR RECORDING METER TIME	

## DESCRIPTION OF WORK PERFORMED— SIGNATURE & CERTIFICATE NO. OF PERSON PERFORMING WORK

TOTALS brought forward from previous page

9-1-2021 Tach: 41.57, TT: unknown

I certify this propeller has been inspected IAW an annual inspection per the scope & detail of 14 CFR, Part 43, appendix D. All AD's are in compliance, as recorded on attached AD report. The prop at this time is found to be in an airwerthy condition.

Paul Domeier A&P 3757961 IA

SUB-TOTALS this page

TOTALS-Carry forward to next page