

N374TL



---

## Propeller Logbook

---

3135 DONALD DOUGLAS LOOP S, SANTA MONICA, CALIF. 90405-6186  
PHONE 1-800-421-9995  
FAA CRS ZY2R362L



# WARRANTY

**AIRCRAFT OWNER PLEASE NOTE:**

**Santa Monica Propeller Inc.** thanks you for purchasing this propeller or overhaul from our facility.

**Santa Monica Propeller Inc.** is proud to offer what we believe to be the most comprehensive **WARRANTY** in the aviation industry.

**Santa Monica Propeller Inc.** warrants this propeller to be free of defects in material and craftsmanship for *TWO (2) YEARS* or *ONE THOUSAND (1000) HOURS* from time of overhaul, whichever comes first.

This **WARRANTY** is not pro-rated and includes commercial usage.

This **WARRANTY** entitles purchaser to repairs by **Santa Monica Propeller Inc.** only.

Assemblies must be shipped prepaid and will be returned within five (5) working days F.O.B. **Santa Monica Propeller Inc.**


Assemblies must be accompanied by the original work order (invoice). NO EXCEPTIONS.

This **WARRANTY** is transferable per conditions on reverse.  
(See inside back cover)



3135 Donald Douglas Loop S  
SANTA MONICA, CA 90405-6186

FAA CR ZY2R362L  
(310) 390-6233  
TOLL FREE  
(800) 421-9995

  
Authorized Signature

72276  
Work Order #

8/30/02  
Date



# PROPELLER MAINTENANCE RECORD

## LEFT ENGINE

Hub Model \_\_\_\_\_

Blade Design \_\_\_\_\_

Diameter \_\_\_\_\_

Hub Ser. No. \_\_\_\_\_

Blade Ser. Nos.

No. 1 \_\_\_\_\_

No. 2 \_\_\_\_\_

No. 3 \_\_\_\_\_

No. 4 \_\_\_\_\_

No. 5 \_\_\_\_\_

### PITCH RANGE

High \_\_\_\_\_ Low \_\_\_\_\_

Feather \_\_\_\_\_ Reverse \_\_\_\_\_

Governor Model \_\_\_\_\_

## RIGHT ENGINE

Hub Model B3D36C431-B

Blade Design 80 VSA-1

Diameter 79"

Hub Ser. No. 981724

Blade Ser. Nos.

No. 1 SD 217

No. 2 SD 238

No. 3 SD 239

No. 4 —

No. 5 —

### PITCH RANGE

High 31.7° Low 14.9°

Feather — Reverse —

Governor Model —



**DESCRIPTION OF ALL OPERATIONS  
PERTAINING TO AIRWORTHINESS DIRECTIVES.  
SERVICE BULLETINS, SERVICE LETTERS  
& MINOR ADJUSTMENTS**

*TTSN 93.8*

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
<i>8/30/02</i>		<b>PROPELLER COMPLETELY OVERHAULED. L.A.W. McCAULEY SERVICE MANUAL # <u>761001</u>, BOM 100-1 SP-1- ALL McCAULEY S.B.'s AND S.L.'s COMPLIED WITH TO DATE. <del>NO AD'S DUE</del> <input checked="" type="checkbox"/> NO AD'S DUE</b>	
<i>T.S.O.</i>	<i>00.00</i>	<b>THE AIRCRAFT AND/OR COMPONENT IDENTIFIED ABOVE WAS REPAIRED AND INSPECTED IN ACCORDANCE WITH CURRENT FEDERAL AIR REGULATIONS AND WAS FOUND AIRWORTHY FOR RETURN TO SERVICE. PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS AGENCY UNDER THIS INVOICE NUMBER AND DATE.</b>	
<i>W.O. 72276</i>		<b>SIGNED <u>[Signature]</u> AUTHORIZED SIGNATURE F.A.A. A.R.S. NO. ZY2R362L</b>	
<i>TACH- 1638.7</i>			


**LEA, INC. DBA LEADING EDGE AVIATION FAA CRS LE6R154J  
2016-L PALOMAR AIRPORT ROAD CARLSBAD, CA 92008-4814 (760) 931-8565**

10/30/2002 N374TC TACH 1638.7. MCCAULEY PROPELLER B3D36C431-B/80VSA-1 SERIAL NUMBER 981724, BLADE SERIALS SD217, SD238, SD239. INSTALLED THIS PROPELLER TO CESSNA 182S SERIAL NUMBER 18280375. GROUND RUNUP/ FUNCTION CHECK/LEAK CHECK OK. WORK ORDER NUMBER 189877

*[Signature]*



**DESCRIPTION OF ALL OPERATIONS  
PERTAINING TO AIRWORTHINESS DIRECTIVES.  
SERVICE BULLETINS, SERVICE LETTERS  
& MINOR ADJUSTMENTS**

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
May 12, 2003		<b>PROPELLER</b>	
N374TC Cessna 182S	S/N-18280374	Tach: 1809.4 ACTT: 1809.4 SMOH: 353.3	
PSMOH: 170.7			
Completed 100hr Inspection in accordance with Part 43: appx. (d). I CERTIFY THAT			
THIS ENGINE WAS INSPECTED IN ACCORDANCE WITH A 100HR INSPECTION			
AND WAS DETERMINED TO BE IN AN AIRWORTHY CONDITION.			
Signed			
Granite Mountain Aviation Services Inc. 6543 Crystal LN, Prescott AZ.			526475413 IA



**DESCRIPTION OF ALL OPERATIONS  
PERTAINING TO AIRWORTHINESS DIRECTIVES.  
SERVICE BULLETINS, SERVICE LETTERS  
& MINOR ADJUSTMENTS**



2650 West Shamrell Blvd  
Flagstaff Pulliam Airport  
Flagstaff, AZ 86001  
520.779.9585  
520.779.9586 fax

**April 19, 2004**

**N374TC**

**Tach: 1925.1**

WO-04-1016

TSMOH: 469.0

Completed Annual inspection in accordance with Cessna service manual and FAR 43 appendix D. Profiled propeller blades. AD's checked through 2004-05.  
I certify this propeller has been inspected in accordance with an Annual inspection and was determined to be in an airworthy condition.

Anthony J. Koehler 524278346 IA



DESCRIPTION OF ALL OPERATIONS  
PERTAINING TO AIRWORTHINESS DIRECTIVES.  
SERVICE BULLETINS, SERVICE LETTERS



2650 West Shamrell Blvd  
Flagstaff Pulliam Airport  
Flagstaff, AZ 86001

520.779.9585

520.779.9586 fax

May 2, 2005

N374TC

Tach: 1975.1

WO-05-1415

Completed Annual inspection in accordance with Cessna maintenance manual. I certify that this propeller has been inspected in accordance with an Annual inspection and was determined to be in an airworthy condition.

Michael J Clever 299827544 IA





2650 West Shamrell Blvd  
Flagstaff Pulliam Airport  
Flagstaff, AZ 86001  
928.779.9585  
928.779.9586 fax

DATE

May 25, 2006

N374TC

Tach 2036.0

SIGNATURE

WO 06-1825

Completed Annual inspection checklist in accordance with Cessna maintenance manual and FAR 43 appendix D. I certify this Propeller has been inspected in accordance with an annual inspection and is approved for return to service.

Michael J Clever 299827544 IA





2650 West Shamrell Blvd  
Flagstaff Pulliam Airport  
Flagstaff, AZ 86001  
928.779.9585  
928.779.9586 fax

DATE

**June 8, 2007**

**N374TC**

**Tach 2060.1**

SIGNATURE

WO 07-2193

Prop TSMOH: 421.4

Completed Annual inspection checklist in accordance with Cessna maintenance manual and FAR 43 appendix D. Dressed and painted blades. I certify this Propeller has been inspected in accordance with an annual inspection and is approved for return to service.

Michael J Clever 299827544 IA

**SAFE FLIGHT AVIATION  
MIDDLETOWN, OHIO  
N374TC  
PROPELLER S/N 981724**

**6-2-2008 TACH-2100.3 PTT-555.4 PSOH-461.6** Researched AD'S through biweekly 2008-11 using the IApproach Pro system. Updated AD list. I certify that this propeller has been inspected I/A/W a 100 hour inspection and was found to be in an airworthy condition at this time. -----Kurt M. Yearout

A&P 3126345



3135 DONALD DOUGLAS LOOP S, SANTA MONICA, CALIF. 90405-6186  
PHONE 1-800-421-9995  
FAA CRS ZY2R362L

## Propeller Logbook

**SANTA MONICA**  
**PROPELLER**



**MOTIVE SERVICES CO.**  
8411 PYOTT ROAD  
LAKE IN THE HILLS, ILLINOIS 60156  
HANGAR P-62 LAKE IN THE HILLS AIRPORT


**JUNE 22, 2009**  
**2151.1 TACH TIME**

**N24389**  
**606.2 TOTAL TIME**

**McCAULEY B3D36C431-B S/N 981724**  
**512.4 TIME SINCE MAJOR OVERHAUL**

**PERFORMED ANNUAL INSPECTION IN ACCORDANCE WITH CESSNA 182S ANNUAL INSPECTION CHECK LIST.**  
**DRESSED AND PAINTED BLADES. AD's CHECKED THROUGH 2009-12 ISSUE. NONE APPLY AT THIS TIME. AN AD**  
**STATUS/COMPLIANCE LIST WAS COMPILED, DOCUMENTED, AND PLACED WITH THE AIRCRAFT RECORDS. END.**

**I CERTIFY THAT THIS PROPELLER HAS BEEN INSPECTED IN ACCORDANCE WITH AN ANNUAL INSPECTION**  
**AND WAS FOUND TO BE AIRWORTHY. LYNN HADLER A&P 1736940 IA**



**Smyrna Air Center**  
**300 Doug Warpoole Rd**  
**Smyrna, TN 37167**  
**(615) 459-3337**

**Date: June 10, 2010**

**N374TC**

**Cessna 182S**

**S/N: 18280374**


**Tach: 2174.3**

**PTSN: 629.4**

**Propeller: McCauley B3D36C431-B**

**S/N: 981724**

**Complied with Annual Inspection using the Cessna 182S inspection guide intervals A, B, C, and D.**  
**I certify this propeller has been inspected IAW Cessna 182S Inspection guide and has been determined**  
**to be in airworthy condition. Details are on file at Smyrna Air Center under W.O. # 23138.**

  
**CRS# RG4R491M David A. Clouse**



Date: 7-01-11

Aircraft # N374TC

Serial # 18280374

Tach: 2207.3

Total Time: 2207.3

SMOH: 751 hr

Comments:

Accomplished Annual Inspection checklist in accordance with Cessna maintenance manual and FAR 43 appendix D. I certify that this propeller has been inspected in accordance with annual inspection and found to be in a airworthy condition.

Prepared By: David Plumley

Certification # A&P/IA 3026056

improper engine lubricants and/or de-ice heater damage due to foreign objects.

 **SANTA MONICA  
PROPELLER**

*see next log book*