

RH

**PROPELLER
MAINTENANCE
RECORDS**

PROPELLER MAINTENANCE RECORDS

Log No

Aircraft Registration No. N155RP

Propeller Manufacturer Hartzell

Hub Model PHC-C3YF-2UF

Blade Design No. EB2727

Hub Serial No. EB 2727

Blade Serial No's.

Right Prop

1. _____

2. _____

3. _____

4. _____

ch Range:


h _____ Low _____

ther _____ Reverse _____

Governor Manufacturer _____

Model No. _____

DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS



GREELEY, CO
REPAIR STATION BX4R092M
(970) 353-9200

02-03-06

Hobbs 3738.4

N155RP

sn 340A1265

Installed overhauled RH propeller Hartzell Model # PHC-C3YF-2UF sn EB2727 after H&S Propeller Shop, Inc. CRS# MQ5R050N WO# 27854.

This aircraft was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is approved for return to service.

LIMITED TO THE WORK PERFORMED

Pertinent details on file at Beegles Aircraft Service, Inc., Greeley, CO.

Work Order # 10,291 CRS BX4R092M

Signed

A handwritten signature in dark ink, appearing to read "Steve V. March", is written over a horizontal line.

Installation Operation Service

PROP MODEL (R):
PHC-C3YF-2UF
PROP S/N (R): EB2727
REG. NO: N155RP
WORK ORDER: 23164

Aerodyne Corporation

Repair Station No. HO1R-199K
5198 West Military Highway
Chesapeake, VA 23321 USA
Phone: (757) 488-2898

1 of 2

DATE: 9/1/2021
A/C TSN: 4550.1
PROP TT (R): 1930.4
TSPOH (R): 812.1
HOBBS: 4550.1


Right Prop Entries

(5) Completed right propeller 100 hour inspection in accordance with the manufacturer's recommendations and a checklist conforming to Title 14 Code of Federal Regulations Chapter 43 Appendix D. Denicked blades. Serviced propeller hub with Aeroshell No. 6 grease.

The article identified hereon was inspected in accordance with a 100 Hour Inspection, found to be in an airworthy condition and approved for return to service.

DATE: 9/1/2021

SIGNED:



Work Order: 23164

Denise Eaton
Certified Repair Station No. HO1R-199K

Printed by EBis 3 (datcomedia.com)
