

#1



N 9505H

Left ☐ Right ☐

AMERICAN PROPELLER SERVICE

20208 Charlane Drive

Redding, California 96002, U.S.A.

PHONE NUMBER (530) 221-4470 / (800) 292-PROP (7767)

FAA REPAIR STATION # NO3R717L

E-mail: amprop@americanpropeller.com

PROPELLER LOGBOOK

PROPELLER MAINTENANCE RECORD

Propeller Manufacturer: MCCAULEY

☐

Left Engine

☐

Right Engine

☒

Front Engine

☐

Rear Engine

Hub Model No. 1C160/DTM7553

Hub Serial No. 727097

Blade Model No. _____

Blade Serial No. 1 _____

No. 2 _____

No. 3 _____

No. 4 _____

No. 5 _____

PITCH RANGE

Low _____ High _____ Feather _____ Reverse _____

Pitch 53"

Governor Manufacturer: _____

Governor Model No. _____

Governor Serial No. _____

DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS

DATE

5-9-01

AMERICAN PROPELLER SERVICE

F.A.A. Repair Station No. NO3R717L

20208 Charlanne Dr., Redding, California 96002, U.S.A.

Work accomplished **COMPLETE OVERHAUL:** Propeller metric and dye
penetrant inspected. Propeller ground, balanced
blodined, painted and detailed.

Complied with S.B. 137S and 195.

The aircraft and/or component identified above was repaired and inspected in accordance with current
Federal Aviation regulations and is approved for return to service.

Pertinent details are on file at this agency under Work Order No. 30627

Invoice No. 49151

Dated May 9, 2001


Signed

Todd Marinkovich


TODD MARINKOVICH

Authorized Individual

**DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS**

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
5-25-05	4575.6	REMOVED SPINNER, CHECKED PROPELLER, BACKING	
	TACH	PLATES, AND PROP BOLTS FOR SECURITY AND	
		CONDITION, FLOWED ON, PAINTED TIPS, AND FACE.	
	266.6		
	SPON	"I certify that this <u>PROPELLER</u>	
		has been inspected in accordance	
		with <u>ANWUL</u> inspection and was	
		determined to be in airworthy condition."	
			
		F. Alan Edwards A&P 556041022 IA	

**DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS**

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
5-17-06	4620.5	REMOVED SPINNER, CHECKED PROPELLER AND	
	TACH	BALANCE PLATES FOR CORRECTION, FOUND OK. AD'S	
		CLEAR THIS DATE, AD LIST W/RECORDS.	
	311.5		
	SPORT		
		"I certify that this <u>PROPELLER</u>	
		has been inspected in accordance	
		with <u>AD-2001</u> inspection and was	
		determined to be in airworthy condition."	
			
		F. Alan Edwards A&P 556041022 <u>IA</u>	

**DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS**

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
5-8-07	4671.0 Tact	REMOVED SPINNER, CHECKED PROPELLER AND BARKING PLATES FOR CORROSION, FOUND OK, REPAIRED FACE AND TIPS. AD'S CLEAR THIS DATE	
	362.0 SPOT	<p>"I certify that this <u>PROPELLER</u></p> <p>has been inspected in accordance with <u>ASA</u> inspection and was determined to be in airworthy condition."</p> <p><u>[Signature]</u></p> <p>F. Alan Edwards A&P 556041022 IA</p>	